LINEAR TRANSLATION STAGE MSM-1001 Date Printed: 12/16/2008

# Standardized Work Sheet



Operation: Station 1 Version:

Approval Date: Approval By:

Part: MSM-1001

Operation Cycle Time: 214

Sheet: 2


### **Bill of Materials**

Jumber	Rev	Description	Qty
HDW-0110	А	M5x14 Socket Head Cap Screw	4.00
HDW-0130	А	M2X8 Socket Head Cap Screw	2.00
HDW-0141	В	M3X8 Socket Head Cap Screw	4.00

### Steps

Linear Stage Prep Clip Center Limit Clip other two wires Strip Insulation
White Wires

<b>←</b> C	Flow	
<b>%</b>	Scope	
<b>(20)</b>	Objective	
	Environmental	
99	Quality	
V	Alert	
5	Instruction	
STOP	Safety	
lcon:	Meaning:	



7

\_

Ryan O'Hagan


11/7/2008

Remove Cover



4

က




Center Limit Switch Cable

5



9



Cut off White Wire

Strip Insulation

# Standardized Work Sheet



Operation: Station 1 Version:

Approval Date: Approval By:


Part: MSM-1001

Sheet: 3 Operation Cycle Time: 214

### Steps

				Manual	Waste	Manual Waste Cumulative
Figure(s)	Sed	Steps	Symbol Time		Time	Time
$\boxed{1} \boxed{2}$	9	Mark Bottom Cable	99	11.00 0.00	0.00	89.3
3	(2)	Solder Wire Pairs	5	9.00 2.00	2.00	100.3
4	8	Crimp Pins	75	11.00 6.70	6.70	118

¥	Flow	
<b>%</b>	Scope	
<b>(2)</b>	Objective	
	Environmental	
9	Quality	
V	Alert	
5	Instruction	
STOP	Safety	
lcon:	Meaning:	




7

\_

Ryan O'Hagan

11/7/2008


က








Installed Crimp Pins





2

Install Male Pins

# Standardized Work Sheet



Part: MSM-1001		0)	Sheet: 4	
Operation: Station 1		)	Operation Cycle Time: 214	ne: 214
Version:	1			
Approval Date:	11/7/2008			
Approval By:	Ryan			
-	O'Hagan			

S	
Step	

Figure(s)	Sed	Steps	Symbol	_	Waste Time	Manual Waste Cumulativ
1 2	6	Solder pins	75	56.00 9.00	9.00	183
ဧ	<del>(1</del> )	Electrical Plug	7	17.00 0.00	0.00	200
4	(11)	Motor Mount Plate	<u> </u>	14.00 0.00	0.00	214

~						m
Time	183	200	214	₩	Flow	
Time	9.00	00.0	00.0	8	Scope	
Time	56.00	17.00	14.00		Objective	
Symbol	5	5	99	<b>(2)</b>		
0)					Environmental	
bs				<b>D9</b>	Quality	
Steps			je.	<b>→</b>	Alert	
	Solder pins	Electrical Plug	Motor Mount Plate	5	Instruction	
Sed	s <u>6</u>	(10) E		STOP	Safety	
Figure(s)	1 2	3	4	lcon:	Meaning:	

