


INSTRUCTIONS

Verification of truth table for NOT gate



TRUTH TABLE

Print

Serial No.	A	Output	Remarks
1	1	0	Correct
2	0	1	Correct

Reset