

Diffusion Weekly PM				User ID: Fabian	
Date:		22.07.2026		System ID: Weekly PM	
Start Time:		11:30:30 am		End Time:	
Before starting PM					
Ensure production is informed of PM action					
ASM Lifetime					
Maschine	QD541.1	QD541.2	QD542.1	<u>Specifications:</u> Poly: Liner: 115'000 Boot: 55'000 Sipos. Liner: 60'000 Boot: 15'000 Nitide: Liner: 58'000 Boot: 15'000 Cold Trap: 18'000	
Liner	62570	3803	24300		
Boot A	33225	6610	3150		
Boot B	29345	20593	14400		
Cool Trap	N/A	N/A	N/A		
Maschine	QD542.2	QD543.1	QD543.2		
Liner	39000	38485	8300		
Boot A	11700	2725	7150		
Boot B	15000	1500	10880		
Cool Trap	6450	N/A	8300		
Spray Pattern Check on Zeta and Mercury					
Maschine	Status				<u>Specification:</u> Check spray pattern as described on instruction:
QD507					
QD508					
QD509					
QD510					
QD511					
QD512					
Drain Check on Zeta and Mercury					
Maschine	Status				<u>Specification:</u> Check if the Drains are opening and closing correctly
QD507					
QD508					
QD509					
QD510					
QD511					
QD512					
Bubbler Check					
Maschine	Level	Temp	<u>Specifications:</u> Level > 15% Temp 20°C (+/- 0.5°C)		
QD521.2	50	19.9			
QD521.3	100	19.8			
QD521.4	100	19.9			
QD525.1	90	20			
QD525.2	101	19.7			
QD525.3	101	20			
QD525.4	27	20.4			
QD525.5	26	19.7			
QD526.1	60	19.9			
QD526.2	60	19.9			
QD526.3	98	20			
QD526.4	60	19.8			
QD540.1	33.5	19.8			
QD540.2	45.3	19.7			
QD545.1	26.5	19.6			
QD545.2	33.1	19.6			
Maschine Panel Check and Waferbreaks					
Maschine	OK	Maschine	OK	<u>Specification:</u> All maschine panels are in place	
QD521	OK	QD542	OK		
QD525	OK	QD543	OK		
QD526	OK	QD544	OK		
QD540	OK	QD545	OK		
QD541	OK	Koyo	OK		
Clean Umhorder and Port Area					
Maschine	OK				<u>Specification:</u> Clean Port area and Umhorder
QD521					
QD525					
QD526					
Check Centrotherm Boots					
Maschine	OK	Date of change		<u>Secification:</u> Check Boots for visible contamination. IF YES: Write down the date of change	
QD521.2	OK				
QD521.3	OK				
QD521.4	OK				
QD521.5	OK				
QD525.2	OK				
QD525.3	OK				
QD525.4	OK				
QD525.5	OK				
QD526.1	OK				
QD526.2	OK				
QD526.3	OK				
QD526.4	OK				
Vacuumwands Control					
Control all vaccum wands in the area for damages. Replace if needed					