9029 E Mace Road Lexington, IN, 47138 hr@beckwithindustries.com | 222 555 7777

REPORT FORM

Report Number: BKT-2050-07-1234

Date: July 04, 20250

Report Details:

Category	Subcategory
Product Defect	Manufacturing Issue

Description of the Issue:

The batch of Model X-1000 smartphones produced on July 3, 2050, showed a high defect rate during quality testing. The defects include malfunctioning touch screens and battery issues.

Location of the Issue:

Manufacturing Plant - Assembly Line 2

Reported By:

Name	Position	Contact Number
Harry Farley	Quality Control Lead	222 555 7777

Witness Details:

Name	Position	Contact Number
Elle Cooper	Production Supervisor	222 555 7777

Injured Person Details:

Name	Position	Injuries
James Smith	Construction Worker	Fractured Arm, Bruises on Right Leg

Action Taken:

- 1. Production of Model X-1000 smartphones on Assembly Line 2 halted immediately after discovering the defects.
- 2. The defective units have been segregated and marked for further investigation.
- 3. Engineering team was notified to conduct a root cause analysis.

Recommendations:

- 1. Conduct a thorough analysis to identify the cause of the defects.
- 2. Implement corrective actions to prevent similar issues in future production runs.
- 3. Increase quality control checks during the manufacturing process.

Additional Notes:

The affected batch size: 1000 units
Estimated percentage of defects: 8%
Estimated financial impact: \$25,000

Report Prepared By:

Name	Position	Contact Number
Lana Hannon	Quality Officer	222 555 7777