STANDARD OPERATING PROCEDURE OF Corrosion Resistance VF-E09

Lab /SOP/51



Immersion dish

Sodium Chloride (NaCl) – AR Grade

Crock meter test cloth

Glass plate



Test two (2) samples per material.



Prepare a 3% sodium chloride water solution.
To prepare 3%, weigh 3 grams of NaCl , dissolve in 97 ml of distilled water.



Place a piece of the white cloth onto the bottom of the immersion dish.
Place the test samples on the white cloth



Pour the 3% NaCl solution into the immersion dish until the test samples is approximately half immersed. Do not completely immerse the test samples, Record the time.



Place the glass plate on top of the immersion dish such that a small opening remains (the opening should be approximately 1/10 the surface area of the opening of the immersion dish).



Examine the samples at least every two (2) hours during the working day, record any changes in appearance to the test sample.
After 24 hours, replace any water which has evaporated from the salt solution.
Conclude the test after 48 hours.



Report any change in the appearance of the test sample or discoloration of the white cloth.
The failure point including signs of rust/corrosion, peeling of plating,discoloration, tarnishing etc.

Prepared by	Approved by	REVISION		DATE	