VF Asia Footwear Laboratory Testing Manual

Test Method for Contact Discoloration	Test method # VF- E05 Page 1 of 2
Date Issued : May, 2019 Revision # : 1 Reason for revision : Change reference # from SATRA 43 to AATCC 8	Created by : Nila Babia Erazo

PURPOSE AND SCOPE: To measure the tendency of a material to cause discoloration of another material when the two materials are in contact.

REFERENCE: AATCC 8

EQUIPMENT AND MATERIAL:

1. Glass plates ,at least 60mm*50mm
2. 1000+/-10grams weight
3. Air-circulating oven, capable of maintaining 60+/-2°C
4. AATCC Chromatic Transference Scale.
5. Various combinations of materials which contact each other and may results in color/dye migration from one of the materials (e.g. an upper material and the pressure –sensitive adhesive used to tack it to a second upper or lining material).

SAMPLE PREPARATION:

1. Condition the sample for at least 24 hours at standard laboratory environment at 23.0±2.0˚C temperature and 55 ±10 % Relative Humidity.
2. Die or hand cut a piece of the darker colored test material 50+/-2mm*40+/-2mm,Die or hand cut a piece of the lighter colored test material 60+/-2mm*50+/-2mm.

Note: If an adhesive is being evaluated, coat the adhesive at a normal thickness centrally onto the darker material such that at least 75% of the surface is coated, allow the adhesive to fully dry at room temperature.

REPETITIONS: Test one (1) sample per material combination.

TEST PROCEDURE:

1. Place the larger of the test materials centrally on a glass plate with the contact face of the test material facing upward.
2. Place the other test material centrally onto the first test material such that the contact faces of the two test materials are brought together.
3. Place a second glass plate centrally on top of the test sample assembly.
4. Place a 1000+/-10grams weight on the top glass plate.
5. Place the assembly in an oven at 60+/-2°C.

Test Method for Contact Discoloration	Test method # VF- E05 Page 1 of 2
Date Issued : May, 2019 Revision # : 1 Reason for revision : Change reference # from SATRA 43 to AATCC 8	Created by : Nila Babia Erazo

6. Example (as described in **STEP7**) the test materials after 4 hours ,1 day,3 days, and 7 days ,by separating the test materials and comparing them to unexposed materials, Following each examination ,reassemble the test materials as before, and replace the assembly into the oven until the next examination time.
7. Compare the darkest portion of the lighter colored test material to the AATCC Chromatic Transference Scale and rate to the nearest 0.5 scale. Rate the color of the unexposed lighter colored test material to the AATCC Chromatic Transference Scale and rate to the nearest 0.5 scale. The evaluation must be performed in normal daylight.

Note:

1. This comparison will typically be made using the lighter colored material ,as the darker material may often be too dark for the AATCC Chromatic Transference Scale ,If this is the case, any color changes to the darker material should be recorded qualitatively. However, if the darker material is not too dark to utilize the AATCC Chromatic Transference Scale, the Contact Discoloration can be measured in the same way as the lighter material

2. Chromatic Transference Scales must be replaced at least every 12 months.

REPORT:

The Contact discoloration is reported to the nearest 0.5 unit based on the AATCC Chromatic Transference Scale.