VF Asia Footwear Laboratory Testing Manual

Test Method for PVC Migration Fastness	Test method # VF- E06 REF # : TM-R -063 Page 1 of 2
Date Issued : July 2, 2014 Revision # : 1 Reason for Revision : TBL and VF compromised on test conditions , refer to option 1 and option 2	Created by : Nila Babia Erazo / Chris Adam

PURPOSE AND SCOPE: To measure the tendency of dyestuffs to migrate from leather, fabrics, and synthetic leathers, as a result of contact with plasticized PVC.

REFERENCE: DIN 53343

EQUIPMENT AND MATERIAL:

1. PVC sheet
2. Glass plates at least 10mm*15mm
3. 1.0kg weight
4. Air-circulating oven, capable of maintaining 60+/-2°C.
5. AATCC Chromatic Transference Scale
6. Fabric, Leather, and synthetic leather.

SAMPLE PREPARATION:

1. Condition the sample for at least 24 hours at standard laboratory environment at 23.0±2.0˚C temperature and 55 ±10 % Relative Humidity.
2. Die or hand cut a piece of test sample 10mm*15mm.
3. Die or hand cut a piece of the PVC sheet 15mm*25mm.

REPETITIONS: Test one (1) sample per material.

TEST PROCEDURE:

1. Remove the protective backing from the PVC sheet, (Do not use any PVC sheet which is soiled, discolored or otherwise damaged).
2. Place the test sample onto the center of the PVC sheet, the side of the test sample which is being evaluated should be in contact with the side of the PVC sheet, which was covered with the protective backing.
3. Place the test sample/PVC sheet lay-up between two pieces of glass, such that the lay-up is located at the center of the glass plates.
4. Place a 1.0+/-0.1kg weight on the top glass plate.

Test Method for PVC Migration Fastness	Test method # VF- E06 REF # : TM-R-063 Page 2 of 2
Date Issued : July 2, 2014 Revision # : 1 Reason for Revision : TBL and VF compromised on test conditions , refer to option 1 and option 2	Created by : Nila Babia Erazo / Chris Adam

Option 1:

Place the entire assembly in an oven at 50+/-2°C for 16 hours.

Option 2: TBL Material

Place the entire assembly in an oven at 60+/-2°C for 24 hours

5. Remove the assembly from the oven, and then remove the weight from the top glass plate. Leave the test sample /PVC sheet lay-up between the glass plates, and allow to cool at 23+/-2°C for 2 hours.
6. Separate the test sample from the PVC sheet.
7. Evaluate the PVC migration fastness of the dye in the test material by comparing the darkest portion of the PVC sheet to the AATCC Chromatic Transference Scale. The evaluation must be performed under normal daylight.

Note: Chromatic Transference Scales must be replaced at least every 12 months.

REPORT: The reading from the AATCC Chromatic Transference Scale to the nearest 0.5.

Note: The PVC sheet material which must be used is TM 727-Soft PVC sheet in conformance with VESLIC-C 4420(IUF 442).