VF Asia Footwear Laboratory Testing Manual

Test Method for Dip Test	Test method # VF-E26 REF #: Page 1 of 2
Date Issued: September 16, 2020 Revision #: 0 Reason for revision:	Created by:

PURPOSE AND SCOPE: To determine the potential color stain, bleeding or migration on footwear upper materials with color-block when the footwear is wetted during wear.

REFERENCE: N/A

EQUIPMENT AND MATERIAL:

1. Distill water
2. Water bath
3. 1 pair of shoes (1 for kept and 1 for testing)
4. Grey Scale

SAMPLE PREPARATION:

Condition the sample for at least 24 hours at standard laboratory environment at 23.0±2.0 °C temperature and 55 ±10 % Relative Humidity.

Samples should have no color stain, bleeding or migration observed.

REPETITIONS: Perform once per sample.

TEST PROCEDURE:

1. Remove sockliner from the shoe prior testing.

2. Pour distilled water into water bath, put the shoe into water bath 1 minute fully submerged until the upper is thoroughly wetted.

3. Empty excess water and leave the footwear to dry at room temperature, clean the water bath and keep it dry before next testing.

4. When the footwear is completely dried, check for any color staining, bleeding or migration.

5. Assess the severity of staining using the Grey Scale for Color Staining and Color Change comparing to the kept sample.

Test Method for Dip Test	Test method # VF-E26 REF #: Page 2 of 2
Date Issued: September 16, 2020 Revision #: 0 Reason for revision:	Created by:

6. Report whether there was any Color Staining and Color Change and the Grey Scale rating for the severity of the Color Staining and Color Change.

Note: Grey Scales must be replaced at least every 12 months.

EVALUATION:

Assess Color Stain and Color Change to Grey Scale or any adverse effects compared to the kept sample. Place the test specimen in the light box, set for 'Daylight' (D65). Examine the change in color - compare the color of the darkest portion of the kept sample.

Note: The bulb shall be replaced when the total hours of usage reach 500 hours.

REPORT:

Report grading of Color Stain and Color Change of the sample.