VF Asia Footwear Laboratory Testing Manual

Test Method for Material Conditioning	Test method # VF- H01 Page 1 of 1
Date Issued : May 27, 2008 Revision # :	Created by : Nila Babia Erazo / Chris Adam

All material must be conditioned for a minimum of twenty four (24) hours at the following conditions:

- Temperature: 23 ± 2 ° C
- Relative Humidity: 55 ± 10 %