VF Asia Footwear Laboratory Testing Manual

Test Method for Electric Shock Resistance Test	Test Method #: VF- J01 Page 1 of 2
Date Issued: May 18, 2019 **Revision #: 2** **Reason for revision: Test reference changed to CSA Z195, Section 5.4**	**Created by: Nila Babia Erazo**

PURPOSE AND SCOPE: To check at dry conditions if the test specimen shall withstand a test potential of 18 kV 60 Hz for a period of 1 min without disruptive discharge to ground with the leakage current not to exceed 1 mA when tested.

REFERENCE: CSA Z195-14, Section 5.4

EQUIPMENT AND MATERIAL:

1. ESR Machine that meets CSA Z195-14 requirement.
2. Solid metal (electrically conductive) spheres of 3 mm in diameter
3. Aluminum plate of 100 mm diameter @ 1 kg mass
4. Stopwatch or timer
5. Steel Ruler
6. Unworn Protective Footwear

SAMPLE PREPARATION:

1. Select sample at random from stock that is at least 14 days old. Samples covering the full range of sizes available shall be tested.

2. Condition the test sample in a standard controlled environment at 23 +/- 2 °C and at 55 +/- 5 % RH for at least 40 hours before being tested.

3. The footwear to be tested, the sock-liner or footbed is removed unless required by the brand.

REPETITIONS: Test a pair or as required.

Test Method for Electric Shock Resistance Test	Test Method #: VF- J01 Page 2 of 2
Date Issued: May 18, 2019 Revision #: 2 Reason for revision: Test reference changed to CSA Z195, Section 5.4	Created by: Nila Babia Erazo

TEST PROCEDURE:

Test should be carried out at standard laboratory conditions @ 23.0±2.0˚C temperature and 55 ±10 % Relative Humidity.

Table 1. VF Footwear Safety Shoe Requirements for Electric Shock Resistance:

Test	Applicable Industry Standard, Including Requirements
Electric Shock Resistance	• CSA Z195-14, Section 5.4