

Fox 32 mm Fork – Full Service Sheet

2010 Trek Remedy · 26" · 15QR · tapered steerer | Prepared 22 Aug 2026 | Specs from Fox Racing Shox service data

Read this first — you must identify your fork before buying anything

The 2010 Remedy shipped with **three different** Fox 32 mm forks, and they do not share internals. The **Remedy 7** got a **32 Float** (fixed 150 mm). The **Remedy 8 / 9 / 9.9** got a **32 TALAS** (110–130–150 mm travel adjust). On top of that, the 150 mm forks were built with **two different dampers** — an open-bath cartridge and a sealed FIT cartridge — and the oil volumes differ by more than 5×. Do the two checks on the next block before ordering parts.

Step 0 · Identify what you actually have

Check	How to tell	Why it matters
1. Air spring (Float or TALAS?)	Look at the left (non-drive) top cap. A single Schrader air valve and nothing else = Float . A valve <i>plus</i> a blue travel-adjust lever/dial = TALAS . The lower-leg decal also says FLOAT or TALAS.	Float → simple air spring. TALAS → extra travel-adjust cartridge, more seals, harder job.
2. Damper (open bath or FIT?)	Find the red rebound knob. On the bottom of the right lower leg = FIT (sealed cartridge). On top of the right leg = open bath . 2010 FIT forks also carry a "FIT" decal on the left leg.	This decides your oil volumes, your damper parts, and whether you need a bleed kit.
3. Damper letters (R / RL / RLC)	Count the adjusters on the right top cap. None = R, lockout lever only = RL, lockout + blue low-speed compression dial = RLC.	Affects only the top-cap internals, not oil volume.

Write your result here: **Spring** = _____ **Damper** = _____ **Adjusters** = _____

Fluids and oil volumes

Verified against the Fox Racing Shox service data (per biketechtools' transcription of the official Fox volume charts).

Use the row that matches your fork.

Fork variant	Damper cartridge	Damper-side bath	Spring-side bath	Air chamber	2nd chamber	Total
32 Float 150 open bath RL/RLC	—	165 ml Fox Green 10 wt	30 ml Fox Green 10 wt	5 ml Float Fluid	—	~200 ml
32 Float 150 FIT RL/RLC	sealed cartridge (Fox Red 10 wt)	30 ml Fox Green 10 wt	10 ml Fox Green 10 wt	5 ml Float Fluid	—	~45 ml + cartridge
32 TALAS 150 FIT RL/RLC	35.2 ml Fox Red 10 wt	30 ml Fox Green 10 wt	10 ml Fox Green 10 wt	3 ml Float Fluid (main)	3 ml Float Fluid (negative)	81.2 ml
32 TALAS 150 open bath R/RL/RLC	—	165 ml Fox Green 10 wt (confirm on your chart)	30 ml Fox Green 10 wt	3 ml Float Fluid	3 ml Float Fluid	~200 ml

What to buy

Fluid / consumable	Quantity	Notes
Fox Green 10 wt bath oil	1 × 32 oz / 946 ml bottle	The 2010 spec bath oil. Motorex Fork Oil 10 wt is the closest cross-reference (~50 cSt vs Fox ~47 cSt @ 40°C). Do not substitute the newer 20 wt Gold.
Fox Red 10 wt damper oil	1 × small bottle — FIT forks only	Only needed if you have the sealed FIT cartridge. Motorex Shock Oil 7.5 wt is the common European substitute.
Fox Float Fluid	1 × small bottle	Air-spring lube. Tiny quantities (3–5 ml) but it is not optional — it is what stops the air piston stick-slip.
Isopropyl alcohol + lint-free rags	500 ml	For flushing the lowers. Brake cleaner will attack the seals — avoid it.
Slick Honey or Fox float grease	1 tub	For seal lips, o-rings and the air piston on reassembly.

Parts and seals

Availability warning — this is the real difficulty of the job

Your fork is 16 years old and well outside Fox's support window, so several original kits are discontinued. Critically: the current Fox 32 mm wiper kit **803-00-944** is the **2016+ flangeless** design and Fox state it is **not** backward compatible with pre-2016 flanged lowers — yours are flanged. Buy an aftermarket kit that explicitly lists 2003–2015 fitment instead. I could not confirm a still-current Fox part number for the flanged 32 mm wiper kit.

Part	Qty	Detail / part number	Confidence
Dust wipers + foam rings (essential)	1 kit	SKF 32 mm dual-compound kit (listed 2003–2015) or Enduro Bearings FK-6650 — contains 2 inner oil seals, 2 dust wipers, 2 foam rings, 2 crush washers, 1 metal washer.	Confirmed — recommended route
Fox flanged 32 mm wiper kit	1 kit	OEM equivalent for pre-2016 lowers. Fox 803-00-944 is the WRONG part (flangeless, 2016+).	Part number unconfirmed — ask a Fox service centre
Cartridge / damper seal kit	1 kit	Fox 803-00-078 "Kit: Cartridge Seals, 32 mm, Open Bath". Reported to include damper cartridge seals, dust wipers, Float Fluid and 250 ml Motorex damping oil. Discontinued by Fox — secondary market only (Retro Bicycle Parts, eBay, TF Tuned).	Part number confirmed; contents per retailer listings, not Fox
Air spring seal kit (pre-NA2)	1 kit	Fox 803-00-704 is listed by retailers as a pre-2016 air spring seal kit. Do NOT buy 803-00-962 — that is the 2016+ NA2 spring and will not fit.	803-00-962 exclusion confirmed; 803-00-704 fitment unconfirmed
Air piston quad ring / glide ring	1	The single most common cause of a Float that loses pressure or feels sticky off the top. Usually inside the air spring kit; otherwise source by dimension.	Wear item — replace
Lower-leg crush / sealing washers	2	Under the bottom nuts. Cheap, single-use, and the usual cause of a weeping lower leg. Included in the Enduro FK-6650 kit.	Confirmed — always replace
Top cap o-rings	2–3	Air top cap and damper top cap. Measure and source generic NBR if the kits do not include them.	Replace if hardened
TALAS travel-adjust seals	1 set	TALAS forks only. The needle-valve and travel-adjust assembly seals. The 2010 TALAS is known for sticky or non-returning travel adjust when these harden.	TALAS only
Lower-leg bushings	4 (set)	Fox 803-00-102 . Only if you have detectable fore/aft play in the lowers. Needs the 803-01-909 extractor and an install kit — not a home job , send it out.	Confirmed; professional fitment
15QR axle hardware	as needed	Fox 803-00-370 service set: axle nut, hold-down and set screw.	Confirmed

Torque values

From the Fox Racing Shox owner's manual torque table, 32 mm air-spring forks. Use an in-lb torque wrench — the bottom nuts in particular are far tighter in most people's hands than 50 in-lb.

Fastener	in-lb	N·m	Tool / note
Top caps (air and damper side)	220 in-lb	24.9 N·m	26 mm socket, 6-point, chamfer-less
Bottom nuts (lower-leg shaft nuts)	50 in-lb	5.7 N·m	usually 10 mm socket
Base valve bolt	75 in-lb	8.5 N·m	open-bath damper
Rebound adjustment insert screw	3 in-lb	0.33 N·m	very light — easy to strip
Rebound knob screw (Fox 36 reference)	11 in-lb	1.2 N·m	use as a guide if not listed for 32 mm
Brake hose guide screw (M3 × 12)	8 in-lb	0.9 N·m	2.5 mm hex
15QR axle	hand-tight via lever	—	quick release — not a torque item

Tools

Stage	Tools
Lower-leg service (everyone)	In-lb torque wrench · 10 mm socket · 26 mm 6-point chamfer-less socket · soft-faced mallet · vice with soft jaws · seal driver for 32 mm (or a length of 32 mm ID pipe) · plastic tyre lever or seal pick · oil measuring syringe with ml graduations · shock pump · drain pan · nitrile gloves
Open-bath damper rebuild	As above plus: base valve removal tool · snap-ring pliers · Fox shaft clamps 803-00-084 (32 mm) · compression adjuster wrench

Stage	Tools
FIT cartridge bleed (the hard part)	Fox FIT bleeder syringe 803-00-276 · bleed adapter 803-00-809 · clear 5/16" ID vinyl tubing · shaft clamps 803-00-147 · removal tool 398-00-681 . These are hard to improvise. If you do not have them, do the lowers and air spring yourself and send the cartridge out.
TALAS travel-adjust	TALAS-specific travel adjust / IFP port tool · shock pump (not a track pump). The forums document a football-pump-adapter workaround for the IFP tool.

Tutorials

Ranked by how closely they match a 2010 32 mm fork. Be wary of anything filmed on a 2016+ Float 32 with a FIT4 or GRIP damper — the air spring and damper are a different design and the oil volumes are wrong for you.

Best matches for your fork

Title	Source	Link	Why it fits
Fox 32 Float RL service (open bath)	YouTube	youtube.com/watch?v=RmsdsoP_Z-Q	Posted 2012 on the exact open-bath RL cartridge. Seal removal, cartridge service, oil fill. Not in English but the visuals carry it.
Fox Talas 32/36 FIT RLC Federgabelservice	YouTube	youtube.com/watch?v=SM6ih1WewEw	German with English subtitles. TALAS travel-adjust + FIT RLC damper + lowers. The closest single video if you have the TALAS FIT fork.
Fox 32 mm TALAS maintenance	YouTube	youtube.com/watch?v=VQ0oZbG3x50	2008-era TALAS, i.e. the generation immediately before yours. Lower leg oil, wipers, foam rings.
How to bleed a Fox FIT cartridge (part 4 of 4)	Hack Racer blog	hackracer.com/2012/04/tech-part-4-of-4-how-to-bleed-fox-fit.html	Written, photographed, done on an F32. The best free walkthrough of the FIT bleed, which is the step most people get wrong.
The Unofficial Fox TALAS Service Guide	manualzz.com	manualzz.com/doc/6304871/the-unofficial-fox-talas-i-service-guide	33-step community guide built from Fox diagrams. TALAS travel-adjust teardown in detail.

Official Fox documentation and general technique

Resource	Link	Use
Fox owner's manual torque values (2011)	tech.ridefox.com/fox_tech_center/owners_manuals/011/Content/Torque_Values.html	The source of the torque table above.
Fox 32 mm part information / exploded drawings	tech.ridefox.com/bike/parts-drawings/558/32mm-part-information	Part numbers and diagrams. Start here when you need to identify a specific o-ring.
Fox 2013–2015 32 mm basic maintenance	tech.ridefox.com/bike/service-procedures/573/2013-2015-32mm-basic-maintenance	Newer than your fork but the closest official written procedure still hosted.
Fox oil volume charts (all years)	biketechtools.com/forks/oil-volumes/fox/select-fork	Pick your exact fork and damper — the source of the volumes on page 1.
Fox DIALED S2 E9: servicing lower legs	youtube.com/watch?v=xB5rc602MhQ	Official Fox technique for lower-leg service. Modern fork, but correct method.
Shockcraft Fox oil equivalents chart	shockcraft.co.nz/oils/oem-equivalents-oil-charts/fox-oem-equivalents	For sourcing Motorex or other equivalents in Norway rather than Fox-branded oil.
MTBR: 2010 Fox 32 RLC (FIT) service manual thread	mtbr.com/threads/2010-fox-32-rlc-fit-service-manual.1575783/	Owners of your exact fork, plus links to archived manuals.
Singletrack World: Fox 32 Float RL open bath servicing	singletrackworld.com/forum/topic/fox-32-float-rl-open-bath-servicing/	Practical notes and improvised-tool workarounds for the open-bath fork.

Notes worth reading before you start

“200 hour service” is newer Fox language

Fox introduced the 50 h / 125 h / 200 h interval scheme for later forks. For a 2010 32 mm the published guidance was a 30 h lower-leg oil change and an annual full strip. What you are doing is simply the full strip: lowers, air spring, damper, all seals.

Scope creep is likely

On a 16-year-old fork, budget for the possibility that the stanchions are pitted, the bushings are worn, or the TALAS assembly is seized. Check for fore/aft play at the lowers and inspect the stanchions for pitting **before** you order seals — if either is bad, the seals are wasted money.

Do the easy 80 % yourself	Lowes, wipers, foam rings, bath oil and the air spring are all genuinely home-serviceable with hand tools. The FIT cartridge bleed and the bushings are the two jobs that need Fox-specific tooling. Splitting the job that way is usually the cheapest sensible route.
Economics check	Consumables run roughly €50–120 depending on OEM vs aftermarket. A shop full service is often in a similar range. Given the age and the 26" wheel size, it is worth deciding up front how much this fork is worth to you.

Every torque value, oil volume and part number here is sourced from Fox service documentation or Fox retailers, with confidence flagged in the parts table. Anything marked unconfirmed should be checked with a Fox service centre before you spend money — part numbers for this generation are poorly documented now that the fork is out of support.