```
2023-02-08 12:18:22, modbusTCP, I6-1, TEMP: 4.4 °C
2023-02-08 12:24:10, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 13:15:51, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:19:55, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 13:20:13, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 13:29:38, modbusTCP, I6-1, TEMP: 3.9 °C
2023-02-08 13:29:40, modbusTCP, I6-1, TEMP: 3.9 °C
2023-02-08 13:30:28, modbusTCP, I6-1, TEMP: 3.6 °C
2023-02-08 13:30:29, modbusTCP, I6-1, TEMP: 3.6 °C
2023-02-08 13:32:38, modbusTCP, I6-1, TEMP: 3.6 °C
2023-02-08 13:37:12, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:37:29, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:37:30, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:46:33, modbusTCP, I6-1, TEMP: 4.1 °C
2023-02-08 13:48:12, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:48:27, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 13:51:14, modbusTCP, I6-1, TEMP: 4.1 °C
2023-02-08 13:56:55, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 13:57:01, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 14:00:02, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 14:06:01, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 14:07:01, modbusTCP, I6-1, TEMP: 3.8 °C
2023-02-08 14:08:01, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 14:09:01, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 14:10:01, modbusTCP, I6-1, TEMP: 4.3 °C
2023-02-08 14:11:02, modbusTCP, I6-1, TEMP: 4.5 °C
```

```
2023-02-08 14:12:01, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 14:13:01, modbusTCP, I6-1, TEMP: 4.4 °C
2023-02-08 14:14:01, modbusTCP, I6-1, TEMP: 4.1 °C
2023-02-08 14:15:01, modbusTCP, I6-1, TEMP: 3.9 °C
2023-02-08 14:16:01, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 14:17:02, modbusTCP, I6-1, TEMP: 3.5 °C
2023-02-08 14:18:01, modbusTCP, I6-1, TEMP: 3.6 °C
2023-02-08 14:19:01, modbusTCP, I6-1, TEMP: 3.9 °C
2023-02-08 14:20:01, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 14:21:01, modbusTCP, I6-1, TEMP: 4.3 °C
2023-02-08 14:22:01, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 14:23:02, modbusTCP, I6-1, TEMP: 4.5 °C
2023-02-08 14:24:01, modbusTCP, I6-1, TEMP: 4.4 °C
2023-02-08 14:25:01, modbusTCP, I6-1, TEMP: 4.1 °C
2023-02-08 14:25:17, modbusTCP, I6-1, TEMP: 4.1 °C
2023-02-08 14:26:01, modbusTCP, I6-1, TEMP: 4.0 °C
2023-02-08 14:26:32, modbusTCP, I6-1, TEMP: 3.8 °C
2023-02-08 14:26:32, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 48.2 %
2023-02-08 14:27:01, modbusTCP, I6-1, TEMP: 3.6 °C
2023-02-08 14:27:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.1 %
```

2023-02-08 14:28:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 14:29:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 14:30:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 14:28:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.8 %

2023-02-08 14:29:02, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.4 %

2023-02-08 14:30:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.9 %

```
2023-02-08 14:31:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-08 14:31:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.7 %

2023-02-08 14:32:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 14:32:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.6 $^{\circ}$ C , RH : 48.6 %

2023-02-08 14:33:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 14:33:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.0 %

2023-02-08 14:34:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:34:02 , modbusTCP , I6-1/S-16-2 , TEMP : 21.6 $^{\circ}$ C , RH : 46.7 %

2023-02-08 14:35:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 14:35:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 45.8 %

2023-02-08 14:35:53, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 14:36:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 14:37:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 14:38:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 14:38:18, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 14:38:18, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 43.3 %

2023-02-08 14:39:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 14:39:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 43.0 %

2023-02-08 14:40:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 14:40:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.4 $^{\circ}$ C , RH : 43.0 %

2023-02-08 14:41:01 , modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 14:41:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 43.9 %

2023-02-08 14:41:22 , modbusTCP , I6-1 , TEMP : 3.9 $^{\circ}\text{C}$

2023-02-08 14:41:22, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.4 %

2023-02-08 14:41:22 , modbusTCP , I6-1/S-16-2 , TEMP : 21.3 $^{\circ}$ C , RH : 44.2 %

2023-02-08 14:42:01, modbusTCP, I6-1, TEMP: 4.0 °C

```
2023-02-08 14:42:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.5 %
```

2023-02-08 14:42:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.9 %

2023-02-08 14:43:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 14:43:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 67.7 %

2023-02-08 14:43:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.4 %

2023-02-08 14:44:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 14:44:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.0 %

2023-02-08 14:44:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 46.6 %

2023-02-08 14:45:00, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:45:00, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 68.1 %

2023-02-08 14:45:00, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 14:45:00 , modbusTCP , I6-1/S-16-2 , TEMP : 21.3 $^{\circ}$ C , RH : 47.6 %

2023-02-08 14:45:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:45:02, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 68.1 %

2023-02-08 14:45:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.6 %

2023-02-08 14:45:02, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 47.6 %

2023-02-08 14:46:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:46:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 68.3 %

2023-02-08 14:46:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 14:46:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 47.8 %

2023-02-08 14:47:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 14:47:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 68.5 %

2023-02-08 14:47:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 14:47:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 48.3 %

2023-02-08 14:48:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 14:48:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 68.7 %

```
2023-02-08 14:48:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %
```

2023-02-08 14:48:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 48.4 %

2023-02-08 14:49:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 14:49:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 68.9 %

2023-02-08 14:49:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-08 14:49:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.3 %

2023-02-08 14:50:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 14:50:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 69.1 %

2023-02-08 14:50:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 14:50:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.3 %

2023-02-08 14:51:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 14:51:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.3 %

2023-02-08 14:51:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 14:51:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.9 %

2023-02-08 14:52:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 14:52:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.5 %

2023-02-08 14:52:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.6 %

2023-02-08 14:52:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.5 $^{\circ}\text{C}$, RH : 50.3 %

2023-02-08 14:53:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 14:53:01 , modbusTCP , I6-1/S-12 , TEMP : 27.7 $^{\circ}\text{C}$, RH : 69.7 %

2023-02-08 14:53:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.8 %

2023-02-08 14:53:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 50.1 %

2023-02-08 14:54:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 14:54:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.9 %

2023-02-08 14:54:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.6 %

2023-02-08 14:54:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 48.9 %

```
2023-02-08 14:55:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-08 14:55:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 70.2 %

2023-02-08 14:55:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.4 %

2023-02-08 14:55:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 48.0 %

2023-02-08 14:56:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:56:02, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 70.4 %

2023-02-08 14:56:02, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.2 %

2023-02-08 14:56:02 , modbusTCP , I6-1/S-16-2 , TEMP : 21.5 $^{\circ}$ C , RH : 46.7 %

2023-02-08 14:57:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:57:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 70.6 %

2023-02-08 14:57:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 14:57:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 46.1 %

2023-02-08 14:58:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 14:58:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 70.9 %

2023-02-08 14:58:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.8 %

2023-02-08 14:58:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.6 %

2023-02-08 14:59:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 14:59:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 71.2 %

2023-02-08 14:59:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-08 14:59:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 45.0 %

2023-02-08 15:00:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 15:00:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 71.5 %

2023-02-08 15:00:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 15:00:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 44.7 %

2023-02-08 15:01:02 , modbusTCP , I6-1 , TEMP : 3.6 $^{\circ}\text{C}$

2023-02-08 15:01:02, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 71.8 %

```
2023-02-08 15:01:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %
```

2023-02-08 15:01:02, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 44.1 %

2023-02-08 15:02:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 15:02:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 72.1 %

2023-02-08 15:02:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 15:02:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.1 %

2023-02-08 15:03:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 15:03:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}\text{C}$, RH : 72.4 %

2023-02-08 15:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 15:03:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.2 %

2023-02-08 15:04:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 15:04:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 72.7 %

2023-02-08 15:04:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.2 %

2023-02-08 15:04:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.5 %

2023-02-08 15:05:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 15:05:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 73.0 %

2023-02-08 15:05:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 15:05:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.3 $^{\circ}$ C , RH : 44.7 %

2023-02-08 15:06:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 15:06:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}$ C , RH : 73.4 $^{\circ}$

2023-02-08 15:06:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 15:06:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.9 %

2023-02-08 15:07:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 15:07:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 73.7 %

2023-02-08 15:07:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 15:07:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.3 %

```
2023-02-08 15:08:01, modbusTCP, I6-1, TEMP: 4.5 °C
```

2023-02-08 15:08:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 74.0 %

2023-02-08 15:08:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-08 15:08:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.5 %

2023-02-08 15:09:01, modbusTCP, I6-1, TEMP: 4.8 °C

2023-02-08 15:09:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 74.4 %

2023-02-08 15:09:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.1 %

2023-02-08 15:09:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.6 %

2023-02-08 15:10:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-08 15:10:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 74.7 %

2023-02-08 15:10:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 15:10:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.4 $^{\circ}$ C , RH : 45.7 %

2023-02-08 15:11:01, modbusTCP, I6-1, TEMP: 5.1 °C

2023-02-08 15:11:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 75.1 %

2023-02-08 15:11:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.4 %

2023-02-08 15:11:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.8 %

2023-02-08 15:12:02, modbusTCP, I6-1, TEMP: 5.4 °C

2023-02-08 15:12:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 75.4 %

2023-02-08 15:12:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 15:12:02, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 46.0 %

2023-02-08 15:13:01, modbusTCP, I6-1, TEMP: 5.5 °C

2023-02-08 15:13:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 75.7 %

2023-02-08 15:13:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 15:13:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.4 %

2023-02-08 15:14:01, modbusTCP, I6-1, TEMP: 5.9 °C

2023-02-08 15:14:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3 $^{\circ}\text{C}$, RH : 75.9 %

```
2023-02-08 15:14:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %
```

2023-02-08 15:14:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.1 %

2023-02-08 15:14:18 / modbusTCP , I6-1 , TEMP : 5.9 °C

2023-02-08 15:14:18, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.6 %

2023-02-08 15:14:18, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 15:14:18, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.1 %

2023-02-08 15:14:18 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:14:18, modbusTCP, I6-2/S-9, TEMP: 20.4 °C, RH: 67.8 %

2023-02-08 15:15:01 / modbusTCP , I6-1 , TEMP : 6.0 °C

2023-02-08 15:15:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.6 %

2023-02-08 15:15:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-08 15:15:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.6 %

2023-02-08 15:15:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:15:01, modbusTCP, I6-2/S-9, TEMP: 20.4 °C, RH: 67.8 %

2023-02-08 15:16:01 / modbusTCP , I6-1 , TEMP : 6.1 °C

2023-02-08 15:16:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 76.1 %

2023-02-08 15:16:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 15:16:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.3 $^{\circ}$ C , RH : 46.5 %

2023-02-08 15:16:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:16:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 %

2023-02-08 15:17:02 / modbusTCP , I6-1 , TEMP : 6.4 °C

2023-02-08 15:17:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.4 %

2023-02-08 15:17:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 15:17:02, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 47.5 %

2023-02-08 15:17:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:17:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

```
2023-02-08 15:18:01 / modbusTCP , I6-1 , TEMP : 6.5 °C
```

2023-02-08 15:18:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.7 %

2023-02-08 15:18:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 15:18:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 47.9 %

2023-02-08 15:18:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:18:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 15:19:01 / modbusTCP , I6-1 , TEMP : 6.8 °C

2023-02-08 15:19:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 77.0 %

2023-02-08 15:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.3 %

2023-02-08 15:19:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 48.9 %

2023-02-08 15:19:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:19:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.7 %

2023-02-08 15:19:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 $^{\circ}$

2023-02-08 15:19:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 59.2 %

2023-02-08 15:19:01 / modbusTCP , I6-1 , TEMP : 6.8 °C

2023-02-08 15:19:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 77.0 %

2023-02-08 15:19:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 15:19:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.3 $^{\circ}$ C , RH : 48.9 %

2023-02-08 15:19:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:19:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 15:19:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 15:19:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 59.2 %

2023-02-08 15:20:01 / modbusTCP , I6-1 , TEMP : 7.0 °C

2023-02-08 15:20:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 77.1 %

2023-02-08 15:20:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 15:20:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 49.2 %

```
2023-02-08 15:20:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 15:20:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.7 %

2023-02-08 15:20:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:20:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.8 %

2023-02-08 15:21:01 / modbusTCP , I6-1 , TEMP : 7.1 °C

2023-02-08 15:21:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 77.3 %

2023-02-08 15:21:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 15:21:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 49.4 %

2023-02-08 15:21:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:21:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.7 %

2023-02-08 15:21:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:21:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.9 %

2023-02-08 15:22:01 / modbusTCP , I6-1 , TEMP : 7.3 °C

2023-02-08 15:22:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.5 %

2023-02-08 15:22:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.3 $^{\circ}$

2023-02-08 15:22:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 49.3 %

2023-02-08 15:22:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:22:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-08 15:22:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:22:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.9 %

2023-02-08 15:22:22 / modbusTCP , I6-1 , TEMP : 7.3 °C

2023-02-08 15:22:22, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.5 %

2023-02-08 15:22:22 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 15:22:22, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 49.3 %

2023-02-08 15:22:22 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:22:22, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

```
2023-02-08 15:22:22, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 15:22:23, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 59.0 %

2023-02-08 15:23:01 / modbusTCP , I6-1 , TEMP : 7.1 °C

2023-02-08 15:23:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6 $^{\circ}$ C , RH : 77.6 $^{\circ}$

2023-02-08 15:23:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %

2023-02-08 15:23:02 , modbusTCP , I6-1/S-16-2 , TEMP : 21.6 $^{\circ}$ C , RH : 49.0 %

2023-02-08 15:23:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:23:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:23:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:23:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 59.1 %

2023-02-08 15:24:01 / modbusTCP , I6-1 , TEMP : 7.0 °C

2023-02-08 15:24:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.8 %

2023-02-08 15:24:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.5 %

2023-02-08 15:24:02, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.9 %

2023-02-08 15:24:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:24:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-08 15:24:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:24:02 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 59.4 %

2023-02-08 15:25:01 / modbusTCP , I6-1 , TEMP : 6.6 °C

2023-02-08 15:25:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5 $^{\circ}$ C , RH : 77.8 %

2023-02-08 15:25:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 15:25:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.8 %

2023-02-08 15:25:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:25:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-08 15:25:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:25:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.9 %

```
2023-02-08 15:26:01 / modbusTCP , I6-1 , TEMP : 6.4 °C
```

2023-02-08 15:26:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 78.0 %

2023-02-08 15:26:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.2 %

2023-02-08 15:26:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.7 %

2023-02-08 15:26:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:26:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:26:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:26:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.5 %

2023-02-08 15:27:01 / modbusTCP , I6-1 , TEMP : 6.0 °C

2023-02-08 15:27:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 78.0 %

2023-02-08 15:27:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 15:27:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 49.3 %

2023-02-08 15:27:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:27:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:27:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:27:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.8 %

2023-02-08 15:28:01 / modbusTCP , I6-1 , TEMP : 5.8 °C

2023-02-08 15:28:01 , modbusTCP , I6-1/S-12 , TEMP : 25.3 $^{\circ}\text{C}$, RH : 78.1 %

2023-02-08 15:28:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 15:28:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.2 %

2023-02-08 15:28:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:28:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:28:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.5 %

2023-02-08 15:28:05 / modbusTCP , I6-1 , TEMP : 5.6 °C

2023-02-08 15:28:05, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.1 %

```
2023-02-08 15:28:05, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %
```

2023-02-08 15:28:05, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 48.1 %

2023-02-08 15:28:05 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:28:05, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:28:05, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:28:05 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}$ C , RH : 58.6 $^{\circ}$

2023-02-08 15:29:01 / modbusTCP , I6-1 , TEMP : 5.4 °C

2023-02-08 15:29:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.1 %

2023-02-08 15:29:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 15:29:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 47.1 %

2023-02-08 15:29:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:29:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:29:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:29:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.5 %

2023-02-08 15:29:28 / modbusTCP , I6-1 , TEMP : 5.1 °C

2023-02-08 15:29:28, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.1 %

2023-02-08 15:29:28, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 15:29:28 , modbusTCP , I6-1/S-16-2 , TEMP : 21.6 $^{\circ}\text{C}$, RH : 46.8 %

2023-02-08 15:29:28 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:29:28 , modbusTCP , I6-2/S-8 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 15:29:28 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:29:28, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.7 %

2023-02-08 15:30:01 / modbusTCP , I6-1 , TEMP : 5.0 $^{\circ}\text{C}$

2023-02-08 15:30:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.1 %

2023-02-08 15:30:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 15:30:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 46.4 %

```
2023-02-08 15:30:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 15:30:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:30:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:30:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.6 %

2023-02-08 15:31:01 / modbusTCP , I6-1 , TEMP : 4.6 °C

2023-02-08 15:31:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.1 %

2023-02-08 15:31:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 15:31:02, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 45.2 %

2023-02-08 15:31:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:31:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:31:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:31:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

2023-02-08 15:32:01 / modbusTCP , I6-1 , TEMP : 4.8 °C

2023-02-08 15:32:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 78.0 %

2023-02-08 15:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 15:32:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 44.7 %

2023-02-08 15:32:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:32:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 15:32:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:32:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 15:33:01 / modbusTCP , I6-1 , TEMP : 4.9 °C

2023-02-08 15:33:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.9 %

2023-02-08 15:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 15:33:01, modbusTCP, I6-1/S-16-2, TEMP: 21.5 °C, RH: 44.7 %

2023-02-08 15:33:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:33:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-08 15:33:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %
```

2023-02-08 15:33:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.7 %

2023-02-08 15:34:01 / modbusTCP , I6-1 , TEMP : 5.0 °C

2023-02-08 15:34:01 , modbusTCP , I6-1/S-12 , TEMP : 25.3 $^{\circ}$ C , RH : 77.8 $^{\circ}$

2023-02-08 15:34:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-08 15:34:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 44.5 %

2023-02-08 15:34:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:34:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:34:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 %

2023-02-08 15:34:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.5 %

2023-02-08 15:35:01 / modbusTCP , I6-1 , TEMP : 5.1 °C

2023-02-08 15:35:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.8 %

2023-02-08 15:35:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.8 %

2023-02-08 15:35:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 44.2 %

2023-02-08 15:35:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:35:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:35:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:35:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.3 %

2023-02-08 15:36:02 / modbusTCP , I6-1 , TEMP : 5.4 °C

2023-02-08 15:36:02 , modbusTCP , I6-1/S-12 , TEMP : 25.3 $^{\circ}\text{C}$, RH : 76.5 %

2023-02-08 15:36:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-08 15:36:02, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.2 %

2023-02-08 15:36:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:36:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:36:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:36:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.7 %

```
2023-02-08 15:37:01 / modbusTCP , I6-1 , TEMP : 5.3 °C
```

2023-02-08 15:37:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 75.5 %

2023-02-08 15:37:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-08 15:37:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.3 %

2023-02-08 15:37:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:37:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:37:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 15:37:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.7 %

2023-02-08 15:38:01 / modbusTCP , I6-1 , TEMP : 5.0 °C

2023-02-08 15:38:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 74.7 %

2023-02-08 15:38:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-08 15:38:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.7 %

2023-02-08 15:38:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:38:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-08 15:38:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 15:38:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.6 %

2023-02-08 15:39:01 / modbusTCP , I6-1 , TEMP : 4.9 °C

2023-02-08 15:39:01 , modbusTCP , I6-1/S-12 , TEMP : 25.3 $^{\circ}\text{C}$, RH : 74.1 %

2023-02-08 15:39:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.6 %

2023-02-08 15:39:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 44.9 %

2023-02-08 15:39:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:39:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-08 15:39:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 15:39:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.1 %

2023-02-08 15:40:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 15:40:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 73.4 %

```
2023-02-08 15:40:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %
```

2023-02-08 15:40:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.1 %

2023-02-08 15:40:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:40:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.7 %

2023-02-08 15:40:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:40:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}$ C , RH : 58.4 $^{\circ}$

2023-02-08 15:41:02 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 15:41:02, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 72.9 %

2023-02-08 15:41:02, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.2 %

2023-02-08 15:41:02, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.1 %

2023-02-08 15:41:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:41:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.7 %

2023-02-08 15:41:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 15:41:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

2023-02-08 15:42:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 15:42:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 72.5 %

2023-02-08 15:42:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 15:42:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.4 $^{\circ}$ C , RH : 45.2 %

2023-02-08 15:42:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:42:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 15:42:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:42:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

2023-02-08 15:43:01 / modbusTCP , I6-1 , TEMP : 4.3 $^{\circ}\text{C}$

2023-02-08 15:43:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 72.1 %

2023-02-08 15:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 15:43:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.2 %

```
2023-02-08 15:43:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 15:43:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.9 %

2023-02-08 15:43:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 15:43:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.7 %

2023-02-08 15:44:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 15:44:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 71.9 %

2023-02-08 15:44:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 15:44:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.4 $^{\circ}$ C , RH : 45.3 %

2023-02-08 15:44:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:44:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 59.0 %

2023-02-08 15:44:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:44:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

2023-02-08 15:45:02 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 15:45:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 71.8 %

2023-02-08 15:45:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 62.1 %

2023-02-08 15:45:02, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.5 %

2023-02-08 15:45:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:45:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 59.1 %

2023-02-08 15:45:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:45:02 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.1 %

2023-02-08 15:46:01 / modbusTCP , I6-1 , TEMP : 4.8 °C

2023-02-08 15:46:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 71.5 %

2023-02-08 15:46:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 15:46:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.5 %

2023-02-08 15:46:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:46:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 59.3 %

```
2023-02-08 15:46:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 15:46:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.8 %

2023-02-08 15:47:01 / modbusTCP , I6-1 , TEMP : 4.9 °C

2023-02-08 15:47:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7 $^{\circ}$ C , RH : 71.3 $^{\circ}$

2023-02-08 15:47:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 15:47:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.6 %

2023-02-08 15:47:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:47:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 59.5 %

2023-02-08 15:47:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 %

2023-02-08 15:47:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.0 %

2023-02-08 15:48:01 / modbusTCP , I6-1 , TEMP : 4.9 °C

2023-02-08 15:48:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 71.0 %

2023-02-08 15:48:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 15:48:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.4 %

2023-02-08 15:48:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:48:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 59.6 %

2023-02-08 15:48:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 15:48:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.3 %

2023-02-08 15:49:01 / modbusTCP , I6-1 , TEMP : 4.8 °C

2023-02-08 15:49:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 70.7 %

2023-02-08 15:49:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 15:49:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.7 %

2023-02-08 15:49:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 15:49:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 61.3 %

2023-02-08 15:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 15:49:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.9 %

```
2023-02-08 15:50:02 / modbusTCP , I6-1 , TEMP : 4.5 °C
```

2023-02-08 15:50:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 70.4 %

2023-02-08 15:50:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 15:50:02, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.7 %

2023-02-08 15:50:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:50:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 63.1 %

2023-02-08 15:50:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:50:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.1 %

2023-02-08 15:51:01 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 15:51:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.0 %

2023-02-08 15:51:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 15:51:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.8 %

2023-02-08 15:51:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:51:01, modbusTCP, I6-2/S-8, TEMP: 20.1 °C, RH: 64.1 %

2023-02-08 15:51:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:51:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.3 %

2023-02-08 15:51:19 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 15:51:19, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.0 %

2023-02-08 15:51:19, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-08 15:51:19, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 45.8 %

2023-02-08 15:51:19 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:51:19, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 64.8 %

2023-02-08 15:51:19, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 15:51:19, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.3 %

2023-02-08 15:52:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 15:52:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 69.7 %

```
2023-02-08 15:52:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %
```

2023-02-08 15:52:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 45.8 %

2023-02-08 15:52:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:52:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 64.9 %

2023-02-08 15:52:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:52:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.6 %

2023-02-08 15:53:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 15:53:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.4 %

2023-02-08 15:53:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 15:53:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 45.9 %

2023-02-08 15:53:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:53:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 65.7 %

2023-02-08 15:53:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 15:53:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.0 %

2023-02-08 15:54:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 15:54:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.0 %

2023-02-08 15:54:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 15:54:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.2 $^{\circ}$ C , RH : 46.0 %

2023-02-08 15:54:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:54:01 , modbusTCP , I6-2/S-8 , TEMP : 20.3 °C , RH : 65.5 %

2023-02-08 15:54:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:54:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.9 %

2023-02-08 15:55:01 / modbusTCP , I6-1 , TEMP : 4.1 $^{\circ}\text{C}$

2023-02-08 15:55:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.7 %

2023-02-08 15:55:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 15:55:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 46.0 %

```
2023-02-08 15:55:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 15:55:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 65.5 %

2023-02-08 15:55:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:55:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.8 %

2023-02-08 15:56:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 15:56:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.4 %

2023-02-08 15:56:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 15:56:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 46.1 %

2023-02-08 15:56:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:56:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 65.7 %

2023-02-08 15:56:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:56:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.0 %

2023-02-08 15:57:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 15:57:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.0 %

2023-02-08 15:57:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.2 %

2023-02-08 15:57:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 46.2 %

2023-02-08 15:57:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:57:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 64.6 %

2023-02-08 15:57:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 15:57:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.8 %

2023-02-08 15:58:01 / modbusTCP , I6-1 , TEMP : 4.6 °C

2023-02-08 15:58:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.7 %

2023-02-08 15:58:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 15:58:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 46.2 %

2023-02-08 15:58:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:58:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 63.9 %

```
2023-02-08 15:58:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %
```

2023-02-08 15:58:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.9 %

2023-02-08 15:59:02 / modbusTCP , I6-1 , TEMP : 4.8 °C

2023-02-08 15:59:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.4 %

2023-02-08 15:59:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 15:59:02, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 46.0 %

2023-02-08 15:59:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 15:59:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 63.4 %

2023-02-08 15:59:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.5 %

2023-02-08 15:59:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.2 %

2023-02-08 16:00:01 / modbusTCP , I6-1 , TEMP : 4.6 °C

2023-02-08 16:00:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 67.1 %

2023-02-08 16:00:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.9 %

2023-02-08 16:00:01, modbusTCP, I6-1/S-16-2, TEMP: 21.6 °C, RH: 45.8 %

2023-02-08 16:00:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:00:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 63.1 %

2023-02-08 16:00:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:00:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 56.9 %

2023-02-08 16:01:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:01:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9 $^{\circ}\text{C}$, RH : 66.9 %

2023-02-08 16:01:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 16:01:01, modbusTCP, I6-1/S-16-2, TEMP: 21.9 °C, RH: 45.5 %

2023-02-08 16:01:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:01:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 62.8 %

2023-02-08 16:01:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:01:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.9 %

```
2023-02-08 16:02:01 / modbusTCP , I6-1 , TEMP : 4.1 °C
```

2023-02-08 16:02:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.6 %

2023-02-08 16:02:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 16:02:01, modbusTCP, I6-1/S-16-2, TEMP: 22.4 °C, RH: 44.7 %

2023-02-08 16:02:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:02:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 62.5 %

2023-02-08 16:02:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:02:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.4 %

2023-02-08 16:03:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 16:03:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.4 %

2023-02-08 16:03:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 16:03:01, modbusTCP, I6-1/S-16-2, TEMP: 22.4 °C, RH: 43.7 %

2023-02-08 16:03:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:03:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 62.3 %

2023-02-08 16:03:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 16:03:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.5 %

2023-02-08 16:04:02 / modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 16:04:02 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}\text{C}$, RH : 66.2 %

2023-02-08 16:04:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 16:04:02, modbusTCP, I6-1/S-16-2, TEMP: 22.3 °C, RH: 42.8 %

2023-02-08 16:04:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:04:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.1 %

2023-02-08 16:04:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:04:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.4 %

2023-02-08 16:05:01 / modbusTCP , I6-1 , TEMP : 3.9 $^{\circ}$ C

2023-02-08 16:05:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.0 %

```
2023-02-08 16:05:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %
```

2023-02-08 16:05:01, modbusTCP, I6-1/S-16-2, TEMP: 22.2 °C, RH: 42.4 %

2023-02-08 16:05:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:05:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.0 %

2023-02-08 16:05:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:05:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.4 %

2023-02-08 16:06:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:06:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.8 %

2023-02-08 16:06:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-08 16:06:01, modbusTCP, I6-1/S-16-2, TEMP: 22.4 °C, RH: 42.2 %

2023-02-08 16:06:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:06:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.8 %

2023-02-08 16:06:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:06:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.5 %

2023-02-08 16:07:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 16:07:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.7 %

2023-02-08 16:07:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 16:07:01, modbusTCP, I6-1/S-16-2, TEMP: 22.5 °C, RH: 42.1 %

2023-02-08 16:07:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:07:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 16:07:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:07:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.5 %

2023-02-08 16:08:01 / modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}\text{C}$

2023-02-08 16:08:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.5 %

2023-02-08 16:08:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 16:08:01, modbusTCP, I6-1/S-16-2, TEMP: 22.3 °C, RH: 42.2 %

```
2023-02-08 16:08:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 16:08:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.6 %

2023-02-08 16:08:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:08:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.0 %

2023-02-08 16:09:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:09:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 65.4 %

2023-02-08 16:09:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-08 16:09:01, modbusTCP, I6-1/S-16-2, TEMP: 22.4 °C, RH: 42.5 %

2023-02-08 16:09:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:09:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.5 %

2023-02-08 16:09:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:09:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 57.4 %

2023-02-08 16:10:01 / modbusTCP , I6-1 , TEMP : 4.6 °C

2023-02-08 16:10:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 65.3 %

2023-02-08 16:10:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.6 %

2023-02-08 16:10:01, modbusTCP, I6-1/S-16-2, TEMP: 22.4 °C, RH: 42.6 %

2023-02-08 16:10:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:10:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.4 %

2023-02-08 16:10:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:10:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 57.3 %

2023-02-08 16:11:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:11:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 65.1 %

2023-02-08 16:11:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 16:11:01, modbusTCP, I6-1/S-16-2, TEMP: 22.2 °C, RH: 42.9 %

2023-02-08 16:11:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.3 %

```
2023-02-08 16:11:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 16:11:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.6 %

2023-02-08 16:12:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 16:12:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 65.2 %

2023-02-08 16:12:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 16:12:01 , modbusTCP , I6-1/S-16-2 , TEMP : 22.2 $^{\circ}$ C , RH : 43.3 %

2023-02-08 16:12:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:12:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 61.2 %

2023-02-08 16:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.5 $^{\circ}$

2023-02-08 16:12:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.9 %

2023-02-08 16:13:02 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 16:13:02, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 65.7 %

2023-02-08 16:13:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 16:13:02, modbusTCP, I6-1/S-16-2, TEMP: 22.1 °C, RH: 43.4 %

2023-02-08 16:13:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:13:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.1 %

2023-02-08 16:13:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:13:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 56.3 %

2023-02-08 16:14:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 16:14:01 , modbusTCP , I6-1/S-12 , TEMP : 27.5 $^{\circ}$ C , RH : 66.1 %

2023-02-08 16:14:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 16:14:01, modbusTCP, I6-1/S-16-2, TEMP: 22.0 °C, RH: 43.6 %

2023-02-08 16:14:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:14:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.9 %

2023-02-08 16:14:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:14:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.1 %

```
2023-02-08 16:15:01 / modbusTCP , I6-1 , TEMP : 3.6 °C
```

2023-02-08 16:15:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 66.4 %

2023-02-08 16:15:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 16:15:01, modbusTCP, I6-1/S-16-2, TEMP: 22.0 °C, RH: 44.1 %

2023-02-08 16:15:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:15:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.9 %

2023-02-08 16:15:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:15:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.2 %

2023-02-08 16:16:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 16:16:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 66.7 %

2023-02-08 16:16:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 16:16:01, modbusTCP, I6-1/S-16-2, TEMP: 22.0 °C, RH: 44.1 %

2023-02-08 16:16:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:16:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.9 %

2023-02-08 16:16:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:16:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 55.6 %

2023-02-08 16:17:01 / modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 16:17:01 , modbusTCP , I6-1/S-12 , TEMP : 27.7 $^{\circ}\text{C}$, RH : 67.0 %

2023-02-08 16:17:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 16:17:01, modbusTCP, I6-1/S-16-2, TEMP: 22.1 °C, RH: 44.6 %

2023-02-08 16:17:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:17:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.9 %

2023-02-08 16:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:17:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 55.9 %

2023-02-08 16:18:02 / modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}$ C

2023-02-08 16:18:02, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 67.3 %

```
2023-02-08 16:18:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %
```

2023-02-08 16:18:02, modbusTCP, I6-1/S-16-2, TEMP: 22.0 °C, RH: 44.2 %

2023-02-08 16:18:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:18:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.8 %

2023-02-08 16:18:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:18:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 56.0 %

2023-02-08 16:19:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 16:19:01 , modbusTCP , I6-1/S-12 , TEMP : 27.7 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.3 %

2023-02-08 16:19:01, modbusTCP, I6-1/S-16-2, TEMP: 21.8 °C, RH: 44.7 %

2023-02-08 16:19:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:19:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.8 %

2023-02-08 16:19:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.5 $^{\circ}$

2023-02-08 16:19:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.4 %

2023-02-08 16:20:01 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 16:20:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 67.8 %

2023-02-08 16:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 16:20:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.8 $^{\circ}$ C , RH : 45.1 %

2023-02-08 16:20:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:20:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.8 %

2023-02-08 16:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:20:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.7 %

2023-02-08 16:21:01 / modbusTCP , I6-1 , TEMP : 4.5 $^{\circ}\text{C}$

2023-02-08 16:21:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.0 %

2023-02-08 16:21:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 16:21:01, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 44.9 %

```
2023-02-08 16:21:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 16:21:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.7 %

2023-02-08 16:21:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:21:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.6 %

2023-02-08 16:22:02 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:22:02, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.3 %

2023-02-08 16:22:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 16:22:02, modbusTCP, I6-1/S-16-2, TEMP: 21.4 °C, RH: 45.2 %

2023-02-08 16:22:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:22:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.7 %

2023-02-08 16:22:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:22:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.3 %

2023-02-08 16:23:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:23:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.5 %

2023-02-08 16:23:01 , modbusTCP , I6-1/S-13 , TEMP : $30.0 \, ^{\circ}\text{C}$, RH : $62.3 \, \%$

2023-02-08 16:23:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 45.6 %

2023-02-08 16:23:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:23:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.7 %

2023-02-08 16:23:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:23:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}$ C , RH : 54.4 %

2023-02-08 16:24:01 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 16:24:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.8 %

2023-02-08 16:24:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 16:24:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 46.6 %

2023-02-08 16:24:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:24:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.6 %

```
2023-02-08 16:24:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 16:24:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 55.7 %

2023-02-08 16:25:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:25:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 69.0 %

2023-02-08 16:25:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 16:25:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 46.3 %

2023-02-08 16:25:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:25:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.6 %

2023-02-08 16:25:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:25:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 56.2 %

2023-02-08 16:26:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 16:26:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 69.3 %

2023-02-08 16:26:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.3 %

2023-02-08 16:26:01, modbusTCP, I6-1/S-16-2, TEMP: 21.3 °C, RH: 45.8 %

2023-02-08 16:26:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:26:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 16:26:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:26:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 57.0 %

2023-02-08 16:27:02 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 16:27:02 , modbusTCP , I6-1/S-12 , TEMP : 27.8 $^{\circ}\text{C}$, RH : 69.5 %

2023-02-08 16:27:02 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 16:27:02, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 45.0 %

2023-02-08 16:27:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:27:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.4 %

2023-02-08 16:27:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:27:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 55.8 %

```
2023-02-08 16:28:01 / modbusTCP , I6-1 , TEMP : 3.6 °C
```

2023-02-08 16:28:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 69.8 %

2023-02-08 16:28:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 16:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 44.2 %

2023-02-08 16:28:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:28:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.4 %

2023-02-08 16:28:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:28:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.3 %

2023-02-08 16:29:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 16:29:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 70.1 %

2023-02-08 16:29:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 16:29:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.9 $^{\circ}$ C , RH : 43.4 %

2023-02-08 16:29:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:29:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 16:29:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 16:29:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.7 %

2023-02-08 16:30:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:30:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 70.3 %

2023-02-08 16:30:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 16:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 42.9 %

2023-02-08 16:30:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:30:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 16:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:30:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 55.3 %

2023-02-08 16:31:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 16:31:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 70.6 %

```
2023-02-08 16:31:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-08 16:31:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 42.5 %

2023-02-08 16:31:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:31:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.5 %

2023-02-08 16:31:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:31:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 54.7 %

2023-02-08 16:32:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 16:32:01 , modbusTCP , I6-1/S-12 , TEMP : 27.5 $^{\circ}\text{C}$, RH : 70.9 %

2023-02-08 16:32:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 16:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 42.5 %

2023-02-08 16:32:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:32:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.4 %

2023-02-08 16:32:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:32:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 53.7 %

2023-02-08 16:33:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:33:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 71.3 %

2023-02-08 16:33:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 16:33:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.8 $^{\circ}$ C , RH : 42.7 %

2023-02-08 16:33:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:33:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.3 %

2023-02-08 16:33:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:33:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.8 %

2023-02-08 16:34:01 / modbusTCP , I6-1 , TEMP : 4.5 $^{\circ}\text{C}$

2023-02-08 16:34:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 71.6 %

2023-02-08 16:34:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 16:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 43.1 %

```
2023-02-08 16:34:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 16:34:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.3 %

2023-02-08 16:34:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:34:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 55.7 %

2023-02-08 16:35:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 16:35:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 71.9 %

2023-02-08 16:35:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-08 16:35:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 43.7 %

2023-02-08 16:35:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:35:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.2 %

2023-02-08 16:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:35:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.2 %

2023-02-08 16:36:02 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:36:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 72.2 %

2023-02-08 16:36:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.5 %

2023-02-08 16:36:02, modbusTCP, I6-1/S-16-2, TEMP: 21.0 °C, RH: 43.7 %

2023-02-08 16:36:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:36:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.2 %

2023-02-08 16:36:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:36:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 55.1 %

2023-02-08 16:37:01 / modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 16:37:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 72.5 %

2023-02-08 16:37:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 16:37:01, modbusTCP, I6-1/S-16-2, TEMP: 21.1 °C, RH: 44.2 %

2023-02-08 16:37:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:37:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

```
2023-02-08 16:37:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %
```

2023-02-08 16:37:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.2 %

2023-02-08 16:38:01 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 16:38:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}$ C , RH : 72.9 $^{\circ}$

2023-02-08 16:38:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-08 16:38:01 , modbusTCP , I6-1/S-16-2 , TEMP : 21.0 $^{\circ}$ C , RH : 44.4 %

2023-02-08 16:38:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:38:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

2023-02-08 16:38:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:38:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 54.7 %

2023-02-08 16:39:01 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 16:39:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 73.2 %

2023-02-08 16:39:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.5 %

2023-02-08 16:39:01, modbusTCP, I6-1/S-16-2, TEMP: 21.0 °C, RH: 44.7 %

2023-02-08 16:39:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:39:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

2023-02-08 16:39:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 16:39:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 54.4 %

2023-02-08 16:40:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 16:40:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9 $^{\circ}\text{C}$, RH : 73.6 %

2023-02-08 16:40:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 16:40:01, modbusTCP, I6-1/S-16-2, TEMP: 21.2 °C, RH: 44.6 %

2023-02-08 16:40:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:40:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.0 %

2023-02-08 16:40:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.5 %

2023-02-08 16:40:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 54.0 %

```
2023-02-08 16:41:01 / modbusTCP , I6-1 , TEMP : 3.9 °C
```

2023-02-08 16:41:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.9 %

2023-02-08 16:41:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 16:41:01, modbusTCP, I6-1/S-16-2, TEMP: 21.0 °C, RH: 44.9 %

2023-02-08 16:41:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:41:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

2023-02-08 16:41:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 16:41:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.3 %

2023-02-08 16:42:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:42:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 74.3 %

2023-02-08 16:42:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.4 %

2023-02-08 16:42:01, modbusTCP, I6-1/S-16-2, TEMP: 21.0 °C, RH: 44.8 %

2023-02-08 16:42:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:42:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.0 %

2023-02-08 16:42:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 16:42:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 54.9 %

2023-02-08 16:43:01 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 16:43:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5 $^{\circ}\text{C}$, RH : 74.7 %

2023-02-08 16:43:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %

2023-02-08 16:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 44.7 %

2023-02-08 16:43:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:43:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.0 %

2023-02-08 16:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 16:43:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.1 %

2023-02-08 16:44:02 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:44:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 75.0 %

```
2023-02-08 16:44:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %
```

2023-02-08 16:44:02, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.6 %

2023-02-08 16:44:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:44:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.0 %

2023-02-08 16:44:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:44:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 53.9 %

2023-02-08 16:45:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:45:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.4 %

2023-02-08 16:45:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 62.2 %

2023-02-08 16:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 44.9 %

2023-02-08 16:45:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:45:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 61.9 %

2023-02-08 16:45:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 16:45:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.8 %

2023-02-08 16:46:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 16:46:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.7 %

2023-02-08 16:46:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 16:46:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 $^{\circ}$ C , RH : 44.9 %

2023-02-08 16:46:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:46:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 63.2 %

2023-02-08 16:46:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:46:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.9 %

2023-02-08 16:47:01 / modbusTCP , I6-1 , TEMP : 4.1 $^{\circ}\text{C}$

2023-02-08 16:47:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 76.1 %

2023-02-08 16:47:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 16:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 45.0 %

```
2023-02-08 16:47:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 16:47:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 65.0 %

2023-02-08 16:47:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:47:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 16:48:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:48:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.3 %

2023-02-08 16:48:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 16:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.7 %

2023-02-08 16:48:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:48:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 65.5 %

2023-02-08 16:48:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:48:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.4 %

2023-02-08 16:49:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 16:49:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.6 %

2023-02-08 16:49:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-08 16:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.7 %

2023-02-08 16:49:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:49:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4 $^{\circ}\text{C}$, RH : 65.6 %

2023-02-08 16:49:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 16:49:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.2 %

2023-02-08 16:50:01 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 16:50:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.8 %

2023-02-08 16:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2 $^{\circ}\text{C}$, RH : 61.2 %

2023-02-08 16:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 44.8 %

2023-02-08 16:50:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:50:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 66.3 %

```
2023-02-08 16:50:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %
```

2023-02-08 16:50:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 16:51:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 16:51:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 77.0 %

2023-02-08 16:51:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 16:51:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7 $^{\circ}$ C , RH : 44.7 %

2023-02-08 16:51:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:51:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 67.1 %

2023-02-08 16:51:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:51:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.8 %

2023-02-08 16:52:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 16:52:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 77.1 %

2023-02-08 16:52:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.9 %

2023-02-08 16:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.5 %

2023-02-08 16:52:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:52:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 67.7 %

2023-02-08 16:52:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:52:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.1 %

2023-02-08 16:53:02 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:53:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.3 %

2023-02-08 16:53:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 16:53:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.5 %

2023-02-08 16:53:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 16:53:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 67.0 %

2023-02-08 16:53:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 16:53:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

```
2023-02-08 16:54:01 / modbusTCP , I6-1 , TEMP : 4.1 °C
```

2023-02-08 16:54:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-08 16:54:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 16:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.5 %

2023-02-08 16:54:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:54:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 67.2 %

2023-02-08 16:54:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:54:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 16:55:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 16:55:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.5 %

2023-02-08 16:55:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 16:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.7 %

2023-02-08 16:55:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:55:01, modbusTCP, I6-2/S-8, TEMP: 20.2 °C, RH: 67.7 %

2023-02-08 16:55:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.8 %

2023-02-08 16:55:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.6 %

2023-02-08 16:56:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:56:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4 $^{\circ}\text{C}$, RH : 77.6 %

2023-02-08 16:56:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 16:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.9 %

2023-02-08 16:56:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:56:01, modbusTCP, I6-2/S-8, TEMP: 20.1 °C, RH: 67.9 %

2023-02-08 16:56:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 16:56:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 53.0 %

2023-02-08 16:57:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 16:57:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.7 %

```
2023-02-08 16:57:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.1 %
```

2023-02-08 16:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.8 %

2023-02-08 16:57:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:57:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 66.5 %

2023-02-08 16:57:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:57:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}$ C , RH : 52.4 $^{\circ}$

2023-02-08 16:58:02 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 16:58:02 , modbusTCP , I6-1/S-12 , TEMP : 25.3 $^{\circ}\text{C}$, RH : 77.8 %

2023-02-08 16:58:02 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}$ C , RH : 62.0 $^{\circ}$

2023-02-08 16:58:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.9 %

2023-02-08 16:58:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:58:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 65.6 %

2023-02-08 16:58:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 $^{\circ}$

2023-02-08 16:58:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

2023-02-08 16:59:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 16:59:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.8 %

2023-02-08 16:59:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-08 16:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.7 %

2023-02-08 16:59:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 16:59:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 65.1 %

2023-02-08 16:59:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 16:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 17:00:01 / modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 17:00:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.9 %

2023-02-08 17:00:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 17:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

```
2023-02-08 17:00:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 17:00:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6 $^{\circ}$ C , RH : 64.6 $^{\circ}$

2023-02-08 17:00:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:00:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.6 %

2023-02-08 17:01:01 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 17:01:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.9 %

2023-02-08 17:01:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 17:01:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 $^{\circ}$ C , RH : 44.8 %

2023-02-08 17:01:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:01:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 64.3 %

2023-02-08 17:01:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:01:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.7 %

2023-02-08 17:02:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 17:02:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.9 %

2023-02-08 17:02:01 , modbusTCP , I6-1/S-13 , TEMP : $30.0 \, ^{\circ}\text{C}$, RH : $62.3 \, \%$

2023-02-08 17:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.7 %

2023-02-08 17:02:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:02:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 64.0 %

2023-02-08 17:02:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:02:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 52.0 %

2023-02-08 17:03:01 / modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 17:03:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.9 %

2023-02-08 17:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 17:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.5 %

2023-02-08 17:03:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:03:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 63.7 %

```
2023-02-08 17:03:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 17:03:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 17:04:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 17:04:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.9 %

2023-02-08 17:04:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 17:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.8 %

2023-02-08 17:04:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:04:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 63.5 %

2023-02-08 17:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 17:04:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.9 %

2023-02-08 17:05:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 17:05:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.8 %

2023-02-08 17:05:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.8 %

2023-02-08 17:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.6 %

2023-02-08 17:05:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:05:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 63.3 %

2023-02-08 17:05:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 17:05:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.8 %

2023-02-08 17:06:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 17:06:01 , modbusTCP , I6-1/S-12 , TEMP : 25.2 $^{\circ}$ C , RH : 77.6 $^{\circ}$

2023-02-08 17:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 17:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.7 %

2023-02-08 17:06:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:06:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 63.1 %

2023-02-08 17:06:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 17:06:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

```
2023-02-08 17:07:02 / modbusTCP , I6-1 , TEMP : 4.5 °C
```

2023-02-08 17:07:02, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.5 %

2023-02-08 17:07:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 17:07:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.5 %

2023-02-08 17:07:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:07:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.9 %

2023-02-08 17:07:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 17:07:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 17:08:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 17:08:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.4 %

2023-02-08 17:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 17:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

2023-02-08 17:08:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:08:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.7 %

2023-02-08 17:08:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 17:08:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 17:09:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 17:09:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.3 %

2023-02-08 17:09:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 17:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

2023-02-08 17:09:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:09:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.6 %

2023-02-08 17:09:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 17:09:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-08 17:10:01 / modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 17:10:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

```
2023-02-08 17:10:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %
```

2023-02-08 17:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.7 %

2023-02-08 17:10:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:10:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 62.5 %

2023-02-08 17:10:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 17:10:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.7 %

2023-02-08 17:11:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 17:11:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-08 17:11:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.5 $^{\circ}$

2023-02-08 17:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.5 %

2023-02-08 17:11:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.4 %

2023-02-08 17:11:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.5 $^{\circ}$

2023-02-08 17:11:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.9 %

2023-02-08 17:12:02 / modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}$ C

2023-02-08 17:12:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-08 17:12:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 17:12:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 44.7 %

2023-02-08 17:12:02 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:12:02 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}$ C , RH : 62.3 %

2023-02-08 17:12:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %

2023-02-08 17:12:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.9 %

2023-02-08 17:13:01 / modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-08 17:13:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-08 17:13:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 17:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

```
2023-02-08 17:13:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C
```

2023-02-08 17:13:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 62.2 %

2023-02-08 17:13:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.5 %

2023-02-08 17:13:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 17:14:01 / modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-08 17:14:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 17:14:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 17:14:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 44.8 %

2023-02-08 17:14:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:14:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 62.2 %

2023-02-08 17:14:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 17:14:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 17:15:01 / modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-08 17:15:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 17:15:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}$ C , RH : 62.7 %

2023-02-08 17:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.0 %

2023-02-08 17:15:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:15:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 62.1 %

2023-02-08 17:15:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %

2023-02-08 17:15:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.6 %

2023-02-08 17:16:01 / modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-08 17:16:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 75.5 %

2023-02-08 17:16:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.9 %

2023-02-08 17:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.0 %

2023-02-08 17:16:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:16:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 62.0 %

```
2023-02-08 17:16:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.6 %
```

2023-02-08 17:16:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 17:17:01 / modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-08 17:17:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 74.4 %

2023-02-08 17:17:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.8 %

2023-02-08 17:17:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.3 %

2023-02-08 17:17:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:17:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.9 %

2023-02-08 17:17:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:17:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 17:18:01 / modbusTCP , I6-1 , TEMP : 4.4 °C

2023-02-08 17:18:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 73.5 %

2023-02-08 17:18:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.4 $^{\circ}$

2023-02-08 17:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 17:18:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:18:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.9 %

2023-02-08 17:18:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:18:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.5 %

2023-02-08 17:19:01 / modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-08 17:19:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 72.7 %

2023-02-08 17:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 17:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 17:19:01 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:19:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.8 %

2023-02-08 17:19:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:19:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

```
2023-02-08 17:20:01 / modbusTCP , I6-1 , TEMP : 4.4 °C
```

2023-02-08 17:20:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.0 %

2023-02-08 17:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 17:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 17:20:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:20:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.8 %

2023-02-08 17:20:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 17:20:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 17:20:34, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 17:20:34, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.7 %

2023-02-08 17:20:34, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 17:20:34 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.1 %

2023-02-08 17:20:34 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:20:34, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.8 %

2023-02-08 17:20:34 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.7 %

2023-02-08 17:20:34, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 17:21:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 17:21:02 , modbusTCP , I6-1/S-12 , TEMP : 26.0 $^{\circ}\text{C}$, RH : 71.5 %

2023-02-08 17:21:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 17:21:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.9 %

2023-02-08 17:21:02 / modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:21:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.8 %

2023-02-08 17:21:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:21:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 17:22:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 17:22:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.0 %

```
2023-02-08 17:22:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %
```

2023-02-08 17:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.9 %

2023-02-08 17:22:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:22:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.6 %

2023-02-08 17:22:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:22:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 17:23:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 17:23:01 , modbusTCP , I6-1/S-12 , TEMP : 26.1 $^{\circ}\text{C}$, RH : 70.6 %

2023-02-08 17:23:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.2 %

2023-02-08 17:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

2023-02-08 17:23:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:23:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.6 %

2023-02-08 17:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 17:23:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 17:24:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 17:24:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.4 %

2023-02-08 17:24:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 17:24:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 44.9 %

2023-02-08 17:24:01 / modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 17:24:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.5 %

2023-02-08 17:24:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 17:24:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 17:25:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 17:25:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.3 %

2023-02-08 17:25:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 17:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.0 %

```
2023-02-08 17:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 17:25:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.4 %

2023-02-08 17:25:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:25:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-08 17:26:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 17:26:02 , modbusTCP , I6-1/S-12 , TEMP : 26.3 $^{\circ}$ C , RH : 70.1 %

2023-02-08 17:26:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 17:26:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

2023-02-08 17:26:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:26:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.4 %

2023-02-08 17:26:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:26:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 17:27:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 17:27:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.8 %

2023-02-08 17:27:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 17:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.8 %

2023-02-08 17:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:27:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.4 %

2023-02-08 17:27:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:27:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 52.5 %

2023-02-08 17:28:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 17:28:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.6 %

2023-02-08 17:28:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.6 %

2023-02-08 17:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.9 %

2023-02-08 17:28:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:28:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.3 %

```
2023-02-08 17:28:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %
```

2023-02-08 17:28:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.4 %

2023-02-08 17:29:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 17:29:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 69.3 %

2023-02-08 17:29:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 17:29:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 44.9 %

2023-02-08 17:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:29:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.3 %

2023-02-08 17:29:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 17:29:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 54.7 %

2023-02-08 17:30:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 17:30:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 69.0 %

2023-02-08 17:30:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.3 %

2023-02-08 17:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.0 %

2023-02-08 17:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:30:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.1 %

2023-02-08 17:30:17, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:30:17 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 55.2 %

2023-02-08 17:31:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 17:31:01 , modbusTCP , I6-1/S-12 , TEMP : 26.6 $^{\circ}$ C , RH : 68.7 %

2023-02-08 17:31:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 17:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.2 %

2023-02-08 17:31:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:31:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.1 %

2023-02-08 17:31:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 17:31:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 54.0 %

```
2023-02-08 17:32:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-08 17:32:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 68.5 %

2023-02-08 17:32:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 17:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.2 %

2023-02-08 17:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:32:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.1 %

2023-02-08 17:32:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:32:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 59.3 %

2023-02-08 17:33:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 17:33:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 68.2 %

2023-02-08 17:33:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 17:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.4 %

2023-02-08 17:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:33:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 61.1 %

2023-02-08 17:33:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 17:33:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 55.7 %

2023-02-08 17:34:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 17:34:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 17:34:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-08 17:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 17:34:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:34:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.2 %

2023-02-08 17:34:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:34:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 60.5 %

2023-02-08 17:35:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 17:35:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 67.6 %

```
2023-02-08 17:35:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %
```

2023-02-08 17:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.1 %

2023-02-08 17:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:35:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.1 %

2023-02-08 17:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:35:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}$ C , RH : 57.5 $^{\circ}$

2023-02-08 17:36:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 17:36:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 67.4 %

2023-02-08 17:36:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 62.0 %

2023-02-08 17:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.3 %

2023-02-08 17:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:36:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 61.0 %

2023-02-08 17:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.7 %

2023-02-08 17:36:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 58.6 %

2023-02-08 17:37:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 17:37:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 67.1 %

2023-02-08 17:37:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 17:37:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}\text{C}$, RH : 45.3 %

2023-02-08 17:37:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:37:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 61.0 %

2023-02-08 17:37:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:37:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 58.3 %

2023-02-08 17:38:01 , modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 17:38:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.9 %

2023-02-08 17:38:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 17:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.2 %

```
2023-02-08 17:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 17:38:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.9 %

2023-02-08 17:38:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 17:38:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 57.9 %

2023-02-08 17:39:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 17:39:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.7 %

2023-02-08 17:39:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 17:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.1 %

2023-02-08 17:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:39:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.8 %

2023-02-08 17:39:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:39:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.7 %

2023-02-08 17:40:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 17:40:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.5 %

2023-02-08 17:40:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 17:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.0 %

2023-02-08 17:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:40:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.7 %

2023-02-08 17:40:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:40:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 57.9 %

2023-02-08 17:41:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 17:41:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.3 %

2023-02-08 17:41:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 17:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.0 %

2023-02-08 17:41:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:41:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.8 %

```
2023-02-08 17:41:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %
```

2023-02-08 17:41:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}$ C , RH : 57.7 $^{\circ}$

2023-02-08 17:42:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 17:42:02, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.1 %

2023-02-08 17:42:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-08 17:42:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.8 %

2023-02-08 17:42:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:42:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.8 %

2023-02-08 17:42:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 17:42:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.4 %

2023-02-08 17:43:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 17:43:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 65.9 %

2023-02-08 17:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.7 %

2023-02-08 17:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.8 %

2023-02-08 17:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:43:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.8 %

2023-02-08 17:43:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:43:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 17:44:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 17:44:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2 $^{\circ}$ C , RH : 65.8 %

2023-02-08 17:44:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 17:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

2023-02-08 17:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:44:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.8 %

2023-02-08 17:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:44:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

```
2023-02-08 17:45:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-08 17:45:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.6 %

2023-02-08 17:45:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.4 %

2023-02-08 17:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.8 %

2023-02-08 17:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:45:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.8 %

2023-02-08 17:45:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:45:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.1 %

2023-02-08 17:46:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 17:46:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.5 %

2023-02-08 17:46:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.6 %

2023-02-08 17:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 17:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:46:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.7 %

2023-02-08 17:46:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:46:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.3 %

2023-02-08 17:47:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-08 17:47:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2 $^{\circ}\text{C}$, RH : 65.4 %

2023-02-08 17:47:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %

2023-02-08 17:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

2023-02-08 17:47:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:47:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.6 %

2023-02-08 17:47:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:47:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 58.2 %

2023-02-08 17:48:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 17:48:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.3 %

```
2023-02-08 17:48:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-08 17:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.1 %

2023-02-08 17:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:48:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.6 %

2023-02-08 17:48:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:48:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}$ C , RH : 58.1 %

2023-02-08 17:49:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 17:49:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2 $^{\circ}\text{C}$, RH : 65.2 %

2023-02-08 17:49:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 62.0 %

2023-02-08 17:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.2 %

2023-02-08 17:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:49:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 17:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 $^{\circ}$

2023-02-08 17:49:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.2 %

2023-02-08 17:50:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 17:50:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.1 %

2023-02-08 17:50:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 17:50:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}$ C , RH : 44.9 %

2023-02-08 17:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:50:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.6 %

2023-02-08 17:50:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:50:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.5 %

2023-02-08 17:51:02 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 17:51:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.0 %

2023-02-08 17:51:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 17:51:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.1 %

```
2023-02-08 17:51:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 17:51:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.6 %

2023-02-08 17:51:02, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.8 %

2023-02-08 17:51:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.9 %

2023-02-08 17:52:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 17:52:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.2 %

2023-02-08 17:52:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 17:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.1 %

2023-02-08 17:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:52:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.6 %

2023-02-08 17:52:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.8 %

2023-02-08 17:52:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 59.0 %

2023-02-08 17:53:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 17:53:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 65.8 %

2023-02-08 17:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.4 %

2023-02-08 17:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

2023-02-08 17:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 17:53:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:53:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0 $^{\circ}\text{C}$, RH : 58.4 %

2023-02-08 17:54:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 17:54:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 66.2 %

2023-02-08 17:54:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 17:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.9 %

2023-02-08 17:54:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:54:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.5 %

```
2023-02-08 17:54:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %
```

2023-02-08 17:54:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.6 %

2023-02-08 17:55:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 17:55:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 66.6 %

2023-02-08 17:55:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-08 17:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

2023-02-08 17:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:55:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.5 %

2023-02-08 17:55:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 17:55:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.8 %

2023-02-08 17:56:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 17:56:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 66.9 %

2023-02-08 17:56:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 17:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 17:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:56:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.5 %

2023-02-08 17:56:01, modbusTCP, I6-2/S-9, TEMP: 20.5 °C, RH: 67.7 %

2023-02-08 17:56:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.5 %

2023-02-08 17:57:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 17:57:01 , modbusTCP , I6-1/S-12 , TEMP : 27.4 $^{\circ}$ C , RH : 67.2 %

2023-02-08 17:57:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 17:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.0 %

2023-02-08 17:57:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 17:57:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.4 %

2023-02-08 17:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 17:57:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 58.2 %

```
2023-02-08 17:58:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-08 17:58:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 67.5 %

2023-02-08 17:58:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 17:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.0 %

2023-02-08 17:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:58:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.4 %

2023-02-08 17:58:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 17:58:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.7 %

2023-02-08 17:59:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 17:59:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 67.8 %

2023-02-08 17:59:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 17:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.7 %

2023-02-08 17:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 17:59:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.4 %

2023-02-08 17:59:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 17:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.6 %

2023-02-08 18:00:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:00:02 , modbusTCP , I6-1/S-12 , TEMP : 27.4 $^{\circ}\text{C}$, RH : 68.1 %

2023-02-08 18:00:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 18:00:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:00:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:00:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.4 %

2023-02-08 18:00:02 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:00:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.5 %

2023-02-08 18:01:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 18:01:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.3 %

```
2023-02-08 18:01:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %
```

2023-02-08 18:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 18:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:01:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.3 %

2023-02-08 18:01:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:01:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.3 %

2023-02-08 18:02:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 18:02:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}\text{C}$, RH : 68.6 %

2023-02-08 18:02:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 18:02:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.0 %

2023-02-08 18:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:02:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.3 %

2023-02-08 18:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 18:02:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.3 %

2023-02-08 18:03:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:03:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.9 %

2023-02-08 18:03:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 18:03:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}\text{C}$, RH : 45.2 %

2023-02-08 18:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:03:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.2 %

2023-02-08 18:03:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:03:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.1 %

2023-02-08 18:04:01 , modbusTCP , I6-1 , TEMP : 4.3 $^{\circ}\text{C}$

2023-02-08 18:04:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.1 %

2023-02-08 18:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.9 %

2023-02-08 18:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

```
2023-02-08 18:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 18:04:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.2 %

2023-02-08 18:04:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:04:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 58.0 %

2023-02-08 18:05:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 18:05:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.4 %

2023-02-08 18:05:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 18:05:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.8 %

2023-02-08 18:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:05:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.2 %

2023-02-08 18:05:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:05:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 57.9 %

2023-02-08 18:06:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:06:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 69.7 %

2023-02-08 18:06:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-08 18:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 18:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:06:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.1 %

2023-02-08 18:06:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:06:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 57.4 %

2023-02-08 18:07:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 18:07:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 69.9 %

2023-02-08 18:07:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 18:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.0 %

2023-02-08 18:07:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 18:07:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

```
2023-02-08 18:07:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.5 %
```

2023-02-08 18:07:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 57.3 %

2023-02-08 18:08:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:08:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.2 %

2023-02-08 18:08:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 18:08:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9 $^{\circ}$ C , RH : 44.8 %

2023-02-08 18:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:08:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.1 %

2023-02-08 18:08:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 18:08:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 57.2 %

2023-02-08 18:09:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 18:09:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.5 %

2023-02-08 18:09:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.4 %

2023-02-08 18:09:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:09:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:09:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.1 %

2023-02-08 18:09:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:09:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 57.3 %

2023-02-08 18:10:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:10:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.8 %

2023-02-08 18:10:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 18:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.0 %

2023-02-08 18:10:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:10:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.1 %

2023-02-08 18:10:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:10:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 57.2 %

```
2023-02-08 18:11:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-08 18:11:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.0 %

2023-02-08 18:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 18:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.0 %

2023-02-08 18:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

2023-02-08 18:11:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:11:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.6 %

2023-02-08 18:12:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:12:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.3 %

2023-02-08 18:12:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-08 18:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:12:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.2 %

2023-02-08 18:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 18:12:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.4 %

2023-02-08 18:13:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 18:13:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 71.6 %

2023-02-08 18:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 18:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 18:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:13:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.2 %

2023-02-08 18:13:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:13:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.6 %

2023-02-08 18:14:02 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 18:14:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 71.9 %

```
2023-02-08 18:14:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %
```

2023-02-08 18:14:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.1 %

2023-02-08 18:14:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:14:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.1 %

2023-02-08 18:14:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:14:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.7 %

2023-02-08 18:15:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 18:15:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}\text{C}$, RH : 72.2 %

2023-02-08 18:15:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 18:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.1 %

2023-02-08 18:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:15:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.1 %

2023-02-08 18:15:01 , modbusTCP , I6-2/S-9 , TEMP : 20.5 $^{\circ}$ C , RH : 67.7 $^{\circ}$

2023-02-08 18:15:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.1 %

2023-02-08 18:16:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:16:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 72.6 %

2023-02-08 18:16:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %

2023-02-08 18:16:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1 $^{\circ}$ C , RH : 44.7 %

2023-02-08 18:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:16:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 60.1 %

2023-02-08 18:16:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:16:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 56.1 %

2023-02-08 18:17:01 , modbusTCP , I6-1 , TEMP : 4.5 $^{\circ}\text{C}$

2023-02-08 18:17:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 72.9 %

2023-02-08 18:17:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.6 %

2023-02-08 18:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

```
2023-02-08 18:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 18:17:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.0 %

2023-02-08 18:17:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:17:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.8 %

2023-02-08 18:18:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:18:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.2 %

2023-02-08 18:18:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 18:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 18:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:18:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 60.0 %

2023-02-08 18:18:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:18:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.7 %

2023-02-08 18:19:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 18:19:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 73.5 %

2023-02-08 18:19:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 62.0 %

2023-02-08 18:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.7 %

2023-02-08 18:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:19:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.0 %

2023-02-08 18:19:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:19:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.5 %

2023-02-08 18:20:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 18:20:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 73.8 %

2023-02-08 18:20:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 18:20:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.8 %

2023-02-08 18:20:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:20:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 60.0 %

```
2023-02-08 18:20:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %
```

2023-02-08 18:20:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.3 %

2023-02-08 18:21:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:21:01 , modbusTCP , I6-1/S-12 , TEMP : 26.4 $^{\circ}\text{C}$, RH : 74.1 %

2023-02-08 18:21:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 18:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.7 %

2023-02-08 18:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:21:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:21:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:21:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.7 %

2023-02-08 18:22:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:22:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 74.4 %

2023-02-08 18:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.2 %

2023-02-08 18:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.6 %

2023-02-08 18:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:22:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:22:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:22:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 55.1 %

2023-02-08 18:23:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:23:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2 $^{\circ}$ C , RH : 74.7 %

2023-02-08 18:23:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 18:23:02, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.8 %

2023-02-08 18:23:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:23:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:23:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:23:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.1 %

```
2023-02-08 18:24:01, modbusTCP, I6-1, TEMP: 3.6 °C
```

2023-02-08 18:24:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.0 %

2023-02-08 18:24:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-08 18:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:24:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:24:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:24:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 55.2 %

2023-02-08 18:25:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 18:25:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.3 %

2023-02-08 18:25:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 18:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.8 %

2023-02-08 18:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:25:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:25:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:25:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.9 %

2023-02-08 18:26:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:26:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 75.6 %

2023-02-08 18:26:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.2 %

2023-02-08 18:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.7 %

2023-02-08 18:26:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:26:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.9 %

2023-02-08 18:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:26:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.9 %

2023-02-08 18:27:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 18:27:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 75.8 %

```
2023-02-08 18:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-08 18:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.7 %

2023-02-08 18:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:27:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.9 %

2023-02-08 18:27:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:27:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.7 %

2023-02-08 18:28:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:28:02 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 76.0 %

2023-02-08 18:28:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 62.0 %

2023-02-08 18:28:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.8 %

2023-02-08 18:28:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:28:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.9 %

2023-02-08 18:28:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:28:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.7 %

2023-02-08 18:29:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:29:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.1 %

2023-02-08 18:29:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 18:29:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}$ C , RH : 44.7 %

2023-02-08 18:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:29:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.8 %

2023-02-08 18:29:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:29:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.6 %

2023-02-08 18:30:01 , modbusTCP , I6-1 , TEMP : 4.3 $^{\circ}\text{C}$

2023-02-08 18:30:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.3 %

2023-02-08 18:30:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 18:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.8 %

```
2023-02-08 18:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 18:30:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.8 %

2023-02-08 18:30:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:30:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.6 %

2023-02-08 18:31:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:31:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.4 %

2023-02-08 18:31:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-08 18:31:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.7 %

2023-02-08 18:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:31:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.8 %

2023-02-08 18:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:31:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.4 %

2023-02-08 18:32:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 18:32:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-08 18:32:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.6 %

2023-02-08 18:32:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.1 %

2023-02-08 18:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:32:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.8 %

2023-02-08 18:32:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:32:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.7 %

2023-02-08 18:33:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:33:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-08 18:33:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 18:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:33:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.7 %

```
2023-02-08 18:33:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %
```

2023-02-08 18:33:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.7 %

2023-02-08 18:34:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:34:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-08 18:34:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 18:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:34:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.7 %

2023-02-08 18:34:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:34:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.1 %

2023-02-08 18:35:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:35:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:35:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 18:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.8 %

2023-02-08 18:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:35:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.7 %

2023-02-08 18:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:35:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.3 %

2023-02-08 18:36:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 18:36:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 18:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.8 %

2023-02-08 18:36:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:36:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.7 %

2023-02-08 18:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:36:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.1 %

```
2023-02-08 18:37:02, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-08 18:37:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:37:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %

2023-02-08 18:37:02, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.8 %

2023-02-08 18:37:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:37:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.7 %

2023-02-08 18:37:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:37:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 54.0 %

2023-02-08 18:38:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 18:38:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 18:38:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 18:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:38:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.8 %

2023-02-08 18:38:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 18:38:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.0 %

2023-02-08 18:39:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:39:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 18:39:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-08 18:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:39:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:39:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.8 %

2023-02-08 18:39:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:39:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 53.9 %

2023-02-08 18:40:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 18:40:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5 $^{\circ}\text{C}$, RH : 77.0 %

```
2023-02-08 18:40:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %
```

2023-02-08 18:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:40:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 59.7 %

2023-02-08 18:40:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:40:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.8 %

2023-02-08 18:41:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:41:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6 $^{\circ}\text{C}$, RH : 77.0 %

2023-02-08 18:41:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.3 %

2023-02-08 18:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 18:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:41:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.7 %

2023-02-08 18:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.7 %

2023-02-08 18:41:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.8 %

2023-02-08 18:42:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 18:42:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:42:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 18:42:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1 $^{\circ}$ C , RH : 44.7 %

2023-02-08 18:42:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:42:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 59.7 %

2023-02-08 18:42:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:42:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 54.0 %

2023-02-08 18:43:01 , modbusTCP , I6-1 , TEMP : 3.9 $^{\circ}\text{C}$

2023-02-08 18:43:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:43:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.3 %

2023-02-08 18:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.6 %

```
2023-02-08 18:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 18:43:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.6 %

2023-02-08 18:43:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:43:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 53.6 %

2023-02-08 18:44:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:44:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 18:44:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 18:44:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.7 %

2023-02-08 18:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:44:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.6 %

2023-02-08 18:44:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:44:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.4 %

2023-02-08 18:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:45:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-08 18:45:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 18:45:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.0 %

2023-02-08 18:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:45:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.6 %

2023-02-08 18:45:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:45:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 53.8 %

2023-02-08 18:46:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 18:46:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 18:46:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 18:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.0 %

2023-02-08 18:46:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 18:46:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.6 %

```
2023-02-08 18:46:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %
```

2023-02-08 18:46:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 53.4 %

2023-02-08 18:47:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 18:47:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-08 18:47:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 18:47:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9 $^{\circ}$ C , RH : 44.9 %

2023-02-08 18:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:47:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.6 %

2023-02-08 18:47:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:47:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.4 %

2023-02-08 18:48:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 18:48:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.4 %

2023-02-08 18:48:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.3 %

2023-02-08 18:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:48:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:48:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:48:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 53.4 %

2023-02-08 18:49:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:49:01 , modbusTCP , I6-1/S-12 , TEMP : 25.8 $^{\circ}$ C , RH : 76.3 $^{\circ}$

2023-02-08 18:49:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 18:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:49:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:49:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 18:49:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

```
2023-02-08 18:50:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-08 18:50:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.2 %

2023-02-08 18:50:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 18:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:50:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:50:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.6 %

2023-02-08 18:50:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.2 %

2023-02-08 18:51:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 18:51:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.1 %

2023-02-08 18:51:02, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-08 18:51:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.9 %

2023-02-08 18:51:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:51:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:51:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.6 $^{\circ}$

2023-02-08 18:51:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 18:52:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 18:52:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 76.0 %

2023-02-08 18:52:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-08 18:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.1 %

2023-02-08 18:52:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 18:52:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.5 %

2023-02-08 18:52:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.6 %

2023-02-08 18:52:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 18:53:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 18:53:01 , modbusTCP , I6-1/S-12 , TEMP : 26.0 $^{\circ}\text{C}$, RH : 76.0 %

```
2023-02-08 18:53:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %
```

2023-02-08 18:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.0 %

2023-02-08 18:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:53:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:53:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:53:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 18:54:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 18:54:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.9 %

2023-02-08 18:54:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.2 $^{\circ}$

2023-02-08 18:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.0 %

2023-02-08 18:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:54:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.5 %

2023-02-08 18:54:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 18:54:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.2 %

2023-02-08 18:55:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 18:55:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.8 %

2023-02-08 18:55:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 18:55:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}\text{C}$, RH : 45.1 %

2023-02-08 18:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:55:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.5 %

2023-02-08 18:55:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 18:55:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.9 %

2023-02-08 18:56:02 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 18:56:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.5 %

2023-02-08 18:56:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 18:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

```
2023-02-08 18:56:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 18:56:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:56:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 18:56:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 18:57:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 18:57:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 74.1 %

2023-02-08 18:57:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 18:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.9 %

2023-02-08 18:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:57:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 18:57:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 18:57:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.0 %

2023-02-08 18:58:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 18:58:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 73.2 %

2023-02-08 18:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.6 %

2023-02-08 18:58:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 45.4 %

2023-02-08 18:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:58:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.4 %

2023-02-08 18:58:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 18:58:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 53.0 $^{\circ}$

2023-02-08 18:59:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 18:59:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 72.4 %

2023-02-08 18:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 18:59:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 45.6 %

2023-02-08 18:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 18:59:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

```
2023-02-08 18:59:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %
```

2023-02-08 18:59:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.0 %

2023-02-08 19:00:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:00:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 71.8 %

2023-02-08 19:00:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-08 19:00:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.4 %

2023-02-08 19:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:00:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.5 %

2023-02-08 19:00:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:00:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 19:01:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 19:01:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 71.3 %

2023-02-08 19:01:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 19:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.6 %

2023-02-08 19:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:01:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.5 %

2023-02-08 19:01:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:01:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.0 %

2023-02-08 19:02:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:02:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 71.0 %

2023-02-08 19:02:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 19:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.3 %

2023-02-08 19:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:02:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.4 %

2023-02-08 19:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 19:02:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

```
2023-02-08 19:03:01, modbusTCP, I6-1, TEMP: 4.5 °C
```

2023-02-08 19:03:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.7 %

2023-02-08 19:03:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 19:03:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.7 %

2023-02-08 19:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:03:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.4 %

2023-02-08 19:03:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:03:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

2023-02-08 19:04:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:04:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.7 %

2023-02-08 19:04:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 19:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.9 %

2023-02-08 19:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:04:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.4 %

2023-02-08 19:04:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:04:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 53.1 %

2023-02-08 19:05:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:05:02, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 70.5 %

2023-02-08 19:05:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 19:05:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.9 %

2023-02-08 19:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:05:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.4 %

2023-02-08 19:05:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:05:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

2023-02-08 19:06:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 19:06:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 70.3 %

```
2023-02-08 19:06:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %
```

2023-02-08 19:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

2023-02-08 19:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:06:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.4 %

2023-02-08 19:06:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:06:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 52.7 $^{\circ}$

2023-02-08 19:07:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:07:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 70.1 %

2023-02-08 19:07:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 19:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.7 %

2023-02-08 19:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:07:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.4 %

2023-02-08 19:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.7 %

2023-02-08 19:07:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:08:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:08:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.8 %

2023-02-08 19:08:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 19:08:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}\text{C}$, RH : 45.8 %

2023-02-08 19:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:08:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.3 %

2023-02-08 19:08:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:08:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

2023-02-08 19:09:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 19:09:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.5 %

2023-02-08 19:09:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 19:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

```
2023-02-08 19:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 19:09:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.3 %

2023-02-08 19:09:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:09:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 53.5 %

2023-02-08 19:10:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 19:10:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 69.3 %

2023-02-08 19:10:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 19:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.7 %

2023-02-08 19:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:10:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:10:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:10:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

2023-02-08 19:11:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 19:11:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 69.1 %

2023-02-08 19:11:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 19:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 19:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:11:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:11:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:11:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 52.8 %

2023-02-08 19:12:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:12:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.8 %

2023-02-08 19:12:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 19:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 19:12:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:12:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

```
2023-02-08 19:12:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %
```

2023-02-08 19:12:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:13:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:13:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.6 %

2023-02-08 19:13:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 19:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 46.0 %

2023-02-08 19:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:13:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.2 %

2023-02-08 19:13:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:13:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:14:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:14:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.3 %

2023-02-08 19:14:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 19:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

2023-02-08 19:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:14:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:14:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:14:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 52.8 %

2023-02-08 19:15:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:15:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.1 %

2023-02-08 19:15:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 19:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 46.0 %

2023-02-08 19:15:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:15:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.2 %

2023-02-08 19:15:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:15:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

```
2023-02-08 19:16:01, modbusTCP, I6-1, TEMP: 4.1 °C
```

2023-02-08 19:16:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.9 %

2023-02-08 19:16:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 19:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 46.1 %

2023-02-08 19:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:16:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:16:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:16:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:17:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:17:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.7 %

2023-02-08 19:17:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 19:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.1 %

2023-02-08 19:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:17:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:17:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:17:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.6 %

2023-02-08 19:18:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:18:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.5 %

2023-02-08 19:18:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 19:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.2 %

2023-02-08 19:18:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:18:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:18:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.6 %

2023-02-08 19:19:02 , modbusTCP , I6-1 , TEMP : 3.4 $^{\circ}\text{C}$

2023-02-08 19:19:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.3 %

```
2023-02-08 19:19:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %
```

2023-02-08 19:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.2 %

2023-02-08 19:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:19:02 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.2 %

2023-02-08 19:19:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:19:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 52.8 $^{\circ}$

2023-02-08 19:20:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-08 19:20:01 , modbusTCP , I6-1/S-12 , TEMP : 26.7 $^{\circ}\text{C}$, RH : 67.1 %

2023-02-08 19:20:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 19:20:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 46.1 %

2023-02-08 19:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:20:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:20:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:20:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.9 %

2023-02-08 19:21:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:21:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.0 %

2023-02-08 19:21:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 19:21:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1 $^{\circ}$ C , RH : 46.3 %

2023-02-08 19:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:21:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 59.2 %

2023-02-08 19:21:16 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 19:21:16, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.8 %

2023-02-08 19:22:02 , modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 19:22:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.8 %

2023-02-08 19:22:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 19:22:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 46.3 %

```
2023-02-08 19:22:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 19:22:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:22:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:22:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:23:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 19:23:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.7 %

2023-02-08 19:23:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 19:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 19:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:23:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.2 %

2023-02-08 19:23:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:23:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:24:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:24:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.5 %

2023-02-08 19:24:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.6 %

2023-02-08 19:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.9 %

2023-02-08 19:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:24:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.2 %

2023-02-08 19:24:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:24:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 52.7 %

2023-02-08 19:25:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:25:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.4 %

2023-02-08 19:25:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.6 %

2023-02-08 19:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 46.1 %

2023-02-08 19:25:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:25:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

```
2023-02-08 19:25:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %
```

2023-02-08 19:25:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.7 %

2023-02-08 19:26:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:26:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.3 %

2023-02-08 19:26:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 19:26:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.9 %

2023-02-08 19:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:26:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.7 %

2023-02-08 19:26:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.6 %

2023-02-08 19:27:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:27:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.2 %

2023-02-08 19:27:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 19:27:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.7 %

2023-02-08 19:27:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:27:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.2 %

2023-02-08 19:27:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:27:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 52.5 %

2023-02-08 19:28:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:28:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}$ C , RH : 66.1 %

2023-02-08 19:28:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 19:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.9 %

2023-02-08 19:28:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:28:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.2 %

2023-02-08 19:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:28:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.6 %

```
2023-02-08 19:29:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-08 19:29:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

2023-02-08 19:29:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 19:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.8 %

2023-02-08 19:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:29:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:29:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:29:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.5 %

2023-02-08 19:30:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:30:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.8 %

2023-02-08 19:30:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 19:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.9 %

2023-02-08 19:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:30:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 19:30:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.4 %

2023-02-08 19:31:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-08 19:31:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}\text{C}$, RH : 65.7 %

2023-02-08 19:31:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 19:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 19:31:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:31:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:31:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:31:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.3 %

2023-02-08 19:32:02 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 19:32:02 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}\text{C}$, RH : 66.0 %

```
2023-02-08 19:32:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %
```

2023-02-08 19:32:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

2023-02-08 19:32:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:32:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:32:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:32:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 52.3 $^{\circ}$

2023-02-08 19:33:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 19:33:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9 $^{\circ}\text{C}$, RH : 66.5 %

2023-02-08 19:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.8 %

2023-02-08 19:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.9 %

2023-02-08 19:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:33:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:33:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:33:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.2 %

2023-02-08 19:34:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 19:34:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.9 %

2023-02-08 19:34:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 19:34:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}\text{C}$, RH : 45.8 %

2023-02-08 19:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:34:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 59.1 %

2023-02-08 19:34:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:34:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.2 %

2023-02-08 19:35:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 19:35:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 67.2 %

2023-02-08 19:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 19:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

```
2023-02-08 19:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 19:35:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:35:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.2 %

2023-02-08 19:36:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:36:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 67.6 %

2023-02-08 19:36:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 19:36:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}\text{C}$, RH : 46.0 %

2023-02-08 19:36:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:36:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:36:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:36:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.1 %

2023-02-08 19:37:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:37:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 67.9 %

2023-02-08 19:37:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.2 %

2023-02-08 19:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.9 %

2023-02-08 19:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:37:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:37:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:37:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 52.1 %

2023-02-08 19:38:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:38:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.1 %

2023-02-08 19:38:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 19:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.8 %

2023-02-08 19:38:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 19:38:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

```
2023-02-08 19:38:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %
```

2023-02-08 19:38:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.1 %

2023-02-08 19:39:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 19:39:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.4 %

2023-02-08 19:39:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 19:39:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 46.0 %

2023-02-08 19:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:39:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:39:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 19:39:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.1 %

2023-02-08 19:40:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:40:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.6 %

2023-02-08 19:40:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.8 %

2023-02-08 19:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.2 %

2023-02-08 19:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:40:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:40:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:40:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 52.0 %

2023-02-08 19:41:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:41:02, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.8 %

2023-02-08 19:41:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 19:41:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 46.0 %

2023-02-08 19:41:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:41:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:41:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:41:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.0 %

```
2023-02-08 19:42:01, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-08 19:42:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.1 %

2023-02-08 19:42:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 19:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.1 %

2023-02-08 19:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:42:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:42:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:42:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.9 %

2023-02-08 19:43:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:43:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.3 %

2023-02-08 19:43:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 19:43:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}$ C , RH : 46.1 %

2023-02-08 19:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:43:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.1 %

2023-02-08 19:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 19:43:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.0 %

2023-02-08 19:44:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 19:44:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2 $^{\circ}\text{C}$, RH : 69.6 %

2023-02-08 19:44:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 19:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 46.0 %

2023-02-08 19:44:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:44:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:44:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:44:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.9 %

2023-02-08 19:45:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 19:45:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.8 %

```
2023-02-08 19:45:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %
```

2023-02-08 19:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 46.1 %

2023-02-08 19:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:45:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:45:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:45:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 52.0 %

2023-02-08 19:46:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:46:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}\text{C}$, RH : 70.0 %

2023-02-08 19:46:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.6 $^{\circ}$

2023-02-08 19:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.7 %

2023-02-08 19:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:46:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:46:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:46:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.9 %

2023-02-08 19:47:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 19:47:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.3 %

2023-02-08 19:47:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 19:47:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.5 %

2023-02-08 19:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:47:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:47:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:47:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.8 %

2023-02-08 19:48:01 , modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}\text{C}$

2023-02-08 19:48:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.5 %

2023-02-08 19:48:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 19:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.7 %

```
2023-02-08 19:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 19:48:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:48:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:48:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.6 %

2023-02-08 19:49:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 19:49:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.7 %

2023-02-08 19:49:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 19:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 19:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:49:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 19:49:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.7 %

2023-02-08 19:50:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:50:02, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.0 %

2023-02-08 19:50:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 19:50:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.7 %

2023-02-08 19:50:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:50:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 59.0 %

2023-02-08 19:50:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.7 %

2023-02-08 19:50:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.7 %

2023-02-08 19:51:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:51:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.2 %

2023-02-08 19:51:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 19:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.8 %

2023-02-08 19:51:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:51:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

```
2023-02-08 19:51:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %
```

2023-02-08 19:51:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.6 %

2023-02-08 19:52:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 19:52:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}$ C , RH : 71.4 $^{\circ}$

2023-02-08 19:52:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 19:52:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 45.6 %

2023-02-08 19:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:52:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.1 %

2023-02-08 19:52:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 19:52:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

2023-02-08 19:53:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:53:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.6 %

2023-02-08 19:53:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 19:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.6 %

2023-02-08 19:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 19:53:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:53:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.5 %

2023-02-08 19:54:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 19:54:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0 $^{\circ}$ C , RH : 71.9 %

2023-02-08 19:54:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 19:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.7 %

2023-02-08 19:54:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:54:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 19:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 19:54:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

```
2023-02-08 19:55:02, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-08 19:55:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.2 %

2023-02-08 19:55:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.7 %

2023-02-08 19:55:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 46.1 %

2023-02-08 19:55:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:55:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:55:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:55:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

2023-02-08 19:56:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 19:56:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.5 %

2023-02-08 19:56:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.8 %

2023-02-08 19:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.9 %

2023-02-08 19:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:56:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 19:56:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:56:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

2023-02-08 19:57:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 19:57:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 72.7 %

2023-02-08 19:57:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 19:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 46.1 %

2023-02-08 19:57:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 19:57:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 19:57:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:57:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.4 %

2023-02-08 19:58:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 19:58:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.0 %

```
2023-02-08 19:58:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %
```

2023-02-08 19:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

2023-02-08 19:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:58:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 19:58:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 19:58:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.4 %

2023-02-08 19:59:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 19:59:01 , modbusTCP , I6-1/S-12 , TEMP : 26.7 $^{\circ}\text{C}$, RH : 73.3 %

2023-02-08 19:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.8 %

2023-02-08 19:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.7 %

2023-02-08 19:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 19:59:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 19:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 19:59:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

2023-02-08 20:00:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 20:00:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.6 %

2023-02-08 20:00:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 20:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}\text{C}$, RH : 45.8 %

2023-02-08 20:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:00:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 59.0 %

2023-02-08 20:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:00:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 20:01:01 , modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}\text{C}$

2023-02-08 20:01:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.9 %

2023-02-08 20:01:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.3 %

2023-02-08 20:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

```
2023-02-08 20:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 20:01:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 20:01:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:01:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 20:02:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:02:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.2 %

2023-02-08 20:02:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 20:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.8 %

2023-02-08 20:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:02:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 59.0 %

2023-02-08 20:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-08 20:02:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 20:03:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:03:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.5 %

2023-02-08 20:03:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 20:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.9 %

2023-02-08 20:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:03:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 58.9 %

2023-02-08 20:03:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:03:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.2 %

2023-02-08 20:04:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 20:04:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.7 %

2023-02-08 20:04:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 20:04:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 46.0 %

2023-02-08 20:04:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:04:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

```
2023-02-08 20:04:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %
```

2023-02-08 20:04:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.2 %

2023-02-08 20:05:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:05:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 75.0 %

2023-02-08 20:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %

2023-02-08 20:05:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.9 %

2023-02-08 20:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:05:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:05:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 20:06:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:06:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.2 %

2023-02-08 20:06:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 20:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.7 %

2023-02-08 20:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:06:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:06:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:06:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.3 %

2023-02-08 20:07:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:07:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.4 %

2023-02-08 20:07:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 20:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.5 %

2023-02-08 20:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:07:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:07:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

```
2023-02-08 20:08:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-08 20:08:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.6 %

2023-02-08 20:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 20:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.6 %

2023-02-08 20:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:08:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:08:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:08:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 20:09:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:09:02, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.8 %

2023-02-08 20:09:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 20:09:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.7 %

2023-02-08 20:09:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:09:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:09:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.9 %

2023-02-08 20:09:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.2 %

2023-02-08 20:10:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:10:01 , modbusTCP , I6-1/S-12 , TEMP : 26.1 $^{\circ}\text{C}$, RH : 76.0 %

2023-02-08 20:10:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 20:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 20:10:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:10:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:10:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:10:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 20:11:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:11:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.1 %

```
2023-02-08 20:11:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %
```

2023-02-08 20:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.7 %

2023-02-08 20:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:11:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.9 %

2023-02-08 20:11:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:11:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 51.1 %

2023-02-08 20:12:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 20:12:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 76.3 %

2023-02-08 20:12:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 20:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.7 %

2023-02-08 20:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:12:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:12:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 20:13:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:13:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.4 %

2023-02-08 20:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-08 20:13:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}\text{C}$, RH : 45.7 %

2023-02-08 20:13:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:13:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 20:13:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 20:13:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 20:14:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 20:14:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 20:14:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 20:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.5 %

```
2023-02-08 20:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 20:14:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 20:14:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:14:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 20:15:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 20:15:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.7 %

2023-02-08 20:15:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 20:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

2023-02-08 20:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:15:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 20:15:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:15:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 20:16:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:16:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 20:16:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 20:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 20:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:16:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 59.0 %

2023-02-08 20:16:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:16:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.0 %

2023-02-08 20:17:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:17:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

2023-02-08 20:17:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 20:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.3 %

2023-02-08 20:17:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:17:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

```
2023-02-08 20:17:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %
```

2023-02-08 20:17:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 50.9 $^{\circ}$

2023-02-08 20:18:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:18:02, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.9 %

2023-02-08 20:18:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-08 20:18:03, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.9 %

2023-02-08 20:18:03, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:18:03, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:18:03 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 20:18:03, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 20:19:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 20:19:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.9 %

2023-02-08 20:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2 $^{\circ}$ C , RH : 61.7 %

2023-02-08 20:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

2023-02-08 20:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:19:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:19:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:19:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 50.8 %

2023-02-08 20:20:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 20:20:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6 $^{\circ}\text{C}$, RH : 76.9 %

2023-02-08 20:20:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 20:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.7 %

2023-02-08 20:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:20:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:20:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

```
2023-02-08 20:21:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-08 20:21:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 20:21:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 20:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 20:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:21:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:21:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:21:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:22:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:22:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 20:22:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 20:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 20:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:22:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 20:22:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:23:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 20:23:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6 $^{\circ}\text{C}$, RH : 77.0 %

2023-02-08 20:23:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 20:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.6 %

2023-02-08 20:23:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:23:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:23:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 20:24:02 , modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}\text{C}$

2023-02-08 20:24:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

```
2023-02-08 20:24:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %
```

2023-02-08 20:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

2023-02-08 20:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:24:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:24:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:24:02 , modbusTCP , I6-2/S-10 , TEMP : 23.4 $^{\circ}$ C , RH : 50.8 $^{\circ}$

2023-02-08 20:25:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:25:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6 $^{\circ}\text{C}$, RH : 77.0 %

2023-02-08 20:25:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.6 %

2023-02-08 20:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 20:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:25:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:25:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.9 %

2023-02-08 20:25:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:26:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:26:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 20:26:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 20:26:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1 $^{\circ}\text{C}$, RH : 45.6 %

2023-02-08 20:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:26:01 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}$ C , RH : 58.8 %

2023-02-08 20:26:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:26:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:27:01 , modbusTCP , I6-1 , TEMP : 3.6 $^{\circ}\text{C}$

2023-02-08 20:27:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.1 %

2023-02-08 20:27:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 20:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.7 %

```
2023-02-08 20:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 20:27:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:27:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 50.8 $^{\circ}$

2023-02-08 20:28:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:28:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 20:28:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 20:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 20:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:28:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.7 %

2023-02-08 20:28:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:28:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:29:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:29:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 20:29:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.6 %

2023-02-08 20:29:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.7 %

2023-02-08 20:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:29:02 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 20:29:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:29:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:30:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:30:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

2023-02-08 20:30:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 20:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 20:30:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:30:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

```
2023-02-08 20:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 20:30:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 20:31:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 20:31:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 20:31:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 20:31:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.7 %

2023-02-08 20:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:31:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:31:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:32:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:32:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 20:32:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.9 %

2023-02-08 20:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

2023-02-08 20:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:32:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:32:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.8 %

2023-02-08 20:32:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 20:33:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:33:02, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 20:33:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 20:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.6 %

2023-02-08 20:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:33:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:33:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 20:33:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

```
2023-02-08 20:34:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-08 20:34:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.5 %

2023-02-08 20:34:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 20:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 20:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:34:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.7 %

2023-02-08 20:34:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:34:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 20:35:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 20:35:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.4 %

2023-02-08 20:35:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 20:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 20:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:35:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.9 %

2023-02-08 20:35:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 20:36:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:36:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 75.0 %

2023-02-08 20:36:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 20:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.5 %

2023-02-08 20:36:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:36:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 20:36:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:37:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:37:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 74.0 %

```
2023-02-08 20:37:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-08 20:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

2023-02-08 20:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:37:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:37:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:37:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:38:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 20:38:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 73.3 %

2023-02-08 20:38:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 20:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 20:38:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:38:02, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.9 %

2023-02-08 20:38:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:38:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:39:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:39:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.6 %

2023-02-08 20:39:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 20:39:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}\text{C}$, RH : 45.4 %

2023-02-08 20:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:39:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.9 %

2023-02-08 20:39:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:39:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:40:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:40:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.0 %

2023-02-08 20:40:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 20:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.5 %

```
2023-02-08 20:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 20:40:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 20:40:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 20:41:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:41:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 71.6 %

2023-02-08 20:41:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 20:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.0 %

2023-02-08 20:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:41:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 20:41:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:41:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:42:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 20:42:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 71.3 %

2023-02-08 20:42:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.0 %

2023-02-08 20:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 20:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:42:02 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 20:42:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:42:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 20:43:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 20:43:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.1 %

2023-02-08 20:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 20:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 20:43:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:43:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

```
2023-02-08 20:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 20:43:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 20:44:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:44:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.9 %

2023-02-08 20:44:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.8 %

2023-02-08 20:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 20:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:44:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 20:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:44:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.2 %

2023-02-08 20:45:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:45:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.7 %

2023-02-08 20:45:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.8 %

2023-02-08 20:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 20:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:45:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:45:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.6 %

2023-02-08 20:46:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 20:46:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.4 %

2023-02-08 20:46:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 20:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 20:46:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:46:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:46:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:46:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

```
2023-02-08 20:47:02, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-08 20:47:02, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.2 %

2023-02-08 20:47:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 20:47:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}\text{C}$, RH : 45.3 %

2023-02-08 20:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:47:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:47:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-08 20:48:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:48:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.9 %

2023-02-08 20:48:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 20:48:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.3 %

2023-02-08 20:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:48:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:48:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.8 %

2023-02-08 20:48:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 20:49:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:49:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2 $^{\circ}\text{C}$, RH : 69.6 %

2023-02-08 20:49:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.2 %

2023-02-08 20:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 20:49:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:49:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:49:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 20:50:01 , modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 20:50:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.3 %

```
2023-02-08 20:50:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %
```

2023-02-08 20:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.7 %

2023-02-08 20:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:50:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 20:50:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.7 %

2023-02-08 20:51:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:51:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3 $^{\circ}\text{C}$, RH : 69.0 %

2023-02-08 20:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.7 %

2023-02-08 20:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 20:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:51:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.9 %

2023-02-08 20:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:51:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.9 %

2023-02-08 20:52:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 20:52:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.7 %

2023-02-08 20:52:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 20:52:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 $^{\circ}\text{C}$, RH : 45.4 %

2023-02-08 20:52:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:52:02 , modbusTCP , I6-2/S-8 , TEMP : 21.0 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 20:52:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:52:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.9 %

2023-02-08 20:53:01 , modbusTCP , I6-1 , TEMP : 3.6 $^{\circ}\text{C}$

2023-02-08 20:53:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.4 %

2023-02-08 20:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 20:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

```
2023-02-08 20:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 20:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:53:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 20:54:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 20:54:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.2 %

2023-02-08 20:54:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 20:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.3 %

2023-02-08 20:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:54:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:54:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:54:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-08 20:55:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 20:55:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.9 %

2023-02-08 20:55:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-08 20:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.3 %

2023-02-08 20:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:55:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:55:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 20:55:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.1 %

2023-02-08 20:56:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 20:56:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.7 %

2023-02-08 20:56:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 20:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.7 %

2023-02-08 20:56:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 20:56:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

```
2023-02-08 20:56:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %
```

2023-02-08 20:56:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 20:57:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 20:57:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.4 %

2023-02-08 20:57:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 20:57:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 44.5 %

2023-02-08 20:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:57:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 67.8 %

2023-02-08 20:57:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 20:58:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 20:58:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.2 %

2023-02-08 20:58:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 20:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.4 %

2023-02-08 20:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 20:58:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 20:58:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 52.5 %

2023-02-08 20:59:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 20:59:01 , modbusTCP , I6-1/S-12 , TEMP : 26.6 $^{\circ}\text{C}$, RH : 67.0 %

2023-02-08 20:59:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 20:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.7 %

2023-02-08 20:59:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 20:59:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 20:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 20:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

```
2023-02-08 21:00:01, modbusTCP, I6-1, TEMP: 4.1 °C
```

2023-02-08 21:00:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.8 %

2023-02-08 21:00:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %

2023-02-08 21:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.5 %

2023-02-08 21:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:00:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-08 21:00:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 21:01:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 21:01:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.6 %

2023-02-08 21:01:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 21:01:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 44.7 %

2023-02-08 21:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:01:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-08 21:01:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 21:02:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 21:02:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}\text{C}$, RH : 66.5 %

2023-02-08 21:02:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 21:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.7 %

2023-02-08 21:02:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:02:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:02:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 21:03:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 21:03:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.3 %

```
2023-02-08 21:03:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %
```

2023-02-08 21:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.6 %

2023-02-08 21:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:03:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-08 21:03:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 52.4 $^{\circ}$

2023-02-08 21:04:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 21:04:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.1 %

2023-02-08 21:04:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 21:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.4 %

2023-02-08 21:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:04:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.7 $^{\circ}$

2023-02-08 21:04:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.6 %

2023-02-08 21:05:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 21:05:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.0 %

2023-02-08 21:05:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 21:05:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1 $^{\circ}$ C , RH : 44.4 %

2023-02-08 21:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:05:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}$ C , RH : 58.8 %

2023-02-08 21:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-08 21:05:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.5 %

2023-02-08 21:06:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 21:06:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.8 %

2023-02-08 21:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 21:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.7 %

```
2023-02-08 21:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 21:06:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:06:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 21:07:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 21:07:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.7 %

2023-02-08 21:07:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 21:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 21:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:07:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:07:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.3 %

2023-02-08 21:08:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 21:08:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.5 %

2023-02-08 21:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 21:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.7 %

2023-02-08 21:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:08:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.9 %

2023-02-08 21:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:08:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.9 %

2023-02-08 21:09:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:09:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.4 %

2023-02-08 21:09:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 21:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 21:09:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:09:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

```
2023-02-08 21:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 21:09:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 21:10:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:10:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.5 %

2023-02-08 21:10:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 21:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.0 %

2023-02-08 21:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:10:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:10:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.8 $^{\circ}$

2023-02-08 21:10:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 21:11:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 21:11:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.1 %

2023-02-08 21:11:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 21:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.7 %

2023-02-08 21:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:11:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 21:12:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 21:12:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1 $^{\circ}$ C , RH : 66.4 %

2023-02-08 21:12:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 21:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.0 %

2023-02-08 21:12:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:12:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:12:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

```
2023-02-08 21:13:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-08 21:13:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.8 %

2023-02-08 21:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-08 21:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.1 %

2023-02-08 21:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:13:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:13:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-08 21:14:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 21:14:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.1 %

2023-02-08 21:14:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.8 %

2023-02-08 21:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.0 %

2023-02-08 21:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:14:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.8 %

2023-02-08 21:14:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 67.9 %

2023-02-08 21:14:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 21:15:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 21:15:02 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}\text{C}$, RH : 67.4 %

2023-02-08 21:15:02, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.1 %

2023-02-08 21:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.1 %

2023-02-08 21:15:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:15:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:15:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:15:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 21:16:01 , modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 21:16:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.7 %

```
2023-02-08 21:16:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-08 21:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 21:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:16:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.7 %

2023-02-08 21:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:16:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-08 21:17:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 21:17:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 67.9 %

2023-02-08 21:17:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 21:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.8 %

2023-02-08 21:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:17:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:17:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 21:18:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 21:18:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.1 %

2023-02-08 21:18:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 21:18:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 44.8 %

2023-02-08 21:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:18:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 21:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:18:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 21:19:01 , modbusTCP , I6-1 , TEMP : 4.3 $^{\circ}\text{C}$

2023-02-08 21:19:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.4 %

2023-02-08 21:19:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 21:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.9 %

```
2023-02-08 21:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 21:19:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:19:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:19:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-08 21:20:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:20:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.6 %

2023-02-08 21:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-08 21:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.8 %

2023-02-08 21:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:20:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:20:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 21:21:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-08 21:21:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.9 %

2023-02-08 21:21:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2 $^{\circ}$ C , RH : 61.5 $^{\circ}$

2023-02-08 21:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.7 %

2023-02-08 21:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:21:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.8 %

2023-02-08 21:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:21:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.0 %

2023-02-08 21:22:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-08 21:22:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 69.1 %

2023-02-08 21:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2 $^{\circ}\text{C}$, RH : 61.3 %

2023-02-08 21:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.5 %

2023-02-08 21:22:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:22:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.7 %

```
2023-02-08 21:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 21:22:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 21:23:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-08 21:23:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 69.3 %

2023-02-08 21:23:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-08 21:23:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 44.7 %

2023-02-08 21:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:23:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.6 %

2023-02-08 21:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:23:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 21:24:02, modbusTCP, I6-1, TEMP: 5.3 °C

2023-02-08 21:24:02, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 69.6 %

2023-02-08 21:24:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 21:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.6 %

2023-02-08 21:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:24:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:24:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:24:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 21:25:01, modbusTCP, I6-1, TEMP: 5.5 °C

2023-02-08 21:25:01 , modbusTCP , I6-1/S-12 , TEMP : 27.4 $^{\circ}$ C , RH : 69.8 %

2023-02-08 21:25:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 21:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.3 %

2023-02-08 21:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:25:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:25:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:25:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

```
2023-02-08 21:26:01, modbusTCP, I6-1, TEMP: 5.6 °C
```

2023-02-08 21:26:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.1 %

2023-02-08 21:26:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 21:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.6 %

2023-02-08 21:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:26:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:26:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 21:27:01, modbusTCP, I6-1, TEMP: 6.0 °C

2023-02-08 21:27:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.3 %

2023-02-08 21:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 21:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-08 21:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:27:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:27:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 21:28:01, modbusTCP, I6-1, TEMP: 6.1 °C

2023-02-08 21:28:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.6 %

2023-02-08 21:28:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 21:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.5 %

2023-02-08 21:28:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:28:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 21:28:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 21:29:01, modbusTCP, I6-1, TEMP: 6.3 °C

2023-02-08 21:29:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.8 %

```
2023-02-08 21:29:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %
```

2023-02-08 21:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-08 21:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:29:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:29:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 50.8 $^{\circ}$

2023-02-08 21:30:01, modbusTCP, I6-1, TEMP: 6.3 °C

2023-02-08 21:30:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 71.1 %

2023-02-08 21:30:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 21:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.6 %

2023-02-08 21:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:30:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:30:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 21:31:01, modbusTCP, I6-1, TEMP: 6.0 °C

2023-02-08 21:31:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 71.4 %

2023-02-08 21:31:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 21:31:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0 $^{\circ}\text{C}$, RH : 44.6 %

2023-02-08 21:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:31:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}$ C , RH : 58.8 %

2023-02-08 21:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:31:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 21:32:01 , modbusTCP , I6-1 , TEMP : 5.9 $^{\circ}\text{C}$

2023-02-08 21:32:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.7 %

2023-02-08 21:32:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 21:32:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 44.8 %

```
2023-02-08 21:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 21:32:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:32:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 21:33:02, modbusTCP, I6-1, TEMP: 5.5 °C

2023-02-08 21:33:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.9 %

2023-02-08 21:33:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 21:33:02 , modbusTCP , I6-1/S-16-2 , TEMP : 19.8 $^{\circ}$ C , RH : 44.9 %

2023-02-08 21:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:33:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:33:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:33:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 21:34:01, modbusTCP, I6-1, TEMP: 5.4 °C

2023-02-08 21:34:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 72.2 %

2023-02-08 21:34:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.0 $^{\circ}$

2023-02-08 21:34:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 45.0 %

2023-02-08 21:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:34:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 21:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:34:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 50.6 $^{\circ}$

2023-02-08 21:35:01 , modbusTCP , I6-1 , TEMP : 5.0 $^{\circ}\text{C}$

2023-02-08 21:35:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.6 %

2023-02-08 21:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 21:35:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 45.3 %

2023-02-08 21:35:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:35:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

```
2023-02-08 21:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 21:35:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 21:36:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-08 21:36:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.9 %

2023-02-08 21:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 21:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.1 %

2023-02-08 21:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:36:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:36:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 21:37:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 21:37:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 73.2 %

2023-02-08 21:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 62.1 %

2023-02-08 21:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.1 %

2023-02-08 21:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:37:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:37:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.8 %

2023-02-08 21:37:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 21:38:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 21:38:02 , modbusTCP , I6-1/S-12 , TEMP : 26.8 $^{\circ}$ C , RH : 73.5 $^{\circ}$

2023-02-08 21:38:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 21:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 21:38:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:38:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:38:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:38:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

```
2023-02-08 21:39:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-08 21:39:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.9 %

2023-02-08 21:39:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 21:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 21:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:39:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:39:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 21:40:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:40:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.3 %

2023-02-08 21:40:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 21:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 21:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:40:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:40:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 21:41:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-08 21:41:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.5 %

2023-02-08 21:41:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 21:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 21:41:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:41:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 21:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:41:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 21:42:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-08 21:42:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.9 %

```
2023-02-08 21:42:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %
```

2023-02-08 21:42:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 21:42:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:42:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:42:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:42:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.3 $^{\circ}$

2023-02-08 21:43:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-08 21:43:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3 $^{\circ}\text{C}$, RH : 75.2 %

2023-02-08 21:43:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.3 %

2023-02-08 21:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 21:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:43:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:43:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 21:44:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-08 21:44:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.5 %

2023-02-08 21:44:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-08 21:44:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 45.4 %

2023-02-08 21:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:44:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 21:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 21:44:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 21:45:01 , modbusTCP , I6-1 , TEMP : 4.6 °C

2023-02-08 21:45:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.7 %

2023-02-08 21:45:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 21:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

```
2023-02-08 21:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 21:45:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.7 %

2023-02-08 21:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:45:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 21:46:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 21:46:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 76.1 %

2023-02-08 21:46:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 21:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 21:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:46:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:46:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.7 %

2023-02-08 21:47:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 21:47:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.3 %

2023-02-08 21:47:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.4 %

2023-02-08 21:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.3 %

2023-02-08 21:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:47:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 21:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:47:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}$ C , RH : 52.1 %

2023-02-08 21:48:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 21:48:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.5 %

2023-02-08 21:48:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.6 %

2023-02-08 21:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 21:48:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:48:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.6 %

```
2023-02-08 21:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 21:48:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 21:49:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 21:49:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.6 %

2023-02-08 21:49:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 21:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 45.2 %

2023-02-08 21:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:49:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 21:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:49:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

2023-02-08 21:50:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 21:50:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.8 %

2023-02-08 21:50:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.2 %

2023-02-08 21:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 45.6 %

2023-02-08 21:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:50:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:50:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 51.9 %

2023-02-08 21:51:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 21:51:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7 $^{\circ}\text{C}$, RH : 76.9 %

2023-02-08 21:51:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 21:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.6 %

2023-02-08 21:51:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:51:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:51:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 21:51:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

```
2023-02-08 21:52:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-08 21:52:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 21:52:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-08 21:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 21:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:52:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.8 %

2023-02-08 21:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:52:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

2023-02-08 21:53:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:53:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.2 %

2023-02-08 21:53:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 21:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.3 %

2023-02-08 21:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 21:53:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.1 %

2023-02-08 21:54:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-08 21:54:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-08 21:54:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 21:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.5 %

2023-02-08 21:54:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 21:54:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.8 %

2023-02-08 21:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 21:54:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.1 %

2023-02-08 21:55:01 , modbusTCP , I6-1 , TEMP : 4.6 $^{\circ}\text{C}$

2023-02-08 21:55:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5 $^{\circ}\text{C}$, RH : 77.4 %

```
2023-02-08 21:55:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %
```

2023-02-08 21:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.5 %

2023-02-08 21:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:55:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:55:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}$ C , RH : 52.2 %

2023-02-08 21:56:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 21:56:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-08 21:56:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 21:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 21:56:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:56:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 21:56:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.9 %

2023-02-08 21:56:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 21:57:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 21:57:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 21:57:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 21:57:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.3 %

2023-02-08 21:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:57:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 21:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 21:57:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.7 %

2023-02-08 21:58:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 21:58:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 21:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 21:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

```
2023-02-08 21:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 21:58:01, modbusTCP, I6-2/S-8, TEMP: 21.0 °C, RH: 58.6 %

2023-02-08 21:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:58:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.7 %

2023-02-08 21:59:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 21:59:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 21:59:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 21:59:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 45.3 %

2023-02-08 21:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 21:59:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 21:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 21:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.7 %

2023-02-08 22:00:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 22:00:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 22:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-08 22:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 22:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:00:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 22:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:00:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.6 %

2023-02-08 22:01:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 22:01:02, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 22:01:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 22:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 22:01:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:01:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

```
2023-02-08 22:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 22:01:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.5 %

2023-02-08 22:02:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:02:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4 $^{\circ}$ C , RH : 77.6 $^{\circ}$

2023-02-08 22:02:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-08 22:02:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 45.4 %

2023-02-08 22:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:02:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:02:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.3 %

2023-02-08 22:03:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 22:03:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-08 22:03:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.6 %

2023-02-08 22:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.6 %

2023-02-08 22:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:03:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:03:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 52.2 %

2023-02-08 22:04:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 22:04:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4 $^{\circ}$ C , RH : 77.5 %

2023-02-08 22:04:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 22:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.5 %

2023-02-08 22:04:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:04:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:04:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.1 %

```
2023-02-08 22:05:01, modbusTCP, I6-1, TEMP: 4.5 °C
```

2023-02-08 22:05:02, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.4 %

2023-02-08 22:05:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-08 22:05:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 22:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:05:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:05:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:05:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.1 %

2023-02-08 22:06:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:06:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.3 %

2023-02-08 22:06:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 22:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 22:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:06:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:06:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 22:07:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 22:07:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5 $^{\circ}\text{C}$, RH : 77.2 %

2023-02-08 22:07:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.3 %

2023-02-08 22:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.4 %

2023-02-08 22:07:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:07:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 22:07:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 22:08:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 22:08:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

```
2023-02-08 22:08:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %
```

2023-02-08 22:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 22:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:08:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:08:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-08 22:09:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:09:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 22:09:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.7 %

2023-02-08 22:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 22:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:09:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:09:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:09:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-08 22:10:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 22:10:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 22:10:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 22:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 22:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:10:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 22:10:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:10:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 22:11:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 22:11:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

2023-02-08 22:11:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 22:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.6 %

```
2023-02-08 22:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 22:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 22:11:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.5 %

2023-02-08 22:12:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 22:12:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 22:12:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 22:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 22:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:12:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:12:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 22:13:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 22:13:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 22:13:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.5 $^{\circ}$

2023-02-08 22:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 22:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:13:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 22:13:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.4 %

2023-02-08 22:14:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:14:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 75.1 %

2023-02-08 22:14:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.3 %

2023-02-08 22:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 22:14:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:14:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

```
2023-02-08 22:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 22:14:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.3 %

2023-02-08 22:15:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 22:15:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}$ C , RH : 74.1 $^{\circ}$

2023-02-08 22:15:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-08 22:15:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.1 %

2023-02-08 22:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:15:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:15:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 22:16:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 22:16:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 73.3 %

2023-02-08 22:16:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.2 %

2023-02-08 22:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.3 %

2023-02-08 22:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:16:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:16:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.2 %

2023-02-08 22:17:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:17:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 72.6 %

2023-02-08 22:17:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 22:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.5 %

2023-02-08 22:17:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:17:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:17:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.2 %

```
2023-02-08 22:18:01, modbusTCP, I6-1, TEMP: 4.5 °C
```

2023-02-08 22:18:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.0 %

2023-02-08 22:18:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 22:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 22:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:18:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:18:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.1 %

2023-02-08 22:19:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 22:19:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 71.5 %

2023-02-08 22:19:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 22:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.5 %

2023-02-08 22:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:19:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:19:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:19:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 22:20:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:20:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.1 %

2023-02-08 22:20:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 22:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.4 %

2023-02-08 22:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:20:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:20:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 22:21:01 , modbusTCP , I6-1 , TEMP : 3.8 °C

2023-02-08 22:21:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.8 %

```
2023-02-08 22:21:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-08 22:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:21:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:21:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 22:22:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:22:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.7 %

2023-02-08 22:22:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.2 %

2023-02-08 22:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 22:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:22:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:22:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.0 %

2023-02-08 22:23:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:23:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.4 %

2023-02-08 22:23:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.1 %

2023-02-08 22:23:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}\text{C}$, RH : 45.3 %

2023-02-08 22:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:23:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 22:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:23:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 22:24:02 , modbusTCP , I6-1 , TEMP : 3.6 $^{\circ}\text{C}$

2023-02-08 22:24:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.2 %

2023-02-08 22:24:02 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 22:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

```
2023-02-08 22:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 22:24:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:24:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:24:02 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}$ C , RH : 51.0 $^{\circ}$

2023-02-08 22:25:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 22:25:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 70.0 %

2023-02-08 22:25:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-08 22:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:25:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:25:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 22:26:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:26:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.7 %

2023-02-08 22:26:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}$ C , RH : 62.0 %

2023-02-08 22:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.0 %

2023-02-08 22:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:26:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 22:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:26:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 50.8 %

2023-02-08 22:27:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 22:27:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.4 %

2023-02-08 22:27:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 22:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.1 %

2023-02-08 22:27:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:27:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

```
2023-02-08 22:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 22:27:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 22:28:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:28:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.1 %

2023-02-08 22:28:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 22:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.2 %

2023-02-08 22:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:28:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:28:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:28:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 22:29:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:29:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.8 %

2023-02-08 22:29:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 22:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 22:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:29:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:29:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 51.0 %

2023-02-08 22:30:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 22:30:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5 $^{\circ}\text{C}$, RH : 68.5 %

2023-02-08 22:30:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 22:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 22:30:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:30:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:30:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 51.4 %

```
2023-02-08 22:31:01, modbusTCP, I6-1, TEMP: 4.1 °C
```

2023-02-08 22:31:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.2 %

2023-02-08 22:31:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 22:31:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.5 %

2023-02-08 22:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:31:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:31:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 22:32:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 22:32:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.0 %

2023-02-08 22:32:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 22:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:32:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:32:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 22:33:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:33:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.7 %

2023-02-08 22:33:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 22:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:33:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 22:33:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 22:33:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 22:34:01 , modbusTCP , I6-1 , TEMP : 3.5 $^{\circ}\text{C}$

2023-02-08 22:34:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.4 %

```
2023-02-08 22:34:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %
```

2023-02-08 22:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 22:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:34:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:34:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.8 $^{\circ}$

2023-02-08 22:35:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:35:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 67.2 %

2023-02-08 22:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.3 %

2023-02-08 22:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 22:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:35:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 22:35:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 22:36:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 22:36:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.9 %

2023-02-08 22:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.2 %

2023-02-08 22:36:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}\text{C}$, RH : 45.4 %

2023-02-08 22:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:36:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 22:36:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 22:37:01 , modbusTCP , I6-1 , TEMP : 3.9 $^{\circ}\text{C}$

2023-02-08 22:37:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.7 %

2023-02-08 22:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 22:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.5 %

```
2023-02-08 22:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 22:37:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:37:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-08 22:38:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:38:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.5 %

2023-02-08 22:38:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-08 22:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 22:38:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:38:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:38:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:38:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-08 22:39:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 22:39:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.3 %

2023-02-08 22:39:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 22:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 22:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:39:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 22:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-08 22:39:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-08 22:40:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:40:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.2 %

2023-02-08 22:40:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.5 %

2023-02-08 22:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 22:40:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:40:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

```
2023-02-08 22:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-08 22:40:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.9 %

2023-02-08 22:41:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:41:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.0 %

2023-02-08 22:41:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-08 22:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.5 %

2023-02-08 22:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:41:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:41:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:41:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

2023-02-08 22:42:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 22:42:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.9 %

2023-02-08 22:42:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}$ C , RH : 62.4 %

2023-02-08 22:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.6 %

2023-02-08 22:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:42:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:42:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 51.9 %

2023-02-08 22:43:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:43:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0 $^{\circ}$ C , RH : 65.8 %

2023-02-08 22:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 22:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.3 %

2023-02-08 22:43:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:43:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 22:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:43:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

```
2023-02-08 22:44:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-08 22:44:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.7 %

2023-02-08 22:44:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 22:44:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}\text{C}$, RH : 45.0 %

2023-02-08 22:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:44:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:44:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 22:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:45:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.5 %

2023-02-08 22:45:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-08 22:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.2 %

2023-02-08 22:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:45:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:45:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.6 %

2023-02-08 22:46:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:46:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.4 %

2023-02-08 22:46:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 22:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.9 %

2023-02-08 22:46:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:46:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:46:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.5 %

2023-02-08 22:47:02 , modbusTCP , I6-1 , TEMP : 3.6 $^{\circ}\text{C}$

2023-02-08 22:47:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.3 %

```
2023-02-08 22:47:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-08 22:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 22:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:47:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:47:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.6 %

2023-02-08 22:48:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 22:48:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.7 %

2023-02-08 22:48:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 22:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:48:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:48:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.6 %

2023-02-08 22:49:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:49:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.1 %

2023-02-08 22:49:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 22:49:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 44.8 %

2023-02-08 22:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:49:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 22:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 22:49:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.6 %

2023-02-08 22:50:01 , modbusTCP , I6-1 , TEMP : 4.1 $^{\circ}\text{C}$

2023-02-08 22:50:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.6 %

2023-02-08 22:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 22:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

```
2023-02-08 22:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 22:50:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:50:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-08 22:51:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 22:51:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.9 %

2023-02-08 22:51:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 22:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 22:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:51:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:51:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.2 %

2023-02-08 22:52:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 22:52:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.2 %

2023-02-08 22:52:02 , modbusTCP , I6-1/S-13 , TEMP : $30.0 \, ^{\circ}\text{C}$, RH : $61.5 \, \%$

2023-02-08 22:52:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:52:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:52:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 22:52:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:52:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 52.0 %

2023-02-08 22:53:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 22:53:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.5 %

2023-02-08 22:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 61.4 %

2023-02-08 22:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 22:53:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

```
2023-02-08 22:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %
```

2023-02-08 22:53:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 52.0 %

2023-02-08 22:54:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 22:54:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}\text{C}$, RH : 67.7 %

2023-02-08 22:54:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 22:54:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}$ C , RH : 45.2 %

2023-02-08 22:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:54:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:54:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:54:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.8 %

2023-02-08 22:55:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 22:55:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.0 %

2023-02-08 22:55:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.7 %

2023-02-08 22:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:55:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:55:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.6 %

2023-02-08 22:56:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 22:56:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}$ C , RH : 68.3 $^{\circ}$

2023-02-08 22:56:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.0 %

2023-02-08 22:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 22:56:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:56:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:56:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 22:56:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

```
2023-02-08 22:57:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-08 22:57:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.5 %

2023-02-08 22:57:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-08 22:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.1 %

2023-02-08 22:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:57:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:57:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 22:57:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-08 22:58:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 22:58:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.8 %

2023-02-08 22:58:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.5 %

2023-02-08 22:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.1 %

2023-02-08 22:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 22:58:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 22:58:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 22:59:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 22:59:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3 $^{\circ}\text{C}$, RH : 69.0 %

2023-02-08 22:59:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.7 %

2023-02-08 22:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 22:59:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 22:59:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 22:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 22:59:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 23:00:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 23:00:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.2 %

```
2023-02-08 23:00:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.6 %
```

2023-02-08 23:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 23:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:00:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.1 %

2023-02-08 23:00:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 23:01:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:01:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.5 %

2023-02-08 23:01:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 23:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.4 %

2023-02-08 23:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:01:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:01:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6 $^{\circ}$ C , RH : 68.1 %

2023-02-08 23:01:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-08 23:02:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 23:02:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.7 %

2023-02-08 23:02:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-08 23:02:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 45.3 %

2023-02-08 23:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:02:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 23:02:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-08 23:03:01 , modbusTCP , I6-1 , TEMP : 4.5 $^{\circ}\text{C}$

2023-02-08 23:03:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.0 %

2023-02-08 23:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 23:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.1 %

```
2023-02-08 23:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 23:03:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:03:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

2023-02-08 23:04:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 23:04:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.2 %

2023-02-08 23:04:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 23:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 23:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:04:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-08 23:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:04:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-08 23:05:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 23:05:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.5 %

2023-02-08 23:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-08 23:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.3 %

2023-02-08 23:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:05:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8 $^{\circ}\text{C}$, RH : 58.7 %

2023-02-08 23:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:05:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.0 %

2023-02-08 23:06:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:06:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.8 %

2023-02-08 23:06:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.2 %

2023-02-08 23:06:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.9 %

2023-02-08 23:06:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:06:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.8 %

```
2023-02-08 23:06:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %
```

2023-02-08 23:06:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-08 23:07:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 23:07:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.0 %

2023-02-08 23:07:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 23:07:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 $^{\circ}$ C , RH : 45.0 %

2023-02-08 23:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:07:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 23:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 68.0 %

2023-02-08 23:07:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 23:08:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:08:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.3 %

2023-02-08 23:08:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.8 %

2023-02-08 23:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.0 %

2023-02-08 23:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:08:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 23:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:08:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 50.9 %

2023-02-08 23:09:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:09:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.6 %

2023-02-08 23:09:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %

2023-02-08 23:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 23:09:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:09:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 23:09:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:09:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

```
2023-02-08 23:10:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-08 23:10:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.9 %

2023-02-08 23:10:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 23:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.4 %

2023-02-08 23:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:10:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.7 %

2023-02-08 23:10:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:10:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 23:11:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 23:11:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.2 %

2023-02-08 23:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 23:11:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 45.4 %

2023-02-08 23:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:11:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.7 %

2023-02-08 23:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:11:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.9 %

2023-02-08 23:12:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:12:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.5 %

2023-02-08 23:12:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-08 23:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.3 %

2023-02-08 23:12:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:12:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:12:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.8 %

2023-02-08 23:13:01 , modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-08 23:13:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.8 %

```
2023-02-08 23:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %
```

2023-02-08 23:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 23:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:13:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:13:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 23:14:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 23:14:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.1 %

2023-02-08 23:14:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 23:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.1 %

2023-02-08 23:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:14:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:14:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.9 %

2023-02-08 23:14:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 23:15:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-08 23:15:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.5 %

2023-02-08 23:15:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 23:15:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4 $^{\circ}\text{C}$, RH : 45.4 %

2023-02-08 23:15:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:15:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:15:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:15:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 23:16:01 , modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}\text{C}$

2023-02-08 23:16:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.8 %

2023-02-08 23:16:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 23:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.0 %

```
2023-02-08 23:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 23:16:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:16:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 23:17:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 23:17:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.1 %

2023-02-08 23:17:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 23:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.1 %

2023-02-08 23:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:17:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:17:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 23:18:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:18:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.4 %

2023-02-08 23:18:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-08 23:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.2 %

2023-02-08 23:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:18:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 23:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:18:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 50.6 %

2023-02-08 23:19:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 23:19:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.7 %

2023-02-08 23:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 23:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.1 %

2023-02-08 23:19:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:19:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

```
2023-02-08 23:19:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 23:19:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 23:20:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:20:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.1 %

2023-02-08 23:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-08 23:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 23:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:20:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 23:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}$ C , RH : 67.9 %

2023-02-08 23:20:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 23:21:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:21:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.4 %

2023-02-08 23:21:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2 $^{\circ}$ C , RH : 61.7 %

2023-02-08 23:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 23:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:21:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:21:01 , modbusTCP , I6-2/S-10 , TEMP : 23.3 $^{\circ}\text{C}$, RH : 50.6 %

2023-02-08 23:22:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:22:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2 $^{\circ}\text{C}$, RH : 75.6 %

2023-02-08 23:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.6 %

2023-02-08 23:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.2 %

2023-02-08 23:22:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:22:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.8 %

2023-02-08 23:22:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

```
2023-02-08 23:23:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-08 23:23:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.9 %

2023-02-08 23:23:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-08 23:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 45.5 %

2023-02-08 23:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:23:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:23:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.8 %

2023-02-08 23:23:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 23:24:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:24:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.1 %

2023-02-08 23:24:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 23:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.2 %

2023-02-08 23:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:24:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:24:02 , modbusTCP , I6-2/S-9 , TEMP : 20.8 $^{\circ}$ C , RH : 67.8 $^{\circ}$

2023-02-08 23:24:02, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 23:25:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 23:25:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.3 %

2023-02-08 23:25:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 23:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.8 %

2023-02-08 23:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:25:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:25:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:25:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 23:26:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 23:26:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.4 %

```
2023-02-08 23:26:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %
```

2023-02-08 23:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 45.3 %

2023-02-08 23:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:26:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:26:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 23:27:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 23:27:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-08 23:27:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.5 %

2023-02-08 23:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 45.0 %

2023-02-08 23:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:27:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:27:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:27:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.7 %

2023-02-08 23:28:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-08 23:28:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

2023-02-08 23:28:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-08 23:28:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 44.9 %

2023-02-08 23:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:28:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 23:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:28:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 23:29:01 , modbusTCP , I6-1 , TEMP : 4.0 $^{\circ}\text{C}$

2023-02-08 23:29:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.9 %

2023-02-08 23:29:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.1 %

2023-02-08 23:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.8 %

```
2023-02-08 23:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 23:29:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:29:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.5 %

2023-02-08 23:30:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 23:30:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 23:30:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-08 23:30:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5 $^{\circ}$ C , RH : 44.9 %

2023-02-08 23:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:30:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:30:01, modbusTCP, I6-2/S-10, TEMP: 23.3 °C, RH: 50.6 %

2023-02-08 23:31:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:31:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.2 %

2023-02-08 23:31:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.6 %

2023-02-08 23:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.0 %

2023-02-08 23:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:31:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:31:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 50.8 %

2023-02-08 23:32:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-08 23:32:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-08 23:32:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 62.4 %

2023-02-08 23:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.9 %

2023-02-08 23:32:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 23:32:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

```
2023-02-08 23:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-08 23:32:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.9 %

2023-02-08 23:33:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:33:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.3 %

2023-02-08 23:33:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 23:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 45.0 %

2023-02-08 23:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:33:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:33:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:33:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-08 23:34:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:34:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.3 %

2023-02-08 23:34:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.0 %

2023-02-08 23:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 44.6 %

2023-02-08 23:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:34:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:34:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.0 %

2023-02-08 23:35:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 23:35:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4 $^{\circ}$ C , RH : 77.4 $^{\circ}$

2023-02-08 23:35:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.8 %

2023-02-08 23:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 44.5 %

2023-02-08 23:35:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:35:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 23:35:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

```
2023-02-08 23:36:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-08 23:36:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-08 23:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 23:36:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 $^{\circ}$ C , RH : 44.6 %

2023-02-08 23:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:36:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-08 23:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:36:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-08 23:37:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 23:37:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-08 23:37:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-08 23:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.2 %

2023-02-08 23:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:37:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:37:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

2023-02-08 23:38:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 23:38:02 , modbusTCP , I6-1/S-12 , TEMP : 25.5 $^{\circ}\text{C}$, RH : 77.4 %

2023-02-08 23:38:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 23:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.0 %

2023-02-08 23:38:02 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:38:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:38:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:38:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-08 23:39:01 , modbusTCP , I6-1 , TEMP : 4.4 $^{\circ}$ C

2023-02-08 23:39:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

```
2023-02-08 23:39:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %
```

2023-02-08 23:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-08 23:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:39:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:39:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 °C , RH : 51.3 %

2023-02-08 23:40:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-08 23:40:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-08 23:40:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.2 %

2023-02-08 23:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-08 23:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:40:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:40:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-08 23:41:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:41:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.3 %

2023-02-08 23:41:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-08 23:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.2 %

2023-02-08 23:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:41:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:41:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-08 23:42:01 , modbusTCP , I6-1 , TEMP : 3.8 $^{\circ}\text{C}$

2023-02-08 23:42:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-08 23:42:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}\text{C}$, RH : 62.3 %

2023-02-08 23:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.7 %

```
2023-02-08 23:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 23:42:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:42:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-08 23:43:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:43:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-08 23:43:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-08 23:43:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-08 23:43:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:43:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:43:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:43:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-08 23:44:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-08 23:44:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-08 23:44:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 62.0 $^{\circ}$

2023-02-08 23:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.2 %

2023-02-08 23:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:44:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:44:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.7 %

2023-02-08 23:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:45:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-08 23:45:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.9 %

2023-02-08 23:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.2 %

2023-02-08 23:45:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:45:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

```
2023-02-08 23:45:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 68.1 %
```

2023-02-08 23:45:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-08 23:46:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 23:46:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-08 23:46:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-08 23:46:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 $^{\circ}$ C , RH : 44.3 %

2023-02-08 23:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:46:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.1 %

2023-02-08 23:46:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-08 23:47:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 23:47:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-08 23:47:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}$ C , RH : 61.8 %

2023-02-08 23:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.5 %

2023-02-08 23:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:47:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:47:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}\text{C}$, RH : 52.3 %

2023-02-08 23:48:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-08 23:48:01 , modbusTCP , I6-1/S-12 , TEMP : 25.8 $^{\circ}\text{C}$, RH : 76.6 %

2023-02-08 23:48:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9 $^{\circ}\text{C}$, RH : 61.7 %

2023-02-08 23:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.5 %

2023-02-08 23:48:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:48:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:48:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 23:48:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

```
2023-02-08 23:49:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-08 23:49:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.5 %

2023-02-08 23:49:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-08 23:49:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}\text{C}$, RH : 44.6 %

2023-02-08 23:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:49:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:49:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 68.1 %

2023-02-08 23:49:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 23:50:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 23:50:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.4 %

2023-02-08 23:50:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-08 23:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.4 %

2023-02-08 23:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:50:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-08 23:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.1 %

2023-02-08 23:50:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 23:51:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-08 23:51:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9 $^{\circ}\text{C}$, RH : 75.6 %

2023-02-08 23:51:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-08 23:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.2 %

2023-02-08 23:51:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:51:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:51:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 23:51:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 23:52:02 , modbusTCP , I6-1 , TEMP : 4.1 $^{\circ}\text{C}$

2023-02-08 23:52:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 74.3 %

```
2023-02-08 23:52:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.2 %
```

2023-02-08 23:52:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-08 23:52:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:52:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:52:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-08 23:52:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}$ C , RH : 52.3 $^{\circ}$

2023-02-08 23:53:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-08 23:53:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 73.4 %

2023-02-08 23:53:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-08 23:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-08 23:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:53:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.6 %

2023-02-08 23:53:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 68.0 %

2023-02-08 23:53:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.2 %

2023-02-08 23:54:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-08 23:54:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.7 %

2023-02-08 23:54:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-08 23:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.4 %

2023-02-08 23:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:54:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:54:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

2023-02-08 23:55:01 , modbusTCP , I6-1 , TEMP : 3.4 $^{\circ}\text{C}$

2023-02-08 23:55:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 72.1 %

2023-02-08 23:55:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.5 %

2023-02-08 23:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.2 %

```
2023-02-08 23:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-08 23:55:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:55:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 $^{\circ}$ C , RH : 51.8 $^{\circ}$

2023-02-08 23:56:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:56:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.6 %

2023-02-08 23:56:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-08 23:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.1 %

2023-02-08 23:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:56:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:56:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:56:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.7 %

2023-02-08 23:57:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-08 23:57:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.2 %

2023-02-08 23:57:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}$ C , RH : 61.3 %

2023-02-08 23:57:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.3 %

2023-02-08 23:57:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-08 23:57:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.5 %

2023-02-08 23:57:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:57:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}\text{C}$, RH : 51.6 %

2023-02-08 23:58:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-08 23:58:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.9 %

2023-02-08 23:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1 $^{\circ}\text{C}$, RH : 61.2 %

2023-02-08 23:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.2 %

2023-02-08 23:58:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-08 23:58:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-08 23:58:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7 $^{\circ}\text{C}$, RH : 67.9 %

2023-02-08 23:58:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.3 $^{\circ}$

2023-02-08 23:59:01, modbusTCP, I6-1, TEMP: 4.0 °C

 $2023-02-08\ 23:59:01$, modbusTCP , I6-1/S-12 , TEMP : 26.1 °C , RH : 70.7 %

2023-02-08 23:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0 $^{\circ}$ C , RH : 61.4 %

2023-02-08 23:59:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 $^{\circ}$ C , RH : 44.3 %

2023-02-08 23:59:01 , modbusTCP , I6-2 , TEMP : 6528.6 $^{\circ}\text{C}$

2023-02-08 23:59:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9 $^{\circ}\text{C}$, RH : 58.6 %

2023-02-08 23:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-08 23:59:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2 $^{\circ}$ C , RH : 51.3 $^{\circ}$