2023-02-09 11:50:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:50:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 67.3 %

2023-02-09 11:50:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 11:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8  $^{\circ}$ C, RH: 48.4  $^{\circ}$ 

2023-02-09 11:50:01, modbusTCP, I6-2, TEMP: 4.0 °C

2023-02-09 11:50:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 11:50:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.5 %

2023-02-09 11:51:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:51:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 67.7 %

2023-02-09 11:51:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 11:51:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.8  $^{\circ}$ C , RH : 48.2 %

2023-02-09 11:51:01, modbusTCP, I6-2, TEMP: 4.3 °C

2023-02-09 11:51:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:51:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

======

2023-02-09 00:00:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 00:00:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}\text{C}$  , RH : 70.5 %

2023-02-09 00:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 00:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.5 %

2023-02-09 00:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:00:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:00:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:00:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

```
2023-02-09 00:01:02, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-09 00:01:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.3 %

2023-02-09 00:01:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 00:01:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 44.5 %

2023-02-09 00:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:01:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:01:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 51.0 %

2023-02-09 00:02:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:02:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.1 %

2023-02-09 00:02:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-09 00:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-09 00:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:02:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:02:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

2023-02-09 00:03:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:03:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.8 %

2023-02-09 00:03:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.5 %

2023-02-09 00:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.3 %

2023-02-09 00:03:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:03:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:03:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.8 %

2023-02-09 00:03:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.9 %

2023-02-09 00:04:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:04:01 , modbusTCP , I6-1/S-12 , TEMP : 26.4  $^{\circ}\text{C}$  , RH : 69.5 %

```
2023-02-09 00:04:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-09 00:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-09 00:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:04:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:04:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.8 %

2023-02-09 00:04:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}$ C , RH : 50.9  $^{\circ}$ 

2023-02-09 00:05:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 00:05:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.2 %

2023-02-09 00:05:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.2 %

2023-02-09 00:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.5 %

2023-02-09 00:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:05:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:05:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:05:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.9 %

2023-02-09 00:06:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:06:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 69.0 %

2023-02-09 00:06:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 00:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.3 %

2023-02-09 00:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:06:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 00:06:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:06:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:07:01 , modbusTCP , I6-1 , TEMP : 3.4  $^{\circ}\text{C}$ 

2023-02-09 00:07:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.7 %

2023-02-09 00:07:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 00:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.1 %

```
2023-02-09 00:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 00:07:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:07:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.6 %

2023-02-09 00:08:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:08:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.4 %

2023-02-09 00:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 00:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-09 00:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:08:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:08:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:09:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 00:09:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.1 %

2023-02-09 00:09:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 00:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-09 00:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:09:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 00:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:09:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.6 %

2023-02-09 00:10:02 , modbusTCP , I6-1 , TEMP : 3.9  $^{\circ}\text{C}$ 

2023-02-09 00:10:02, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.9 %

2023-02-09 00:10:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 00:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-09 00:10:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 00:10:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

```
2023-02-09 00:10:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-09 00:10:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:11:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:11:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.6 %

2023-02-09 00:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 00:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-09 00:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:11:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:11:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:11:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 00:12:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:12:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.4 %

2023-02-09 00:12:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 62.0 %

2023-02-09 00:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-09 00:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:12:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:12:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 50.9 %

2023-02-09 00:13:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:13:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 67.2 %

2023-02-09 00:13:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 00:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.4 %

2023-02-09 00:13:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:13:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:13:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:13:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

```
2023-02-09 00:14:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-09 00:14:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 67.0 %

2023-02-09 00:14:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 00:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.3 %

2023-02-09 00:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:14:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:14:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

2023-02-09 00:15:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 00:15:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.7 %

2023-02-09 00:15:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 00:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.6 %

2023-02-09 00:15:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:15:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:15:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:15:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-09 00:16:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:16:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 00:16:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 00:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.5 %

2023-02-09 00:16:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:16:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:16:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:16:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-09 00:17:01 , modbusTCP , I6-1 , TEMP : 3.6 °C

2023-02-09 00:17:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.4 %

```
2023-02-09 00:17:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %
```

2023-02-09 00:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.2 %

2023-02-09 00:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:17:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 00:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 68.0 %

2023-02-09 00:17:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 51.5  $^{\circ}$ 

2023-02-09 00:18:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:18:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 00:18:01 , modbusTCP , I6-1/S-13 , TEMP : 29.8  $^{\circ}$ C , RH : 61.5  $^{\circ}$ 

2023-02-09 00:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.3 %

2023-02-09 00:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:18:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.9 %

2023-02-09 00:18:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-09 00:19:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:19:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.1 %

2023-02-09 00:19:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.8 %

2023-02-09 00:19:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 44.6 %

2023-02-09 00:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:19:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 00:19:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:19:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 00:20:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 00:20:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.9 %

2023-02-09 00:20:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 00:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

```
2023-02-09 00:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 00:20:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:20:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 51.3  $^{\circ}$ 

2023-02-09 00:21:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 00:21:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.8 %

2023-02-09 00:21:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 00:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 44.5 %

2023-02-09 00:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:21:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:21:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.4 %

2023-02-09 00:22:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 00:22:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.7 %

2023-02-09 00:22:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.4 %

2023-02-09 00:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-09 00:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:22:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:22:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 00:23:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 00:23:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.6 %

2023-02-09 00:23:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.4 %

2023-02-09 00:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-09 00:23:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:23:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

```
2023-02-09 00:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %
```

2023-02-09 00:23:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-09 00:24:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:24:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.4 %

2023-02-09 00:24:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 00:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.3 %

2023-02-09 00:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:24:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:24:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.9 %

2023-02-09 00:24:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-09 00:25:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:25:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.6 %

2023-02-09 00:25:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.7 %

2023-02-09 00:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.2 %

2023-02-09 00:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:25:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:25:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 51.8 %

2023-02-09 00:26:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:26:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}$ C , RH : 66.2 %

2023-02-09 00:26:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 00:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 44.4 %

2023-02-09 00:26:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:26:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:26:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.1 %

```
2023-02-09 00:27:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 00:27:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.6 %

2023-02-09 00:27:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 00:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.1 %

2023-02-09 00:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:27:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:27:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.1 %

2023-02-09 00:28:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 00:28:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.9 %

2023-02-09 00:28:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 00:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.3 %

2023-02-09 00:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:28:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.6 %

2023-02-09 00:28:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:28:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-09 00:29:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:29:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.2 %

2023-02-09 00:29:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 00:29:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.1 %

2023-02-09 00:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:29:02, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:29:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:29:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-09 00:30:01 , modbusTCP , I6-1 , TEMP : 3.4  $^{\circ}\text{C}$ 

2023-02-09 00:30:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}\text{C}$  , RH : 67.6 %

```
2023-02-09 00:30:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %
```

2023-02-09 00:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.3 %

2023-02-09 00:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:30:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:30:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 52.2 %

2023-02-09 00:31:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:31:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.9 %

2023-02-09 00:31:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.4 %

2023-02-09 00:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.4 %

2023-02-09 00:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:31:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.5 %

2023-02-09 00:31:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.8  $^{\circ}$ 

2023-02-09 00:31:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-09 00:32:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:32:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.1 %

2023-02-09 00:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 00:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.4 %

2023-02-09 00:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:32:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 00:32:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:32:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-09 00:33:01 , modbusTCP , I6-1 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 00:33:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.4 %

2023-02-09 00:33:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 00:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.4 %

```
2023-02-09 00:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 00:33:02 , modbusTCP , I6-2/S-8 , TEMP : 20.9  $^{\circ}$ C , RH : 58.4  $^{\circ}$ 

2023-02-09 00:33:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:33:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.4 %

2023-02-09 00:34:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:34:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.6 %

2023-02-09 00:34:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.4 %

2023-02-09 00:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 44.4 %

2023-02-09 00:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:34:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.4 %

2023-02-09 00:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:34:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-09 00:35:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 00:35:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.9 %

2023-02-09 00:35:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.5 %

2023-02-09 00:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 44.2 %

2023-02-09 00:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:35:01 , modbusTCP , I6-2/S-8 , TEMP : 20.9  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 00:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:35:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 52.1 %

2023-02-09 00:36:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:36:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.2 %

2023-02-09 00:36:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 00:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.8 %

2023-02-09 00:36:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:36:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

```
2023-02-09 00:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-09 00:36:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-09 00:37:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:37:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}\text{C}$  , RH : 69.3 %

2023-02-09 00:37:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 62.1 %

2023-02-09 00:37:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 43.9 %

2023-02-09 00:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:37:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:37:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.8 %

2023-02-09 00:37:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.7 %

2023-02-09 00:38:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:38:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.6 %

2023-02-09 00:38:02 , modbusTCP , I6-1/S-13 , TEMP : 29.8  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 00:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.7 %

2023-02-09 00:38:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:38:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:38:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:38:02 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 51.6 %

2023-02-09 00:39:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 00:39:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.9 %

2023-02-09 00:39:01, modbusTCP, I6-1/S-13, TEMP: 29.8 °C, RH: 61.9 %

2023-02-09 00:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.7 %

2023-02-09 00:39:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:39:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:39:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.8 %

2023-02-09 00:39:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.4 %

```
2023-02-09 00:40:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 00:40:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.2 %

2023-02-09 00:40:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 00:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.7 %

2023-02-09 00:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:40:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:40:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.3 %

2023-02-09 00:41:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 00:41:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.4 %

2023-02-09 00:41:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 00:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.8 %

2023-02-09 00:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:41:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:41:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:41:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-09 00:42:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:42:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.6 %

2023-02-09 00:42:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 00:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.6 %

2023-02-09 00:42:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:42:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.4 %

2023-02-09 00:42:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.8 %

2023-02-09 00:42:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-09 00:43:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}$ C

2023-02-09 00:43:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.9 %

```
2023-02-09 00:43:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %
```

2023-02-09 00:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.2 %

2023-02-09 00:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:43:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.9 %

2023-02-09 00:43:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}$ C , RH : 51.0  $^{\circ}$ 

2023-02-09 00:44:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 00:44:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.2 %

2023-02-09 00:44:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.6 %

2023-02-09 00:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.0 %

2023-02-09 00:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:44:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.9 %

2023-02-09 00:44:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-09 00:45:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 00:45:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.4 %

2023-02-09 00:45:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 00:45:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 43.9 %

2023-02-09 00:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:45:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 00:45:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.9 %

2023-02-09 00:45:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-09 00:46:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 00:46:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.7 %

2023-02-09 00:46:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 00:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 43.9 %

```
2023-02-09 00:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 00:46:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:46:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 00:47:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:47:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.0 %

2023-02-09 00:47:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 00:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.0 %

2023-02-09 00:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:47:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 00:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:47:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 00:48:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 00:48:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.3 %

2023-02-09 00:48:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.2 %

2023-02-09 00:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.0 %

2023-02-09 00:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:48:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.4 %

2023-02-09 00:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-09 00:48:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 00:49:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:49:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.5 %

2023-02-09 00:49:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 00:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 44.2 %

2023-02-09 00:49:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 00:49:01, modbusTCP, I6-2/S-8, TEMP: 20.9 °C, RH: 58.4 %

```
2023-02-09 00:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %
```

2023-02-09 00:49:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:50:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:50:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 72.9 %

2023-02-09 00:50:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 00:50:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6 °C , RH : 43.8 %

2023-02-09 00:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:50:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 00:50:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.8 %

2023-02-09 00:50:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:51:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 00:51:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.2 %

2023-02-09 00:51:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 00:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 43.6 %

2023-02-09 00:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:51:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.8 %

2023-02-09 00:51:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 50.6 %

2023-02-09 00:52:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:52:02 , modbusTCP , I6-1/S-12 , TEMP : 26.6  $^{\circ}\text{C}$  , RH : 73.5 %

2023-02-09 00:52:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 00:52:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 44.0 %

2023-02-09 00:52:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:52:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:52:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.7 %

2023-02-09 00:52:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

```
2023-02-09 00:53:01, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-09 00:53:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 73.9 %

2023-02-09 00:53:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-09 00:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.8 %

2023-02-09 00:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:53:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.7 %

2023-02-09 00:53:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

2023-02-09 00:54:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 00:54:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.2 %

2023-02-09 00:54:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 00:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.6 %

2023-02-09 00:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:54:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:54:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.7 %

2023-02-09 00:54:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 00:55:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 00:55:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.5 %

2023-02-09 00:55:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 00:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.8 %

2023-02-09 00:55:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 00:55:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:55:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.6 %

2023-02-09 00:55:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.0 %

2023-02-09 00:56:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 00:56:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 74.8 %

```
2023-02-09 00:56:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %
```

2023-02-09 00:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.7 %

2023-02-09 00:56:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:56:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 00:56:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.6 %

2023-02-09 00:56:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.2 %

2023-02-09 00:57:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 00:57:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.1 %

2023-02-09 00:57:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 00:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.1 %

2023-02-09 00:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:57:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 67.6 %

2023-02-09 00:57:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.6 %

2023-02-09 00:58:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 00:58:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.3 %

2023-02-09 00:58:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 00:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.0 %

2023-02-09 00:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 00:58:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 00:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 00:58:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.5 %

2023-02-09 00:59:01 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 00:59:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.5 %

2023-02-09 00:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 00:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 43.0 %

```
2023-02-09 00:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 00:59:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 00:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.6 %

2023-02-09 00:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-09 01:00:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:00:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.8 %

2023-02-09 01:00:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 01:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0  $^{\circ}\text{C}$  , RH : 43.3 %

2023-02-09 01:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:00:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.6 %

2023-02-09 01:00:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-09 01:01:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:01:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.0 %

2023-02-09 01:01:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.8 %

2023-02-09 01:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 43.1 %

2023-02-09 01:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:01:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 01:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.6 %

2023-02-09 01:01:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 01:02:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 01:02:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.2 %

2023-02-09 01:02:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 01:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.2 %

2023-02-09 01:02:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:02:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

```
2023-02-09 01:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.6 %
```

2023-02-09 01:02:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-09 01:03:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:03:01 , modbusTCP , I6-1/S-12 , TEMP : 25.8  $^{\circ}$ C , RH : 76.3  $^{\circ}$ 

2023-02-09 01:03:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 01:03:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.9 %

2023-02-09 01:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:03:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:03:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.5  $^{\circ}$ 

2023-02-09 01:03:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-09 01:04:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 01:04:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.5 %

2023-02-09 01:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.4 %

2023-02-09 01:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.2 %

2023-02-09 01:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:04:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:04:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 01:05:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 01:05:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 01:05:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 01:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.9 %

2023-02-09 01:05:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:05:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:05:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.5 %

2023-02-09 01:05:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

```
2023-02-09 01:06:02, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 01:06:02, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-09 01:06:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 01:06:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.9 %

2023-02-09 01:06:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:06:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:06:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:06:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.4 %

2023-02-09 01:07:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 01:07:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 01:07:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-09 01:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.0 %

2023-02-09 01:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:07:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:07:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 01:08:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 01:08:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6  $^{\circ}\text{C}$  , RH : 76.9 %

2023-02-09 01:08:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 01:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.7 %

2023-02-09 01:08:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:08:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:08:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.5 %

2023-02-09 01:09:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:09:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}\text{C}$  , RH : 77.0 %

```
2023-02-09 01:09:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-09 01:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.0 %

2023-02-09 01:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:09:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:09:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.5 %

2023-02-09 01:10:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 01:10:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 01:10:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.5 %

2023-02-09 01:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.8 %

2023-02-09 01:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:10:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:10:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.5 %

2023-02-09 01:10:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.9 %

2023-02-09 01:11:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:11:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 01:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 01:11:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.7 %

2023-02-09 01:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:11:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 01:11:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.5 %

2023-02-09 01:11:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.1 %

2023-02-09 01:12:01 , modbusTCP , I6-1 , TEMP : 4.3  $^{\circ}\text{C}$ 

2023-02-09 01:12:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 01:12:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 01:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.9 %

```
2023-02-09 01:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 01:12:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:12:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.3 %

2023-02-09 01:13:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:13:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 01:13:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 01:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.7 %

2023-02-09 01:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:13:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:13:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.3 %

2023-02-09 01:14:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:14:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 01:14:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 01:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.5 %

2023-02-09 01:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:14:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 01:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:14:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 52.2 %

2023-02-09 01:15:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:15:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 01:15:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 01:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.6 %

2023-02-09 01:15:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:15:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

```
2023-02-09 01:15:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %
```

2023-02-09 01:15:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.3 %

2023-02-09 01:16:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 01:16:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}\text{C}$  , RH : 77.0 %

2023-02-09 01:16:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 01:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.6 %

2023-02-09 01:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:16:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:16:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.4 %

2023-02-09 01:17:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:17:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 01:17:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.3 %

2023-02-09 01:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.4 %

2023-02-09 01:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:17:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:17:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 52.2 %

2023-02-09 01:18:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:18:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}$ C , RH : 77.0 %

2023-02-09 01:18:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-09 01:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.5 %

2023-02-09 01:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:18:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.4 %

2023-02-09 01:18:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 52.0 %

```
2023-02-09 01:19:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 01:19:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 01:19:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 01:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.4 %

2023-02-09 01:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:19:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.3 %

2023-02-09 01:19:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.8 %

2023-02-09 01:20:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:20:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 01:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %

2023-02-09 01:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.5 %

2023-02-09 01:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:20:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:20:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.6 %

2023-02-09 01:21:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:21:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6  $^{\circ}\text{C}$  , RH : 76.7 %

2023-02-09 01:21:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 01:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.6 %

2023-02-09 01:21:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:21:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:21:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.4 %

2023-02-09 01:21:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 01:22:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 01:22:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.6 %

```
2023-02-09 01:22:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %
```

2023-02-09 01:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.5 %

2023-02-09 01:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:22:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:22:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 51.4  $^{\circ}$ 

2023-02-09 01:23:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:23:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7  $^{\circ}\text{C}$  , RH : 76.4 %

2023-02-09 01:23:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 01:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.7 %

2023-02-09 01:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:23:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.4 %

2023-02-09 01:23:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.3 %

2023-02-09 01:24:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:24:02, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.3 %

2023-02-09 01:24:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 01:24:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.7 %

2023-02-09 01:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:24:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 01:24:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:24:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

2023-02-09 01:25:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 01:25:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.2 %

2023-02-09 01:25:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 01:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.8 %

```
2023-02-09 01:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 01:25:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:25:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

2023-02-09 01:26:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:26:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.0 %

2023-02-09 01:26:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-09 01:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.7 %

2023-02-09 01:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:26:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:26:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 51.1 %

2023-02-09 01:27:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:27:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 75.9 %

2023-02-09 01:27:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 01:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.8 %

2023-02-09 01:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:27:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:27:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 50.9 %

2023-02-09 01:28:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 01:28:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 75.8 %

2023-02-09 01:28:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 01:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.8 %

2023-02-09 01:28:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:28:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

```
2023-02-09 01:28:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.3 %
```

2023-02-09 01:28:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 01:29:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:29:02, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.7 %

2023-02-09 01:29:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 01:29:02 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9  $^{\circ}$ C , RH : 42.6 %

2023-02-09 01:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:29:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:29:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.3 %

2023-02-09 01:29:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 01:30:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 01:30:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.6 %

2023-02-09 01:30:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 62.1 %

2023-02-09 01:30:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.7 %

2023-02-09 01:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:30:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.4 %

2023-02-09 01:30:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 50.7 %

2023-02-09 01:31:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:31:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}$ C , RH : 75.5  $^{\circ}$ 

2023-02-09 01:31:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 01:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.8 %

2023-02-09 01:31:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:31:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:31:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.3 %

2023-02-09 01:31:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.7 %

```
2023-02-09 01:32:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 01:32:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 74.1 %

2023-02-09 01:32:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 01:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 43.0 %

2023-02-09 01:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:32:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.3 %

2023-02-09 01:32:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.6 %

2023-02-09 01:33:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:33:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 73.2 %

2023-02-09 01:33:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 01:33:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 42.6 %

2023-02-09 01:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:33:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:33:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.3 %

2023-02-09 01:33:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.6 %

2023-02-09 01:34:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:34:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}\text{C}$  , RH : 72.3 %

2023-02-09 01:34:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 01:34:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.6 %

2023-02-09 01:34:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:34:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:34:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.3 %

2023-02-09 01:34:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.4 %

2023-02-09 01:35:01 , modbusTCP , I6-1 , TEMP : 4.3 °C

2023-02-09 01:35:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 71.6 %

```
2023-02-09 01:35:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %
```

2023-02-09 01:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.8 %

2023-02-09 01:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:35:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}$ C , RH : 58.5  $^{\circ}$ 

2023-02-09 01:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.3 %

2023-02-09 01:35:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}$ C , RH : 50.5  $^{\circ}$ 

2023-02-09 01:36:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:36:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 71.1 %

2023-02-09 01:36:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 01:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.8 %

2023-02-09 01:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:36:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.2  $^{\circ}$ 

2023-02-09 01:36:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.5 %

2023-02-09 01:37:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 01:37:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 70.7 %

2023-02-09 01:37:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 01:37:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}\text{C}$  , RH : 42.7 %

2023-02-09 01:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:37:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 01:37:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.2 %

2023-02-09 01:37:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.4 %

2023-02-09 01:38:02 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 01:38:02, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 70.4 %

2023-02-09 01:38:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 01:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.6 %

```
2023-02-09 01:38:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 01:38:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:38:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.1 %

2023-02-09 01:38:02, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.5 %

2023-02-09 01:39:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 01:39:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 70.3 %

2023-02-09 01:39:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 01:39:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.4 %

2023-02-09 01:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:39:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.1 %

2023-02-09 01:39:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.4 %

2023-02-09 01:40:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:40:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 70.1 %

2023-02-09 01:40:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 01:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.7 %

2023-02-09 01:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:40:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.1 %

2023-02-09 01:40:01 , modbusTCP , I6-2/S-10 , TEMP : 23.2  $^{\circ}\text{C}$  , RH : 50.5 %

2023-02-09 01:41:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:41:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.9 %

2023-02-09 01:41:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.2 %

2023-02-09 01:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.7 %

2023-02-09 01:41:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:41:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

```
2023-02-09 01:41:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.1 %
```

2023-02-09 01:41:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.8 %

2023-02-09 01:42:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:42:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5  $^{\circ}$ C , RH : 69.7  $^{\circ}$ 

2023-02-09 01:42:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 01:42:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 42.6 %

2023-02-09 01:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:42:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-09 01:42:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.1 %

2023-02-09 01:42:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.8 %

2023-02-09 01:43:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:43:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 69.4 %

2023-02-09 01:43:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.0 %

2023-02-09 01:43:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.5 %

2023-02-09 01:43:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:43:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:43:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:43:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 51.0 %

2023-02-09 01:44:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:44:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5  $^{\circ}$ C , RH : 69.2 %

2023-02-09 01:44:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 01:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.7 %

2023-02-09 01:44:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:44:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 01:44:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

```
2023-02-09 01:45:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 01:45:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.9 %

2023-02-09 01:45:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 01:45:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.4 %

2023-02-09 01:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:45:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:45:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 67.0 %

2023-02-09 01:45:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

2023-02-09 01:46:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:46:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.6 %

2023-02-09 01:46:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 01:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.7 %

2023-02-09 01:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:46:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:46:01, modbusTCP, I6-2/S-9, TEMP: 20.8 °C, RH: 66.9 %

2023-02-09 01:46:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

2023-02-09 01:47:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 01:47:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.3 %

2023-02-09 01:47:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-09 01:47:02 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9 °C , RH : 42.7 %

2023-02-09 01:47:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:47:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:47:02 , modbusTCP , I6-2/S-9 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 01:47:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

2023-02-09 01:48:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:48:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 68.1 %

```
2023-02-09 01:48:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %
```

2023-02-09 01:48:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.6 %

2023-02-09 01:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:48:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 01:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:48:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

2023-02-09 01:49:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:49:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.8 %

2023-02-09 01:49:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.9 %

2023-02-09 01:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.5 %

2023-02-09 01:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:49:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 67.0  $^{\circ}$ 

2023-02-09 01:49:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.2 %

2023-02-09 01:50:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:50:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.6 %

2023-02-09 01:50:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 01:50:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.0  $^{\circ}\text{C}$  , RH : 42.6 %

2023-02-09 01:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:50:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7 °C , RH : 58.5 %

2023-02-09 01:50:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 01:50:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.2 %

2023-02-09 01:51:01 , modbusTCP , I6-1 , TEMP : 3.4  $^{\circ}\text{C}$ 

2023-02-09 01:51:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.3 %

2023-02-09 01:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 01:51:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.6 %

```
2023-02-09 01:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 01:51:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:51:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 01:52:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:52:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.1 %

2023-02-09 01:52:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 01:52:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.6 %

2023-02-09 01:52:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:52:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:52:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:52:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 01:53:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 01:53:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.9 %

2023-02-09 01:53:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 01:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.5 %

2023-02-09 01:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:53:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:53:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 01:54:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 01:54:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.7 %

2023-02-09 01:54:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 01:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.2 %

2023-02-09 01:54:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:54:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 01:54:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %
```

2023-02-09 01:54:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.6 %

2023-02-09 01:55:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 01:55:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.6 %

2023-02-09 01:55:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 01:55:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.3 %

2023-02-09 01:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:55:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:55:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 01:55:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.6 %

2023-02-09 01:56:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:56:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.4 %

2023-02-09 01:56:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.3 %

2023-02-09 01:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 01:56:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:56:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:56:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:56:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.5 %

2023-02-09 01:57:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 01:57:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}$ C , RH : 66.3  $^{\circ}$ 

2023-02-09 01:57:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 01:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.2 %

2023-02-09 01:57:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 01:57:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 01:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 01:57:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.8 %

```
2023-02-09 01:58:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 01:58:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.1 %

2023-02-09 01:58:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 01:58:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 42.3 %

2023-02-09 01:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:58:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:58:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.9 %

2023-02-09 01:59:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 01:59:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

2023-02-09 01:59:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 01:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.2 %

2023-02-09 01:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 01:59:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 01:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 01:59:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.2 %

2023-02-09 02:00:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:00:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 02:00:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 02:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.2 %

2023-02-09 02:00:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:00:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.5 %

2023-02-09 02:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 02:00:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.3 %

2023-02-09 02:01:02 , modbusTCP , I6-1 , TEMP : 3.6  $^{\circ}\text{C}$ 

2023-02-09 02:01:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.7 %

```
2023-02-09 02:01:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %
```

2023-02-09 02:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.7 %

2023-02-09 02:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:01:02 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:01:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.1 %

2023-02-09 02:02:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 02:02:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.6 %

2023-02-09 02:02:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 02:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.3 %

2023-02-09 02:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:02:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.9 %

2023-02-09 02:02:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.1 %

2023-02-09 02:03:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:03:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.5 %

2023-02-09 02:03:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 02:03:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9  $^{\circ}$ C , RH : 42.5 %

2023-02-09 02:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:03:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:03:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.3 %

2023-02-09 02:04:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 02:04:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.9 %

2023-02-09 02:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 02:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.4 %

```
2023-02-09 02:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 02:04:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 02:04:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.2 %

2023-02-09 02:05:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 02:05:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.4 %

2023-02-09 02:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 02:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.5 %

2023-02-09 02:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:05:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 02:05:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.9 %

2023-02-09 02:06:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:06:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.8 %

2023-02-09 02:06:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 02:06:02, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.2 %

2023-02-09 02:06:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:06:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:06:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:06:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.7 %

2023-02-09 02:07:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:07:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 67.1 %

2023-02-09 02:07:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 02:07:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.4 %

2023-02-09 02:07:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:07:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 02:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %
```

2023-02-09 02:07:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.5 %

2023-02-09 02:08:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:08:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0  $^{\circ}$ C , RH : 67.5  $^{\circ}$ 

2023-02-09 02:08:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 02:08:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.8  $^{\circ}$ C , RH : 42.5 %

2023-02-09 02:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:08:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 02:08:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.5 %

2023-02-09 02:09:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 02:09:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 67.7 %

2023-02-09 02:09:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.7 %

2023-02-09 02:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.6 %

2023-02-09 02:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:09:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 67.0 %

2023-02-09 02:09:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 02:10:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:10:02 , modbusTCP , I6-1/S-12 , TEMP : 27.0  $^{\circ}\text{C}$  , RH : 68.0 %

2023-02-09 02:10:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 02:10:02, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.5 %

2023-02-09 02:10:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:10:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:10:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.9 %

2023-02-09 02:10:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.1 %

```
2023-02-09 02:11:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 02:11:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.3 %

2023-02-09 02:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 02:11:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.8  $^{\circ}$ C , RH : 42.5 %

2023-02-09 02:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:11:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:11:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

2023-02-09 02:12:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:12:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 68.6 %

2023-02-09 02:12:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 02:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.4 %

2023-02-09 02:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:12:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:12:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

2023-02-09 02:13:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:13:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}\text{C}$  , RH : 68.9 %

2023-02-09 02:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-09 02:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.5 %

2023-02-09 02:13:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:13:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:13:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.9 %

2023-02-09 02:13:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.8 %

2023-02-09 02:14:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 02:14:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.1 %

```
2023-02-09 02:14:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %
```

2023-02-09 02:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.3 %

2023-02-09 02:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:14:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.9 %

2023-02-09 02:14:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 02:15:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:15:02 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}\text{C}$  , RH : 69.3 %

2023-02-09 02:15:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.6  $^{\circ}$ 

2023-02-09 02:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.2 %

2023-02-09 02:15:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:15:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:15:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.9 %

2023-02-09 02:15:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.8 %

2023-02-09 02:16:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:16:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.5 %

2023-02-09 02:16:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 02:16:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 °C , RH : 42.2 %

2023-02-09 02:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:16:01 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 02:16:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.9 %

2023-02-09 02:16:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 02:17:01 , modbusTCP , I6-1 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 02:17:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 69.7 %

2023-02-09 02:17:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 02:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

```
2023-02-09 02:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 02:17:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:17:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

2023-02-09 02:18:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:18:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.0 %

2023-02-09 02:18:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 02:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.1 %

2023-02-09 02:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:18:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:18:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

2023-02-09 02:19:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:19:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.2 %

2023-02-09 02:19:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 02:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.0 %

2023-02-09 02:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:19:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:19:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}$ C , RH : 50.5 %

2023-02-09 02:20:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:20:02, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.4 %

2023-02-09 02:20:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 02:20:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.3 %

2023-02-09 02:20:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:20:02, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.3 %

```
2023-02-09 02:20:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %
```

2023-02-09 02:20:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.4 %

2023-02-09 02:21:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 02:21:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}$ C , RH : 70.7  $^{\circ}$ 

2023-02-09 02:21:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 02:21:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 42.3 %

2023-02-09 02:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:21:01, modbusTCP, I6-2/S-8, TEMP: 20.8 °C, RH: 58.4 %

2023-02-09 02:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:21:01, modbusTCP, I6-2/S-10, TEMP: 23.2 °C, RH: 50.3 %

2023-02-09 02:22:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 02:22:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 70.9 %

2023-02-09 02:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.2 %

2023-02-09 02:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.1 %

2023-02-09 02:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:22:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:22:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 50.3 %

2023-02-09 02:23:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:23:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0  $^{\circ}$ C , RH : 71.2 %

2023-02-09 02:23:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 02:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 02:23:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:23:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.8 %

2023-02-09 02:23:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

```
2023-02-09 02:24:02, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 02:24:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.4 %

2023-02-09 02:24:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 02:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.2 %

2023-02-09 02:24:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:24:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:24:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:24:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.6 %

2023-02-09 02:25:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 02:25:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.7 %

2023-02-09 02:25:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 02:25:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.2 %

2023-02-09 02:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:25:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %

2023-02-09 02:25:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 02:26:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 02:26:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 71.9 %

2023-02-09 02:26:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 02:26:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 42.6 %

2023-02-09 02:26:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:26:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.7 %

2023-02-09 02:26:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

2023-02-09 02:27:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 02:27:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.2 %

```
2023-02-09 02:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %
```

2023-02-09 02:27:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 42.6 %

2023-02-09 02:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:27:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %

2023-02-09 02:27:01 , modbusTCP , I6-2/S-10 , TEMP : 23.1 °C , RH : 51.0 %

2023-02-09 02:28:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 02:28:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.5 %

2023-02-09 02:28:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.2 %

2023-02-09 02:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.5 %

2023-02-09 02:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:28:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.7 %

2023-02-09 02:28:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

2023-02-09 02:29:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 02:29:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 72.7 %

2023-02-09 02:29:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.4 %

2023-02-09 02:29:02 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9  $^{\circ}$ C , RH : 42.4 %

2023-02-09 02:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:29:02 , modbusTCP , I6-2/S-8 , TEMP : 20.8  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 02:29:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.7 %

2023-02-09 02:29:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.0 %

2023-02-09 02:30:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:30:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.0 %

2023-02-09 02:30:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.5 %

2023-02-09 02:30:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 42.5 %

```
2023-02-09 02:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 02:30:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:30:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:30:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.0 %

2023-02-09 02:31:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:31:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.3 %

2023-02-09 02:31:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 02:31:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 42.6 %

2023-02-09 02:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:31:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 02:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:31:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.0 %

2023-02-09 02:32:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 02:32:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.5 %

2023-02-09 02:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 02:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.6 %

2023-02-09 02:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:32:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:32:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.1 %

2023-02-09 02:33:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:33:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.8 %

2023-02-09 02:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 02:33:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.6 %

2023-02-09 02:33:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:33:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 02:33:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %
```

2023-02-09 02:33:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 02:34:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:34:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.1 %

2023-02-09 02:34:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 02:34:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.9  $^{\circ}$ C , RH : 42.3 %

2023-02-09 02:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:34:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:34:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.8 %

2023-02-09 02:34:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 02:35:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:35:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.4 %

2023-02-09 02:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.0 %

2023-02-09 02:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 02:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:35:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.8 %

2023-02-09 02:35:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 02:36:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:36:01 , modbusTCP , I6-1/S-12 , TEMP : 26.4  $^{\circ}$ C , RH : 74.7 %

2023-02-09 02:36:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 02:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 02:36:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:36:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.8 %

2023-02-09 02:36:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

```
2023-02-09 02:37:01, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-09 02:37:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.0 %

2023-02-09 02:37:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 02:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 02:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:37:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %

2023-02-09 02:37:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.3 %

2023-02-09 02:38:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:38:02, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.2 %

2023-02-09 02:38:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 02:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 42.2 %

2023-02-09 02:38:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:38:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:38:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.7 %

2023-02-09 02:38:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 02:39:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:39:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}\text{C}$  , RH : 75.4 %

2023-02-09 02:39:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 02:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.3 %

2023-02-09 02:39:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:39:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:39:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.7 %

2023-02-09 02:39:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 02:40:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 02:40:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.6 %

```
2023-02-09 02:40:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %
```

2023-02-09 02:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.8 %

2023-02-09 02:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:40:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %

2023-02-09 02:40:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 02:41:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:41:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.8 %

2023-02-09 02:41:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 02:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.8 %

2023-02-09 02:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:41:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.6  $^{\circ}$ 

2023-02-09 02:41:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.9 %

2023-02-09 02:42:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 02:42:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 75.9 %

2023-02-09 02:42:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 02:42:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.7 %

2023-02-09 02:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:42:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 02:42:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 02:42:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.7 %

2023-02-09 02:43:01 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 02:43:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.0 %

2023-02-09 02:43:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 02:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.4 %

```
2023-02-09 02:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 02:43:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:43:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 52.2 %

2023-02-09 02:44:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:44:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.2 %

2023-02-09 02:44:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 02:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.6 %

2023-02-09 02:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:44:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:44:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.3 %

2023-02-09 02:45:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 02:45:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.3 %

2023-02-09 02:45:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.4 %

2023-02-09 02:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 42.6 %

2023-02-09 02:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:45:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:45:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 52.1 %

2023-02-09 02:46:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:46:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.4 %

2023-02-09 02:46:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 02:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 42.4 %

2023-02-09 02:46:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:46:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 02:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %
```

2023-02-09 02:46:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.2 %

2023-02-09 02:47:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 02:47:02 , modbusTCP , I6-1/S-12 , TEMP : 25.8  $^{\circ}$ C , RH : 76.5  $^{\circ}$ 

2023-02-09 02:47:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 02:47:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 42.3 %

2023-02-09 02:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:47:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:47:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 52.2 %

2023-02-09 02:48:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 02:48:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.5 %

2023-02-09 02:48:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.8 %

2023-02-09 02:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.5 %

2023-02-09 02:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:48:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.7 %

2023-02-09 02:48:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 52.1 %

2023-02-09 02:49:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:49:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 02:49:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 02:49:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 43.0 %

2023-02-09 02:49:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:49:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 02:49:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.9 %

```
2023-02-09 02:50:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 02:50:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 02:50:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 02:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.4 %

2023-02-09 02:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:50:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:50:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.7 %

2023-02-09 02:51:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 02:51:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 02:51:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 02:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.3 %

2023-02-09 02:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:51:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:51:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.4 %

2023-02-09 02:52:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:52:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 02:52:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-09 02:52:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.5 %

2023-02-09 02:52:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 02:52:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:52:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 02:52:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.3 %

2023-02-09 02:53:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:53:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

```
2023-02-09 02:53:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %
```

2023-02-09 02:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.5 %

2023-02-09 02:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:53:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:53:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 51.3  $^{\circ}$ 

2023-02-09 02:54:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 02:54:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 02:54:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.1 %

2023-02-09 02:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.1 %

2023-02-09 02:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:54:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.7  $^{\circ}$ 

2023-02-09 02:54:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.2 %

2023-02-09 02:55:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 02:55:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 02:55:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 02:55:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 °C , RH : 42.2 %

2023-02-09 02:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:55:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:55:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 02:55:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 51.0 %

2023-02-09 02:56:01 , modbusTCP , I6-1 , TEMP : 4.3  $^{\circ}\text{C}$ 

2023-02-09 02:56:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 02:56:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 02:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.1 %

```
2023-02-09 02:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 02:56:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:56:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:56:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.8 %

2023-02-09 02:57:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 02:57:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 02:57:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 02:57:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 02:57:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:57:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 02:57:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:57:02, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 02:58:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 02:58:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 02:58:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 02:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.4 %

2023-02-09 02:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 02:58:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 02:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 02:58:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 02:59:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 02:59:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 02:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 02:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.2 %

2023-02-09 02:59:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 02:59:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

```
2023-02-09 02:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %
```

2023-02-09 02:59:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.6 %

2023-02-09 03:00:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 03:00:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 03:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 03:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 03:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:00:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:00:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.6 %

2023-02-09 03:00:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.6 %

2023-02-09 03:01:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 03:01:02, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-09 03:01:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 03:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 03:01:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:01:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:01:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 03:01:02 , modbusTCP , I6-2/S-10 , TEMP : 23.1  $^{\circ}\text{C}$  , RH : 50.5 %

2023-02-09 03:02:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 03:02:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7  $^{\circ}\text{C}$  , RH : 76.7 %

2023-02-09 03:02:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 03:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.7 %

2023-02-09 03:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:02:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 03:02:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

```
2023-02-09 03:03:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 03:03:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 03:03:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 03:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.7 %

2023-02-09 03:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:03:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 03:03:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.6 %

2023-02-09 03:04:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 03:04:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.4 %

2023-02-09 03:04:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 03:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:04:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.6 %

2023-02-09 03:04:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.7 %

2023-02-09 03:05:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 03:05:01 , modbusTCP , I6-1/S-12 , TEMP : 25.8  $^{\circ}\text{C}$  , RH : 76.3 %

2023-02-09 03:05:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 03:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 03:05:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:05:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:05:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 03:05:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.9 %

2023-02-09 03:06:02 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}$ C

2023-02-09 03:06:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.2 %

```
2023-02-09 03:06:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %
```

2023-02-09 03:06:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 03:06:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:06:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:06:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:06:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 51.0  $^{\circ}$ 

2023-02-09 03:07:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 03:07:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.1 %

2023-02-09 03:07:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.8 %

2023-02-09 03:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:07:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.6  $^{\circ}$ 

2023-02-09 03:07:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 03:08:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 03:08:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.0 %

2023-02-09 03:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 03:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:08:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 03:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:08:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 03:09:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 03:09:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.9 %

2023-02-09 03:09:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 03:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

```
2023-02-09 03:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 03:09:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:09:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 03:10:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 03:10:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 74.6 %

2023-02-09 03:10:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 03:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.9 %

2023-02-09 03:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:10:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:10:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 03:11:02, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 03:11:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 73.5 %

2023-02-09 03:11:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.5 %

2023-02-09 03:11:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:11:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:11:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-09 03:11:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:11:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.1 %

2023-02-09 03:12:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 03:12:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 72.7 %

2023-02-09 03:12:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 03:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 03:12:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:12:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 03:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %
```

2023-02-09 03:12:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 03:13:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 03:13:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 72.0 %

2023-02-09 03:13:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 03:13:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 41.9 %

2023-02-09 03:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:13:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:13:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 03:13:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 03:14:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 03:14:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.5 %

2023-02-09 03:14:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 60.9 %

2023-02-09 03:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:14:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 03:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:14:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 03:15:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 03:15:02 , modbusTCP , I6-1/S-12 , TEMP : 26.1 °C , RH : 71.1 %

2023-02-09 03:15:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 03:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:15:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:15:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:15:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 03:15:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.4 %

```
2023-02-09 03:16:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 03:16:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.9 %

2023-02-09 03:16:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 03:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:16:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:16:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.6 %

2023-02-09 03:17:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 03:17:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.6 %

2023-02-09 03:17:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 03:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.1 %

2023-02-09 03:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:17:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 03:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.5 %

2023-02-09 03:17:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.5 %

2023-02-09 03:18:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 03:18:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.4 %

2023-02-09 03:18:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 03:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:18:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:18:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 03:18:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.5 %

2023-02-09 03:19:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 03:19:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.2 %

```
2023-02-09 03:19:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %
```

2023-02-09 03:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 03:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:19:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:19:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.6  $^{\circ}$ 

2023-02-09 03:20:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 03:20:02, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.9 %

2023-02-09 03:20:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 03:20:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 03:20:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:20:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:20:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 03:20:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.6 %

2023-02-09 03:21:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 03:21:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.6 %

2023-02-09 03:21:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 03:21:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.0 %

2023-02-09 03:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:21:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 03:21:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.5 %

2023-02-09 03:21:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.8 %

2023-02-09 03:22:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 03:22:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.3 %

2023-02-09 03:22:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 03:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

```
2023-02-09 03:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 03:22:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:22:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 52.0  $^{\circ}$ 

2023-02-09 03:23:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 03:23:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.0 %

2023-02-09 03:23:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 03:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.0 %

2023-02-09 03:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:23:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:23:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.3 %

2023-02-09 03:24:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 03:24:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.8 %

2023-02-09 03:24:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 03:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 03:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:24:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 03:24:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.5 %

2023-02-09 03:24:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.3 %

2023-02-09 03:25:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 03:25:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.5 %

2023-02-09 03:25:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 03:25:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.0 %

2023-02-09 03:25:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 03:25:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 03:25:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %
```

2023-02-09 03:25:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

2023-02-09 03:26:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 03:26:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.2 %

2023-02-09 03:26:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 03:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.9 %

2023-02-09 03:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:26:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:26:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

2023-02-09 03:27:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 03:27:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.0 %

2023-02-09 03:27:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.8 %

2023-02-09 03:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:27:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:27:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 52.4 %

2023-02-09 03:28:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-09 03:28:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5  $^{\circ}$ C , RH : 67.7 %

2023-02-09 03:28:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 03:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.2 %

2023-02-09 03:28:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:28:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.4 %

2023-02-09 03:28:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

```
2023-02-09 03:29:01, modbusTCP, I6-1, TEMP: 5.0 °C
```

2023-02-09 03:29:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.5 %

2023-02-09 03:29:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 03:29:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 03:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:29:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:29:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:29:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.0 %

2023-02-09 03:30:01, modbusTCP, I6-1, TEMP: 5.3 °C

2023-02-09 03:30:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.2 %

2023-02-09 03:30:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 03:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.1 %

2023-02-09 03:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:30:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 03:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.3 %

2023-02-09 03:30:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.7 %

2023-02-09 03:31:01, modbusTCP, I6-1, TEMP: 5.5 °C

2023-02-09 03:31:01 , modbusTCP , I6-1/S-12 , TEMP : 26.6  $^{\circ}\text{C}$  , RH : 67.0 %

2023-02-09 03:31:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 03:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:31:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:31:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:31:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.5 %

2023-02-09 03:32:01, modbusTCP, I6-1, TEMP: 5.6 °C

2023-02-09 03:32:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 66.8 %

```
2023-02-09 03:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.2 %
```

2023-02-09 03:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:32:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 03:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:32:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 51.5 %

2023-02-09 03:33:01, modbusTCP, I6-1, TEMP: 5.9 °C

2023-02-09 03:33:01 , modbusTCP , I6-1/S-12 , TEMP : 26.7  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 03:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.1 %

2023-02-09 03:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 03:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:33:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 03:33:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:33:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.3 %

2023-02-09 03:34:02, modbusTCP, I6-1, TEMP: 6.0 °C

2023-02-09 03:34:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.4 %

2023-02-09 03:34:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.3 %

2023-02-09 03:34:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 42.0 %

2023-02-09 03:34:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:34:02 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 03:34:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.4 %

2023-02-09 03:34:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 03:35:01 , modbusTCP , I6-1 , TEMP : 6.3  $^{\circ}\text{C}$ 

2023-02-09 03:35:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.3 %

2023-02-09 03:35:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 03:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

```
2023-02-09 03:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 03:35:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-09 03:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:35:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 03:36:01, modbusTCP, I6-1, TEMP: 6.5 °C

2023-02-09 03:36:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.1 %

2023-02-09 03:36:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 03:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 03:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:36:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %

2023-02-09 03:36:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.9 %

2023-02-09 03:37:01, modbusTCP, I6-1, TEMP: 6.5 °C

2023-02-09 03:37:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

2023-02-09 03:37:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 03:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 03:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:37:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:37:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 50.8 %

2023-02-09 03:38:01, modbusTCP, I6-1, TEMP: 6.4 °C

2023-02-09 03:38:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.8 %

2023-02-09 03:38:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.2 %

2023-02-09 03:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 42.4 %

2023-02-09 03:38:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 03:38:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

```
2023-02-09 03:38:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.4 %
```

2023-02-09 03:38:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.8 %

2023-02-09 03:39:02, modbusTCP, I6-1, TEMP: 6.1 °C

2023-02-09 03:39:02 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 03:39:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 03:39:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 42.0 %

2023-02-09 03:39:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:39:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:39:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.4 %

2023-02-09 03:39:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.7 %

2023-02-09 03:40:01, modbusTCP, I6-1, TEMP: 6.0 °C

2023-02-09 03:40:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.5 %

2023-02-09 03:40:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 03:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 03:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:40:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:40:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 50.7 %

2023-02-09 03:41:01, modbusTCP, I6-1, TEMP: 5.6 °C

2023-02-09 03:41:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.5 %

2023-02-09 03:41:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 03:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 03:41:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:41:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 03:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.3 %

2023-02-09 03:41:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

```
2023-02-09 03:42:01, modbusTCP, I6-1, TEMP: 5.4 °C
```

2023-02-09 03:42:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.0 %

2023-02-09 03:42:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 03:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.1 %

2023-02-09 03:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:42:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:42:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.4 %

2023-02-09 03:43:02, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-09 03:43:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 66.4 %

2023-02-09 03:43:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 03:43:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 03:43:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:43:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 03:43:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.3 %

2023-02-09 03:43:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.5 %

2023-02-09 03:44:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 03:44:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0  $^{\circ}\text{C}$  , RH : 66.8 %

2023-02-09 03:44:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 03:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:44:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:44:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 03:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.3 %

2023-02-09 03:44:01, modbusTCP, I6-2/S-10, TEMP: 23.1 °C, RH: 50.5 %

2023-02-09 03:45:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 03:45:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 67.2 %

```
2023-02-09 03:45:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %
```

2023-02-09 03:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.2 %

2023-02-09 03:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:45:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 03:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:45:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.8 %

2023-02-09 03:46:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 03:46:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 67.5 %

2023-02-09 03:46:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 03:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.1 %

2023-02-09 03:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:46:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.6 %

2023-02-09 03:46:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.3  $^{\circ}$ 

2023-02-09 03:46:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.7 %

2023-02-09 03:47:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 03:47:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.8 %

2023-02-09 03:47:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 03:47:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 41.8 %

2023-02-09 03:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:47:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 03:47:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.3 %

2023-02-09 03:47:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.9 %

2023-02-09 03:48:02 , modbusTCP , I6-1 , TEMP : 4.6  $^{\circ}\text{C}$ 

2023-02-09 03:48:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.0 %

2023-02-09 03:48:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 03:48:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

```
2023-02-09 03:48:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 03:48:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:48:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:48:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 03:49:01, modbusTCP, I6-1, TEMP: 4.8 °C

2023-02-09 03:49:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.2 %

2023-02-09 03:49:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 03:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 03:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:49:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 03:49:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 03:50:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-09 03:50:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.5 %

2023-02-09 03:50:01 , modbusTCP , I6-1/S-13 , TEMP :  $30.0 \, ^{\circ}\text{C}$  , RH :  $61.7 \, \%$ 

2023-02-09 03:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 03:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:50:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 03:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:50:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 51.3 %

2023-02-09 03:51:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-09 03:51:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.7 %

2023-02-09 03:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 03:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.0 %

2023-02-09 03:51:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 03:51:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

```
2023-02-09 03:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %
```

2023-02-09 03:51:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.3 %

2023-02-09 03:52:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-09 03:52:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.0 %

2023-02-09 03:52:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 03:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 03:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:52:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:52:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.3 %

2023-02-09 03:52:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 03:53:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 03:53:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.2 %

2023-02-09 03:53:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.4 %

2023-02-09 03:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 03:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:53:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 03:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:53:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 03:54:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 03:54:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.4 %

2023-02-09 03:54:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 03:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 03:54:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:54:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.3 %

2023-02-09 03:54:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

```
2023-02-09 03:55:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 03:55:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.6 %

2023-02-09 03:55:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 03:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 03:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:55:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:55:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.3 %

2023-02-09 03:56:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 03:56:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.8 %

2023-02-09 03:56:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 03:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 03:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:56:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:56:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 03:56:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.4 %

2023-02-09 03:57:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 03:57:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.1 %

2023-02-09 03:57:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 03:57:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 03:57:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 03:57:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 03:57:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 03:57:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.5 %

2023-02-09 03:58:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 03:58:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.3 %

```
2023-02-09 03:58:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %
```

2023-02-09 03:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.2 %

2023-02-09 03:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:58:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 03:58:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.6  $^{\circ}$ 

2023-02-09 03:59:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 03:59:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}\text{C}$  , RH : 70.5 %

2023-02-09 03:59:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.4 %

2023-02-09 03:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.2 %

2023-02-09 03:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 03:59:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 03:59:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 03:59:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.6 %

2023-02-09 04:00:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 04:00:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.9 %

2023-02-09 04:00:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 04:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}\text{C}$  , RH : 42.0 %

2023-02-09 04:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:00:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 04:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:00:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.6 %

2023-02-09 04:01:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:01:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.0 %

2023-02-09 04:01:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 04:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.2 %

```
2023-02-09 04:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 04:01:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:01:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:01:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.5 %

2023-02-09 04:02:02, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 04:02:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.3 %

2023-02-09 04:02:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 04:02:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.1 %

2023-02-09 04:02:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:02:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:02:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:02:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.9 %

2023-02-09 04:03:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 04:03:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.5 %

2023-02-09 04:03:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 04:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 04:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:03:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 04:03:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.9 %

2023-02-09 04:04:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:04:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.8 %

2023-02-09 04:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 04:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.2 %

2023-02-09 04:04:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:04:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

```
2023-02-09 04:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %
```

2023-02-09 04:04:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.3 %

2023-02-09 04:05:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 04:05:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 72.1 %

2023-02-09 04:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 04:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 04:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:05:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:05:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.3 %

2023-02-09 04:05:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.3 %

2023-02-09 04:06:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:06:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.3 %

2023-02-09 04:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.9 %

2023-02-09 04:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.1 %

2023-02-09 04:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:06:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 04:06:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 52.2 %

2023-02-09 04:07:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 04:07:02 , modbusTCP , I6-1/S-12 , TEMP : 27.0 °C , RH : 72.6 %

2023-02-09 04:07:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.2 %

2023-02-09 04:07:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 04:07:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:07:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:07:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.3 %

2023-02-09 04:07:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

```
2023-02-09 04:08:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 04:08:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.9 %

2023-02-09 04:08:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 04:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 04:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:08:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.3 %

2023-02-09 04:08:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.3 %

2023-02-09 04:09:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 04:09:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.2 %

2023-02-09 04:09:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 04:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 04:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:09:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 04:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:09:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

2023-02-09 04:10:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:10:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.6 %

2023-02-09 04:10:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 04:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 04:10:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:10:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 04:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:10:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.9 %

2023-02-09 04:11:02 , modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-09 04:11:02 , modbusTCP , I6-1/S-12 , TEMP : 26.7  $^{\circ}\text{C}$  , RH : 73.9 %

```
2023-02-09 04:11:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %
```

2023-02-09 04:11:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 04:11:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:11:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:11:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:11:02 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.8  $^{\circ}$ 

2023-02-09 04:12:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 04:12:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.2 %

2023-02-09 04:12:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 04:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 04:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:12:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.2 %

2023-02-09 04:12:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.6 %

2023-02-09 04:13:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:13:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.5 %

2023-02-09 04:13:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 04:13:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2 °C , RH : 41.9 %

2023-02-09 04:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:13:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.4 %

2023-02-09 04:13:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 04:13:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.4 %

2023-02-09 04:14:01 , modbusTCP , I6-1 , TEMP : 4.5  $^{\circ}\text{C}$ 

2023-02-09 04:14:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.9 %

2023-02-09 04:14:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 04:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.1 %

```
2023-02-09 04:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 04:14:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:14:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 04:15:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:15:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.2 %

2023-02-09 04:15:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 04:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 04:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:15:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:15:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.0 %

2023-02-09 04:16:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 04:16:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.5 %

2023-02-09 04:16:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.4 %

2023-02-09 04:16:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.9 %

2023-02-09 04:16:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:16:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:16:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:16:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 51.0 %

2023-02-09 04:17:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:17:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.7 %

2023-02-09 04:17:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 04:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

2023-02-09 04:17:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:17:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

```
2023-02-09 04:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %
```

2023-02-09 04:17:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.9 %

2023-02-09 04:18:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 04:18:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 75.9 %

2023-02-09 04:18:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 04:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.9 %

2023-02-09 04:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:18:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.4 %

2023-02-09 04:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:18:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.8 %

2023-02-09 04:19:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:19:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.2 %

2023-02-09 04:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 60.9 %

2023-02-09 04:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.8 %

2023-02-09 04:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:19:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:19:01 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 50.8 %

2023-02-09 04:20:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:20:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.3 %

2023-02-09 04:20:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 04:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 04:20:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:20:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 04:20:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

```
2023-02-09 04:21:02, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 04:21:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.4 %

2023-02-09 04:21:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 04:21:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 41.9 %

2023-02-09 04:21:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:21:02, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:21:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:21:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

2023-02-09 04:22:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 04:22:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.6 %

2023-02-09 04:22:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 04:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:22:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:22:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.5 %

2023-02-09 04:23:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:23:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-09 04:23:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 04:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:23:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:23:01, modbusTCP, I6-2/S-8, TEMP: 20.7 °C, RH: 58.5 %

2023-02-09 04:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 04:23:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.7 %

2023-02-09 04:24:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 04:24:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

```
2023-02-09 04:24:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %
```

2023-02-09 04:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:24:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:24:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.2 %

2023-02-09 04:24:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.7 %

2023-02-09 04:25:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:25:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-09 04:25:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 62.4 %

2023-02-09 04:25:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 04:25:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:25:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:25:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:25:02, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.8 %

2023-02-09 04:26:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 04:26:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-09 04:26:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-09 04:26:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.8 %

2023-02-09 04:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:26:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 04:26:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 04:26:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.9 %

2023-02-09 04:27:01 , modbusTCP , I6-1 , TEMP : 4.1  $^{\circ}\text{C}$ 

2023-02-09 04:27:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 04:27:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 04:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.0 %

```
2023-02-09 04:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 04:27:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:27:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.2 %

2023-02-09 04:28:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:28:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 04:28:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 04:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:28:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:28:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:28:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.1 %

2023-02-09 04:29:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 04:29:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 04:29:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 04:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 04:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:29:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:29:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 04:30:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:30:02, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 04:30:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 04:30:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 04:30:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:30:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

```
2023-02-09 04:30:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %
```

2023-02-09 04:30:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.1 %

2023-02-09 04:31:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:31:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 04:31:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 04:31:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.0 %

2023-02-09 04:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:31:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:31:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 04:32:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 04:32:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 04:32:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.1 %

2023-02-09 04:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:32:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:32:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 04:33:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 04:33:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 04:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 04:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 04:33:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:33:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:33:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 04:33:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.3 %

```
2023-02-09 04:34:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 04:34:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 04:34:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 04:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 04:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:34:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:34:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.3 %

2023-02-09 04:35:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 04:35:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 04:35:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.1 %

2023-02-09 04:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:35:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:35:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:35:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

2023-02-09 04:36:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:36:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}\text{C}$  , RH : 77.0 %

2023-02-09 04:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 04:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:36:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:36:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 04:36:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.7 %

2023-02-09 04:37:01 , modbusTCP , I6-1 , TEMP : 4.5 °C

2023-02-09 04:37:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

```
2023-02-09 04:37:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-09 04:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:37:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 04:37:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.6  $^{\circ}$ 

2023-02-09 04:38:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 04:38:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}\text{C}$  , RH : 76.9 %

2023-02-09 04:38:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 04:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:38:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:38:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 04:38:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 04:39:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:39:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 04:39:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 04:39:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.8 %

2023-02-09 04:39:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:39:02 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 04:39:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 04:39:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 04:40:01 , modbusTCP , I6-1 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 04:40:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 04:40:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 04:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

```
2023-02-09 04:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 04:40:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:40:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 04:41:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:41:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.6 %

2023-02-09 04:41:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 04:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:41:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:41:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 04:41:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.8 %

2023-02-09 04:42:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:42:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.4 %

2023-02-09 04:42:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.8 %

2023-02-09 04:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:42:01 , modbusTCP , I6-2/S-8 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 04:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 04:42:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.9 %

2023-02-09 04:43:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:43:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.3 %

2023-02-09 04:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 04:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:43:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:43:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.5 %

```
2023-02-09 04:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %
```

2023-02-09 04:43:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 04:44:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 04:44:02 , modbusTCP , I6-1/S-12 , TEMP : 25.8  $^{\circ}\text{C}$  , RH : 76.2 %

2023-02-09 04:44:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

 $2023-02-09\ 04:44:02$  , modbusTCP , I6-1/S-16-2 , TEMP :  $20.2\ ^{\circ}\text{C}$  , RH :  $41.9\ \%$ 

2023-02-09 04:44:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:44:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:44:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:44:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 04:45:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:45:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.0 %

2023-02-09 04:45:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 04:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 04:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:45:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:45:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.2 %

2023-02-09 04:46:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 04:46:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.0 %

2023-02-09 04:46:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 04:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:46:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:46:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 04:46:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.1 %

```
2023-02-09 04:47:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-09 04:47:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 74.5 %

2023-02-09 04:47:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-09 04:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:47:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:47:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.2 %

2023-02-09 04:48:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 04:48:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 73.5 %

2023-02-09 04:48:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 04:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 04:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:48:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 04:48:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 52.0 %

2023-02-09 04:49:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 04:49:02 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}\text{C}$  , RH : 72.7 %

2023-02-09 04:49:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 04:49:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 04:49:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:49:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:49:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 04:49:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.8 %

2023-02-09 04:50:01 , modbusTCP , I6-1 , TEMP : 4.1 °C

2023-02-09 04:50:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 72.0 %

```
2023-02-09 04:50:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %
```

2023-02-09 04:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:50:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 04:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:50:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.8  $^{\circ}$ 

2023-02-09 04:51:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 04:51:01 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}\text{C}$  , RH : 71.4 %

2023-02-09 04:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 04:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:51:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:51:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.6 %

2023-02-09 04:52:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:52:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.9 %

2023-02-09 04:52:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 04:52:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.8 %

2023-02-09 04:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:52:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 04:52:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.2 %

2023-02-09 04:52:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.5 %

2023-02-09 04:53:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 04:53:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.7 %

2023-02-09 04:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 04:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

```
2023-02-09 04:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 04:53:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.7 %

2023-02-09 04:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:53:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 04:54:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 04:54:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.4 %

2023-02-09 04:54:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 04:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:54:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 04:54:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:54:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 04:55:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 04:55:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.3 %

2023-02-09 04:55:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 04:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:55:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 04:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:55:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}$ C , RH : 51.0 %

2023-02-09 04:56:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 04:56:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.0 %

2023-02-09 04:56:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.2 %

2023-02-09 04:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 04:56:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:56:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

```
2023-02-09 04:56:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %
```

2023-02-09 04:56:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 51.0 %

2023-02-09 04:57:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 04:57:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.8 %

2023-02-09 04:57:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 04:57:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.9 %

2023-02-09 04:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:57:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 04:57:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 04:58:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 04:58:02, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.5 %

2023-02-09 04:58:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.0 %

2023-02-09 04:58:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 04:58:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 04:58:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:58:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 04:58:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}\text{C}$  , RH : 50.8 %

2023-02-09 04:59:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 04:59:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}$ C , RH : 69.3  $^{\circ}$ 

2023-02-09 04:59:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 04:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 04:59:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 04:59:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 04:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 04:59:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

```
2023-02-09 05:00:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-09 05:00:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.9 %

2023-02-09 05:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 05:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.7 %

2023-02-09 05:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:00:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:00:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

2023-02-09 05:01:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:01:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.6 %

2023-02-09 05:01:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 05:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:01:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:01:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:01:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

2023-02-09 05:02:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:02:01 , modbusTCP , I6-1/S-12 , TEMP : 26.5  $^{\circ}\text{C}$  , RH : 68.3 %

2023-02-09 05:02:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 05:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:02:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 05:02:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.6 %

2023-02-09 05:03:02 , modbusTCP , I6-1 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 05:03:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.0 %

```
2023-02-09 05:03:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %
```

2023-02-09 05:03:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:03:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:03:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:03:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:03:02 , modbusTCP , I6-2/S-10 , TEMP : 23.0  $^{\circ}$ C , RH : 50.5  $^{\circ}$ 

2023-02-09 05:04:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:04:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.8 %

2023-02-09 05:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.9 %

2023-02-09 05:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:04:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:04:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.8 %

2023-02-09 05:05:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:05:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.5 %

2023-02-09 05:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 05:05:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.7 %

2023-02-09 05:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:05:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 05:05:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 05:05:01, modbusTCP, I6-2/S-10, TEMP: 23.0 °C, RH: 50.9 %

2023-02-09 05:06:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 05:06:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.2 %

2023-02-09 05:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 05:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

```
2023-02-09 05:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 05:06:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:06:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.1 %

2023-02-09 05:07:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 05:07:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.0 %

2023-02-09 05:07:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 05:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:07:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:07:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.1 %

2023-02-09 05:07:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 05:08:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 05:08:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.8 %

2023-02-09 05:08:01 , modbusTCP , I6-1/S-13 , TEMP :  $30.0 \, ^{\circ}\text{C}$  , RH :  $61.3 \, \%$ 

2023-02-09 05:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.6 %

2023-02-09 05:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:08:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:08:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.5 %

2023-02-09 05:09:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:09:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.6 %

2023-02-09 05:09:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 05:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:09:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 05:09:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

```
2023-02-09 05:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %
```

2023-02-09 05:09:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.4 %

2023-02-09 05:10:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:10:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}\text{C}$  , RH : 66.4 %

2023-02-09 05:10:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.2 %

2023-02-09 05:10:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.9 %

2023-02-09 05:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:10:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:10:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.3 %

2023-02-09 05:11:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:11:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.2 %

2023-02-09 05:11:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.5 %

2023-02-09 05:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 05:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:11:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:11:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 05:12:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:12:02 , modbusTCP , I6-1/S-12 , TEMP : 26.8 °C , RH : 66.1 %

2023-02-09 05:12:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.8 %

2023-02-09 05:12:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 05:12:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:12:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 05:12:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 05:12:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

```
2023-02-09 05:13:01, modbusTCP, I6-1, TEMP: 4.1 °C
```

2023-02-09 05:13:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.9 %

2023-02-09 05:13:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 05:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 05:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:13:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:13:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

2023-02-09 05:14:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:14:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.7 %

2023-02-09 05:14:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 05:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 05:14:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:14:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:14:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

2023-02-09 05:15:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 05:15:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.6 %

2023-02-09 05:15:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 05:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 05:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:15:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:15:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 05:15:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 05:16:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 05:16:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.5 %

```
2023-02-09 05:16:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %
```

2023-02-09 05:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 05:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:16:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:16:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

2023-02-09 05:17:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:17:02 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 65.3 %

2023-02-09 05:17:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.6  $^{\circ}$ 

2023-02-09 05:17:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:17:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:17:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:17:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.0 %

2023-02-09 05:17:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.7 %

2023-02-09 05:18:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:18:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.3 %

2023-02-09 05:18:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 05:18:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.5 %

2023-02-09 05:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:18:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 05:18:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:18:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.7 %

2023-02-09 05:19:01 , modbusTCP , I6-1 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 05:19:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.9 %

2023-02-09 05:19:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 05:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

```
2023-02-09 05:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 05:19:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:19:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 51.7 %

2023-02-09 05:20:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 05:20:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.4 %

2023-02-09 05:20:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 05:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.7 %

2023-02-09 05:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:20:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:20:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 05:21:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:21:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.8 %

2023-02-09 05:21:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 05:21:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.4 %

2023-02-09 05:21:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:21:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:21:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:21:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.0 %

2023-02-09 05:22:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:22:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.1 %

2023-02-09 05:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 05:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.6 %

2023-02-09 05:22:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:22:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

```
2023-02-09 05:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %
```

2023-02-09 05:22:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.6 %

2023-02-09 05:23:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:23:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}$ C , RH : 67.5  $^{\circ}$ 

2023-02-09 05:23:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 05:23:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.5 %

2023-02-09 05:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:23:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:23:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.4 %

2023-02-09 05:24:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:24:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.8 %

2023-02-09 05:24:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 05:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:24:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:24:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:24:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.4 %

2023-02-09 05:25:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:25:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}$ C , RH : 68.0 %

2023-02-09 05:25:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 05:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:25:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:25:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:25:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:25:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

```
2023-02-09 05:26:02, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 05:26:02, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.3 %

2023-02-09 05:26:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 05:26:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:26:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:26:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:26:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:26:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 05:27:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:27:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.5 %

2023-02-09 05:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 05:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.8 %

2023-02-09 05:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:27:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:27:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 05:28:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 05:28:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}\text{C}$  , RH : 68.8 %

2023-02-09 05:28:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.6 %

2023-02-09 05:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:28:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:28:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:28:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 05:28:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 05:29:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:29:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.0 %

```
2023-02-09 05:29:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %
```

2023-02-09 05:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.5 %

2023-02-09 05:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:29:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:29:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 52.0  $^{\circ}$ 

2023-02-09 05:30:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 05:30:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.2 %

2023-02-09 05:30:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.5 %

2023-02-09 05:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 05:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:30:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:30:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.8 %

2023-02-09 05:31:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 05:31:02, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.4 %

2023-02-09 05:31:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 05:31:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 05:31:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:31:02 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 05:31:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:31:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 05:32:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 05:32:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.6 %

2023-02-09 05:32:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 05:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

```
2023-02-09 05:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 05:32:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:32:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 51.4 %

2023-02-09 05:33:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:33:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.9 %

2023-02-09 05:33:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 05:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 05:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:33:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:33:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:33:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.2 %

2023-02-09 05:34:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:34:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.1 %

2023-02-09 05:34:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.6  $^{\circ}$ 

2023-02-09 05:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.5 %

2023-02-09 05:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:34:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 05:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:34:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 05:35:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:35:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.4 %

2023-02-09 05:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 05:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.5 %

2023-02-09 05:35:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 05:35:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 05:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 66.0 %
```

2023-02-09 05:35:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.1 %

2023-02-09 05:36:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:36:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.7 %

2023-02-09 05:36:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 05:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 05:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:36:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:36:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 66.0 %

2023-02-09 05:36:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.0 %

2023-02-09 05:37:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 05:37:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.9 %

2023-02-09 05:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.0 %

2023-02-09 05:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 05:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:37:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 66.0 %

2023-02-09 05:37:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 50.9 %

2023-02-09 05:38:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:38:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}$ C , RH : 71.2  $^{\circ}$ 

2023-02-09 05:38:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 05:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.8 %

2023-02-09 05:38:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:38:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.6 %

2023-02-09 05:38:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:38:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.0 %

```
2023-02-09 05:39:01, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-09 05:39:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.4 %

2023-02-09 05:39:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 05:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 42.0 %

2023-02-09 05:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:39:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:39:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.7 %

2023-02-09 05:40:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:40:02, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.7 %

2023-02-09 05:40:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 05:40:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.7 %

2023-02-09 05:40:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:40:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:40:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:40:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.6 %

2023-02-09 05:41:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:41:01 , modbusTCP , I6-1/S-12 , TEMP : 27.0  $^{\circ}\text{C}$  , RH : 72.0 %

2023-02-09 05:41:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 05:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.5 %

2023-02-09 05:41:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:41:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:41:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.6 %

2023-02-09 05:42:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 05:42:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.3 %

```
2023-02-09 05:42:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %
```

2023-02-09 05:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.9 %

2023-02-09 05:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:42:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}$ C , RH : 58.6  $^{\circ}$ 

2023-02-09 05:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:42:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.5 %

2023-02-09 05:43:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:43:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 72.6 %

2023-02-09 05:43:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 05:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:43:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.8 %

2023-02-09 05:43:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 05:44:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 05:44:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 72.9 %

2023-02-09 05:44:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 05:44:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 41.9 %

2023-02-09 05:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:44:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}$ C , RH : 58.6  $^{\circ}$ 

2023-02-09 05:44:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:44:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 05:45:02 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 05:45:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.2 %

2023-02-09 05:45:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 05:45:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

```
2023-02-09 05:45:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 05:45:02, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:45:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:45:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.0 %

2023-02-09 05:46:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:46:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.6 %

2023-02-09 05:46:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 05:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:46:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 05:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 05:46:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.2 %

2023-02-09 05:47:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 05:47:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 73.9 %

2023-02-09 05:47:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 05:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 05:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:47:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 05:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:47:01 , modbusTCP , I6-2/S-10 , TEMP : 22.9  $^{\circ}\text{C}$  , RH : 51.5 %

2023-02-09 05:48:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:48:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.2 %

2023-02-09 05:48:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 05:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:48:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 05:48:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 05:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %
```

2023-02-09 05:48:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 05:49:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 05:49:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.6 %

2023-02-09 05:49:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 05:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.9 %

2023-02-09 05:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:49:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 05:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:49:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.3 %

2023-02-09 05:50:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:50:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 74.8 %

2023-02-09 05:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 60.8 %

2023-02-09 05:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:50:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 05:50:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.4 %

2023-02-09 05:51:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 05:51:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}$ C , RH : 75.1 %

2023-02-09 05:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 05:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 05:51:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:51:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:51:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.8 %

2023-02-09 05:51:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

```
2023-02-09 05:52:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 05:52:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.4 %

2023-02-09 05:52:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 05:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:52:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 05:52:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.3 %

2023-02-09 05:53:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 05:53:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.7 %

2023-02-09 05:53:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 05:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:53:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 05:53:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

2023-02-09 05:54:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 05:54:02 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}\text{C}$  , RH : 76.0 %

2023-02-09 05:54:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 05:54:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.7 %

2023-02-09 05:54:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 05:54:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:54:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.8 %

2023-02-09 05:54:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

2023-02-09 05:55:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:55:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.2 %

```
2023-02-09 05:55:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %
```

2023-02-09 05:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 05:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:55:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 05:55:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

2023-02-09 05:56:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:56:01 , modbusTCP , I6-1/S-12 , TEMP : 25.9  $^{\circ}\text{C}$  , RH : 76.3 %

2023-02-09 05:56:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.8 %

2023-02-09 05:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 05:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:56:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:56:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.8 %

2023-02-09 05:56:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 05:57:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 05:57:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.5 %

2023-02-09 05:57:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 05:57:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 42.0 %

2023-02-09 05:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:57:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 05:57:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 05:57:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.7 %

2023-02-09 05:58:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 05:58:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 05:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 05:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.7 %

```
2023-02-09 05:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 05:58:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:58:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 05:59:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 05:59:02, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

2023-02-09 05:59:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 05:59:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 05:59:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 05:59:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 05:59:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 05:59:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 06:00:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 06:00:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 06:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 06:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:00:01 , modbusTCP , I6-2/S-8 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 06:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:00:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.7 %

2023-02-09 06:01:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:01:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-09 06:01:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 06:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:01:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 06:01:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

```
2023-02-09 06:01:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.9 %
```

2023-02-09 06:01:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 06:02:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:02:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 06:02:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 06:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 06:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:02:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 06:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.9 %

2023-02-09 06:02:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.6 %

2023-02-09 06:03:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:03:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 06:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.8 %

2023-02-09 06:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:03:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 06:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:03:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.4 %

2023-02-09 06:04:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:04:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 06:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 06:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:04:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:04:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 06:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 06:04:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.5 %

```
2023-02-09 06:05:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 06:05:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 06:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 06:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:05:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:05:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.3 %

2023-02-09 06:06:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:06:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 06:06:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 06:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.5 %

2023-02-09 06:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:06:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:06:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 06:07:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 06:07:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4  $^{\circ}\text{C}$  , RH : 77.1 %

2023-02-09 06:07:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 06:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 06:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:07:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 06:07:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 06:08:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 06:08:02, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

```
2023-02-09 06:08:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %
```

2023-02-09 06:08:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:08:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:08:02 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 06:08:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:08:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.1 %

2023-02-09 06:09:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 06:09:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 06:09:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 06:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:09:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:09:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.8 %

2023-02-09 06:09:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.0 %

2023-02-09 06:10:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 06:10:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

2023-02-09 06:10:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 06:10:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.7 %

2023-02-09 06:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:10:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 06:10:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.8 %

2023-02-09 06:10:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.9 %

2023-02-09 06:11:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 06:11:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.0 %

2023-02-09 06:11:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 06:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

```
2023-02-09 06:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 06:11:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:11:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 51.7 %

2023-02-09 06:12:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 06:12:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 06:12:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 06:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

2023-02-09 06:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:12:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:12:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

2023-02-09 06:13:02, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:13:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 06:13:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 06:13:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 06:13:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:13:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:13:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:13:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.4 %

2023-02-09 06:14:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:14:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 06:14:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 06:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:14:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:14:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

```
2023-02-09 06:14:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %
```

2023-02-09 06:14:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.2 %

2023-02-09 06:15:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:15:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 06:15:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 06:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.9 %

2023-02-09 06:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:15:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:15:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.1 %

2023-02-09 06:16:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 06:16:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6  $^{\circ}\text{C}$  , RH : 76.6 %

2023-02-09 06:16:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 62.1 %

2023-02-09 06:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.9 %

2023-02-09 06:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:16:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:16:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.9 %

2023-02-09 06:16:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

2023-02-09 06:17:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 06:17:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.4 %

2023-02-09 06:17:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 06:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 06:17:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:17:01, modbusTCP, I6-2/S-8, TEMP: 20.6 °C, RH: 58.5 %

2023-02-09 06:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 06:17:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.0 %

```
2023-02-09 06:18:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 06:18:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.3 %

2023-02-09 06:18:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 06:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 06:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:18:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:18:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.9 %

2023-02-09 06:18:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 51.1 %

2023-02-09 06:19:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:19:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.2 %

2023-02-09 06:19:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 06:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:19:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.9 %

2023-02-09 06:19:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.9 %

2023-02-09 06:20:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 06:20:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.0 %

2023-02-09 06:20:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-09 06:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.8 %

2023-02-09 06:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:20:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.8 %

2023-02-09 06:20:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 06:21:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 06:21:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 75.9 %

```
2023-02-09 06:21:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %
```

2023-02-09 06:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 06:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:21:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:21:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 06:22:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:22:02 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}\text{C}$  , RH : 75.8 %

2023-02-09 06:22:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 06:22:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.9 %

2023-02-09 06:22:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:22:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:22:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.8 %

2023-02-09 06:22:02, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.8 %

2023-02-09 06:23:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 06:23:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.6 %

2023-02-09 06:23:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 06:23:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 41.8 %

2023-02-09 06:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:23:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 06:23:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.9 %

2023-02-09 06:23:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.7 %

2023-02-09 06:24:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 06:24:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 74.0 %

2023-02-09 06:24:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 06:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

```
2023-02-09 06:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 06:24:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:24:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.9 %

2023-02-09 06:24:01, modbusTCP, I6-2/S-10, TEMP: 22.9 °C, RH: 50.9 %

2023-02-09 06:25:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:25:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 73.1 %

2023-02-09 06:25:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-09 06:25:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.6 %

2023-02-09 06:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:25:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:25:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.9 %

2023-02-09 06:25:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.2 %

2023-02-09 06:26:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:26:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 72.3 %

2023-02-09 06:26:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 06:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 06:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:26:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 06:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:26:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 06:27:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 06:27:02, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 71.6 %

2023-02-09 06:27:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 06:27:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:27:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 06:27:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 06:27:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %
```

2023-02-09 06:27:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

2023-02-09 06:28:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 06:28:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 71.1 %

2023-02-09 06:28:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 06:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.4 %

2023-02-09 06:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:28:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:28:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:28:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.3 %

2023-02-09 06:29:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:29:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.8 %

2023-02-09 06:29:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.1 %

2023-02-09 06:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 06:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:29:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:29:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:29:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.3 %

2023-02-09 06:30:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 06:30:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}\text{C}$  , RH : 70.6 %

2023-02-09 06:30:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 06:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.5 %

2023-02-09 06:30:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:30:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:30:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.5 %

```
2023-02-09 06:31:01, modbusTCP, I6-1, TEMP: 4.4 °C
```

2023-02-09 06:31:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.4 %

2023-02-09 06:31:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.7 %

2023-02-09 06:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:31:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.8 %

2023-02-09 06:31:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 06:32:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:32:02, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 70.2 %

2023-02-09 06:32:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-09 06:32:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:32:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:32:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:32:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 06:32:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.6 %

2023-02-09 06:33:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:33:01 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}\text{C}$  , RH : 69.9 %

2023-02-09 06:33:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 06:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:33:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:33:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:33:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 06:34:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 06:34:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.7 %

```
2023-02-09 06:34:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %
```

2023-02-09 06:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:34:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:34:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 51.6  $^{\circ}$ 

2023-02-09 06:35:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:35:01 , modbusTCP , I6-1/S-12 , TEMP : 26.4  $^{\circ}\text{C}$  , RH : 69.4 %

2023-02-09 06:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 06:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:35:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 06:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7  $^{\circ}$ 

2023-02-09 06:35:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.7 %

2023-02-09 06:36:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:36:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 69.1 %

2023-02-09 06:36:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 06:36:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.5 %

2023-02-09 06:36:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:36:02 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 06:36:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:36:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.7 %

2023-02-09 06:37:01 , modbusTCP , I6-1 , TEMP : 3.4  $^{\circ}\text{C}$ 

2023-02-09 06:37:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.8 %

2023-02-09 06:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 06:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

```
2023-02-09 06:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 06:37:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:37:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.8 %

2023-02-09 06:38:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:38:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.5 %

2023-02-09 06:38:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 06:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 06:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:38:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:38:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:38:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.0 %

2023-02-09 06:39:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 06:39:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 68.2 %

2023-02-09 06:39:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 06:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 06:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:39:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 06:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:39:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.8 %

2023-02-09 06:40:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:40:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.9 %

2023-02-09 06:40:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 06:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:40:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 06:40:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 06:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %
```

2023-02-09 06:40:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.0 %

2023-02-09 06:41:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:41:02, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.7 %

2023-02-09 06:41:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 06:41:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.6 %

2023-02-09 06:41:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:41:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:41:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 06:41:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.0 %

2023-02-09 06:42:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:42:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.4 %

2023-02-09 06:42:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.5 %

2023-02-09 06:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 06:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:42:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:42:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 52.5 %

2023-02-09 06:43:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:43:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.2 %

2023-02-09 06:43:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 06:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.5 %

2023-02-09 06:43:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:43:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:43:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

```
2023-02-09 06:44:01, modbusTCP, I6-1, TEMP: 4.1 °C
```

2023-02-09 06:44:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.0 %

2023-02-09 06:44:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 06:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 06:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:44:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:44:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

2023-02-09 06:45:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:45:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.8 %

2023-02-09 06:45:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 62.0 %

2023-02-09 06:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 41.6 %

2023-02-09 06:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:45:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:45:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.3 %

2023-02-09 06:46:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 06:46:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.6 %

2023-02-09 06:46:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 06:46:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 06:46:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:46:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:46:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:46:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.2 %

2023-02-09 06:47:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:47:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.4 %

```
2023-02-09 06:47:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %
```

2023-02-09 06:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:47:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:47:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 52.3  $^{\circ}$ 

2023-02-09 06:48:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:48:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.2 %

2023-02-09 06:48:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 06:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.8 %

2023-02-09 06:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:48:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 06:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:48:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.3 %

2023-02-09 06:49:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:49:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

2023-02-09 06:49:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 06:49:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 41.7 %

2023-02-09 06:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:49:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:49:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:49:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.0 %

2023-02-09 06:50:01 , modbusTCP , I6-1 , TEMP : 3.6  $^{\circ}\text{C}$ 

2023-02-09 06:50:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.9 %

2023-02-09 06:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 06:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.8 %

```
2023-02-09 06:50:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 06:50:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:50:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 06:50:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.9 %

2023-02-09 06:51:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 06:51:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.7 %

2023-02-09 06:51:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 06:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 06:51:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:51:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 06:51:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:51:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.6 %

2023-02-09 06:52:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 06:52:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.6 %

2023-02-09 06:52:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 06:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.6 %

2023-02-09 06:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:52:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 06:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:52:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.5 %

2023-02-09 06:53:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:53:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.4 %

2023-02-09 06:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 06:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:53:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 06:53:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

```
2023-02-09 06:53:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 06:53:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.4 %

2023-02-09 06:54:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 06:54:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 65.3 %

2023-02-09 06:54:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

 $2023-02-09\ 06:54:01$  , modbusTCP , I6-1/S-16-2 , TEMP :  $20.2\ ^{\circ}\text{C}$  , RH :  $41.7\ \%$ 

2023-02-09 06:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:54:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 06:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 06:54:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.2 %

2023-02-09 06:55:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 06:55:02, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.7 %

2023-02-09 06:55:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.1 %

2023-02-09 06:55:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.7 %

2023-02-09 06:55:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:55:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 06:55:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:55:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.1 %

2023-02-09 06:56:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 06:56:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}$ C , RH : 66.2 %

2023-02-09 06:56:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 06:56:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 06:56:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:56:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 06:56:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:56:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

```
2023-02-09 06:57:01, modbusTCP, I6-1, TEMP: 3.9 °C
```

2023-02-09 06:57:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.5 %

2023-02-09 06:57:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 06:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.5 %

2023-02-09 06:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:57:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 06:57:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:57:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 50.9 %

2023-02-09 06:58:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 06:58:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.9 %

2023-02-09 06:58:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 06:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.5 %

2023-02-09 06:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 06:58:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 06:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 06:58:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.8 %

2023-02-09 06:59:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 06:59:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}\text{C}$  , RH : 67.2 %

2023-02-09 06:59:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 06:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.4 %

2023-02-09 06:59:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 06:59:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 06:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 06:59:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

2023-02-09 07:00:02 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 07:00:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.5 %

```
2023-02-09 07:00:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %
```

2023-02-09 07:00:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

2023-02-09 07:00:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:00:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:00:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:00:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.7 %

2023-02-09 07:01:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:01:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.8 %

2023-02-09 07:01:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 07:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 41.6 %

2023-02-09 07:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:01:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 07:01:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:01:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.0 %

2023-02-09 07:02:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:02:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.1 %

2023-02-09 07:02:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 07:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 41.5 %

2023-02-09 07:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:02:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 07:02:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 07:02:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.0 %

2023-02-09 07:03:01 , modbusTCP , I6-1 , TEMP : 3.9  $^{\circ}\text{C}$ 

2023-02-09 07:03:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.3 %

2023-02-09 07:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 07:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.6 %

```
2023-02-09 07:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 07:03:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:03:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:03:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 51.0  $^{\circ}$ 

2023-02-09 07:04:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:04:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 68.6 %

2023-02-09 07:04:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 07:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 41.7 %

2023-02-09 07:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:04:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:04:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.0 %

2023-02-09 07:05:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:05:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 68.8 %

2023-02-09 07:05:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 07:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.6 %

2023-02-09 07:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:05:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 07:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:05:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.0 %

2023-02-09 07:06:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 07:06:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.0 %

2023-02-09 07:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 07:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 45.6 %

2023-02-09 07:06:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 07:06:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 07:06:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 07:06:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

2023-02-09 07:07:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:07:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}\text{C}$  , RH : 69.2 %

2023-02-09 07:07:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 07:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 47.0 %

2023-02-09 07:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:07:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 07:07:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.2 %

2023-02-09 07:08:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:08:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 69.5 %

2023-02-09 07:08:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 60.8 %

2023-02-09 07:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 47.3 %

2023-02-09 07:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:08:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:08:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.4 %

2023-02-09 07:09:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 07:09:02 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}$ C , RH : 69.7  $^{\circ}$ 

2023-02-09 07:09:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.7 %

2023-02-09 07:09:02, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 45.4 %

2023-02-09 07:09:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:09:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:09:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 07:09:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.3 %

```
2023-02-09 07:10:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 07:10:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 69.9 %

2023-02-09 07:10:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 07:10:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}$ C , RH : 43.7 %

2023-02-09 07:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:10:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:10:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.2 %

2023-02-09 07:11:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:11:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.2 %

2023-02-09 07:11:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 07:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 42.5 %

2023-02-09 07:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:11:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:11:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.3 %

2023-02-09 07:12:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:12:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}\text{C}$  , RH : 70.4 %

2023-02-09 07:12:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-09 07:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 41.9 %

2023-02-09 07:12:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:12:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 07:12:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.4 %

2023-02-09 07:13:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:13:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 70.7 %

```
2023-02-09 07:13:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %
```

2023-02-09 07:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.7 %

2023-02-09 07:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:13:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 07:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:13:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 51.4  $^{\circ}$ 

2023-02-09 07:14:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:14:02 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}\text{C}$  , RH : 70.9 %

2023-02-09 07:14:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 07:14:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.7 %

2023-02-09 07:14:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:14:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:14:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 07:14:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.4 %

2023-02-09 07:15:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 07:15:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.1 %

2023-02-09 07:15:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 07:15:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 41.6 %

2023-02-09 07:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:15:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 07:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:15:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.5 %

2023-02-09 07:16:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 07:16:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 71.4 %

2023-02-09 07:16:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 07:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 41.8 %

```
2023-02-09 07:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 07:16:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:16:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.5 %

2023-02-09 07:17:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:17:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.7 %

2023-02-09 07:17:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 07:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.1 %

2023-02-09 07:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:17:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:17:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:17:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.7 %

2023-02-09 07:18:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 07:18:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 71.9 %

2023-02-09 07:18:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.5 %

2023-02-09 07:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 42.3 %

2023-02-09 07:18:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:18:02 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 07:18:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:18:02 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.7 %

2023-02-09 07:19:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 07:19:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.2 %

2023-02-09 07:19:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 07:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 42.3 %

2023-02-09 07:19:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:19:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

```
2023-02-09 07:19:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 07:19:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.9 %

2023-02-09 07:20:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:20:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.5 %

2023-02-09 07:20:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 07:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.4 %

2023-02-09 07:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:20:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 07:20:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.1 %

2023-02-09 07:21:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:21:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 72.8 %

2023-02-09 07:21:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 07:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.5 %

2023-02-09 07:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:21:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:21:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 52.0 %

2023-02-09 07:22:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:22:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.1 %

2023-02-09 07:22:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 07:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 42.5 %

2023-02-09 07:22:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:22:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.5 %

2023-02-09 07:22:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.2 %

```
2023-02-09 07:23:02, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-09 07:23:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.4 %

2023-02-09 07:23:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 07:23:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 43.1 %

2023-02-09 07:23:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:23:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:23:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 07:23:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.7 %

2023-02-09 07:24:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:24:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.7 %

2023-02-09 07:24:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 07:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 43.6 %

2023-02-09 07:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:24:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:24:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:24:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.5 %

2023-02-09 07:25:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:25:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.0 %

2023-02-09 07:25:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 07:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.1 %

2023-02-09 07:25:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:25:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:25:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.6 %

2023-02-09 07:26:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 07:26:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.3 %

```
2023-02-09 07:26:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %
```

2023-02-09 07:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 42.9 %

2023-02-09 07:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:26:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 07:26:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:26:01 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}$ C , RH : 52.5  $^{\circ}$ 

2023-02-09 07:27:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:27:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.6 %

2023-02-09 07:27:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.8 %

2023-02-09 07:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.1 %

2023-02-09 07:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:27:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:27:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 07:27:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

2023-02-09 07:28:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 07:28:02, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.9 %

2023-02-09 07:28:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 07:28:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 43.2 %

2023-02-09 07:28:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:28:02 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 07:28:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:28:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

2023-02-09 07:29:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 07:29:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.1 %

2023-02-09 07:29:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 07:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.1 %

```
2023-02-09 07:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 07:29:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:29:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:29:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 52.4 %

2023-02-09 07:30:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:30:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.4 %

2023-02-09 07:30:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 07:30:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 43.4 %

2023-02-09 07:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:30:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 07:30:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:30:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.2 %

2023-02-09 07:31:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:31:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.7 %

2023-02-09 07:31:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 07:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.3 %

2023-02-09 07:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:31:01 , modbusTCP , I6-2/S-8 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 58.5 %

2023-02-09 07:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.8 %

2023-02-09 07:31:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 52.0 %

2023-02-09 07:32:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 07:32:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 75.8 %

2023-02-09 07:32:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 07:32:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.3 %

2023-02-09 07:32:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 07:32:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

```
2023-02-09 07:32:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 07:32:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.8 %

2023-02-09 07:33:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:33:01 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}$ C , RH : 76.0  $^{\circ}$ 

2023-02-09 07:33:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 07:33:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 43.7 %

2023-02-09 07:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:33:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.5 %

2023-02-09 07:33:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 07:33:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.5 %

2023-02-09 07:34:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:34:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.1 %

2023-02-09 07:34:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.0 %

2023-02-09 07:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.8 %

2023-02-09 07:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:34:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:34:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:34:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.5 %

2023-02-09 07:35:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:35:01 , modbusTCP , I6-1/S-12 , TEMP : 25.8  $^{\circ}$ C , RH : 76.3  $^{\circ}$ 

2023-02-09 07:35:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 07:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.8 %

2023-02-09 07:35:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:35:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 07:35:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.2 %

```
2023-02-09 07:36:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 07:36:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.4 %

2023-02-09 07:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 07:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 43.6 %

2023-02-09 07:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:36:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:36:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.2 %

2023-02-09 07:37:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:37:02, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.5 %

2023-02-09 07:37:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 07:37:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 43.7 %

2023-02-09 07:37:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:37:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:37:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:37:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.0 %

2023-02-09 07:38:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 07:38:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7  $^{\circ}\text{C}$  , RH : 76.7 %

2023-02-09 07:38:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 07:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 43.8 %

2023-02-09 07:38:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:38:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:38:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 07:38:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.0 %

2023-02-09 07:39:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:39:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.7 %

```
2023-02-09 07:39:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %
```

2023-02-09 07:39:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 45.8 %

2023-02-09 07:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:39:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 07:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:39:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 51.0  $^{\circ}$ 

2023-02-09 07:40:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:40:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 07:40:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 07:40:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 47.8 %

2023-02-09 07:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:40:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:40:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 07:40:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.7 %

2023-02-09 07:41:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 07:41:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-09 07:41:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 07:41:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.5  $^{\circ}$ C , RH : 48.5  $^{\circ}$ 

2023-02-09 07:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:41:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 07:41:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 07:41:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.7 %

2023-02-09 07:42:01 , modbusTCP , I6-1 , TEMP : 4.1  $^{\circ}\text{C}$ 

2023-02-09 07:42:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:42:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 07:42:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 48.6 %

```
2023-02-09 07:42:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 07:42:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:42:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:42:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.9 %

2023-02-09 07:43:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:43:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:43:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 07:43:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 48.5 %

2023-02-09 07:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:43:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:43:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 50.9 %

2023-02-09 07:44:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 07:44:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:44:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 07:44:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.5 %

2023-02-09 07:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:44:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 07:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:44:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 51.0 %

2023-02-09 07:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:45:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:45:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 07:45:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.5 %

2023-02-09 07:45:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:45:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

```
2023-02-09 07:45:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 07:45:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

2023-02-09 07:46:02, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:46:02 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}\text{C}$  , RH : 76.9 %

2023-02-09 07:46:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 07:46:02 , modbusTCP , I6-1/S-16-2 , TEMP : 19.8  $^{\circ}$ C , RH : 48.5 %

2023-02-09 07:46:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:46:02, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 07:46:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 07:46:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 51.1 %

2023-02-09 07:47:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:47:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:47:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.3 %

2023-02-09 07:47:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 48.5 %

2023-02-09 07:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:47:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:47:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.2 %

2023-02-09 07:48:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 07:48:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}$ C , RH : 76.9 %

2023-02-09 07:48:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 07:48:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 48.5 %

2023-02-09 07:48:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:48:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.7 %

2023-02-09 07:48:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 07:48:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.1 %

```
2023-02-09 07:49:01, modbusTCP, I6-1, TEMP: 3.8 °C
```

2023-02-09 07:49:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:49:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %

2023-02-09 07:49:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.5 %

2023-02-09 07:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:49:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:49:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.2 %

2023-02-09 07:50:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 07:50:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.9 %

2023-02-09 07:50:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.0 %

2023-02-09 07:50:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.8  $^{\circ}$ C , RH : 48.5 %

2023-02-09 07:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:50:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 07:50:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:50:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.4 %

2023-02-09 07:51:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 07:51:02, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 76.8 %

2023-02-09 07:51:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 07:51:02, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 48.4 %

2023-02-09 07:51:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 07:51:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 07:51:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 07:51:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.4 %

2023-02-09 07:52:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 07:52:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

```
2023-02-09 07:52:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %
```

2023-02-09 07:52:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.5 %

2023-02-09 07:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:52:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:52:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 51.3  $^{\circ}$ 

2023-02-09 07:53:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 07:53:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.7 %

2023-02-09 07:53:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 07:53:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.6 %

2023-02-09 07:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:53:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:53:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 07:53:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.4 %

2023-02-09 07:54:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 07:54:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.6 %

2023-02-09 07:54:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 07:54:01 , modbusTCP , I6-1/S-16-2 , TEMP : 19.6  $^{\circ}$ C , RH : 48.8 %

2023-02-09 07:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:54:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 07:54:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 07:54:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.6 %

2023-02-09 07:55:01 , modbusTCP , I6-1 , TEMP : 3.9  $^{\circ}\text{C}$ 

2023-02-09 07:55:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.5 %

2023-02-09 07:55:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 07:55:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 49.0 %

```
2023-02-09 07:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 07:55:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 07:55:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.6 %

2023-02-09 07:56:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:56:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.4 %

2023-02-09 07:56:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 07:56:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 49.0 %

2023-02-09 07:56:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:56:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:56:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:56:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 51.6 %

2023-02-09 07:57:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:57:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.2 %

2023-02-09 07:57:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 07:57:01, modbusTCP, I6-1/S-16-2, TEMP: 19.6 °C, RH: 49.0 %

2023-02-09 07:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:57:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 07:57:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 07:57:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 51.6 %

2023-02-09 07:58:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 07:58:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.1 %

2023-02-09 07:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 07:58:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 49.0 %

2023-02-09 07:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:58:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

```
2023-02-09 07:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 07:58:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 51.7 %

2023-02-09 07:59:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 07:59:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.0 %

2023-02-09 07:59:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 07:59:01, modbusTCP, I6-1/S-16-2, TEMP: 19.7 °C, RH: 48.9 %

2023-02-09 07:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 07:59:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 07:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 07:59:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 51.9 %

2023-02-09 08:00:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 08:00:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 74.8 %

2023-02-09 08:00:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.7 %

2023-02-09 08:00:02, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 48.9 %

2023-02-09 08:00:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:00:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:00:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:00:02 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}\text{C}$  , RH : 51.9 %

2023-02-09 08:01:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:01:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 73.7 %

2023-02-09 08:01:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 08:01:01, modbusTCP, I6-1/S-16-2, TEMP: 19.8 °C, RH: 48.7 %

2023-02-09 08:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:01:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

2023-02-09 08:01:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:01:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.0 %

```
2023-02-09 08:02:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 08:02:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.9 %

2023-02-09 08:02:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 08:02:01, modbusTCP, I6-1/S-16-2, TEMP: 19.9 °C, RH: 48.6 %

2023-02-09 08:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:02:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:02:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.1 %

2023-02-09 08:03:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:03:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 72.2 %

2023-02-09 08:03:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 08:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 48.5 %

2023-02-09 08:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:03:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:03:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.1 %

2023-02-09 08:04:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 08:04:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 71.7 %

2023-02-09 08:04:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 08:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.4 %

2023-02-09 08:04:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:04:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:04:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.5 %

2023-02-09 08:05:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 08:05:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 71.2 %

```
2023-02-09 08:05:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %
```

2023-02-09 08:05:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.3 %

2023-02-09 08:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:05:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:05:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:05:02 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}$ C , RH : 52.6  $^{\circ}$ 

2023-02-09 08:06:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:06:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 71.0 %

2023-02-09 08:06:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 61.3  $^{\circ}$ 

2023-02-09 08:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.6 %

2023-02-09 08:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:06:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:06:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 08:06:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 52.4 %

2023-02-09 08:07:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:07:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.8 %

2023-02-09 08:07:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %

2023-02-09 08:07:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 48.3 %

2023-02-09 08:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:07:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 08:07:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 08:07:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.3 %

2023-02-09 08:08:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 08:08:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.6 %

2023-02-09 08:08:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 08:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.4 %

```
2023-02-09 08:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 08:08:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:08:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:08:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.2 %

2023-02-09 08:09:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 08:09:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.3 %

2023-02-09 08:09:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 08:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.3 %

2023-02-09 08:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:09:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:09:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:09:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

2023-02-09 08:10:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:10:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 70.1 %

2023-02-09 08:10:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 08:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.0 %

2023-02-09 08:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:10:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 08:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:10:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

2023-02-09 08:11:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:11:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.8 %

2023-02-09 08:11:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 08:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.0 %

2023-02-09 08:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:11:01, modbusTCP, I6-2/S-8, TEMP: 20.5 °C, RH: 58.6 %

```
2023-02-09 08:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %
```

2023-02-09 08:11:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.9 %

2023-02-09 08:12:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 08:12:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.5 %

2023-02-09 08:12:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 08:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.1 %

2023-02-09 08:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:12:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.7 %

2023-02-09 08:12:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 53.3 %

2023-02-09 08:13:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:13:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 69.2 %

2023-02-09 08:13:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.5 %

2023-02-09 08:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.1 %

2023-02-09 08:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:13:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 08:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:13:01 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}\text{C}$  , RH : 54.4 %

2023-02-09 08:14:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:14:02 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}$ C , RH : 68.9 %

2023-02-09 08:14:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 08:14:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.0 %

2023-02-09 08:14:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:14:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:14:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 08:14:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.1 %

```
2023-02-09 08:15:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 08:15:01 , modbusTCP , I6-1/S-12 , TEMP : 26.4  $^{\circ}$ C , RH : 68.5 %

2023-02-09 08:15:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 08:15:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 48.0 %

2023-02-09 08:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:15:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:15:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 54.6 %

2023-02-09 08:16:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 08:16:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.3 %

2023-02-09 08:16:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 08:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.0 %

2023-02-09 08:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:16:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 08:16:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 53.9 %

2023-02-09 08:17:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:17:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.0 %

2023-02-09 08:17:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.8 %

2023-02-09 08:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.0 %

2023-02-09 08:17:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:17:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.5 %

2023-02-09 08:17:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 54.6 %

2023-02-09 08:18:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:18:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.7 %

```
2023-02-09 08:18:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %
```

2023-02-09 08:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.1 %

2023-02-09 08:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:18:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 08:18:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 54.7  $^{\circ}$ 

2023-02-09 08:19:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 08:19:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.4 %

2023-02-09 08:19:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 08:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.2 %

2023-02-09 08:19:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:19:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:19:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.5  $^{\circ}$ 

2023-02-09 08:19:02, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.2 %

2023-02-09 08:20:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 08:20:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.2 %

2023-02-09 08:20:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 08:20:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 48.3 %

2023-02-09 08:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:20:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4 °C , RH : 58.7 %

2023-02-09 08:20:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:20:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.2 %

2023-02-09 08:21:01 , modbusTCP , I6-1 , TEMP : 3.4  $^{\circ}\text{C}$ 

2023-02-09 08:21:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.0 %

2023-02-09 08:21:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 08:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.5 %

```
2023-02-09 08:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 08:21:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:21:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.4 %

2023-02-09 08:22:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:22:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 66.8 %

2023-02-09 08:22:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 08:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.6 %

2023-02-09 08:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:22:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:22:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:22:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.4 %

2023-02-09 08:23:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 08:23:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.6 %

2023-02-09 08:23:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.3 %

2023-02-09 08:23:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.7 %

2023-02-09 08:23:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:23:02 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 08:23:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:23:02, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.4 %

2023-02-09 08:24:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:24:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.3 %

2023-02-09 08:24:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.4 %

2023-02-09 08:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.7 %

2023-02-09 08:24:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 08:24:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

```
2023-02-09 08:24:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 08:24:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.5 %

2023-02-09 08:25:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:25:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.2 %

2023-02-09 08:25:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 08:25:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}$ C , RH : 48.7 %

2023-02-09 08:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:25:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:25:01, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 56.8 %

2023-02-09 08:26:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:26:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

2023-02-09 08:26:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.7 %

2023-02-09 08:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.2 %

2023-02-09 08:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:26:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:26:01 , modbusTCP , I6-2/S-10 , TEMP : 22.5  $^{\circ}\text{C}$  , RH : 56.0 %

2023-02-09 08:27:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 08:27:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}$ C , RH : 65.8  $^{\circ}$ 

2023-02-09 08:27:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-09 08:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.1 %

2023-02-09 08:27:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:27:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:27:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:27:01, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 57.4 %

```
2023-02-09 08:28:02, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 08:28:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.6 %

2023-02-09 08:28:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 08:28:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.4 %

2023-02-09 08:28:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:28:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:28:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:28:02, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 56.1 %

2023-02-09 08:29:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:29:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 65.5 %

2023-02-09 08:29:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %

2023-02-09 08:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.9 %

2023-02-09 08:29:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:29:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:29:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:29:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 56.2 %

2023-02-09 08:30:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:30:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.4 %

2023-02-09 08:30:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 08:30:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 49.0 %

2023-02-09 08:30:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:30:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:30:01, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 57.8 %

2023-02-09 08:31:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:31:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.2 %

```
2023-02-09 08:31:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %
```

2023-02-09 08:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 49.0 %

2023-02-09 08:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:31:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:31:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:31:01 , modbusTCP , I6-2/S-10 , TEMP : 22.5  $^{\circ}$ C , RH : 56.4  $^{\circ}$ 

2023-02-09 08:32:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 08:32:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:32:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.7 %

2023-02-09 08:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.9 %

2023-02-09 08:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:32:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 08:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:32:01, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 57.1 %

2023-02-09 08:33:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:33:02, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 66.0 %

2023-02-09 08:33:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %

2023-02-09 08:33:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 48.8 %

2023-02-09 08:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:33:02 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 08:33:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:33:02, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 57.0 %

2023-02-09 08:34:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 08:34:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.4 %

2023-02-09 08:34:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 08:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.7 %

```
2023-02-09 08:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 08:34:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:34:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:34:01, modbusTCP, I6-2/S-10, TEMP: 22.5 °C, RH: 56.7 %

2023-02-09 08:35:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 08:35:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 66.6 %

2023-02-09 08:35:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 08:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.6 %

2023-02-09 08:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:35:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:35:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:35:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 56.6 %

2023-02-09 08:36:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:36:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.9 %

2023-02-09 08:36:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 08:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.4 %

2023-02-09 08:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:36:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 08:36:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:36:01 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}\text{C}$  , RH : 56.5 %

2023-02-09 08:37:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:37:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 67.1 %

2023-02-09 08:37:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 08:37:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.6 %

2023-02-09 08:37:02 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 08:37:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

```
2023-02-09 08:37:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 08:37:02 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}$ C , RH : 56.4  $^{\circ}$ 

2023-02-09 08:38:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 08:38:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.4 %

2023-02-09 08:38:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 08:38:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 47.5 %

2023-02-09 08:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:38:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 08:38:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:38:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 56.3 %

2023-02-09 08:39:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 08:39:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 67.6 %

2023-02-09 08:39:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 08:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.2 %

2023-02-09 08:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:39:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:39:01 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}\text{C}$  , RH : 56.1 %

2023-02-09 08:40:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:40:01 , modbusTCP , I6-1/S-12 , TEMP : 27.4  $^{\circ}$ C , RH : 67.8  $^{\circ}$ 

2023-02-09 08:40:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 08:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.8 %

2023-02-09 08:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:40:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:40:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:40:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 56.0 %

```
2023-02-09 08:41:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 08:41:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.1 %

2023-02-09 08:41:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 08:41:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 49.0 %

2023-02-09 08:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:41:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:41:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:41:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.9 %

2023-02-09 08:42:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 08:42:02, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.3 %

2023-02-09 08:42:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 08:42:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.0 %

2023-02-09 08:42:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:42:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:42:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 08:42:02, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.8 %

2023-02-09 08:43:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:43:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.5 %

2023-02-09 08:43:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 08:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.0 %

2023-02-09 08:43:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:43:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:43:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 08:43:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 55.6 %

2023-02-09 08:44:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:44:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 68.7 %

```
2023-02-09 08:44:01, modbusTCP, I6-1/S-13, TEMP: 30.3 °C, RH: 61.3 %
```

2023-02-09 08:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.9 %

2023-02-09 08:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:44:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}$ C , RH : 58.7 %

2023-02-09 08:44:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:44:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.5 %

2023-02-09 08:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:45:01 , modbusTCP , I6-1/S-12 , TEMP : 27.4  $^{\circ}\text{C}$  , RH : 68.9 %

2023-02-09 08:45:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}$ C , RH : 61.1 %

2023-02-09 08:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.8 %

2023-02-09 08:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:45:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:45:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:45:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.4 %

2023-02-09 08:46:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 08:46:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.1 %

2023-02-09 08:46:01, modbusTCP, I6-1/S-13, TEMP: 30.3 °C, RH: 60.9 %

2023-02-09 08:46:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.7 %

2023-02-09 08:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:46:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 08:46:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 08:46:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.3 %

2023-02-09 08:47:01 , modbusTCP , I6-1 , TEMP : 3.9  $^{\circ}\text{C}$ 

2023-02-09 08:47:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 69.4 %

2023-02-09 08:47:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.7 %

2023-02-09 08:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.0 %

```
2023-02-09 08:47:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 08:47:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:47:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.2 %

2023-02-09 08:48:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 08:48:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.6 %

2023-02-09 08:48:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.6 %

2023-02-09 08:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.6 %

2023-02-09 08:48:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:48:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:48:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:48:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.1 %

2023-02-09 08:49:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:49:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 69.8 %

2023-02-09 08:49:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 08:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.5 %

2023-02-09 08:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:49:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 08:49:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 08:49:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.0 %

2023-02-09 08:50:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 08:50:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.1 %

2023-02-09 08:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 08:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.5 %

2023-02-09 08:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:50:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

```
2023-02-09 08:50:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 08:50:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.8 %

2023-02-09 08:51:02, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 08:51:02, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 70.4 %

2023-02-09 08:51:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 08:51:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 48.5 %

2023-02-09 08:51:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:51:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:51:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 08:51:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.8 %

2023-02-09 08:52:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 08:52:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 70.6 %

2023-02-09 08:52:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.7 %

2023-02-09 08:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.2 %

2023-02-09 08:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:52:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:52:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 54.7 %

2023-02-09 08:53:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:53:01 , modbusTCP , I6-1/S-12 , TEMP : 27.3  $^{\circ}$ C , RH : 70.9 %

2023-02-09 08:53:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 08:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.2 %

2023-02-09 08:53:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:53:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 08:53:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:53:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.7 %

```
2023-02-09 08:54:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 08:54:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.2 %

2023-02-09 08:54:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 08:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.2 %

2023-02-09 08:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:54:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 08:54:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:54:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.4 %

2023-02-09 08:55:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 08:55:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 71.4 %

2023-02-09 08:55:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-09 08:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.1 %

2023-02-09 08:55:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:55:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.7 %

2023-02-09 08:55:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 08:55:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.5 %

2023-02-09 08:56:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 08:56:02 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}\text{C}$  , RH : 71.7 %

2023-02-09 08:56:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 08:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.9 %

2023-02-09 08:56:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 08:56:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:56:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:56:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.7 %

2023-02-09 08:57:01 , modbusTCP , I6-1 , TEMP : 3.5 °C

2023-02-09 08:57:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 72.0 %

```
2023-02-09 08:57:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %
```

2023-02-09 08:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.7 %

2023-02-09 08:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:57:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 08:57:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 08:57:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.3 %

2023-02-09 08:58:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 08:58:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 72.2 %

2023-02-09 08:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.5  $^{\circ}$ 

2023-02-09 08:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.6 %

2023-02-09 08:58:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:58:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 08:58:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:58:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.3 %

2023-02-09 08:59:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 08:59:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 72.5 %

2023-02-09 08:59:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.2 %

2023-02-09 08:59:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6  $^{\circ}$ C , RH : 48.5 %

2023-02-09 08:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 08:59:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 08:59:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 08:59:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.3 %

2023-02-09 09:00:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 09:00:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 72.8 %

2023-02-09 09:00:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 09:00:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 47.9 %

```
2023-02-09 09:00:02, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 09:00:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:00:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:00:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 54.0 %

2023-02-09 09:01:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 09:01:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.1 %

2023-02-09 09:01:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 09:01:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 47.6 %

2023-02-09 09:01:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:01:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:01:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:01:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.9 %

2023-02-09 09:02:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 09:02:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.4 %

2023-02-09 09:02:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 09:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 47.2 %

2023-02-09 09:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:02:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 09:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 09:02:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.9 %

2023-02-09 09:03:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 09:03:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 73.8 %

2023-02-09 09:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 09:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.6 %

2023-02-09 09:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:03:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

```
2023-02-09 09:03:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 09:03:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.8 %

2023-02-09 09:04:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:04:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 74.1 %

2023-02-09 09:04:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 09:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.0 %

2023-02-09 09:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:04:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:04:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:04:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.7 %

2023-02-09 09:05:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 09:05:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.3 %

2023-02-09 09:05:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 09:05:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.2 %

2023-02-09 09:05:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:05:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:05:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:05:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.6 %

2023-02-09 09:06:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 09:06:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 74.7 %

2023-02-09 09:06:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 09:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.1 %

2023-02-09 09:06:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:06:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:06:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:06:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

```
2023-02-09 09:07:01, modbusTCP, I6-1, TEMP: 3.4 °C
```

2023-02-09 09:07:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 75.0 %

2023-02-09 09:07:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 09:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.0 %

2023-02-09 09:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:07:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:07:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.7 %

2023-02-09 09:08:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 09:08:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 75.2 %

2023-02-09 09:08:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.2 %

2023-02-09 09:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 47.8 %

2023-02-09 09:08:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:08:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:08:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.7 %

2023-02-09 09:08:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

2023-02-09 09:09:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 09:09:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}\text{C}$  , RH : 75.5 %

2023-02-09 09:09:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 09:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 47.5 %

2023-02-09 09:09:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:09:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:09:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:09:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

2023-02-09 09:10:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 09:10:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 75.7 %

```
2023-02-09 09:10:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %
```

2023-02-09 09:10:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 47.4 %

2023-02-09 09:10:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:10:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 09:10:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:10:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.5 %

2023-02-09 09:11:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:11:01 , modbusTCP , I6-1/S-12 , TEMP : 26.0  $^{\circ}\text{C}$  , RH : 75.9 %

2023-02-09 09:11:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 09:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 47.4 %

2023-02-09 09:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:11:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 09:11:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:11:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.3 %

2023-02-09 09:12:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 09:12:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.2 %

2023-02-09 09:12:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 09:12:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3 °C , RH : 47.2 %

2023-02-09 09:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:12:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.6 %

2023-02-09 09:12:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:12:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 09:13:01 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 09:13:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.3 %

2023-02-09 09:13:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 09:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 47.1 %

```
2023-02-09 09:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 09:13:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 09:13:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:13:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 09:14:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 09:14:02, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.5 %

2023-02-09 09:14:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 09:14:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 47.1 %

2023-02-09 09:14:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:14:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.6 %

2023-02-09 09:14:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 09:14:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 09:15:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 09:15:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.7 %

2023-02-09 09:15:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 09:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 47.1 %

2023-02-09 09:15:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:15:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:15:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 09:15:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 53.1 %

2023-02-09 09:16:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:16:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.8 %

2023-02-09 09:16:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 09:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 47.1 %

2023-02-09 09:16:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:16:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

```
2023-02-09 09:16:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 09:16:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 09:17:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 09:17:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7  $^{\circ}\text{C}$  , RH : 76.9 %

2023-02-09 09:17:01, modbusTCP, I6-1/S-13, TEMP: 30.3 °C, RH: 61.1 %

2023-02-09 09:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.2 %

2023-02-09 09:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:17:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 09:17:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.3 %

2023-02-09 09:18:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 09:18:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.0 %

2023-02-09 09:18:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 60.9 %

2023-02-09 09:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.2 %

2023-02-09 09:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:18:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:18:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:18:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.1 %

2023-02-09 09:19:02, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 09:19:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.1 %

2023-02-09 09:19:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.8 %

2023-02-09 09:19:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.1 %

2023-02-09 09:19:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:19:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:19:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 09:19:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.0 %

```
2023-02-09 09:20:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 09:20:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-09 09:20:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.8 %

2023-02-09 09:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 47.1 %

2023-02-09 09:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:20:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:20:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.1 %

2023-02-09 09:21:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 09:21:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-09 09:21:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.8 %

2023-02-09 09:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 47.2 %

2023-02-09 09:21:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:21:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:21:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:21:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.0 %

2023-02-09 09:22:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 09:22:01 , modbusTCP , I6-1/S-12 , TEMP : 25.4  $^{\circ}\text{C}$  , RH : 77.0 %

2023-02-09 09:22:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 09:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 47.2 %

2023-02-09 09:22:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:22:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:22:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.9 %

2023-02-09 09:23:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:23:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.1 %

```
2023-02-09 09:23:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %
```

2023-02-09 09:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 47.3 %

2023-02-09 09:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:23:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:23:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:23:02 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 52.9  $^{\circ}$ 

2023-02-09 09:24:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 09:24:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:24:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 09:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.5 %

2023-02-09 09:24:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:24:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:24:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 09:24:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.9 %

2023-02-09 09:25:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 09:25:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:25:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 09:25:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.1  $^{\circ}\text{C}$  , RH : 47.6 %

2023-02-09 09:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:25:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 09:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:25:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 09:26:01 , modbusTCP , I6-1 , TEMP : 4.3  $^{\circ}\text{C}$ 

2023-02-09 09:26:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:26:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 09:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.8 %

```
2023-02-09 09:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 09:26:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:26:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:26:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 09:27:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:27:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.2 %

2023-02-09 09:27:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 47.9 %

2023-02-09 09:27:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:27:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:27:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:27:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 09:28:02, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 09:28:02, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:28:02 , modbusTCP , I6-1/S-13 , TEMP :  $30.0 \, ^{\circ}\text{C}$  , RH :  $62.2 \, \%$ 

2023-02-09 09:28:02, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 47.9 %

2023-02-09 09:28:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:28:02 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 09:28:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:28:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.7 %

2023-02-09 09:29:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 09:29:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 09:29:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 09:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.1 %

2023-02-09 09:29:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 09:29:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

```
2023-02-09 09:29:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %
```

2023-02-09 09:29:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.7 %

2023-02-09 09:30:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 09:30:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.2 %

2023-02-09 09:30:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.5 %

2023-02-09 09:30:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 48.2 %

2023-02-09 09:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:30:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 09:30:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 09:30:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.5 %

2023-02-09 09:31:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 09:31:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 09:31:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.1 %

2023-02-09 09:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.2 %

2023-02-09 09:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:31:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:31:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.6 %

2023-02-09 09:32:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 09:32:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}$ C , RH : 77.0 %

2023-02-09 09:32:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 09:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 48.3 %

2023-02-09 09:32:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:32:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:32:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 09:32:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.6 %

```
2023-02-09 09:33:02, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 09:33:02, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.9 %

2023-02-09 09:33:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.7 %

2023-02-09 09:33:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 48.6 %

2023-02-09 09:33:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:33:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.7 %

2023-02-09 09:33:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:33:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.5 %

2023-02-09 09:34:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 09:34:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 76.8 %

2023-02-09 09:34:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 09:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.6 %

2023-02-09 09:34:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:34:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:34:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:34:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.5 %

2023-02-09 09:35:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 09:35:01 , modbusTCP , I6-1/S-12 , TEMP : 25.7  $^{\circ}\text{C}$  , RH : 76.7 %

2023-02-09 09:35:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 09:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.6 %

2023-02-09 09:35:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:35:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 09:35:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.2 %

2023-02-09 09:36:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-09 09:36:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.2 %

```
2023-02-09 09:36:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.5 %
```

2023-02-09 09:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.7 %

2023-02-09 09:36:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:36:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:36:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:36:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.0 %

2023-02-09 09:37:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-09 09:37:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 74.8 %

2023-02-09 09:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.7 %

2023-02-09 09:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.0 °C, RH: 48.5 %

2023-02-09 09:37:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:37:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:37:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 09:37:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.0 %

2023-02-09 09:38:01, modbusTCP, I6-1, TEMP: 5.3 °C

2023-02-09 09:38:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 73.9 %

2023-02-09 09:38:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.9 %

2023-02-09 09:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.4 %

2023-02-09 09:38:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:38:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 09:38:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:38:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 09:39:01 , modbusTCP , I6-1 , TEMP : 5.5  $^{\circ}\text{C}$ 

2023-02-09 09:39:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 73.1 %

2023-02-09 09:39:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 09:39:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 47.7 %

```
2023-02-09 09:39:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 09:39:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:39:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:39:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 52.8  $^{\circ}$ 

2023-02-09 09:40:01, modbusTCP, I6-1, TEMP: 5.6 °C

2023-02-09 09:40:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 72.5 %

2023-02-09 09:40:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 09:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 48.5 %

2023-02-09 09:40:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:40:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:40:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 09:41:01, modbusTCP, I6-1, TEMP: 5.9 °C

2023-02-09 09:41:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 71.9 %

2023-02-09 09:41:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 09:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 49.1 %

2023-02-09 09:41:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:41:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 09:41:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 09:41:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 54.4 %

2023-02-09 09:42:02, modbusTCP, I6-1, TEMP: 6.0 °C

2023-02-09 09:42:02, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 71.5 %

2023-02-09 09:42:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 09:42:02, modbusTCP, I6-1/S-16-2, TEMP: 20.1 °C, RH: 49.1 %

2023-02-09 09:42:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:42:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

```
2023-02-09 09:42:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %
```

2023-02-09 09:42:02 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 53.7  $^{\circ}$ 

2023-02-09 09:43:01, modbusTCP, I6-1, TEMP: 6.1 °C

2023-02-09 09:43:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 71.3 %

2023-02-09 09:43:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.4 %

2023-02-09 09:43:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.2  $^{\circ}$ C , RH : 49.1 %

2023-02-09 09:43:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:43:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:43:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.5 %

2023-02-09 09:44:01, modbusTCP, I6-1, TEMP: 6.4 °C

2023-02-09 09:44:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 71.0 %

2023-02-09 09:44:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.6 %

2023-02-09 09:44:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 49.0 %

2023-02-09 09:44:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:44:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:44:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 09:44:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 54.1 %

2023-02-09 09:45:01, modbusTCP, I6-1, TEMP: 6.3 °C

2023-02-09 09:45:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 70.7 %

2023-02-09 09:45:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 09:45:01, modbusTCP, I6-1/S-16-2, TEMP: 20.2 °C, RH: 49.0 %

2023-02-09 09:45:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:45:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 09:45:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.5 %

2023-02-09 09:45:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.6 %

```
2023-02-09 09:46:01, modbusTCP, I6-1, TEMP: 6.0 °C
```

2023-02-09 09:46:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.4 %

2023-02-09 09:46:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 09:46:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 48.8 %

2023-02-09 09:46:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:46:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:46:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.1 %

2023-02-09 09:47:02, modbusTCP, I6-1, TEMP: 5.8 °C

2023-02-09 09:47:02, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.1 %

2023-02-09 09:47:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 09:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.6 %

2023-02-09 09:47:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:47:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:47:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:47:02, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 54.9 %

2023-02-09 09:48:01, modbusTCP, I6-1, TEMP: 5.5 °C

2023-02-09 09:48:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 69.8 %

2023-02-09 09:48:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.7 %

2023-02-09 09:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.5 %

2023-02-09 09:48:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:48:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:48:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:48:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.9 %

2023-02-09 09:49:01, modbusTCP, I6-1, TEMP: 5.3 °C

2023-02-09 09:49:01, modbusTCP, I6-1/S-12, TEMP: 26.1 °C, RH: 69.5 %

```
2023-02-09 09:49:01, modbusTCP, I6-1/S-13, TEMP: 30.3 °C, RH: 61.5 %
```

2023-02-09 09:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.4 %

2023-02-09 09:49:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:49:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}$ C , RH : 58.7 %

2023-02-09 09:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:49:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 54.9  $^{\circ}$ 

2023-02-09 09:50:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-09 09:50:01 , modbusTCP , I6-1/S-12 , TEMP : 26.2  $^{\circ}\text{C}$  , RH : 69.2 %

2023-02-09 09:50:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}$ C , RH : 61.2 %

2023-02-09 09:50:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.3 %

2023-02-09 09:50:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:50:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:50:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 09:50:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.0 %

2023-02-09 09:51:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 09:51:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 68.8 %

2023-02-09 09:51:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 09:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.5 %

2023-02-09 09:51:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:51:02 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.7 %

2023-02-09 09:51:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 09:51:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.0 %

2023-02-09 09:52:01 , modbusTCP , I6-1 , TEMP : 4.3  $^{\circ}\text{C}$ 

2023-02-09 09:52:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 68.5 %

2023-02-09 09:52:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 09:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.4 %

```
2023-02-09 09:52:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 09:52:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:52:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 09:52:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 55.0 %

2023-02-09 09:53:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 09:53:01, modbusTCP, I6-1/S-12, TEMP: 26.3 °C, RH: 68.2 %

2023-02-09 09:53:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 09:53:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 47.5 %

2023-02-09 09:53:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:53:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:53:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 09:53:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.9 %

2023-02-09 09:54:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 09:54:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 67.9 %

2023-02-09 09:54:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.8 %

2023-02-09 09:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.3 %

2023-02-09 09:54:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:54:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:54:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:54:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 54.9 %

2023-02-09 09:55:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 09:55:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 67.7 %

2023-02-09 09:55:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 09:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.9 %

2023-02-09 09:55:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 09:55:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

```
2023-02-09 09:55:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %
```

2023-02-09 09:55:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.8 %

2023-02-09 09:56:02, modbusTCP, I6-1, TEMP: 4.8 °C

2023-02-09 09:56:02, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.4 %

2023-02-09 09:56:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-09 09:56:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 49.3 %

2023-02-09 09:56:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:56:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:56:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}$ C , RH : 65.7 %

2023-02-09 09:56:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.7 %

2023-02-09 09:57:01, modbusTCP, I6-1, TEMP: 4.9 °C

2023-02-09 09:57:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 67.1 %

2023-02-09 09:57:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.7 %

2023-02-09 09:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 49.5 %

2023-02-09 09:57:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:57:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:57:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:57:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 54.5 %

2023-02-09 09:58:01, modbusTCP, I6-1, TEMP: 5.0 °C

2023-02-09 09:58:01, modbusTCP, I6-1/S-12, TEMP: 26.6 °C, RH: 66.8 %

2023-02-09 09:58:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 09:58:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 49.1 %

2023-02-09 09:58:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 09:58:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:58:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 09:58:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.6 %

```
2023-02-09 09:59:01, modbusTCP, I6-1, TEMP: 4.9 °C
```

2023-02-09 09:59:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.6 %

2023-02-09 09:59:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 09:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.9 %

2023-02-09 09:59:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 09:59:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 09:59:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 09:59:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.6 %

2023-02-09 10:00:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:00:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.4 %

2023-02-09 10:00:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 10:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.7 %

2023-02-09 10:00:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:00:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:00:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:00:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.4 %

2023-02-09 10:01:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:01:02, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.2 %

2023-02-09 10:01:02, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.3 %

2023-02-09 10:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.6 %

2023-02-09 10:01:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 10:01:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:01:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 10:01:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.2 %

2023-02-09 10:02:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:02:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.0 %

```
2023-02-09 10:02:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %
```

2023-02-09 10:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.5 %

2023-02-09 10:02:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:02:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:02:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 10:02:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.3 %

2023-02-09 10:03:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 10:03:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}\text{C}$  , RH : 65.8 %

2023-02-09 10:03:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.6 %

2023-02-09 10:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.5 %

2023-02-09 10:03:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:03:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:03:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.5  $^{\circ}$ 

2023-02-09 10:03:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 54.2 %

2023-02-09 10:04:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 10:04:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.6 %

2023-02-09 10:04:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 10:04:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.2 %

2023-02-09 10:04:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:04:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 10:04:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.5 %

2023-02-09 10:04:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 54.2 %

2023-02-09 10:05:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 10:05:01, modbusTCP, I6-1/S-12, TEMP: 26.9 °C, RH: 65.4 %

2023-02-09 10:05:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.1 %

2023-02-09 10:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.7 %

```
2023-02-09 10:05:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 10:05:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:05:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 10:05:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 54.1 %

2023-02-09 10:06:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 10:06:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.3 %

2023-02-09 10:06:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 10:06:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.0 %

2023-02-09 10:06:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:06:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:06:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 10:06:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.9 %

2023-02-09 10:07:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:07:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.0 %

2023-02-09 10:07:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.4 %

2023-02-09 10:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.6 %

2023-02-09 10:07:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:07:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:07:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:07:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 53.8 %

2023-02-09 10:08:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:08:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 65.4 %

2023-02-09 10:08:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 10:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.8 %

2023-02-09 10:08:01 , modbusTCP , I6-2 , TEMP : 6528.6 °C

2023-02-09 10:08:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

```
2023-02-09 10:08:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %
```

2023-02-09 10:08:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.7 %

2023-02-09 10:09:01, modbusTCP, I6-1, TEMP: 4.6 °C

2023-02-09 10:09:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 65.8 %

2023-02-09 10:09:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 10:09:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 48.8 %

2023-02-09 10:09:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:09:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:09:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6 %

2023-02-09 10:09:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.9 %

2023-02-09 10:10:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:10:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 66.2 %

2023-02-09 10:10:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.7 %

2023-02-09 10:10:02, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.9 %

2023-02-09 10:10:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:10:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:10:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:10:02 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.8 %

2023-02-09 10:11:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:11:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 66.4 %

2023-02-09 10:11:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 10:11:01, modbusTCP, I6-1/S-16-2, TEMP: 20.3 °C, RH: 48.8 %

2023-02-09 10:11:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:11:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:11:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 10:11:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.8 %

```
2023-02-09 10:12:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 10:12:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 66.7 %

2023-02-09 10:12:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 10:12:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.3  $^{\circ}$ C , RH : 48.8 %

2023-02-09 10:12:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:12:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:12:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:12:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.7 %

2023-02-09 10:13:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 10:13:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 67.0 %

2023-02-09 10:13:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 10:13:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.8 %

2023-02-09 10:13:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:13:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:13:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:13:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.7 %

2023-02-09 10:14:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:14:01 , modbusTCP , I6-1/S-12 , TEMP : 27.5  $^{\circ}\text{C}$  , RH : 67.3 %

2023-02-09 10:14:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 10:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.7 %

2023-02-09 10:14:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 10:14:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:14:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 10:14:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.3 %

2023-02-09 10:15:02 , modbusTCP , I6-1 , TEMP : 3.6  $^{\circ}\text{C}$ 

2023-02-09 10:15:02, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 67.5 %

```
2023-02-09 10:15:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %
```

2023-02-09 10:15:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.7 %

2023-02-09 10:15:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:15:02 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 10:15:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:15:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.5 %

2023-02-09 10:16:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 10:16:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 67.7 %

2023-02-09 10:16:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.7 %

2023-02-09 10:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.7 %

2023-02-09 10:16:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:16:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:16:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:16:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.5 %

2023-02-09 10:17:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:17:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 67.9 %

2023-02-09 10:17:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 10:17:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 48.3 %

2023-02-09 10:17:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:17:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 10:17:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 10:17:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.3 %

2023-02-09 10:18:01 , modbusTCP , I6-1 , TEMP : 4.1  $^{\circ}\text{C}$ 

2023-02-09 10:18:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 68.2 %

2023-02-09 10:18:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 10:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 47.8 %

```
2023-02-09 10:18:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 10:18:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:18:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 10:18:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.4 %

2023-02-09 10:19:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:19:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 68.4 %

2023-02-09 10:19:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 10:19:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 47.7 %

2023-02-09 10:19:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:19:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:19:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:19:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.1 %

2023-02-09 10:20:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:20:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 68.6 %

2023-02-09 10:20:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}$ C , RH : 61.5 %

2023-02-09 10:20:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 48.3 %

2023-02-09 10:20:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:20:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:20:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:20:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 53.2 %

2023-02-09 10:21:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:21:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 68.8 %

2023-02-09 10:21:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}\text{C}$  , RH : 61.2 %

2023-02-09 10:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.5 %

2023-02-09 10:21:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 10:21:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

```
2023-02-09 10:21:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %
```

2023-02-09 10:21:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.3 %

2023-02-09 10:22:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 10:22:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.1 %

2023-02-09 10:22:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 10:22:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.8 %

2023-02-09 10:22:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:22:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:22:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 10:22:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.1 %

2023-02-09 10:23:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:23:01 , modbusTCP , I6-1/S-12 , TEMP : 27.7  $^{\circ}\text{C}$  , RH : 69.3 %

2023-02-09 10:23:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 60.9 %

2023-02-09 10:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.8 %

2023-02-09 10:23:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:23:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 10:23:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:23:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 53.1 %

2023-02-09 10:24:02, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 10:24:02 , modbusTCP , I6-1/S-12 , TEMP : 27.7  $^{\circ}\text{C}$  , RH : 69.5 %

2023-02-09 10:24:02 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 10:24:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.8 %

2023-02-09 10:24:02 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 10:24:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.7 %

2023-02-09 10:24:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.5 %

2023-02-09 10:24:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.9 %

```
2023-02-09 10:25:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 10:25:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.8 %

2023-02-09 10:25:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 60.9 %

2023-02-09 10:25:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.7 %

2023-02-09 10:25:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:25:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:25:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:25:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.0 %

2023-02-09 10:26:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:26:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 70.1 %

2023-02-09 10:26:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 10:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.5 %

2023-02-09 10:26:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:26:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:26:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:26:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.0 %

2023-02-09 10:27:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 10:27:01 , modbusTCP , I6-1/S-12 , TEMP : 27.6  $^{\circ}\text{C}$  , RH : 70.3 %

2023-02-09 10:27:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.4 %

2023-02-09 10:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.8 %

2023-02-09 10:27:01 , modbusTCP , I6-2 , TEMP : 6528.6  $^{\circ}\text{C}$ 

2023-02-09 10:27:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:27:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 10:27:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.7 %

2023-02-09 10:28:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 10:28:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 70.6 %

```
2023-02-09 10:28:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %
```

2023-02-09 10:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.5 %

2023-02-09 10:28:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:28:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}$ C , RH : 58.8 %

2023-02-09 10:28:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:28:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.4 %

2023-02-09 10:29:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:29:02, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 70.8 %

2023-02-09 10:29:02 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 61.9 %

2023-02-09 10:29:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.4 %

2023-02-09 10:29:02, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:29:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:29:02, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:29:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.4 %

2023-02-09 10:30:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 10:30:01, modbusTCP, I6-1/S-12, TEMP: 27.5 °C, RH: 71.1 %

2023-02-09 10:30:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 10:30:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 47.7 %

2023-02-09 10:30:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:30:01 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.8 %

2023-02-09 10:30:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 10:30:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 54.3  $^{\circ}$ 

2023-02-09 10:31:01 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 10:31:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 71.4 %

2023-02-09 10:31:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 10:31:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.6 %

```
2023-02-09 10:31:01, modbusTCP, I6-2, TEMP: 6528.6 °C
```

2023-02-09 10:31:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 10:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 10:31:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 54.6 %

2023-02-09 10:32:01, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:32:01, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 71.8 %

2023-02-09 10:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 10:32:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.1 %

2023-02-09 10:32:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:32:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:32:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 10:32:01, modbusTCP, I6-2/S-10, TEMP: 22.6 °C, RH: 54.6 %

2023-02-09 10:33:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 10:33:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 72.0 %

2023-02-09 10:33:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.8 %

2023-02-09 10:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.4 %

2023-02-09 10:33:01, modbusTCP, I6-2, TEMP: 6528.6 °C

2023-02-09 10:33:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 10:33:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 10:33:01 , modbusTCP , I6-2/S-10 , TEMP : 22.6  $^{\circ}\text{C}$  , RH : 54.4 %

2023-02-09 10:34:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:34:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 72.3 %

2023-02-09 10:34:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 10:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.3 %

2023-02-09 10:35:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 10:35:01 , modbusTCP , I6-1/S-12 , TEMP : 27.1  $^{\circ}\text{C}$  , RH : 72.6 %

```
2023-02-09 10:35:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %
```

2023-02-09 10:35:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.2 %

2023-02-09 10:36:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:36:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 73.0 %

2023-02-09 10:36:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 10:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.0 %

2023-02-09 10:37:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:37:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 73.3 %

2023-02-09 10:37:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.4 %

2023-02-09 10:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.0 %

2023-02-09 10:38:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:38:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 73.7 %

2023-02-09 10:38:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.6  $^{\circ}$ 

2023-02-09 10:38:02, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.7 %

2023-02-09 10:39:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 10:39:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 74.0 %

2023-02-09 10:39:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 10:39:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.7 %

2023-02-09 10:40:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 10:40:01 , modbusTCP , I6-1/S-12 , TEMP : 26.6  $^{\circ}$ C , RH : 74.5 %

2023-02-09 10:40:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 10:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.2 %

2023-02-09 10:41:01 , modbusTCP , I6-1 , TEMP : 4.0  $^{\circ}\text{C}$ 

2023-02-09 10:41:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 74.8 %

2023-02-09 10:41:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 10:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.8 %

```
2023-02-09 10:42:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 10:42:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 75.1 %

2023-02-09 10:42:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.4 %

2023-02-09 10:42:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 47.6 %

2023-02-09 10:43:02, modbusTCP, I6-1, TEMP: 4.5 °C

2023-02-09 10:43:02 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}$ C , RH : 75.5 %

2023-02-09 10:43:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.2 %

2023-02-09 10:43:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.0  $^{\circ}$ 

2023-02-09 10:44:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:44:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 75.7 %

2023-02-09 10:44:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 10:44:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 49.1 %

2023-02-09 10:46:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:46:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 76.4 %

2023-02-09 10:46:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.4 %

2023-02-09 10:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.5 %

2023-02-09 10:47:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 10:47:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 76.6 %

2023-02-09 10:47:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 10:47:02, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.6 %

2023-02-09 10:48:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:48:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 76.7 %

2023-02-09 10:48:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 10:48:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.4 %

2023-02-09 10:49:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:49:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 76.9 %

```
2023-02-09 10:49:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %
```

2023-02-09 10:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 49.4 %

2023-02-09 10:50:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:50:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.1 %

2023-02-09 10:50:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.8 %

2023-02-09 10:50:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 49.3 %

2023-02-09 10:51:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 10:51:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 77.2 %

2023-02-09 10:51:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.6  $^{\circ}$ 

2023-02-09 10:51:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.9 %

2023-02-09 10:52:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:52:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.3 %

2023-02-09 10:52:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}$ C , RH : 61.4 %

2023-02-09 10:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.2 %

2023-02-09 10:53:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 10:53:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.4 %

2023-02-09 10:53:01, modbusTCP, I6-1/S-13, TEMP: 30.3 °C, RH: 61.2 %

2023-02-09 10:53:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}$ C , RH : 48.1 %

2023-02-09 10:54:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 10:54:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.5 %

2023-02-09 10:54:01 , modbusTCP , I6-1/S-13 , TEMP : 30.3  $^{\circ}\text{C}$  , RH : 61.0 %

2023-02-09 10:54:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 47.9 %

2023-02-09 10:55:01 , modbusTCP , I6-1 , TEMP : 4.4  $^{\circ}\text{C}$ 

2023-02-09 10:55:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.6 %

2023-02-09 10:55:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 10:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.1 %

```
2023-02-09 10:56:01, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 10:56:02, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.6 %

2023-02-09 10:56:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 10:56:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 49.3 %

2023-02-09 10:57:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 10:57:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.7 %

2023-02-09 10:57:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.9 %

2023-02-09 10:57:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 50.4  $^{\circ}$ 

2023-02-09 10:58:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 10:58:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.7 %

2023-02-09 10:58:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 10:58:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.4  $^{\circ}$ C , RH : 50.7 %

2023-02-09 10:59:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 10:59:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.8 %

2023-02-09 10:59:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 10:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.4 °C, RH: 50.1 %

2023-02-09 11:00:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:00:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.8 %

2023-02-09 11:00:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 11:00:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.5  $^{\circ}\text{C}$  , RH : 49.6 %

2023-02-09 11:01:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:01:02, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.7 %

2023-02-09 11:01:02 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.1 %

2023-02-09 11:01:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.4 %

2023-02-09 11:02:01 , modbusTCP , I6-1 , TEMP : 3.6  $^{\circ}\text{C}$ 

2023-02-09 11:02:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.7 %

```
2023-02-09 11:02:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %
```

2023-02-09 11:02:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 49.2 %

2023-02-09 11:03:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 11:03:01, modbusTCP, I6-1/S-12, TEMP: 25.2 °C, RH: 77.7 %

2023-02-09 11:03:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 11:03:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 49.0 %

2023-02-09 11:04:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 11:04:01 , modbusTCP , I6-1/S-12 , TEMP : 25.2  $^{\circ}\text{C}$  , RH : 77.7 %

2023-02-09 11:04:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.7 %

2023-02-09 11:04:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 48.6 %

2023-02-09 11:05:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 11:05:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.5 %

2023-02-09 11:05:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}$ C , RH : 61.5 %

2023-02-09 11:05:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 48.0 %

2023-02-09 11:06:02, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 11:06:02, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.4 %

2023-02-09 11:06:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 11:06:02, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 47.6 %

2023-02-09 11:07:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 11:07:01, modbusTCP, I6-1/S-12, TEMP: 25.3 °C, RH: 77.3 %

2023-02-09 11:07:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 11:07:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 47.5 %

2023-02-09 11:08:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 11:08:01, modbusTCP, I6-1/S-12, TEMP: 25.4 °C, RH: 77.2 %

2023-02-09 11:08:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 11:08:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 48.2 %

```
2023-02-09 11:09:01, modbusTCP, I6-1, TEMP: 3.9 °C
```

2023-02-09 11:09:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 77.1 %

2023-02-09 11:09:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.4 %

2023-02-09 11:09:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.2 %

2023-02-09 11:10:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:10:01 , modbusTCP , I6-1/S-12 , TEMP : 25.5  $^{\circ}$ C , RH : 76.8 %

2023-02-09 11:10:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 11:10:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 49.3 %

2023-02-09 11:11:01, modbusTCP, I6-1, TEMP: 3.4 °C

2023-02-09 11:11:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 75.3 %

2023-02-09 11:11:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 11:11:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}$ C , RH : 49.3 %

2023-02-09 11:12:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:12:01, modbusTCP, I6-1/S-12, TEMP: 25.5 °C, RH: 74.3 %

2023-02-09 11:12:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 11:12:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.2 %

2023-02-09 11:13:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:13:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6  $^{\circ}\text{C}$  , RH : 73.4 %

2023-02-09 11:13:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.1 %

2023-02-09 11:13:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 49.1 %

2023-02-09 11:14:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 11:14:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 72.7 %

2023-02-09 11:14:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.3 %

2023-02-09 11:14:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.1 %

2023-02-09 11:15:01 , modbusTCP , I6-1 , TEMP : 4.0 °C

2023-02-09 11:15:01 , modbusTCP , I6-1/S-12 , TEMP : 25.6  $^{\circ}\text{C}$  , RH : 72.0 %

```
2023-02-09 11:15:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %
```

2023-02-09 11:15:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.3 %

2023-02-09 11:16:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 11:16:01, modbusTCP, I6-1/S-12, TEMP: 25.6 °C, RH: 71.6 %

2023-02-09 11:16:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.8 %

2023-02-09 11:16:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.8 %

2023-02-09 11:17:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 11:17:01, modbusTCP, I6-1/S-12, TEMP: 25.7 °C, RH: 71.2 %

2023-02-09 11:17:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.1 %

2023-02-09 11:17:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.7 %

2023-02-09 11:18:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 11:18:01, modbusTCP, I6-1/S-12, TEMP: 25.8 °C, RH: 70.9 %

2023-02-09 11:18:01 , modbusTCP , I6-1/S-13 , TEMP : 29.9  $^{\circ}$ C , RH : 62.2 %

2023-02-09 11:18:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 49.2 %

2023-02-09 11:19:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 11:19:01, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 70.7 %

2023-02-09 11:19:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.3 %

2023-02-09 11:19:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6  $^{\circ}$ C , RH : 49.2 %

2023-02-09 11:20:02, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 11:20:02, modbusTCP, I6-1/S-12, TEMP: 25.9 °C, RH: 70.4 %

2023-02-09 11:20:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.0 %

2023-02-09 11:20:02, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.1 %

2023-02-09 11:21:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 11:21:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 70.1 %

2023-02-09 11:21:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.7 %

2023-02-09 11:21:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.2 %

```
2023-02-09 11:22:01, modbusTCP, I6-1, TEMP: 3.5 °C
```

2023-02-09 11:22:01, modbusTCP, I6-1/S-12, TEMP: 26.0 °C, RH: 69.8 %

2023-02-09 11:22:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 11:22:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.6 %

2023-02-09 11:23:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:23:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.5 %

2023-02-09 11:23:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 11:23:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.7 %

2023-02-09 11:24:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:24:01, modbusTCP, I6-1/S-12, TEMP: 26.2 °C, RH: 69.1 %

2023-02-09 11:24:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 60.8 %

2023-02-09 11:24:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.4 %

2023-02-09 11:24:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:24:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:24:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 11:24:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

2023-02-09 11:25:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 11:25:02 , modbusTCP , I6-1/S-12 , TEMP : 26.3  $^{\circ}\text{C}$  , RH : 68.8 %

2023-02-09 11:25:02, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.0 %

2023-02-09 11:25:02, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.3 %

2023-02-09 11:25:02 , modbusTCP , I6-2 , TEMP : 6353.7  $^{\circ}\text{C}$ 

2023-02-09 11:25:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:25:02 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 11:25:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

2023-02-09 11:26:01 , modbusTCP , I6-1 , TEMP : 3.9 °C

2023-02-09 11:26:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.5 %

```
2023-02-09 11:26:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.3 %
```

2023-02-09 11:26:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.2 %

2023-02-09 11:26:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:26:01 , modbusTCP , I6-2/S-8 , TEMP : 20.4  $^{\circ}$ C , RH : 58.8 %

2023-02-09 11:26:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.7 %

2023-02-09 11:26:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.6 %

2023-02-09 11:27:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 11:27:01, modbusTCP, I6-1/S-12, TEMP: 26.4 °C, RH: 68.1 %

2023-02-09 11:27:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 11:27:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.9 %

2023-02-09 11:28:01, modbusTCP, I6-1, TEMP: 4.3 °C

2023-02-09 11:28:01, modbusTCP, I6-1/S-12, TEMP: 26.5 °C, RH: 67.8 %

2023-02-09 11:28:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}$ C , RH : 61.8 %

2023-02-09 11:28:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 48.1 %

2023-02-09 11:28:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:28:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:28:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 11:28:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 53.7 %

2023-02-09 11:29:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 11:29:01 , modbusTCP , I6-1/S-12 , TEMP : 26.6  $^{\circ}$ C , RH : 67.5 %

2023-02-09 11:29:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 62.0 %

2023-02-09 11:29:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 47.9 %

2023-02-09 11:29:01 , modbusTCP , I6-2 , TEMP : 0.0  $^{\circ}\text{C}$ 

2023-02-09 11:29:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:29:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:29:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.7 %

```
2023-02-09 11:30:02, modbusTCP, I6-1, TEMP: 4.3 °C
```

2023-02-09 11:30:02, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 67.1 %

2023-02-09 11:30:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 62.1 %

2023-02-09 11:30:02, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 47.8 %

2023-02-09 11:30:02, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:30:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:30:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:30:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.5 %

2023-02-09 11:31:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 11:31:01, modbusTCP, I6-1/S-12, TEMP: 26.7 °C, RH: 66.9 %

2023-02-09 11:31:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.9 %

2023-02-09 11:31:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}$ C , RH : 48.4 %

2023-02-09 11:31:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:31:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:31:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 11:31:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.5 %

2023-02-09 11:32:01, modbusTCP, I6-1, TEMP: 3.9 °C

2023-02-09 11:32:01 , modbusTCP , I6-1/S-12 , TEMP : 26.8  $^{\circ}\text{C}$  , RH : 66.6 %

2023-02-09 11:32:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.7 %

2023-02-09 11:32:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 49.3 %

2023-02-09 11:32:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:32:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:32:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 11:32:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.4 %

2023-02-09 11:33:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 11:33:01, modbusTCP, I6-1/S-12, TEMP: 26.8 °C, RH: 66.4 %

```
2023-02-09 11:33:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.5 %
```

2023-02-09 11:33:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.6 %

2023-02-09 11:33:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:33:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:33:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:33:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 53.4  $^{\circ}$ 

2023-02-09 11:34:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:34:01 , modbusTCP , I6-1/S-12 , TEMP : 26.9  $^{\circ}\text{C}$  , RH : 66.1 %

2023-02-09 11:34:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 11:34:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.5 %

2023-02-09 11:34:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:34:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:34:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}$ C , RH : 65.6  $^{\circ}$ 

2023-02-09 11:34:02, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 11:35:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:35:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.9 %

2023-02-09 11:35:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.5 %

2023-02-09 11:35:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6  $^{\circ}$ C , RH : 49.9 %

2023-02-09 11:35:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:35:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:35:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:35:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 53.2 %

2023-02-09 11:36:01, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 11:36:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.7 %

2023-02-09 11:36:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 61.6 %

2023-02-09 11:36:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.8 %

```
2023-02-09 11:36:01, modbusTCP, I6-2, TEMP: 0.0 °C
```

2023-02-09 11:36:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:36:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:36:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.2 %

2023-02-09 11:37:01, modbusTCP, I6-1, TEMP: 3.8 °C

2023-02-09 11:37:01, modbusTCP, I6-1/S-12, TEMP: 27.0 °C, RH: 65.5 %

2023-02-09 11:37:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.7 %

2023-02-09 11:37:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 49.5 %

2023-02-09 11:37:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:37:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:37:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 11:37:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 53.2 %

2023-02-09 11:38:01, modbusTCP, I6-1, TEMP: 4.0 °C

2023-02-09 11:38:01, modbusTCP, I6-1/S-12, TEMP: 27.1 °C, RH: 65.4 %

2023-02-09 11:38:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 11:38:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 49.3 %

2023-02-09 11:38:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:38:01 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.9 %

2023-02-09 11:38:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:38:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 53.1 %

2023-02-09 11:39:02, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 11:39:02, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 65.2 %

2023-02-09 11:39:02 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.4 %

2023-02-09 11:39:02, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 49.0 %

2023-02-09 11:39:02 , modbusTCP , I6-2 , TEMP : 0.0  $^{\circ}\text{C}$ 

2023-02-09 11:39:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

```
2023-02-09 11:39:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %
```

2023-02-09 11:39:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.9 %

2023-02-09 11:40:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 11:40:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}$ C , RH : 65.1  $^{\circ}$ 

2023-02-09 11:40:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 11:40:01, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 49.1 %

2023-02-09 11:40:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:40:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.9 %

2023-02-09 11:40:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:40:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.8 %

2023-02-09 11:41:01, modbusTCP, I6-1, TEMP: 4.4 °C

2023-02-09 11:41:01, modbusTCP, I6-1/S-12, TEMP: 27.2 °C, RH: 64.9 %

2023-02-09 11:41:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.1 %

2023-02-09 11:41:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 48.1 %

2023-02-09 11:41:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:41:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:41:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:41:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.6 %

2023-02-09 11:42:01, modbusTCP, I6-1, TEMP: 4.1 °C

2023-02-09 11:42:01 , modbusTCP , I6-1/S-12 , TEMP : 27.2  $^{\circ}$ C , RH : 64.7  $^{\circ}$ 

2023-02-09 11:42:01 , modbusTCP , I6-1/S-13 , TEMP : 30.1  $^{\circ}\text{C}$  , RH : 60.9 %

2023-02-09 11:42:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.8  $^{\circ}$ C , RH : 47.8 %

2023-02-09 11:42:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:42:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.8 %

2023-02-09 11:42:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:42:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.6 %

```
2023-02-09 11:43:01, modbusTCP, I6-1, TEMP: 4.0 °C
```

2023-02-09 11:43:01, modbusTCP, I6-1/S-12, TEMP: 27.3 °C, RH: 65.2 %

2023-02-09 11:43:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.0 %

2023-02-09 11:43:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 47.9 %

2023-02-09 11:43:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:43:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 11:43:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 11:43:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.7 %

2023-02-09 11:44:02, modbusTCP, I6-1, TEMP: 3.6 °C

2023-02-09 11:44:02, modbusTCP, I6-1/S-12, TEMP: 27.4 °C, RH: 65.6 %

2023-02-09 11:44:02, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.3 %

2023-02-09 11:44:02 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}$ C , RH : 48.5 %

2023-02-09 11:44:02, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:44:02, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.7 %

2023-02-09 11:44:02, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:44:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.8 %

2023-02-09 11:45:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:45:01 , modbusTCP , I6-1/S-12 , TEMP : 27.5  $^{\circ}\text{C}$  , RH : 66.0 %

2023-02-09 11:45:01, modbusTCP, I6-1/S-13, TEMP: 30.0 °C, RH: 61.6 %

2023-02-09 11:45:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 49.1 %

2023-02-09 11:45:01 , modbusTCP , I6-2 , TEMP : 0.0  $^{\circ}\text{C}$ 

2023-02-09 11:45:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:45:01 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:45:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.6 %

2023-02-09 11:46:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:46:01 , modbusTCP , I6-1/S-12 , TEMP : 27.5  $^{\circ}\text{C}$  , RH : 66.3 %

```
2023-02-09 11:46:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 61.9 %
```

2023-02-09 11:46:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 49.1 %

2023-02-09 11:46:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:46:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:46:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:46:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}$ C , RH : 52.6  $^{\circ}$ 

2023-02-09 11:47:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:47:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 66.6 %

2023-02-09 11:47:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.1 %

2023-02-09 11:47:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.9 %

2023-02-09 11:47:01, modbusTCP, I6-2, TEMP: 0.0 °C

2023-02-09 11:47:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:47:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 11:47:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.6 %

2023-02-09 11:48:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:48:01, modbusTCP, I6-1/S-12, TEMP: 27.6 °C, RH: 66.9 %

2023-02-09 11:48:01, modbusTCP, I6-1/S-13, TEMP: 29.9 °C, RH: 62.2 %

2023-02-09 11:48:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 48.8 %

2023-02-09 11:48:01, modbusTCP, I6-2, TEMP: 4.6 °C

2023-02-09 11:48:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:48:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:48:02, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.5 %

2023-02-09 11:49:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:49:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 67.1 %

2023-02-09 11:49:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 62.3 %

2023-02-09 11:49:01, modbusTCP, I6-1/S-16-2, TEMP: 20.7 °C, RH: 48.6 %

```
2023-02-09 11:49:01, modbusTCP, I6-2, TEMP: 3.9 °C
```

2023-02-09 11:49:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:49:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:49:01, modbusTCP, I6-2/S-10, TEMP: 22.7 °C, RH: 52.4 %

## <<<<< HEAD

2023-02-09 11:52:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:52:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 67.8 %

2023-02-09 11:52:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.3 %

2023-02-09 11:52:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 48.0 %

2023-02-09 11:52:01, modbusTCP, I6-2, TEMP: 4.4 °C

2023-02-09 11:52:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:52:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.5 %

2023-02-09 11:52:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 52.4 %

2023-02-09 11:53:02, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:53:02 , modbusTCP , I6-1/S-12 , TEMP : 27.8  $^{\circ}$ C , RH : 68.1 %

2023-02-09 11:53:02, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.1 %

2023-02-09 11:53:02, modbusTCP, I6-1/S-16-2, TEMP: 20.9 °C, RH: 47.5 %

2023-02-09 11:53:02 , modbusTCP , I6-2 , TEMP : 4.3 °C

2023-02-09 11:53:02, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:53:02 , modbusTCP , I6-2/S-9 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:53:02 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}\text{C}$  , RH : 52.3 %

2023-02-09 11:54:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:54:01 , modbusTCP , I6-1/S-12 , TEMP : 27.8  $^{\circ}\text{C}$  , RH : 68.4 %

2023-02-09 11:54:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.2 %

2023-02-09 11:54:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.8  $^{\circ}$ C , RH : 47.4 %

2023-02-09 11:54:01, modbusTCP, I6-2, TEMP: 4.0 °C

```
2023-02-09 11:54:01, modbusTCP, I6-2/S-8, TEMP: 20.4 °C, RH: 58.9 %
```

2023-02-09 11:54:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:54:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

======

>>>>> master

>>>>> develop\_v1

2023-02-09 11:55:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:55:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.5 %

2023-02-09 11:55:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}$ C , RH : 61.4 %

2023-02-09 11:55:01, modbusTCP, I6-1/S-16-2, TEMP: 20.8 °C, RH: 47.2 %

2023-02-09 11:55:01, modbusTCP, I6-2, TEMP: 3.8 °C

2023-02-09 11:55:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.8 %

2023-02-09 11:55:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 11:55:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.3 %

2023-02-09 11:56:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:56:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 68.8 %

2023-02-09 11:56:01, modbusTCP, I6-1/S-13, TEMP: 30.2 °C, RH: 61.6 %

2023-02-09 11:56:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.7  $^{\circ}\text{C}$  , RH : 48.0 %

2023-02-09 11:56:01, modbusTCP, I6-2, TEMP: 3.5 °C

2023-02-09 11:56:01 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.9 %

2023-02-09 11:56:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.6 %

2023-02-09 11:56:01 , modbusTCP , I6-2/S-10 , TEMP : 22.7  $^{\circ}$ C , RH : 52.3  $^{\circ}$ 

2023-02-09 11:57:01 , modbusTCP , I6-1 , TEMP : 3.5  $^{\circ}\text{C}$ 

2023-02-09 11:57:01, modbusTCP, I6-1/S-12, TEMP: 27.8 °C, RH: 69.0 %

2023-02-09 11:57:01 , modbusTCP , I6-1/S-13 , TEMP : 30.2  $^{\circ}\text{C}$  , RH : 61.8 %

2023-02-09 11:57:01, modbusTCP, I6-1/S-16-2, TEMP: 20.6 °C, RH: 48.4 %

```
2023-02-09 11:57:01, modbusTCP, I6-2, TEMP: 3.4 °C
```

2023-02-09 11:57:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:57:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:57:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 11:58:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:58:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.3 %

2023-02-09 11:58:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.8 %

2023-02-09 11:58:01 , modbusTCP , I6-1/S-16-2 , TEMP : 20.6  $^{\circ}$ C , RH : 48.6  $^{\circ}$ 

2023-02-09 11:58:01, modbusTCP, I6-2, TEMP: 3.5 °C

2023-02-09 11:58:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 11:58:01, modbusTCP, I6-2/S-9, TEMP: 20.7 °C, RH: 65.6 %

2023-02-09 11:58:01, modbusTCP, I6-2/S-10, TEMP: 22.8 °C, RH: 52.2 %

2023-02-09 11:59:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 11:59:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.6 %

2023-02-09 11:59:01, modbusTCP, I6-1/S-13, TEMP: 30.1 °C, RH: 61.6 %

2023-02-09 11:59:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.7 %

2023-02-09 11:59:01, modbusTCP, I6-2, TEMP: 3.5 °C

2023-02-09 11:59:01 , modbusTCP , I6-2/S-8 , TEMP : 20.3  $^{\circ}\text{C}$  , RH : 58.9 %

2023-02-09 11:59:01, modbusTCP, I6-2/S-9, TEMP: 20.6 °C, RH: 65.6 %

2023-02-09 11:59:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.2 %

2023-02-09 12:00:01, modbusTCP, I6-1, TEMP: 3.5 °C

2023-02-09 12:00:01, modbusTCP, I6-1/S-12, TEMP: 27.7 °C, RH: 69.8 %

2023-02-09 12:00:01 , modbusTCP , I6-1/S-13 , TEMP : 30.0  $^{\circ}\text{C}$  , RH : 61.5 %

2023-02-09 12:00:01, modbusTCP, I6-1/S-16-2, TEMP: 20.5 °C, RH: 48.9 %

2023-02-09 12:00:01 , modbusTCP , I6-2 , TEMP : 3.8  $^{\circ}\text{C}$ 

2023-02-09 12:00:01, modbusTCP, I6-2/S-8, TEMP: 20.3 °C, RH: 58.9 %

2023-02-09 12:00:01 , modbusTCP , I6-2/S-9 , TEMP : 20.6  $^{\circ}\text{C}$  , RH : 65.7 %

2023-02-09 12:00:01 , modbusTCP , I6-2/S-10 , TEMP : 22.8  $^{\circ}\text{C}$  , RH : 52.0 %