# 微机原理实验二 四字节十六进制数转十进制数

2021/11/26


#### 一、实验目的

进一步熟悉 8086 汇编指令,了解十六进制数转十进制数的方法。

#### 二、实验内容

从键盘上输入 8 位十六进制数,实现四字节十六进制数转 8 位十进制数,并在数码管上显示。注意输入数据必须在 00000000H~05F00000H 范围, 否则, 结果超出 8 位十进制数, 无法正确显示。

#### 三、程序框图



## 四、实验步骤

- 1、连线说明:
- D3  $\boxtimes$ : CS, AO, A1 A3  $\boxtimes$ : CS1, AO, A1
- D3 X: PCO, PC1 F5 X: KL1, KL2
- D3  $\boxtimes$ : JP20, B, C F5  $\boxtimes$ : A, B, C
- 2、在F5 区的键盘上输入8 位十六进制数
- 3、结果显示在F5 区的数码管上

#### 五、画出程序流程图编写并调试程序

本程序用到1个外部变量F1和3个外部程序

- 1、InitKeyDisplay; 初始化键盘、LED 数码管控制器8255, A 口、B 口输出, C 口输入
- 2、GetKey 接收一组压缩16 进制键值

输入参数: DI — 指向接收缓冲区

CX -- 接收键值数量

F1 -- 0: 先清除显示, 再接收键输入

F1 -- 1:接收到第一个按键后,先清除原来显示的内容,再显示键值

3、Display8显示子程序(8255 对数码管扫描)

输入参数: SI—指向8 字节显示缓冲区;

如果需要显示小数点, 8 位16 进制数的最高位为1, 例如: 80H;

如果某位不需要显示, 符值10H;

如果需要显示负号"-",符值11H

例子: 00H, 00H, 00H, 00H, 82H, 03H, 10H, 10H 显示为: "32.0000"

在程序头,以上变量和外部程序时必须以EXTRN 予以声明

### 六、实验扩展及思考

- 1、 如果不考虑在数码管上显示,不限制数据范围,程序应如何编写。
- 2、 绘制本实验的详细实验电路图原理图。

#### 七、程序清单

EXTRN InitKeyDisplay:NEAR, Display8:NEAR, GetKey:NEAR EXTRN F1:BYTE

STACK SEGMENT STACK

DW 1000 DUP(?)

STACK ENDS

DATA SEGMENT WORD PUBLIC 'DATA'

BUFFER DB 8 DUP(?)

\_DATA ENDS

CODE SEGMENT

START PROC NEAR

ASSUME CS:CODE, DS:\_DATA, SS:\_STACK


MOV AX, \_DATA

```
MOV DS, AX
  MOV
         ES, AX
  NOP
        InitKeyDisplay ;对键盘、数码管扫描控制器8255初始化
  CALL
  MOV F1,0
                    ;先清除显示,再接收键输入
START1:
        LEADI, BUFFER
  MOVCX, 8
                     ;按键次数
   CALL
                       :得到4字节十六进制数
        GetKev
                     ;接收到第一个键,才清除显示
  MOV F1, 1
  MOVSI, WORD PTR BUFFER
  MOVDI, WORD PTR BUFFER + 2
  CALL B4toD4
                       ;转换成十进制数
  LEADI, BUFFER
                     ;存放显示结果
  CALL
       B1toB2
                       ;低位
  MOVAL, AH
  CALL
        B1toB2
  MOVAL, BL
  CALL B1toB2
  MOV
      AL, BH
  CALL B1toB2
  LEA
        SI, BUFFER+7
  MOV CX, 7
  CALL
        BlackDisplay
                        ;将高位0消隐
   LEA
        SI, BUFFER
  CALL
        Display8
   JMP
        START1
;将一个字节压缩BCD码转换成二个字节非压缩BCD码
   B1toB2 PROC NEAR
  PUSH
        AX
  AND
         AL,0FH
  ST0SB
  POP
        AX
        AL,0F0H
  AND
  ROR
      AL,4
  ST0SB
  RET
B1toB2 ENDP
BlackDisplay PROC NEAR
   STD
  MOV DI, SI
BlackDisplay1: LODSB
                                        ;将高位0消隐
   CMP AL, 0
   JNZ Exit
```

```
MOV
         AL,10H
   ST0SB
   L00P
         BlackDisplay1
Exit: CLD
   RET
BlackDisplay ENDP
;四字节十六进制数转十进制数: DISI为十六进制, BXAX为压缩BCD码
B4toD4 PROC
           NEAR
   XOR
         AX,AX
   XOR
         BX,BX
   MOV
         CX,32
B4toD4_1:
   RCLSI,1
   RCL DI,1
   ADC AL, AL
   DAA
   XCHG
         AL,AH
   ADC
         AL,AL
   DAA
   XCHG
         AL,BL
   ADC
         AL,AL
   DAA
   XCHG
         AL,BH
   ADC
         AL,AL
   DAA
   XCHG
         AL,BH
   XCHG
         AL,BL
   XCHG
         AL,AH
   L00P
         B4toD4_1
   RET
B4toD4 ENDP
START ENDP
CODE
      ENDS
```

**END START** 

## 八、实验电路图



#### 如果不考虑在数码管上显示,不限制数据范围,程序应如何编写

```
EXTRN InitKeyDisplay:NEAR, GetKey:NEAR
EXTRN F1:BYTE
STACK SEGMENT STACK
DW 1000 DUP(?)
_STACK ENDS
DATA SEGMENT WORD PUBLIC 'DATA'
BUFFER DB 8 DUP(?)
DATA ENDS
CODE
     SEGMENT
START PROC NEAR
  ASSUME CS:CODE, DS:_DATA, SS:_STACK
  MOV AX, _DATA
  MOV DS, AX
  MOV
        ES, AX
  NOP
  CALL
        InitKeyDisplay ;对键盘、数码管扫描控制器8255初始化
  MOV F1.0
                    ;先清除显示,再接收键输入
       LEADI, BUFFER
START1:
  MOVCX, 8
                    ;按键次数
  CALL GetKey
                       ;得到4字节十六进制数
                    ;接收到第一个键,才清除显示
  MOV F1, 1
  MOVSI, WORD PTR BUFFER
  MOVDI, WORD PTR BUFFER + 2
  CALL B4toD4
                       ;转换成十进制数
  LEA DI, BUFFER
                        ;存放显示结果
  CALL B1toB2
                       ;低位
  MOV AL, AH
  CALL B1toB2
        AL, BL
  MOV
  CALL B1toB2
  MOV AL, BH
  CALL
        B1toB2
  MOV AL, DL
  CALL B1toB2
  LEA
        SI, BUFFER+7
         CX, 7
  MOV
   CALL
         BlackDisplay ;将高位0消隐
```

```
LEA SI, BUFFER+15
   MOV CX, 8
   CALL BlackDisplay
         SI, BUFFER
   LEA
   JMP
         START1
;将一个字节压缩BCD码转换成二个字节非压缩BCD码
   B1toB2 PROC
               NEAR
   PUSH
         AX
   AND
         AL,0FH
   ST0SB
   POP
         AX
   AND
         AL,0F0H
   ROR
         AL,4
   ST0SB
   RET
B1toB2 ENDP
BlackDisplay PROC NEAR
   STD
   MOV DI, SI
BlackDisplay1: LODSB
                                           ;将高位0消隐
   CMP AL, 0
   JNZ Exit
   MOV
         AL,10H
   ST0SB
   L00P
         BlackDisplay1
Exit: CLD
   RET
BlackDisplay ENDP
;四字节十六进制数转十进制数: DISI为十六进制,BXAX为压缩BCD码
B4toD4 PROC
            NEAR
         AX,AX
   XOR
         BX,BX
   XOR
   MOV
         CX,32
B4toD4_1:
   RCL SI, 1
   RCL DI,1
   ADC AL, AL
   DAA
   XCHG
        AL,AH
   ADC
         AL,AL
   DAA
   XCHG
        AL,BL
```

ADC AL,AL DAA

XCHG AL,DL

ADC AL,AL

DAA

XCHG AL,DL

XCHG AL,BH

XCHG AL,BL

XCHG AL,AH

LOOP B4toD4\_1

RET

B4toD4 ENDP

START ENDP

CODE ENDS

**END START**