

# Engineering & Design


## Product Drawings & layout

Cube Robot




**Tower Robot** 









Nano warehouse








### Controls System Architecture

Product & System Electrical Schematics

Panels & Devices Layout

Panel Wiring Schematics-




#### Note:


```
M4RC-1 -> Main Panel 4 Pin Rtex(Male & Female) Connector -MA M2GC-1 -> Main Panel 2 GX-16(Male & Female) Connector -MB M2GC-2 -> Main Panel 2 GX-16(Male & Female) Connector -MC M2GC-3 -> Main Panel 2 GX-16(Male & Female) Connector -MC M2GC-3 -> Main Panel 2 GX-16(Male & Female) Connector -MD M4RC-2 -> Main Panel 4 Pin Rtex(Male & Female) Connector -ME M3PS-1 -> Main Panel 3 Pin (Plua & Socket) -SSI.
```

7) M3PS-2 -> Main Panel 3 Pin (Plug & Socket) -SK2 8) M3PS-4 -> Main Panel 3 Pin (Plug & Socket) -SK4 9) M3PS-5 -> Main Panel 3 Pin (Plug & Socket) -SK5 10) M3PS-6 -> Main Panel 3 Pin (Plug & Socket) -SK5 11) M3PS-7 -> Main Panel 3 Pin (Plug & Socket) -SK6 11) M3PS-7 -> Main Panel 3 Pin (Plug & Socket) -SK7 12) M3PS-6 -> Main Panel 3 Pin (Plug & Socket) -SK7 13) M3PS-9 -> Main Panel 3 Pin (Plug & Socket) -SK9 14) M3PS-9 -> Main Panel 3 Pin (Plug & Socket) -SK9 14) M3PS-9 -> Main Panel 3 Pin (Plug & Socket) -SK9 14) M3PS-9 -> Main Panel 3 Pin (Plug & Socket) -SK9

Field Wiring Schematics



Power & Data Supply Layout



Bill of Material

- Insert Config Slides

Cube DC Challan Data

DODOT OTRUCTURE			
ROBOT STRUCTURE	•		
Frames-Bottom			6
Frame -Top			6
Vertical Member			108
Center-Top			25
Center-Bottom			25
Leveling Foot and Stud			265 Pair
LM Guides			4
Rack and Pinion			12
Fasteners set (Rack assembly)			
Shuttle System			
Horizontal System			1
Vertical System			1
Vertical Control Panel			1
Top guide and guide roller Assy			1
Horizontal Motors			1
Vertical motor			1
Fasteners (Shuttle assembly)			
Main Control Panel			
PC , Monitor , Keyboard & Mouse, Camera, Router, Ethernet Switch			1 set
Control Panel Unit			1

\_\_\_\_\_

#### Assembly Plan

#### 1. Base Assembly

- a. Aluminium Extrusion / Frame Assembly
- b. Levelling Foot
- c. Levelling the base Structure

### 2. Horizontal Slide Assembly

- a. Guide Assembly
- b. Gear System Assembly

- c. Motor & Bracket Assembly
- 3. Vertical System Assembly
  - a. Control Panel Assembly
- 4. Push-Pull System Assembly
- 5. Structure Assembly
  - a. Bay Area assembly
  - b. Panel Assembly
  - c. Bay Control Panel
  - d. Main Control Panel
- 6. Slot Assembly
- 7. Anti-Friction Coating on Slots
- 8. Electrical Wiring
- 9. Camera System and Lighting assembly
- 10. Testing

#### Recommended Spare Parts List

- 1. Anti-Friction Coating Spray Rs 800
- 2. Anti-Friction Tape Rs
- 3. Holding Magnet Rs 750
- 4. Current Collector Rs 6500
- 5. Top Guide Roller Rs
- 6. Relay Modules
- 7. Brass Guide Blocks
- 7. Tool Kit

Equipment Sizing Calculation / Configuration Tools

Screenshot of diagnostic tools

Preventative Maintenance and Service Manual Niranjan TN

- Checklist for FE Maintenance Visit
- Parts Manual