

## **PHYWE multimeters**

for science education







Analog multimeter for beginners of electrical measuring

Ideal for first-time users and virtually indestructible

Universal multimeter for I, U, R, C, f and T

Item no.	07021-11	07127-00 ("AmpSafe")	07122-00
Display (analog/digital)	analog	digital	digital
Measurement (manual/automatic)	manual	automatic	manual
Measurement parameters and ranges			
DC voltage	03/15/60/150/600 V	0600 V	00,2/2/20/200/600 V
AC voltage	015/60/150/600 V	0600 V	02/20/200/600 V
DC current	0100μA/10 mA/500 mA/10 A	0200 mA	02/20/200 mA/10 A
AC current	010 mA/500 mA/10 A	0200 mA	02/200 mA /10 A
Resistance	0200 Ω/2/20/200 kΩ/2 ΜΩ	020 ΜΩ	0200 Ω/2/20/200 kΩ/2/20 ΜΩ
Capacitance	-	-	02/20/200 nF/2/200 μF
Frequency	-	-	020 kHz
Temperature	-	-	-20°C760°C
Special feature	mirror scale	flashlight	
	overload protection	electronic overload protection	-
Overvoltage category	CAT III 600V	CAT III 600V	CAT III 600V

## Cover all requirements from grade 5 up to university level:

Ideal as a classroom set (Item no. MULTIMETER-SET):







Phy

info@phywe.com

PHYWE Systeme GmbH & Co. KG

Robert-Bosch-Breite 10 37079 Göttingen / Germany P. +49 (0)551 604 - 0

F. +49 (0)551 604 - 107 www.phywe.com

facebook.com/phywe



linkedin.com/company/phywe



