ASSIGNMENT 4

DISTANCE DETECTION USING ULTRASONIC SENSOR


DATE	03-11-22
REGISTER NUMBER	771019106002
NAME	B. EBICIA SELVIN
MARK	2 MARKS

QUESTION:

Write code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.

SOLUTION:

CIRCUIT:




CODE:

```
// ARDUINO PINS (TRIGGER PIN, ECHO PIN)
const int TRIG PIN = 7;
const int ECHO PIN = 8;
// Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int max dist = 23200;
void setup() {
// The Trigger pin will tell the sensor to range find
pinMode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG PIN, LOW);
//Set Echo pin as input to measure the time duration of pulse returning back from the distance
sensor
pinMode(ECHO PIN, INPUT);
// We'll use the serial monitor to view the sensor output
Serial.begin(9600);
}
void loop() {
unsigned long t1;
unsigned long t2;
unsigned long pulse width;
float cm;
float inches:
// Hold the trigger pin high for at least 10 us
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG PIN, LOW);
// Wait for pulse on echo pin
while ( digitalRead(ECHO PIN) == 0 );
// Measure how long the echo pin was held high (pulse width)
// Note: the micros() counter will overflow after ~70 min
t1 = micros();
while (digitalRead(ECHO PIN) == 1);
t2 = micros();
pulse width = t2 - t1;
// Calculate distance in centimeters and inches. The constants
// are found in the datasheet, and calculated from the assumed speed
//of sound in air at sea level (~340 m/s).
cm = pulse width / 58.0;
inches = pulse_width / 148.0;
// Print out results
if ( pulse_width > max_dist ) {
```


OUTPUT:

DESIGN:




IBM CLOUD OUTPUT:

NEAR:



FAR:



SIMULATION LINK:

https://wokwi.com/projects/347241261861700178