
## Diagrama fasorial das condições iniciais



 $\vec{E'}$  = 1.141551 + j0.332294  $E_{FD0}$  = 1.772269  $\vec{V}$  = 1.048612 + j0.095000  $\vec{I}$  = 0.988725 - j0.387246  $\delta$  = 0.28326242  $P_m$  = 1.000000