top (+z) (axes in mm from the view origin)



side (+x) (axes in mm from the view origin)



front (-y) (axes in mm from the view origin)



iso



DRAWING battery_spacer
qty per robot: 8 (R-hand part = this one mirrored about XZ)
material: 6061 d10/5.6
process: cut tube spacer, 11 mm
finish:
mass: 1.6 g overall: 10.0 x 11.0 x 10.0 mm (x, y, z)
note:
general tolerances ISO 2768-mK, edges broken 0.3 x 45, units mm
geometry master: parts/battery_spacer.step
view origin = bounding-box centre = robot (105.00, -40.50, -95.00)

HOLE TABLE (view coords of the screw seat, mm)

feature	x	y	z	axis
d5.5 through	0.00	13.50	0.00	-y