How I need to mount each LED onto the board:



Assembly jig to help mount all 24 LEDs:



Standoffs on jig to ensure correct distance from LED to board surface.
With the LEDs in place, I will solder the leads onto the board; then I can just Lift the jig up vertically to remove it. Of course, I will have to do this with the Whole board and jig turned upside down so the LED doesn't fall vertically Downward because, as seen above, there is nothing to hold the LED against The jig.