



<- put solder joint here for polarity inversion (motor valves)

Section Control V1.1

Sect 0 or Speed Sensor

NPN OV PNP +12V

Sect 2

Sect 3 AgopenGPS Sect 6

Sect 7

Main Valve





