



WEICON®

WEICON

APPLICATIONS AND PRODUCTS MARINE INDUSTRY



www.weicon.com

V 1.23



Management System
ISO 9001:2015
ISO 14001:2015
www.tuv.com
ID 9108636595

WHERE YOU CAN USE...

WEICON CBC Chocking Backing Compound

Specially developed for the shimming and back filling of systems that are difficult to align.



WEICON Ceramic BL

Coating of a butterfly valve.




WEICON Ceramic BL

Coating of ship propellers.



WEICON Urethane 85

Repair of a shaft seal ring on a ship propulsion system.



WEICON WR

Repair of a ship propulsion shaft. Repairing and filling the damage caused by cavitation.



WEICON Ceramic BL

Corrosion protection coating with WEICON Ceramic BL.

WEICON Urethane 80

Final coating for protection against marine animals.

**W 44 T®**

Combines corrosion protection, water repellency, lubrication, conservation and cleaning in one single product.

**VA 100**

WEICON Contact VA 100 is a universal type for the bonding of metals, plastic and rubber.

**WEICON A**

Gap compensation on the anchor capstan.

**WEICON HB 300**


Sealing of the stabilizer shaft.

**Fast-Metal
Minute Adhesive**

Repair of the cylinder block of a ship engine.

WEICON BR

Repair of a bronze propeller shaft.



Repair of a ship or boat propeller



Description:

- Clean with WEICON Cleaner Spray S
- Sandblast
- Clean again with Cleaner Spray S
- Fill the cavitation damage with WEICON HB 300
- Grind the repaired surface until flat
- Seal the surface with WEICON Ceramic BL



Cleaner Spray S

- 500 ml
11202500
IMPA: 45 08 01
- 0,2 kg
10450002
- 0,5 kg
10450005
- 1,0 kg
10450010

WEICON HB 300

IMPA: 81 29 51



WEICON Ceramic BL

- 0,2 kg
10400002
- 0,5 kg
10400005
- 2,0 kg
10400020

IMPA: 81 29 37 IMPA: 81 29 38

Advantages of our solution:

- No need to purchase new parts
- Fast, cost-effective repair/maintenance

Attachment and alignment to hose covers and couplings on bunker station in harbour



Description:

- ▶ Clean the surface with WEICON Cleaner Spray S
- ▶ Align hose covers
- ▶ Apply WEICON Repair-Tape 10 cm x 3.5 m



WEICON Repair-Tape

- | | | |
|----------------------------|----------------------------|-----------------------------|
| ▶ 5 cm x 1,5 m
10710515 | ▶ 5 cm x 3,5 m
10710536 | ▶ 10 cm x 3,5 m
10711036 |
|----------------------------|----------------------------|-----------------------------|



Advantages of our solution:

- ▶ Simple, inexpensive and reliable sealing



Fixing indicators on chain links for quality assurance



Description:

- roughening the surface by sanding
- cleaning with WEICON Cleaner Spray S
- fixation of labels/indicators with NFC chips
with the aid of WEICON Epoxy Minute Adhesive



Cleaner Spray S

► 500 ml
11202500
IMPA: 45 08 01



Epoxy Minute Adhesive

► 24 ml
10550024



Advantages of our solution:

- withstands permanent exposure to seawater
- one year after bonding, continued perfect adhesion and surface quality was demonstrated in a test
- reading of the labels and thus traceability of the chain links permanently possible

Repair of the seal of a butterfly valve on a ship



Description:

- ▶ Rubber area on the body of a ship's butterfly valve damaged by maintenance/assembly
- ▶ Grind the surface
- ▶ Clean with WEICON Cleaner Spray S
- ▶ Apply WEICON Primer G
- ▶ Repair with WEICON Urethane 85
- ▶ Grind the surface again
- ▶ The repair withstood 6 bar during pressure test



Cleaner Spray S

- ▶ 500 ml
11202500
IMPA: 45 08 01

Primer G

Special bonding agent for urethanes for the pre-treatment of rubber and metal surfaces

- ▶ 50 g
10809050



WEICON Urethane 85


Shore hardness: A 85

- ▶ 500 g
10800005
Work Package
- ▶ 540 g
10800540
Cartridge

Advantages of our solution:

- ▶ Fast, cost-effective, contour and congruent repair
- ▶ No new purchase necessary

Repair and coating of a steel platform



Description:

- ▶ repair of the heavily corroded platform of an evaporation condenser
- ▶ sanding off the coarse rust
- ▶ neutralisation of the rusty surfaces with WEICON Rust Converter
- ▶ coating with the epoxy resin system WEICON Ceramic BL



WEICON Ceramic BL

▶ 0,2 kg 10400002 ▶ 0,5 kg 10400005 ▶ 2,0 kg 10400020
IMPA: 81 29 37 IMPA: 81 29 38



Rust Converter

▶ 400 ml 11155400
IMPA: 45 08 20



Advantages of our solution:

- ▶ easy application
- ▶ long-lasting protection against heavy stresses

Renewal of the anti-slip coating on a sailing yacht



Description:

- ▶ sanding the surface
- ▶ cleaning with WEICON Cleaner Spray S
- ▶ applying WEICON GMK 2510 onto the prepared surface on deck as well as onto the underside of the new coating
- ▶ fixation of the new coating after 15 minutes flash-off time



Cleaner Spray S

► 500 ml
11202500
IMPA: 45 08 01



GMK 2510

► 324 g
16200324
IMPA: 81 52 39

► 690 g
16200690
IMPA: 81 52 40

Work Package (consisting of 300 g adhesive, 24 g bonding agent and wooden spatula)

Work Package (consisting of 650 g adhesive, 40 g bonding agent and processing spatula)


Advantages of our solution:

- ▶ very good adhesion of WEICON GMK 2510 to various materials
- ▶ fast and easy application
- ▶ deck can be walked on again immediately after attaching the new coatings
- ▶ permanent weather and ageing-resistant solution



RN: GMK008

Repair of the end cover of a seawater filter on a yacht



Description:

- ▶ repairing damages on the end covers, which had been caused by mounting errors
- ▶ cutting out and removing the damaged area
- ▶ additional roughening and sanding of material residues with an angle grinder
- ▶ enclosing the damaged area with a common tape
- ▶ cleaning the sanded surface with WEICON Cleaner Spray S
- ▶ even casting of the WEICON Urethane 80



Cleaner Spray S



Advantages of our solution:

- ▶ fast on-site repair during ongoing use of the yacht
- ▶ high layer build-up and wear protection thanks to the self-levelling WEICON Urethane 80




Urethane 80

Shore hardness: A 80
 ▶ 500 g
 10518005
 IMPA: 81 29 63

▶ 500 ml
 11202500
 IMPA: 45 08 01

Repair of a rudder steering shaft on a deep-sea vessel



Description:

- ▶ removal of the corrosion layer by grinding the rudder steering post
- ▶ cleaning the grinded steering post with WEICON Cleaner Spray S
- ▶ application of WEICON Ceramic BL to the steering post during permanent, slow rotation
- ▶ curing of WEICON Ceramic BL at slow rotation for eight hours



WEICON Ceramic BL

▶ 0,2 kg	▶ 0,5 kg	▶ 2,0 kg	▶ 500 ml
10400002	10400005	10400020	11202500

IMPA: 81 29 37 IMPA: 81 29 38 IMPA: 45 08 01


Cleaner Spray S

Advantages of our solution:



- ▶ durable, substance-resistant coating to protect against corrosion
- ▶ uncomplicated, fast, economical repair of the rudder steering post

Coating a pump housing



Description:

- cleaning with WEICON Cleaner Spray S
- first application with WEICON GL as base coat and control layer
- second application with WEICON Ceramic BL as wear protection



WEICON GL

► 0,5 kg
10700005

► 1,0 kg
10700010



Cleaner Spray S

► 500 ml
11202500
IMPA: 45 08 01



WEICON Ceramic BL

► 0,2 kg
10400002

► 0,5 kg
10400005

► 2,0 kg
10400020

IMPA: 81 29 37 IMPA: 81 29 38



Advantages of our solution:

- better adhesion of the wear protection layer WEICON Ceramic BL due to filling the pinholes with WEICON GL
- cost-effective repair
- no replacement of the component necessary

Coating of jet pumps for sand backfill



Description:

- ▶ two jet pumps were coated with the epoxy resin system WEICON Ceramic HC 220
- ▶ the pumps are used to build artificial islands in the sea
- ▶ at the beginning, the contours were restored with Plastic Metal WEICON WR2



WEICON Ceramic HC 220

- ▶ 0,2 kg 10120002
- ▶ 0,5 kg 10120005
- ▶ 2,0 kg 10120020



Cleaner Spray S

- ▶ 500 ml 11202500
- IMPA: 45 08 01



WEICON WR2

- ▶ 0,5 kg 10350005
- ▶ 2,0 kg 10350020

Advantages of our solution:



- ▶ increasing the conveyor rate
- ▶ short downtime and fast recommissioning
- ▶ very cost-effective repair and maintenance
- ▶ durable wear protection
- ▶ long service life despite sand-water mixture

Coating of ship propellers



Description:

- ▶ as part of the recertification, a total of six propellers on three ships were coated
- ▶ the propellers were coated with WEICON Ceramic BL to protect them from cavitation and epibiosis
- ▶ due to the technical properties of WEICON Ceramic BL, no imbalance occurs during propeller coating



WEICON Ceramic BL

▶ 0,2 kg 10400002	▶ 0,5 kg 10400005	▶ 2,0 kg 10400020
		IMPA: 81 29 37
		IMPA: 81 29 38



Cleaner Spray S

▶ 500 ml 11202500
IMPA: 45 08 01



Advantages of our solution:

- ▶ avoidance of a cost-intensive replacement
- ▶ fast repair without long downtimes

Repair of the fan housing of a ventilator



Description:

- ▶ pre-treatment with sandblasting (SA 2½)
- ▶ replacing the missing material surface by inserting a stainless steel sheet
- ▶ cleaning the entire surfaces to be coated with WEICON Cleaner Spray S
- ▶ sanding the stainless steel sheet to improve surface roughness
- ▶ application of WEICON A to build up basic coating on the inside and outside
- ▶ after curing: smoothing and sanding the excess material
- ▶ WEICON Cleaner Spray S
- ▶ application of WEICON Ceramic BL as finish
- ▶ for visual upgrading and as corrosion protection application of WEICON Rust Protection 2000 Plus



Cleaner Spray S

► 500 ml
11202500
IMPA: 45 08 01



WEICON A

► 0,2 kg
10000002
IMPA: 81 29 01

► 0,5 kg
10000005
IMPA: 81 29 02

► 2,0 kg
10000020
IMPA: 81 29 02



Rust Protection 2000 PLUS

► 400 ml
11013400
silver grey

► 0,2 kg
10400002
IMPA: 81 29 37

► 0,5 kg
10400005
IMPA: 81 29 37

► 2,0 kg
10400020
IMPA: 81 29 38



WEICON Ceramik BL

► 0,2 kg
10400002
IMPA: 81 29 37

► 0,5 kg
10400005
IMPA: 81 29 37

► 2,0 kg
10400020
IMPA: 81 29 38

Advantages of our solution:

- ▶ cost-effective repair and avoiding a replacement with long delivery times

Repair of a bronze propeller shaft



Description:

- propeller shaft had shrunk slightly by approx. 5 mm in the sealing area due to sediment build-up (stern tube)
- shaft was sanded down by 4 mm and by 200 mm in width
- cleaning with WEICON Cleaner Spray S
- creating a barrier by means of tape (3 mm)
- application of WEICON BR at slow rotation of the shaft
- slow rotation of the shaft during curing to prevent WEICON BR from dripping off
- sanding the shaft to size after curing
- finishing the shaft with fine abrasive cloth (approx. 0.2 mm)
- reinstalling the propeller shaft



WEICON BR

► 0,2 kg 10420002	► 0,5 kg 10420005
IMPA: 81 29 10	
► 2,0 kg 10420020	
IMPA: 81 29 11	



Cleaner Spray S

► 500 ml 11202500
IMPA: 45 08 01

VIDEO



Advantages of our solution:

- avoidance of a cost-intensive replacement
- easy and time-saving repair
- good material compatibility and seawater resistance of WEICON BR

Repair of a roller fender on a quay wall



Description:

- damages on a roller fender on a quay wall
- application of WEICON Primer G
- filling the damaged areas with WEICON Urethane 85



Urethane 85

Shore hardness: A 85



- | | |
|-------------------------------------|----------------------------------|
| ► 500 g
10800005
Work Package | ► 540 g
10800540
Cartridge |
|-------------------------------------|----------------------------------|

Primer G

Special bonding agent for urethanes for the pre-treatment of rubber and metal surfaces

- | |
|--------------------|
| ► 50 g
10809050 |
|--------------------|



Advantages of our solution:

- fast and cost-effective repair solution
- excellent mechanical strength and elasticity
- durable wear protection



Repair of a ship propeller



Description:

- ▶ Roughening of the surfaces by sanding them
- ▶ Cleaning with WEICON Cleaner Spray S
- ▶ Application of the primer coat with WEICON BR
- ▶ Re-sanding and cleaning of the surface
- ▶ Application of the final coating with WEICON Ceramic BL



Cleaner Spray S

► 500 ml
11202500
IMPA: 45 08 01



WEICON BR

► 0,2 kg ► 0,5 kg ► 2,0 kg
10420002 10420005 10420020
IMPA: 81 29 10 IMPA: 81 29 11



WEICON Ceramic BL

► 0,2 kg ► 0,5 kg ► 2,0 kg
10400002 10400005 10400020
IMPA: 81 29 37 IMPA: 81 29 38

Advantages of our solution:

- ▶ Cheaper and faster than a new purchase



Repair of a catamaran



Description:

- ▶ sandblasting (SA 2 1/2) of the damaged areas
- ▶ application of WEICON HP
- ▶ final coating after curing with WEICON Ceramic BL
- ▶ 48 kg WEICON HP and 36 kg WEICON Ceramic BL were used on an area of 16 square metres



WEICON HP

- | | |
|----------------------|----------------------|
| ▶ 0,5 kg
10390005 | ▶ 2,0 kg
10390020 |
|----------------------|----------------------|



WEICON Ceramic BL

- | | | |
|----------------------|----------------------|----------------------|
| ▶ 0,2 kg
10400002 | ▶ 0,5 kg
10400005 | ▶ 2,0 kg
10400020 |
| IMPA: 81 29 37 | | IMPA: 81 29 38 |

Advantages of our solution:



- ▶ fast and precise repair
- ▶ reconditioning of the hull surface
- ▶ strengthening the material against new cavitation damages
- ▶ efficiency of the hull remains intact

Coating of an intercooler in a ship engine



Description:

- ▶ Severe corrosion of the condenser due to condensation caused by cooling compressed air in the turbocharger
- ▶ Loose rust was removed with a needle hammer
- ▶ The surface was cleaned with WEICON Cleaner Spray S
- ▶ WEICON Rust Converter was applied to stop existing corrosion
- ▶ A total of 10 kg of WEICON Ceramic BL was applied with a layer thickness of approx. 1 mm on an area of approx. 5 m²



Cleaner Spray S



Rust Converter

► 500 ml
11202500
IMPA: 45 08 01

► 400 ml
11155400
IMPA: 45 08 20




WEICON Ceramic BL

► 0,2 kg 10400002 IMPA: 81 29 37	► 0,5 kg 10400005 IMPA: 81 29 37	► 2,0 kg 10400020 IMPA: 81 29 38
--	--	--

Advantages of our solution:

- ▶ Restoration of spare parts that are no longer available

Repair of several fenders/buffers at a port facility for cruise ships



Description:

- ▶ removing the loose rubber pieces
- ▶ cleaning with WEICON Cleaner Spray S
- ▶ roughening the damaged areas with sandpaper
- ▶ application of WEICON Primer G
- ▶ application of WEICON Urethane 85



Cleaner Spray S

▶ 500 ml
11202500
IMPA: 45 08 01



Urethane 85

Shore hardness: A 85

▶ 500 g
10800005
Work Package

▶ 540 g
10800540
Cartridge



Primer G

special bonding agent for urethanes for the pre-treatment of rubber and metal surfaces

▶ 50 g
10809050



Dispenser 2C 10:1

recommended for the 2-component 540g cartridge

10653491



Advantages of our solution:

- ▶ inner steel plate is protected from external influences by the repair
- ▶ prevention of corrosion



Restoration work on a large submersible pump



Description:

- ▶ Heavily eroded cast iron on pump
- ▶ Clean with WEICON Cleaner Spray S
- ▶ Apply WEICON Rust Converter
- ▶ Correct the largest damages with WEICON A
- ▶ After curing, coat with WEICON HB 300
- ▶ After curing of WEICON HB 300, coat with WEICON GL and finally with WEICON Ceramic BL
- ▶ The different colours of the two wear protection systems make wear of the coating clearly visible



Rust Converter

► 400 ml	► 0,2 kg 10000002	► 0,5 kg 10000005	► 2,0 kg 10000020
11155400			IMPA: 81 29 01 IMPA: 81 29 02



Cleaner Spray S

► 500 ml 11202500	► 0,2 kg 10450002	► 0,5 kg 10450005	► 1,0 kg 10450010
IMPA: 45 08 01			IMPA: 81 29 51



WEICON GL

► 0,2 kg 10700002	► 0,5 kg 10700005	► 1,0 kg 10700010
		IMPA: 81 29 38

Advantages of our solution:

- ▶ Function of the pump restored
- ▶ No new purchase necessary

Repair of a drive shaft



Description:

- ▶ reducing the drive shaft to an undersize of > 3 mm
- ▶ creating a barrier (tape) to remove access material in uncured state
- ▶ circumferential application of WEICON HB 300 in a layer thickness of approx. > 5 mm
- ▶ after curing (24 h), the repaired area is reduced to the desired size



▶ 0,2 kg ▶ 0,5 kg ▶ 1,0 kg
 10450002 10450005 10450010
 IMPA: 81 29 51

[VIDEO](#)



Advantages of our solution:

- ▶ fast and cost-effective repair
- ▶ avoiding long delivery times
- ▶ fast recommissioning of the system
- ▶ cost savings of approx. 8,000 EUR compared to a replacement




RN: PS200





Offshore Transport of an oil rig







Securing the transport of an oilrig with WEICON Plastic Metal RFC, a specially developed type for extreme requirements in the off-shore sector.

1.500 – 2.000 kg of WEICON Plastic Metal RFC are used for each transport job.

Previous solution:



Current solution:



Offshore

Transport of an oil rig



**WEICON GmbH & Co. KG
(Headquarters)**

Königsberger Str. 255 · DE-48157 Münster
P.O. Box 84 60 · DE-48045 Münster
Germany
phone +49 (0) 251 9322 0
WhatsApp + 49 (0) 251 9322 393
info@weicon.de

JELN GmbH

Vogelsrather Weg 25 · DE-41366 Schwalmstadt
Germany
phone +49 (0) 2161 898 857
info@jeln.de · www.jeln.de

WEICON Middle East L.L.C.

Jebel Ali Ind Area 1
P.O. Box 118 216 · Dubai
United Arab Emirates
phone +971 4 880 25 05
info@weicon.ae

WEICON Inc.

20 Steckle Place · Unit 20
Kitchener · Ontario N2E 2C3 · Canada
phone +1 877 620 8889
info@weicon.ca

WEICON Kimya Sanayi Tic. Ltd. Şti.

Orhan Gazi Mahallesi 16. Yol Sokak No: 6
34538 Hadimköy-Esenyurt · İstanbul
Türkiye
phone +90 (0) 212 465 33 65
info@weicon.com.tr

WEICON Romania SRL

Str. Podului Nr. 1
547176 Budiu Mic (Targu Mures) · Romania
phone +40 (0) 3 65 730 763
office@weicon.com

WEICON SA (Pty) Ltd

Unit No. D1 · Enterprise Village
Capricorn Drive · Capricorn Park
Muizenberg 7945 (Cape Town) · South Africa
phone +27 (0) 21 709 0088
info@weicon.co.za

WEICON South East Asia Pte Ltd

7 Soon Lee Street
#01-11 iSPACE · Singapore 627608
Phone (+65) 6710 7671
info@weicon.com.sg

WEICON Czech Republic s.r.o.

Teplická 305

CZ-417 61 Teplice-Bystřany

Česká republika

phone +42 (0) 417 533 013

info@weicon.cz

WEICON Ibérica S.L.

Av. de Somosierra 18, Nave 6
San Sebastián de los Reyes
28703 Madrid · Spain
phone +34 (0) 914 7997 34
info@weicon.es

WEICON Italia S.r.l.

Via Capitano del Popolo, 20
16154 Genova · Italy
phone +39 010 2924 871
info@weicon.it

www.weicon.com



Management
System
ISO 9001:2015
ISO 14001:2015

www.tuv.com
ID 9108636595



WEICON

**APPLICATIONS AND
PRODUCTS**
MARINE INDUSTRY

Art.-No. 10906952

Distributed by:

www.weicon.com