


Handson Technology

User Guide

HMC5883L 3-Axis Electronic Compass Module

This Compass Module is designed for low-field magnetic sensing with a digital interface and perfect to give precise direction information. This compact sensor fits into small projects such as UAVs and robot navigation systems. The sensor converts magnetic field to a differential voltage output on 3 axis.







SKU: SSR1063

Brief Data:

Name: GY-271 HMC5883L Module.

• Number of Axis: 3.

• 16 Bit ADC With Low Noise AMR Sensors.

• Sensor Chip: HMC5883L.


• Power Supply: 3~5V;

• Communication Mode: I2C.

Measuring Range: ±8 Gauss.

Mechanical Dimension:

Unit: mm




Pin Function Assignment:

GY-271 Module has 5 pins. The application of them is as follows:


- VCC: Module power supply 3 to 5 volts.
- GND: Ground.
- SCL: I2C Clock pin.
- SDA: I2C Data pin.
- DRDY (Data Ready): When the output value of the sensor is ready, an interrupt occurs in this pin. This pin is pulled up inside the module by default. When the output value of the module is ready, the pin is "0" for 250 microseconds.





Application Examples:

Step 1: Connect the circuit:



GY-271	Arduino uno
VCC	VCC
GND	GND
SCL	A 5
SDA	A4

Upload the below sketch to the Arduino controller board:

/*

* HMC5883L Demo.

*

* Hardware Used:

*

- * Arduino UNO or compatible
- * GY271 module (dipmicro part DE4196
- * Arduino GND -> GY271/HMC5883L GND
- * Arduino 3.3V -> GY271/HMC5883L VCC

```
* Arduino A4 (SDA) -> GY271/HMC5883L SDA
* Arduino A5 (SCL) -> GY271/HMC5883L SCL
#include <Wire.h> //I2C Arduino Library
#define HMC5883L_ADDR 0x1E //0011110b, I2C 7bit address of HMC5883
bool haveHMC5883L = false;
bool detectHMC5883L ()
{
 // read identification registers
 Wire.beginTransmission(HMC5883L_ADDR); //open communication with HMC5883
 Wire.write(10); //select Identification register A
 Wire.endTransmission();
 Wire.requestFrom(HMC5883L_ADDR, 3);
 if(3 == Wire.available()) {
  char a = Wire.read();
  char b = Wire.read();
  char c = Wire.read();
  if(a == 'H' \&\& b == '4' \&\& c == '3')
   return true;
 return false;
void setup()
 //Initialize Serial and I2C communications
 Serial.begin(9600);
```

```
Serial.println("GY271 TEST");
 Wire.begin();
// lower I2C clock http://www.gammon.com.au/forum/?id=10896
TWBR = 78; // 25 \text{ kHz}
TWSR |= _BV (TWPS0); // change prescaler
}
void loop()
bool detect = detectHMC5883L();
if(!haveHMC5883L)
  if(detect)
   haveHMC5883L = true;
   Serial.println("We have HMC5883L, moving on");
   // Put the HMC5883 IC into the correct operating mode
   Wire.beginTransmission(HMC5883L_ADDR); //open communication with HMC5883
   Wire.write(0x02); //select mode register
   Wire.write(0x00); //continuous measurement mode
   Wire.endTransmission();
  }
  else
   Serial.println("No HMC5883L detected!");
   delay(2000);
   return;
```

```
}
else
  if(!detect) {
   haveHMC5883L = false;
   Serial.println("Lost connection to HMC5883L!");
   delay(2000);
   return;
int x,y,z; //triple axis data
//Tell the HMC5883 where to begin reading data
Wire.beginTransmission(HMC5883L_ADDR);
Wire.write(0x03); //select register 3, X MSB register
Wire.endTransmission();
//Read data from each axis, 2 registers per axis
Wire.requestFrom(HMC5883L_ADDR, 6);
if(6<=Wire.available()){</pre>
 x = Wire.read() << 8; //X msb
  x = Wire.read(); //X lsb
  z = Wire.read() << 8; //Z msb
  z = Wire.read(); //Z lsb
  y = Wire.read() << 8; //Y msb
 y |= Wire.read(); //Y lsb
//Print out values of each axis
```

```
Serial.print("x: ");
Serial.print(x);
Serial.print(" y: ");
Serial.print(y);
Serial.print(" z: ");
Serial.println(z);
delay(250);
}
```

The serial monitor shows the results (X plane angle, Y plane angle, Z plane angle in degrees) of different positions of the module.

```
COMS (Arduna/Genuino Una)
209.26,186.27,191.10;
208.73,186.41,191.58;
208.07,186.54,192.13;
208.73,185.95,190.77;
209.55,185.65,189.90;
209.71,185.63,189.81;
208.98,186.29,191.26;
208.73,186.71,192.11;
208.18,186.06,191.20;
208.79,186.27,191.31;
209.60,185.79,190.12;
209.26,186.42,191.36;
208.79,186.58,191.85;
208.14,186.56,192.13;
208.44,185.82,190.65;
209.00,185.91,190.57;
209.65,185.62,189.81;
```

R	esources:
	ttps://electropeak.com/learn/interfacing-gy-271-hmc58831-compass-magnetometr-with-arduino
	ttp://wiki.sunfounder.cc/index.php?title=GY-271_HMC5883L_3-
	Axis Magnetic Electronic Compass Module
ht	ttps://learn.adafruit.com/adafruit-hmc58831-breakout-triple-axis-magnetometer-compass-sensor



Handsontec.com

We have the parts for your ideas

HandsOn Technology provides a multimedia and interactive platform for everyone interested in electronics. From beginner to diehard, from student to lecturer. Information, education, inspiration and entertainment. Analog and digital, practical and theoretical; software and hardware.



Hands *On* Technology support Open Source Hardware (OSHW) Development Platform.

Learn: Design: Share

handsontec.com



The Face behind our product quality...

In a world of constant change and continuous technological development, a new or replacement product is never far away – and they all need to be tested.

Many vendors simply import and sell without checks and this cannot be the ultimate interests of anyone, particularly the customer. Every part sell on Handsotec is fully tested. So when buying from Handsontec products range, you can be confident you're getting outstanding quality and value.

We keep adding the new parts so that you can get rolling on your next project.



Breakout Boards & Modules



Connectors



Electro-Mechanical Parts



Engineering Material



Mechanical Hardware



Electronics Components

P



Power Supply



Arduino Board & Shield



Tools & Accessory