This is a list of devices that were tested hands-on by Apriva . There are many other device/OS/hardware combinations that are most likely compatible. However, unless a device/OS/hardware combination was tested explicitly by Apriva, it will not be on this list.

Apple

Manufacturer	<u>Model</u>	Model #	<u>Carrier</u>	iOS	App Version	Rambler 1	Rambler 2
Apple	iPhone 4	N/A	AT&T	5.1.1	2.1.0.199	Success	Success
Apple	iPhone 4	N/A	Verizon	6.1	2.1.0.199	Success	Success
Apple	iPhone 4s	N/A	Verizon	6.0.1	2.1.0.199	Success	Success
Apple	iPhone 4s	N/A	Verizon	6.1.2	2.1.0.199	Success	Success
Apple	iPhone 5	N/A	Verizon	6.0.1	2.1.0.199	Success	Success
Apple	iPhone 5	N/A	Verizon	6.1.2	2.1.0.199	Success	Success
Apple	iPad	N/A	WiFi	5.1.1	2.1.0.199	Failure	Failure
Apple	iPad 2	N/A	WiFi	6.0.0	2.1.0.199	Success	Success
Apple	iPad 2	N/A	WiFi	6.1.2	2.1.0.199	Success	Success
Apple	iPad 3	N/A	WiFi	6.1.1	2.1.0.199	Success	Success
Apple	iPod Touch - 4th Gen	MC544LL/A	WiFi	6.1.1	2.1.0.199	Unknown	Success

Coolpad

<u>Manufacturer</u>	<u>Model</u>	Model #	<u>Carrier</u>	<u>OS</u>	App Version	Rambler 1	Rambler 2
Coolpad	Quattro	5860E	Metro PCS	2.3.7	2.2.2	Unknown	Success

Huawei

<u>Manufacturer</u>	<u>Model</u>	Model #	<u>Carrier</u>	<u>OS</u>	App Version	Rambler 1	Rambler 2
Huawei	Prism	HUA-U8651T	T-Mobile	2.3.6	2.0.0	Unknown	Success

HTC

Manufacturer	<u>Model</u>	Model #	<u>Carrier</u>	<u>OS</u>	App Version	Rambler 1	Rambler 2
HTC	EVO 4G LTE	EVO	Sprint	4.0.4	2.0.0	Success	Success
HTC	EVO 4G LTE	EVO	Sprint	4.1.1	2.0.0	Success	Success
HTC	EVO 3D	EVO	Sprint	4.0.3	2.2	Unknown	Success
HTC	One Vx	PM36100	AT&T	4.0.4	2.0.0	Success	Success
HTC	One X	PM63100	AT&T	4.0.4	2.0.0	Success	Success
HTC	Sensation 4G	SENSATION	T-Mobile	4.0.3	2.0.0	Success	Success
HTC	Thunderbolt	ADR6400L	Verizon	2.3.4	2.0.0	Unknown	Failure
HTC	Thunderbolt	ADR6400L	Verizon	4.0.4	2.2.2	Failure	Success
HTC	Vivid	PH39100	AT&T	4.0.3	2.0.0	Success	Success

Manufacturer	<u>Model</u>	Model #	<u>Carrier</u>	<u>OS</u>	App Version	Rambler 1	Rambler 2
LG	Esteem	MS910	MetroPCS	Metro PCS	2.0.0	Unknown	Success
LG	Optimus	LX-670	Sprint	2.3.3	2.0.0	Failure	Failure
LG	Optimus	LG-LS970	Sprint	4.0.4	2.1	Failure	Failure
LG	Motion	MS770	MetroPCS	4.0.4	2.0.0	Unknown	Success
LG	MyTouch 4G	E739	T-Mobile	2.3.6	2.0.0	Failure	Failure
LG	MyTouch Q	LG C800	T-Mobile	2.3.6	2.2.2	Unknown	Failure

Pantech

<u>Manufacturer</u>	<u>Model</u>	Model #	<u>Carrier</u>	<u>os</u>	App Version	Rambler 1	Rambler 2
Pantech	Burst	P-9070	AT&T	2.3.4	2.0.0	Failure	Success
Pantech	Flex	P-8010	AT&T	4.0.3	2.0.0	Failure	Success

Motorola

Manufacturer	<u>Model</u>	Model #	<u>Carrier</u>	<u>os</u>	App Version	Rambler 1	Rambler 2
Motorola	Atrix HD	MB-886	AT&T	4.0.4	2.2	Unknown	Failure
Motorola	Droid Milestone 2	MB-867	US Cellular	2.3.6	2.0.0	Failure	Failure
Motorola	Droid X	Model-X	Verizon	2.3.4	2.0.0	Failure	Success
Motorola	Droid X2	Model-X2	Verizon	2.3.5	2.2.2	Success	Success
Motorola	Droid Razr	XT912	Verizon	4.1.2	2.2.2	Success	Success
Motorola	Droid Razr Maxx	XT912	Verizon	4.0.4	2.0.0	Unknown	Success
Motorola	Electrify	MB853	US Cellular	2.3.5	2.2.2	Unknown	Success
Motorola	Photon	MB855	Sprint	2.3.5	2.0.0	Unknown	Failure

Samsung

Manufacturer	<u>Model</u>	Model #	<u>Carrier</u>	<u>os</u>	App Version	Rambler 1	Rambler 2
Samsung	Captive	SGH-i927	AT&T	2.3.6	2.1.1	Unknown	Success
Samsung	Exhilarate	SGH-I577	AT&T	2.3.6	2.0.0	Success	Success
Samsung	Galaxy Appeal	SGH-1827	AT&T	2.3.6	2.0.0	Success	Success
Samsung	Galaxy Express	SGH-I437	AT&T	4.0.4	2.0.0	Failure	Success
Samsung	Galaxy Nexus	SCH-1515	Verizon	4.1.1	2.0.0	Failure	Failure
Samsung	Galaxy Note II	N-7100	Verizon	4.1.1	2.0.0	Failure	Failure
Samsung	Galaxy Note II	SGH-I317	AT&T	4.1.2	2.2.2	Unknown	Success
Samsung	Galaxy S I / Razor	SGH-T769	T-Mobile	2.3.6	2.0.0	Success	Success
Samsung	Galaxy S II / Skyrocket	SGH-i727	AT&T	2.3.6	2.0.0	Success	Success
Samsung	Galaxy S II / Titanium	SGH-T989	T-Mobile	2.3.6	2.0.0	Success	Success
Samsung	Galaxy S II / Epic 4G	SPH-D710	Sprint	4.0.4	2.0.0	Success	Success
Samsung	Galaxy S III	SCH-R530	Metro PCS	4.0.4	2.0.0	Unknown	Failure
Samsung	Galaxy S III	SGH-T999	T-Mobile	4.1.1	2.0.0	Success	Success
Samsung	Galaxy S III	SPH-L710	Sprint	2.1.1	2.1.1	Unknown	Success
Samsung	Galaxy S III	SCH-I535	Verizon	4.0.4	2.0.0	Unknown	Failure
Samsung	Habrok	SGH-1857	AT&T	2.2.2	2.0.0	Success	Success
Samsung	Infuse 4G	SGH-1997	AT&T	2.2.1	2.0.0	Failure	Failure
Samsung	Transform Ultra	SPH-M930	Sprint	2.3.6	2.0.0	Success	Success