

MINUTES OF MANAGEMENT MEETING HELD ON JULY 20, 2026

Attendance

Mr. Lanre Adebayo
Mr. Anthony Aigbokhai
Mr. Michael Obadan
Mr. Desmond Ikwuezuma
Ms. Vivian Iyaha
Ms. Princess Obaseki
Mrs. Gloria Morka
Mr. Ajibola Agoro
Mr. Harrison Obayi
Mr. Kenneth Onyemachi

The meeting commenced at 10:13 a.m. with an opening prayer led by **Mr. Kenneth Onyemachi**.

Amendments

Airtel Chip: Mr. Tony corrected that the delay is due to chip supply issues.

Contactless Card Problem: Mr. Tony corrected that the contactless card issue was caused by a data structure problem.

Adoption of Minutes: Moved by Mr. Ken, seconded by Mr. Michael.

MATTER ARISING

Tally: Access to price list has not been granted to business yet.

Palmpay: Mr. Kenneth reported that one card data was modified by our IT department and turned on. Another card without modification was turned on but failed.

Providus Software:

Mr. Kenneth reported the following:

Team 1: Said he will rebuild the software afresh and share source, but there has been no response from him.

Team 2 (Deji): Was able to regenerate logs; changes are yet to be agreed upon.

Team 3: Will rebuild the software and share an invoice (estimated timeframe: 4 weeks).

Team 4 (Tosin): Log was shared with him today; a decision will be made before the close of business today.

Airtel: Mail sent by the business (Mrs. Gloria).

DEPARTMENTAL REPORTS

Business Development & Sales Report

MAINTENANCE REPORT

1. TITLE: Replacement of the Broken X-Arm Module Shaft (Milling and Embedding Machine 2 – TELCO)

ACTIONS TAKEN:

- Loosened and dismantled the damaged X-arm module.
- Replaced the defective X-arm with a new one.
- Properly aligned, coupled, and secured the assembly.
- Conducted a test run to verify machine performance.

OBSERVATION:

The X-arm module is operating optimally and the machine is functioning normally.

2. TITLE: Card Jamming at the Half-Card and Quarter-Card Punching Units (TELCO)

ACTIONS TAKEN:

- Closely monitored the punching units to identify the root cause of the issue.
- Dismantled the affected units for inspection.
- Performed the necessary adjustments and realignment.
- Reassembled the units and carried out a successful test run.

OBSERVATION:

The card jamming issue was completely resolved, and the punching units are operating efficiently.

3. TITLE: SM74 Double Printing Issue (PRESS)

ACTIONS TAKEN:

- Adjusted the grippers on Units 1, 2, and 3.
- Performed additional mechanical adjustments to optimize print registration.
- Conducted a test run to verify printing quality.

OBSERVATION:

The double-printing issue was resolved, and the print quality improved significantly.

4. TITLE: Milling and Embedding Machine 2 – Chip Picker Stuck at the Punch Unit (TELCO)

ACTIONS TAKEN:

- Carried out troubleshooting to determine the root cause of the fault.
- Identified a faulty Z-axis upper limit sensor.
- Removed the defective sensor and installed a new one.
- Conducted a test run to confirm proper operation.

OBSERVATION:

The chip picker is now functioning perfectly, and the machine is operating efficiently.

5. TITLE: Emergency Reinstallation of the 37kW Compressor Reservoir Tank

ACTIONS TAKEN:

- Reinstalled the previously dismantled reservoir tank.
- Reconnected all associated piping.
- Powered on the compressor and verified system operation.

OBSERVATION:

The compressor is operating normally, and the reservoir system is functioning satisfactorily.

6. TITLE: Installation of the New Compressor and Relocation of the Reservoir Tank

ACTIONS TAKEN:

- Installed the electrical power supply line for the new compressor.
- Mounted and connected the gear switch.

NEXT STEPS:

- Continue the relocation and installation of the reservoir tank.
- Position and align the new compressor.
- Complete the compressed air piping installation.
- Perform commissioning and operational testing upon completion.

QC REPORT

1. Executive Summary & Quality Scorecard

The focus is on strict ISO-grade quality controls and data guidelines compliance.

2. Unit-Specific Quality Metrics & Status

A. TELCO SECTION

GLO PREPAID CARDS

- **Total Good Embedded Cards:** 1,100,700
- **Total Good Perso Production:** 1,092,584 (99.3%)

- **Total Rejects from Embedding:** 4,796 (0.4%)
- **Total Reject from Perso:** 2,960 (0.3%)
- **Total Good Embedded Card Remaining - 360**
- **Total Reject (Embedding & Perso):** 7,756 (0.7%)

B. MAILER SECTION

GLO PREPAID

- **Total Output Volume:** 2500 Copies
- **Quality Achieved:** 2500 (100%)
- **Waste/Defects:** 0.00 (0.00%).
- **Priorities for Next week:** Unknown

POLARIS BANK

GLO MAINTENANCE

- **Total Output Volume:** 6500 Copes
- **Quality Achieved:** 6500 Copies (100%)
- **Waste/Defects:** 0.00 (0.00%)
- **Priorities for Next week:** Unknown

C. PMC SECTION

LUTH POLARIS

- **Total Output Volume:** 580
- **Good Quality Embedded:** 571(98.5%)
- **Error Cards:** 9 (ATR) 1.5%

PRODUCTION REPORT

1. Production Overview

During the previous week, production activities were primarily driven by high-volume jobs from key clients, with selective contributions from smaller accounts. Output was concentrated on instant card issuance and selected customized card batches.

2. Total Production by Customer (Weekly Summary)

Total Cards Produced - 918

High-Volume Production

- Opay

Total output: 0 cards

- Palmpay

Total Output: 0 cards

- WEMA Verve

Total Output: 0 cards

- Polaris Bank

Total Output: 918 cards

- Wesley

Total Output: 0

3. Operational Insights/Difficulties

a. Production Concentration Risk

- Downturn in card requests

b. Machine Utilization

- Machines in working condition
- Mag Encoder Readings

Matica 1	809,044
Matica 2	1,075,426
MS-5000 1	2,078,291
MS-5000 2	285,121

c. Job Scheduling Efficiency

- Experiencing reduced workflow

D. Airtel Cards printed at OC 200. Front (89,800) Back (109,000)

INTERNAL AUDIT AND COMPLIANCE

S/N	DESCRIPTIONS	REMARKS
ACTIVITIES		
1.	Preventive Maintenance	Maplesoft’s work is Still ongoing. Sylvester has commenced his part too.

2.	Hardware and Software end of life	Still comparing and expecting quotes from different vendors. In the meantime, we are looking at working on the upgrade of the operating systems from windows 10 to 11 in HAS and doing Windows Server 2019 license for 3 servers.
4.	Mastercard & AGES Audit	Mastercard Audit is scheduled for 27 th and 28 th of July, 2026.

CARD PERSO UPDATES		
1	Personalization	Personalization was carried out for Opay and Polaris.

SOFTWARE AND LICENSES

S/N	ITEM	EXPIRING DATE	STATUS
1	MasterCard	April 2026	Expired
2	Verve Certificate	October 2026	Active
3	PCI DSS	November 2025	Active
4	ManageEngine SIEM	March 30 th ,2027	Active

5	CCS License	July 14th 2026	Active
6	Symantec Antivirus	June 25 th 2026	Expired
7	Fortinet Firewall	Dec., 2026	Active
8	Patch Manager Plus	June. 2026	Active
13	NDPR	Dec 31st 2026	Active
14	Fire Service Certificate	December 2026	Active
9	NESSUS	August 1 st 2026	Active
10	Complete SFTP License		Active
11	Outpost24	May 2027	Active
12	ISO 27001:2022 (Surveillance)	April 16th 2026	Active

HR/ADMIN DEPARTMENT REPORT

Administrative Activities

S/N	Activity	Action Taken/Status
1	Inventory Management	New administrative inventories were checked and

recorded.

2	File Management	Office files were rearranged and organized for improved accessibility and record keeping.
3	Staff Overtime	Overtime records were compiled and raised for eligible staff.
4	Payables Management	Payables were recorded and updated accordingly.
5	Casual Worker Administration	Perso casual worker timesheets were cross-checked, vetted, and payments raised for processing.
6	Glo Fulfilment Activities	Glo fulfilment records were documented and monitored.
7	Glo Casual Worker Payments	Casual worker records were vetted and payments raised accordingly.
8	Staff Documentation	Documentation and onboarding activities were completed for newly engaged staff.
9	KPI Administration	Staff KPI forms were distributed to employees.
10	Official Correspondence	Official emails were prepared and sent as required.
12	Welfare Activities	Welfare support was provided for Management, the Managing Director's guests, and visiting INEC officials.
13	Memo Preparation	Internal memos were raised to facilitate operational and administrative activities.
15	Staff Attendance Monitoring	Daily attendance records were maintained throughout the week.
16	Diesel Monitoring	Routine diesel checks were carried out to ensure

		uninterrupted operations.
17	Banking Activities	Official banking transactions and related errands were conducted.
18	Vehicle Registration Collection	The company's vehicle plate number was collected from Berger Sawyer.
19	Market Survey	A market survey was conducted in Yaba to gather relevant market information.
20	Airport Assignment	INEC officials were received and picked up from the airport.

Generator Status

Generator	Status
All Generators	Functional and operating satisfactorily.
500kVA Generator	One battery was temporarily removed by Mr. Adelekan for use on the forklift and requires replacement/restoration.

Vehicle Status Report

Kia

Issue	Status
Air Conditioning Fault	Follow up on driver
Body Work and Painting	
Rear Driver-Side Light	

Elantra

Issue	Status
Front Suspension Components (Hub and Tie Rod)	Follow up on driver
Floor Mat Replacement	
Bonnet Opener	

Mitsubishi Pick-Up

Issue	Status
Body Work	Follow up on driver
Front Lights (Both)	
Steering Pump	

Chevrolet

Issue	Status
Body Work	Required
Front Lights (Both)	Require replacement
Dashboard	Requires repair
Gear 5 Malfunction	Requires attention
Battery	Requires replacement/maintenance

Chevrolet Staff Bus

Issue	Status
Wheel Alignment and Balancing	Follow up on driver

Jack

Battery

White Chevrolet Staff Bus

Issue	Status
Servicing	Due for routine servicing

Recommendations

1. Approve and carry out outstanding vehicle repairs to ensure reliability and safety.
2. Replace or restore the battery removed from the 500kVA generator to maintain full operational capacity.
3. Continue routine maintenance of generators and vehicles to prevent unexpected breakdowns.
4. Maintain proper monitoring of casual worker records and payments to ensure accuracy and timely processing.
5. Continue staff welfare initiatives and onboarding support to improve employee engagement and productivity.

Conclusion

The department successfully carried out its administrative and operational responsibilities during the reporting period. Key activities included inventory management, casual worker payment processing, onboarding of new staff, KPI distribution, welfare support for Management and visitors, attendance monitoring, banking activities, and support for INEC officials. All generators remain operational; however, attention is required for the replacement of the battery removed from the 500kVA generator. Several company vehicles also require maintenance and repairs, and timely intervention is recommended to ensure uninterrupted operations and operational efficiency.

IT Report -

Adjournment

The meeting ended at...

