


3-8 PRECAUTIONS FOR PAINTING

There are cab and the chassis component which marketability is dropped due to the heat from painting and drying, and likely to become the cause of a serious accident.

1 Cab painting

- Precautions before and after painting
- When cleaning a cab, do not use thinner and gasoline but IPA (isopropyl alcohol).
- To enhance coating adhesion, thoroughly sand undercoat surface. Be sure that the sanding pattern is uniform, and the sealant at the joints of steel plates must not be removed.

Good and poor sanded surface conditions



2 Paint

- Urethane paint is recommended for its high luster and distinctness-of-image gloss, and it allows low-temperature baking.
- Contact ISUZU distributor or ISUZU dealership for cab color.