

# PSX Soldering guide

## 1 CONFIGURATION JUMPERS

### 1.1 1 PLAYER



#### 1.2 2 PLAYER



## 2 HEADERS


Facing the same side as the configuration pins, solder:

1x20 2.54mm socket header

2x4 2.54mm socket header

1x2 2.54mm socket header

## **3** CONNECTORS



Solder the controller cables to J\_PS\_1 and for 2 players, J\_PS\_2, ensuring you follow the colour guide.