Chapter 10, Problem 34.

Use mesh analysis to find I_o in Fig. 10.28 (for Example 10.10).




Figure 10.28 For Prob. 10.34.