Chapter 9, Problem 16.

Transform the following sinusoids to phasors:

- (a) $-20\cos(4t + 135^{\circ})$
- (b) $8 \sin(20t + 30^\circ)$ (c) $20 \cos(2t) + 15 \sin(2t)$