Chapter 11, Solution 25.

Find the rms value of the signal shown in Fig. 11.56.




Figure 11.56 For Prob. 11.25.

Solution

$$f_{\text{rms}}^2 = \frac{1}{T} \int_0^T f^2(t) dt = \frac{1}{3} \left[\int_0^1 (-4)^2 dt + \int_1^2 0 dt + \int_2^3 4^2 dt \right]$$
$$= \frac{1}{3} [16 + 0 + 16] = \frac{32}{3}$$

$$f_{rms} = \sqrt{\frac{32}{3}} = \underline{3.266}$$

$$f_{rms} = 3.266$$