Addr Shift	Fields	BE1	BE3	ВЕ9х	BE4	BK214	BE234	ВЦ1901	
0x0	RXTX	+	+	+	+	+	+	+	[150].bx: 0/1
0x4	OE	+	+	+	+	+	+	+	[150].bx: 0 - IN, 1 - OUT
0x8	FUNC	+	+	+	+	+	+	+	[310].bxx: 0 - port, 1 - main, 2 - alter, 3 - overr
0xC	ANALOG	+	+	+	+	+	+	+	[150].bx: 0 - Analog, 1 - Digit
0x10	PULL	+	+	+	+	+	+	+	[150].1 - PullDown / [3116].1 - PullUp / - NoPull
0x14	PD	+	+	+	+	+	+	+	[150].1 - OpenDrain , 0 - Diver / [3116].1 - Schmitt 400mV, 0 - 200mV
0x18	PWR	+	+	+	+	+	+	+	[310].bxx: 0 - Off, 1 - Slow, 2 - Fast, 3 - MaxFast
0x1C	GFEN	+	+	+	+	+	+	+	[015].bx: 0 - InpFilter Off, 1 - On
0x20	SETTX	+	+	-	-	+	-	-	[015].bx: 1 - Set, 0 - nothing
0x24	CLRTX	+	+	-	-	+	-	-	[015].bx: 1 - Clear, 0 - nothing
0x28	RDTX	+	+	-	-	+	-	-	[015].bx: 0 / 1 - Last set RXTX value in Port function

Addr for Bl	Port Pins count								
0x400A_8000	PORT_A	16	16	16	16	16	16	16	
0x400B_0000	PORT_B	16	16	16	15	15	15	16	
0x400B_8000	PORT_C	16	16	16	8	16	8	16	
0x400C_0000	PORT_D	16	16	16	-	-	-	16	
0x400C_8000	PORT_E	16	16	16	-	-	-	16	
0x400E_8000	PORT_F	16	16	16	-	-	-	16	
0x4011_8000	PORT_G	-	16	-	-	-	-	-	
0x4013_8000	PORT_H	-	16	-	-	-	-	-	
0x4014_0000	PORT_I	-	16	-	-	-	-	-	
			·						
Addr for BE4	T, BK214, BK234		·						
0x4008_0000	PORT_A	-	-	-	+	+	+	-	
0x4008_8000	PORT_B	-	-	-	+	+	+	-	
0x4009_0000	PORT_C	-	-	-	+	+	+	-	