	Regs	Access	BE1	BE3	BE9x	ВЦ1901	BE4	BK214	BE234
BaseAddr			-	-	0x4005_0000	0x4005_0000	-	0x4003_0000	-

2 22	I							
0x00	PRL							
07	PR	Div[7:0]						
0x04	PRH							
07	PR	Div[15:8]						
	0x0000	ResetValue						
	0x00FF	MaskValue						
2 22								
0x08	CTR							
04		0. lo 400KHz 1. lo 1MHz						
5 6	S_I2C	0: le 400KHz 1: le 1MHz IRQ Enable						
	EN_INT							
7	EN_I2C	1: Enable						
	0x0000	ResetValue						
	0x00E0	MaskValue I I I I I I I I I I I I I I I I I I I						
0x0C	RXD	Pageigad Data						
	RXD	Received Data						
07	0x0000	Last Received Byte						
	0x0000	ResetValue						
	UXUUFF	MaskValue						
0x10	STA	Chahua						
0	INT	1: IRQ Flag active						
1	TR_Prog	1: Transferring 0: Comleted						
24	TK_FTOg	1. Hansiering O. Conneteu						
5	Lost ARB	1: Lost Arbitrage (Collision) 0: No error						
6	BUSY	1: Start received, 0: Stop Received - Line status						
7	Rx_ACK	0: Ack received, 1: No Ack						
/	0x0000	ResetValue						
	0x00E3	MaskValue						
	UNIO 20							
0x14	TXD	Data to Send						
07	TXD	Data for transfer. Address b0 - 0: WR, 1: RW						
	0x0000	ResetValue						
	0x00FF	MaskValue						
0x18	CMD	Command						
0	CLR_INT	1 - clear IRQ						
12	-							
3	ACK	1 - Send Ack						
4	WR	1 - Start Write						
5	RD	1 - Start Read						
6	Stop	1 - Send Stop bit						
7	Start	1 - Send Start bit						
	0x0000	ResetValue						
	0x00F9	MaskValue						

SampleRate = HCLK/(5 * (DIV + 1))