
Assignment - 1

Raj Jain (CH17B066)
Department of Chemical Engineering, IIT Madras


Question-1

- (a)
- 1. <u>Controlled Variable:</u> Temperature of the room.
- 2. Manipulated Variable: Switch Position (On/Off).
- 3. <u>Disturbance Variable</u>: Ambient Air temperature

(b) Feedback control diagram:



(c) Feedforward control diagram:



Question - 2

The process given in this problem is a continuous process.

- 1. Controlled variable: Flow rate of the blood.
- 2. Manipulated Variable: Temperature of the unit, concentration of waste substances in blood.
- 3. Disturbance Variable: Changes in waste concentration due to metabolic activities in the body.

Question - 3

For finding steady state values-

At steady state
$$\frac{dw}{dt} = 0$$
 and $\frac{dz}{dt} = 0$

$$\frac{dw}{dt} = -\frac{L + Va}{M}w + \frac{Va}{M}z = 0$$

$$\frac{dz}{dt} = \frac{L}{M}w - \frac{L + Va}{M}z + \frac{V}{M}z_f = 0$$

Solving these two equations, we get:

$$w_{ss} = \frac{V^2 a Z_f}{V^2 a^2 + L^2 + VaL}$$

$$z_{ss} = \left(\frac{L}{Va} + 1\right) w_{ss}$$

L = 80 gmol/min; V = 100 gmol/min; M = 20 gmol/min; a = 0.5; $z_f = 0.1 \text{ gmol solute/gmol vapour}$

From these, we get, $w_{ss} = 0.0387$; $z_{ss} = 0.1006$

For linearizing the system of ODEs:

The model has two states, w and z.

And two outputs, again w and z.

We define-

State vector:
$$\mathbf{x} = \begin{bmatrix} w \\ z \end{bmatrix}$$

Output vector:
$$g(x) = y = \begin{bmatrix} w \\ z \end{bmatrix}$$

Input vector:
$$\boldsymbol{u} = \begin{bmatrix} L \\ V \end{bmatrix}$$

Given system of equations:

$$f(x) = \dot{x} = \begin{bmatrix} \dot{w} \\ \dot{z} \end{bmatrix} = \begin{bmatrix} -\frac{L+Va}{M}w + \frac{Va}{M}z \\ \frac{L}{M}w - \frac{L+Va}{M}z + \frac{V}{M}z_f \end{bmatrix}$$

Linearized system is written as:

$$\dot{\overline{x}} = A\overline{x} + B\overline{u}$$

$$\overline{y} = C\overline{x} + D\overline{u}$$

Where,
$$\overline{x} = x - x_{ss}$$
; $\overline{y} = y - y_{ss}$; $\overline{u} = u - u_{ss}$

$$A = \begin{bmatrix} \frac{\partial f_1}{\partial w} & \frac{\partial f_1}{\partial z} \\ \frac{\partial f_2}{\partial w} & \frac{\partial f_2}{\partial z} \end{bmatrix}_{SS} = \begin{bmatrix} -\frac{L+Va}{M} & \frac{Va}{M} \\ \frac{L}{M} & -\frac{L+Va}{M} \end{bmatrix}$$

$$B = \begin{bmatrix} \frac{\partial f_1}{\partial L} & \frac{\partial f_1}{\partial V} \\ \frac{\partial f_2}{\partial L} & \frac{\partial f_2}{\partial V} \end{bmatrix}_{SS} = \begin{bmatrix} -\frac{w_{SS}}{M} & \frac{a}{M}(z_{SS} - w_{SS}) \\ \frac{w_{SS} - z_{SS}}{M} & -\frac{z_f - az_{SS}}{M} \end{bmatrix}$$

Putting all the input, steady state and parameter values to get-

$$A = \begin{bmatrix} -6.5 & 2.5 \\ 4 & -6.5 \end{bmatrix} B = \begin{bmatrix} -0.002 & 0.0015 \\ -0.003 & -0.0025 \end{bmatrix} C = \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} D = \begin{bmatrix} 0 & 0 \\ 0 & 0 \end{bmatrix}$$

Eigen-Values & direction of slowest and fastest change:

Eigen values of the matrix A are -3.33 and -9.66.

The eigen value -9.66 corresponds to that eigen vector which is the direction of fastest change at the initial steady state.

 $\begin{bmatrix} -0.620 \\ 0.784 \end{bmatrix}$ is the direction of fastest change, and $\begin{bmatrix} 0.620 \\ 0.784 \end{bmatrix}$ is the direction of smallest change.

SIMULINK Modelling, steady state using 'trim', and linearized model using 'linmod':




Figure: Block diagram of non-linear system of ODEs

Figure: Output of step input (in L) response

Using 'trim' we get, $w_{ss} = 0.0386$; $z_{ss} = 0.1006$.

Using 'linmod' we get the linearized model with

Date:


Jan-May 2020

$$A = \begin{bmatrix} -6.5 & 2.5 \\ 4 & -6.5 \end{bmatrix} B = \begin{bmatrix} -0.002 & 0.0015 \\ -0.003 & -0.0025 \end{bmatrix} C = \begin{bmatrix} 1 & 0 \\ 0 & 1 \end{bmatrix} D = \begin{bmatrix} 0 & 0 \\ 0 & 0 \end{bmatrix}$$

The following code is used:

```
x0 = [0;0]
y0 = [0;0]
u0 = [80;100]
[X,U,Y] = trim('Altrim', x0, u0)
[A,B,C,D] = linmod('Altrim',X,u0)
```

Responses to step input changes in linear and non-linear models:



The plots obtained by a 5% and 15% increase in L are as shown below.


For 5% change in flow rate L:

Simout(1) - w as calculated by non linear model

Simout(1) – z as calculated by non linear model

Simout(3) – w as calculated by linear model

Simout(4) – z as calculated by linear model



Plot showing the response in w and z as calculated by the linear and non-linear models for a 5% change in L.

The linear model is sufficiently capable of capturing the transience and the final steady state in this case.


For 15% change in flow rate L:

Simout(1) - w as calculated by non-linear model

Simout(1) - z as calculated by non-linear model

Simout(3) - w as calculated by linear model

Simout(4) – z as calculated by linear model



Plot showing the response in w and z as calculated by the linear and non-linear models for a 15% change in L.

In this case the linear model is not sufficient in estimating the steady state but however is capable of modelling the transience to a fair degree as seen from the plots.

Question-4

(a) Laplace transform of function:

$$x = \begin{cases} t - 3; & 0 \le t < 3 \\ 0; & 3 \le t < 4 \\ \sin(3\pi(t - 4)); & 4 \le t < 5 \\ e^{-2t}\sin(5\pi t); & 5 \le t < \infty \end{cases}$$

$$X(s) = \mathcal{L}(x(t)) = \int_0^3 (t-3)e^{-st}dt + \int_3^4 (0)e^{-st}dt + \int_4^5 \sin(3\pi(t-4))e^{-st}dt + \int_5^\infty e^{-2t}\sin(5\pi t)e^{-st}dt$$

$$I_{1} = \int_{0}^{3} (t - 3)e^{-st}dt = \frac{-3s + e^{-3s} - 1}{s^{2}}$$

$$I_{2} = \int_{3}^{4} (0)e^{-st}dt = 0$$

$$I_{3} = \int_{4}^{5} \sin(3\pi(t - 4))e^{-st}dt = \frac{3\pi e^{-5s}(e^{s} + 1)}{s^{2} + 9\pi^{2}}$$

$$I_{4} = \int_{5}^{\infty} e^{-2t}\sin(5\pi t)e^{-st}dt = \frac{-5e^{-10}\pi e^{-5s}}{s^{2} + 4s + 25\pi^{2} + 4s}$$

$$X(s) = I_1 + I_2 + I_3 + I_4 = \frac{-3s + e^{-3s} - 1}{s^2} + \frac{3\pi e^{-5s}(e^s + 1)}{s^2 + 9\pi^2} + \frac{-5e^{-10}\pi e^{-5s}}{s^2 + 4s + 25\pi^2 + 4}$$

(b) Inverse Laplace:

We break up the expression into the constitutive partial fractions.

$$\frac{s-1}{s(T^2s^2+2\in Ts+1)} = -\frac{1}{s} + \frac{s}{2\in \frac{s}{T}+s^2+\frac{1}{T^2}} + \frac{1}{T^2} \frac{(1+2\in T)}{2\in \frac{s}{T}+s^2+\frac{1}{T^2}}$$

Rewriting the denominator in terms of a square, we can write:

$$= -\frac{1}{s} + \frac{s}{\left(s + \frac{\epsilon}{T}\right)^2 + \frac{1 - \epsilon^2}{T^2}} + \frac{1}{T^2} \frac{(1 + 2 \epsilon T)}{\left(s + \frac{\epsilon}{T}\right)^2 + \frac{1 - \epsilon^2}{T^2}}$$

Manipulating the second term:

$$= -\frac{1}{s} + \frac{\left(s + \frac{\epsilon}{T}\right)}{\left(s + \frac{\epsilon}{T}\right)^2 + \frac{1 - \epsilon^2}{T^2}} + \frac{1}{T^2} \frac{(1 + \epsilon T)}{\left(s + \frac{\epsilon}{T}\right)^2 + \frac{1 - \epsilon^2}{T^2}}$$

For the case where \in > 1 we have:

$$-L(t) + e^{\left(\frac{-\epsilon}{T}\right)} \cosh(wt) + \frac{1+\epsilon T}{T} \frac{1}{(1-\epsilon^2)^{0.5}} e^{-\frac{\epsilon}{T}} \sinh(wt) \text{ where } w = \frac{(\epsilon^2 - 1)^{0.5}}{T}$$

For the case where $0 \le \le 1$ we have:

$$-L(t) + e^{\left(\frac{-\epsilon}{T}\right)}\cos{(wt)} + \frac{1+\epsilon T}{T} \frac{1}{(1-\epsilon^2)^{0.5}} e^{-\frac{\epsilon}{T}}\sin{(wt)} \ where \ w = \frac{(1-\epsilon^2)^{0.5}}{T}$$

For the case where $\in = 1$ we have:

$$-L(t) + e^{\left(\frac{-\epsilon}{T}\right)} + \frac{1+\epsilon T}{T}e^{-\frac{\epsilon}{T}} where \ w = \frac{(1-\epsilon^2)^{0.5}}{T}$$