

GRIDLENS RESTOREIQ - AFTER-ACTION REPORT

ADVISORY: This report is for informational purposes only.

Operator validation required before any actions.

OUTAGE SUMMARY

Outage ID: 00000000-0000-0000-0000-000000000001

Tenant: DEMO_TENANT

Start Time: 12/19/2025, 6:09:33 PM

Primary Feeder: N/A

Affected Customers: 150

Severity: medium

KEY METRICS

Affected Meters: 0

Total Events: 0

EXECUTIVE SUMMARY

On 12/19/2025, 6:09:33 PM, an unplanned outage occurred affecting 150 customer(s). Zone "North Feeder Pocket" ranked highest with severity score 0.00. Advisory-only recommendations. Operator validation required. Generated from telemetry available at the time of generation.

TIMELINE

[12/19/2025, 6:09:33 PM] Outage detected on unknown feeder

FINDINGS

1. [HIGH] Primary Fault Zone Identified

Zone "North Feeder Pocket" ranked highest with severity score 0.00

Recommendation: Prioritize inspection of this zone for root cause analysis

RECOMMENDATIONS

1. Prioritize inspection of this zone for root cause analysis

Rationale: Zone "North Feeder Pocket" ranked highest with severity score 0.00

2. Complete after-action report and file for regulatory compliance

Rationale: Standard post-outage documentation requirement

DISCLAIMER

Advisory-only recommendations. Operator validation required. Generated from telemetry available at the time of generation.

Report Generated: 12/20/2025, 2:41:24 PM

Replay ID: 6f0cae7a-e484-43c0-859f-e761839cbc38

GridLens RestoreIQ - Outage Intelligence Platform