3.0 IEC101 Initialization

No.	Inspection	OK	NO
1	Send **Link Status Request** from ASE2000 to RTU. RTU should reply with **Status of Link response**.	☐	☐
2	Send **Reset Link Request** from ASE2000 to RTU. RTU should reply with **Ack/Fixed response**.	☐	☐
3	Send a **Delay Acquisition Request** from ASE2000 to RTU. RTU should reply with **Delay Acquisition Response**.	☐	☐
4	Send a **Clock Synchronization Request** from ASE2000 to RTU. RTU should reply with **Clock Synchronization Response**.	☐	☐
5	Send a **Broadcast Clock Synchronization Request** from ASE2000 to RTU using CASDU = 65535 and RTU should reply with **Clock Synchronization Response**.	☐	☐
6	Send an **Interrogation Request** from ASE2000 to RTU. RTU shall report all signals mapped to Master (without time tag).	☐	☐

4.0 IEC104 Initialization

No.	Inspection	OK	NO
1	Send **STARTDT ACT** from ASE2000 to RTU. RTU should reply with **STARTDT CON.**	☐	☐
2	Send **TESTFR ACT** from ASE2000 to RTU. RTU should reply with **TESTFR CON**.	☐	☐
3	Send a **Clock Synchronization Request** from ASE2000 to RTU. RTU should reply with **Clock Synchronization Response**.	☐	☐
4	Send a **Broadcast Clock Synchronization Request** from ASE2000 to RTU using CASDU = 65535 and RTU should reply with **Clock Synchronization Response**.	☐	☐
5	Send an **Interrogation Request** from ASE2000 to RTU. RTU shall report all signals mapped to Master (without time tag).	☐	☐

Ir. Ts. RAMLAH
19 DEC 24
ES
DISTRIBUTION NETWORK DIVISION, TNB

Tested By:
(Signature/Official Stamp)

Tester's
Name:
Date:

Witnessed By:
(Signature/Official Stamp)

AUTHORISED
QUALITY ASSURANCE EXECUTIVE
GRID VISION T&D S/B

TNB QAI's
Name: Muhammad Azamuddin Bin Hasan
Date: