

CompTIA A+ Core 1 Playbook

IT Labs

Prepared by Garrick White

Install USB Devices

As an IT helpdesk technician, you are tasked with setting up a testing station to evaluate a variety of peripherals and devices. Your goal is to ensure that all devices are connected using the appropriate USB cables, providing a reliable environment for testing and troubleshooting.

- Place the USB Hub on the workbench and connect it to the computer.
- Connect the following devices to the USB Hub:
 - Inkjet Printer
 - Laser Printer
 - Scanner
- Place the portable USB hard drive on the workbench and connect it to the computer.

Explanation

Complete this lab as follows:

1. Connect the USB hub to the computer.
 1. Switch to the **Back** view of the computer.
 2. Under Inventory, expand **Networking Devices**.
 3. Drag the **External USB hub** to the Workspace.
 4. Switch to the **Back** view of the USB hub.
 5. Under Inventory, expand **Cables**.
 6. Select **USB Cable Mini-B to Type A**.
 7. From the Selected Item pane:
 - Drag the **USB Mini-B Vertical Connector** to the USB port on the back of the USB hub.

- Drag the **USB Type A Standard Connector** to an open USB port on the back of the computer.
 - 8. Switch to the **Front** view of the USB hub.
- 2. Connect the inkjet printer to the USB hub.
 - 1. Switch to the **Back** view of the inkjet printer.
 - 2. Identify the **USB port**.
 - 3. Under Inventory, select **USB Cable Type B (Standard) to Type A (Standard)**.
 - 4. From the Selected Item pane:
 - Drag the **USB Type B Standard Connector** to the USB port on the inkjet printer.
 - Drag the **USB Type A Standard Connector** to an open USB port on the USB hub.
- 3. Connect the laser printer to the USB hub.
 - 1. Above the laser printer, select the Change View icon and then **Back**.
 - 2. Identify the **USB port**.
 - 3. Under Inventory, select **USB Cable Type B (Standard) to Type A (Standard)**.
 - 4. From the Selected Item pane:
 - Drag the **USB Type B Standard Connector** to the USB port on the laser printer.
 - Drag the **USB Type A Standard Connector** to an open USB port on the USB hub.
- 4. Connect the scanner to the USB hub.
 - 1. Above the scanner, select the Change View icon and then **Back**.
 - 2. Identify the **USB port**.
 - 3. Under Inventory, select **USB Cable Type B (Standard) to Type A (Standard)**.
 - 4. From the Selected Item pane:
 - Drag the **USB Type B Standard Connector** to the USB port on the scanner.
 - Drag the **USB Type A Standard Connector** to an open USB port on the USB hub.
- 5. Connect the portable USB hard drive to the computer.
 - 1. Under Inventory, select **Cables** to return to the list of inventory categories, then expand **Storage**.
 - 2. Drag the **Portable USB Hard Drive** onto the Workspace.
 - 3. Above the portable USB hard drive, select the Change View icon and then **Back**.
 - 4. Identify the **USB port**.

5. Under Inventory, select **Storage** to return to the list of inventory categories, then expand **Cables**.
6. Select **USB Cable Mini-B to Type A**.
7. From the Selected Item pane:
 - Drag the **USB Mini-B Vertical Connector** to the USB port on the external hard drive.
 - Drag the **USB Type A Standard Connector** to an open USB port on the computer.