

CompTIA A+ Core 1 Playbook

IT Labs

Prepared by Garrick White

9.1.11 Configure a laptop Dock and external Peripherals

An employee that works in the field has a laptop as their primary PC, but they would like an easy way to connect their laptop to their monitor and peripherals when they are in the office. You will install a USB-C dock in the office and connect all the peripherals to it so the employee only has to connect one cable to their laptop.

Step 1: Connect Monitor

Using a Displayport Cable, connect the external monitor to the Universal Dock

Connect power cable to external monitor

Step 2: Connect peripherals

Locate the USB keyboard and Mouse and connect them both to the Universal Dock

Step 3: Connect Ethernet

Locate the ethernet cable connected to the wall and connect the other end to the Universal Dock

Step 4: Connect Dock Power Adapter

Plug in Universal Dock power adapter to a power outlet and connect it to the dock

Step 5: Connect Dock to Laptop

Using the USB-C cable, connect the Universal Dock to the laptop

Step 6: Power on the External Monitor

Step 7: Test the Dock

Using the power button above the laptop keyboard, turn on the laptop to ensure external monitor and peripherals work properly