

AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

11/26/2024 4:55:57 PM

Repair Order #

41953

AUSTIN AUTOMOTIVE LLC
2625 E MAIN ST
CANON CITY, CO 81212
719-275-5055

11/27/2024 10:41:20

Credit Sale

Transaction #: 1
Card Type: Visa
Account: ****4619
Entry: Manual
Amount: USD\$89.27
Ref. Number: 631808397
HREF: 631808397
Global UID: 124007172202411271041202179
Auth. Code: 04539D
Batch #: 118
Response: Transaction approved

ND SOLAR

2001 Ford F250 Super Duty 3/4 Ton - Pickup

Odometer In: 207950

Odometer Out: 207950

License: CTA-523 CO

VIN: 1FTNF21L51EC24667

Eng: 5.4 L 330 CID V8 SOHC

757Jason

CUSTOMER COPY

Thank You!

Vehicle Time In: 11/25/2024 9:11:10AM

Vehicle Time Out: 11/26/2024 4:54:56PM

LUBE, OIL, AND FILTER CHANGE

DRAIN AND REFILL CRANKCASE WITH PREMIUM MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER, TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$25.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

5W/20 Synthetic Blend Oil

Oil Filter

Air Filter

Labor: \$0.00

Parts: \$50.53

Sublet: \$0.00

Quantity	Sale	Extended
6.00	\$3.99	\$23.94
1.00	\$5.27	\$5.27
1.00	\$21.32	\$21.32

Job Total: \$50.53



Service Advisor: Kevin Owens

Technician(s): Kyle S #55,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$25.00
Parts Total: \$50.53

Shop Supplies: \$6.04
HazMat: \$2.95

Sub Total: \$84.52
Tax Total: \$4.75
Grand Total: \$89.27
Balance Due: \$89.27



SIGNATURE.....

DATE.....



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MONDAY - THURSDAY 7:30AM - 5:30PM / FRIDAY 7:30-4:30

04/20/2020 1:54:14 PM

Invoice #
21473

MAIN PROPERTY SERVICES

CITY RD 356
WESTCLIFFE CO, 81252
Day 719-306-9606 MATT

2001 Ford F250 Super Duty 3/4 Ton - Pickup

Odometer In: 198678

Odometer Out: 198678

License: CTA-523 CO

VIN: 1FTNF21L51EC24667

Eng: 5.4 L 330 CID V8 SOHC

INVOICE

Vehicle Time In: 3/27/2020 8:49:14AM

Vehicle Time Out: 4/20/2020 1:53:38PM

CONCERN AND CAUSE

CUSTOMER STATES : CHECK SERVICE ENGINE SOON LIGHT WAS ON, HAD A PRNDL CODE. CHECK 4X4 SYSTEM, 4 WHEEL DRIVE WORKS, BUT HUBS ARE HARD TO TURN. ALSO IN 4X4 HEAR A SHIELD OR SOMETHING RUBBING OR SPRING COMPRESSION SOUND IN DRIVERS SIDE. PERFORM VEHICLE INSPECTION. CHECK HORN INOP, AIR BAG LIGHT ON, AND WHEEL IS SLIGHTLY OFF. CHECK FOR SPARE TIRE WINCH. SEE IF POSSIBLE TO REPLACE SPLINED LUG NUTS.

INSPECTION RESULTS: SCANNED AND FOUND CODE P0705 TRANSMISSION RANGE SENSOR, NEEDS NEUTRAL SAFETY SWITCH/SENSOR REPLACED. CLOCK SPRING IS BROKES CAUSING HORN AND AIR BAG LIGHT. SHIFT TUBE IS WORN AND HAS SLOP, SHIFT LINKAGE BOLTS ARE LOOSE. FRONT AXLE U-JOINTS ARE BAD, BOTH 4X4 SWITCHING HUBS ARE WORN INTERNALLY. NEEDS UPPER AND LOWER BALL JOINTS, BOTH TIE RODS FOR DRAG LINK ARE LOOSE CAUSING STEERING WHEEL TO BE OFF CENTER. SPARE TIRE WINCH CABLE IS BROKEN AND SPARE IS IN BED OF TRUCK. REAR DIFFERENTIAL WILL NEED OVERHAULED IN FUTURE.

STEERING COLUMN SHIFT TUBE Remove & Replace

Includes Air Bag Clockspring

Description

Steering Column Shift Tube Assembly
Air Bag Clock Spring

Quantity

Sale

Extended

1.00

\$67.02

\$67.02

1.00

\$226.99

\$226.99

Labor: \$303.00

Parts: \$294.01

Sublet: \$0.00

Job Total: \$597.01

NEUTRAL SAFETY SWITCH Remove & Replace

Description

Neutral Safety Switch / Range Sensor

Quantity

Sale

Extended

1.00

\$91.35

\$91.35

Labor: \$50.50

Parts: \$91.35

Sublet: \$0.00

Job Total: \$141.85

SPARE TIRE WINCH Remove & Replace

Description

Spare Tire Winch

Quantity

Sale

Extended

1.00

\$59.99

\$59.99

Labor: \$101.00

Parts: \$59.99

Sublet: \$0.00

Job Total: \$160.99

BALL JOINT Remove & Replace

Upper & Lower Both Sides, DOES NOT include alignment.

Description

Ball Joint - Front Upper
Ball Joint - Front Lower
Wheel Bearing Assembly with Sensor - Front Right
Four Wheel Drive Locking Hub - Warn
14mm x 2.0 19mm Hex Chrome Acorn Lug - Long

Quantity

Sale

Extended

2.00

\$65.99

\$131.98

2.00

\$90.99

\$181.98

1.00

\$226.24

\$226.24

1.00

\$388.99

\$388.99

32.00

\$1.59

\$50.88

Labor: \$505.00

Parts: \$980.07

Sublet: \$0.00

Job Total: \$1,485.07

AXLE UNIVERSAL JOINT Remove & Replace

Description

Universal Joint (U-Joint) - Wheel Joint

Quantity

Sale

Extended

2.00

\$64.99

\$129.98

Labor: \$101.00

Parts: \$129.98

Sublet: \$0.00

Job Total: \$230.98



Continued From Previous Page

DRAG LINK Remove & Replace

Description

Drag Link
 Tie Rod End - Inner
 Steering Stabilizer

Quantity	Sale	Extended
1.00	\$74.99	\$74.99
1.00	\$154.99	\$154.99
1.00	\$47.99	\$47.99

Labor: \$101.00

Parts: \$277.97

Sublet: \$0.00

Job Total: \$378.97

FRONT WHEEL ALIGNMENT

2 WHEEL THRUST ALIGNMENT, INCLUDES COMPLETE INSPECTION OF ALL FRONT AND REAR SUSPENSION AND STEERING COMPONENTS. ADJUST CASTER, CAMBER AND TOE IN OF FRONT END TO FACTORY SPECIFICATIONS, STRAIGHTEN STEERING WHEEL IF NEEDED. DOES NOT INCLUDE REPLACEMENT OF ANY WORN OR DAMAGED PARTS.

Labor: \$79.95

Parts: \$0.00

Sublet: \$0.00

Job Total: \$79.95

PAID
 Visa

Recommendations

04/20/2020 RO# 21473 Sub Estimate 1 indicates a REAR DIFFERENTIAL OVERHAUL \$1025 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.

Service Advisor: KEVIN OWENS

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

A 12 month or 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All local warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA AutoCare Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total:	\$1,241.45
Parts Total:	\$1,833.37
Sublet Total:	\$0.00
Shop Sup:	\$20.00
HazMat:	\$0.00

Sub Total:	\$3,094.82
Tax Total:	\$155.68
Grand Total:	\$3,250.50



SIGNATURE.....

DATE.....



B&D AUTOMOTIVE

601 Main St

Silver Cliff, CO. 81252

Phone: 719-783-4222 Fax: 719-783-4222

Experience Eliminates Experiments

INVOICE**24995****INVOICE**

Work Completed : 11/22/2019

Date: 11/25/2019

BAYER, MATT

1094 CR 260

Westcliffe, CO 81252

Home 719-306-9606

2001 Ford - Pickup F250 Super Duty -

Lic # :

Odometer In : 197009

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
SERPENTINE BELT 5081000	1.00	70.72	70.72	FUEL PUMP	3.50	308.00
ELECTRIC FUEL PUMP FE0479	1.00	220.02	220.02	RAISE VEHICLE. DISCONNECT FUEL LINES. DISCONNECT FILL TUBE. DISCONNECT ELECTRICAL CONNECTORS. REMOVE FUEL TANK. REMOVE OLD AND INSTALL NEW FUEL PUMP AND STRAINER. REASSEMBLE IN REVERSE ORDER. TEST DRIVE AND RECHECK OPERATION. EVERYTHING OK AT THIS TIME.		
FUEL PUMP STRAINER FS0093	1.00	51.60	51.60	FRONT DIFFERENTIAL FLUID CHANGE	0.50	44.00
PCM XTP88491F	1.00	545.96	545.96	REMOVE COVER. REMOVE OLD GASKET MATERIAL, DRAIN OLD FLUID, INSPECT INTERNALS AND REASSEMBLE WITH NEW GASKET. INSTALL NEW FLUID TO PROPER LEVELS. ROAD TEST VEHICLE FOR PROPER OPERATION.		
Automatic Transmission Fluid ATF	17.00	5.99	101.83	REAR DIFFERENTIAL FLUID CHANGE	0.50	44.00
SYNTHETIC GEAR OIL 75-140 Size: QT 690-32	4.00	25.98	103.92	REMOVE COVER. REMOVE OLD GASKET MATERIAL, DRAIN OLD FLUID. INSPECT INTERNALS AND REASSEMBLE WITH NEW GASKET. INSTALL NEW FLUID TO PROPER LEVEL. ROAD TEST VEHICLE FOR PROPER OPERATION.		
LS II BG328	1.00	17.30	17.30	TRANSFER CASE FLUID CHANGE	0.50	44.00
ATC + BG310	1.00	26.10	26.10	SERVICED AS REQUESTED.		
CONVENTIONAL GEAR OIL 80-90 Size: QT 780-32	2.00	14.58	29.16	AUTOMATIC TRANSMISSION FLUID FLUSH	2.00	176.00
Shop Supplies			6.00	ROAD TEST AND VERIFY ENGINE PERFORMANCE, TRANSMISSION OPERATION, AND SHIFT PATTERNS. FLUSH TRANSMISSION WHICH INCLUDES: FLUSHING OF TRANSMISSION COOLER, COOLER LINES, VALVE BODY, AND TORQUE CONVERTER. FLUSH ALL CONTAMINATED FLUID OUT AND REPLACE WITH PROPER ATF, USING BG ADDITIVES.		
				CHECK NO START	3.00	264.00
				AFTER REMOVING AND REPLACING FUEL PUMP VEHICLE STILL WOULD NOT START. WENT THROUGH ALL FUSES AND PCM CONNECTIONS SPOKE WITH CUSTOMER AND FOUND THEY WERE WELDING ON VEHICLE AND DETERMINED PCM BAD. REMOVED OLD PCM AND INSTALLED NEW. PROGRAMMED PCM FOR VEHICLE. TEST DROVE AND CHECKED OPERATION. ALL OKAY AT THIS TIME.		
				SERPENTINE BELT	0.70	61.60
				REMOVED AND REPLACED SERPENTINE BELT		
				[Discount] 10.00% off parts, 10.00% off labor		
				Hazardous Materials		2.50

- B&D 5100 series clocks (x4)
- Fuel filter - Napa gold
- Air filter - Napa gold
- Oil change - 10W30
- oil filter - Napa gold
- New Battery - Interstate
- Radiator flush - Green

Our Email Address: **KOESTER1717@AOL.COM**

B&D AUTOMOTIVE

601 Main St

Silver Cliff, CO. 81252

Phone: 719-783-4222 Fax: 719-783-4222

Experience Eliminates Experiments

INVOICE**24995****INVOICE**

Work Completed : 11/22/2019

Date: 11/25/2019

BAYER, MATT

1094 CR 260

Westcliffe, CO 81252

Home 719-306-9606

2001 Ford - Pickup F250 Super Duty -

Lic # :

Odometer In : 197009

VIN# :

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

[Payments - Check (#2126) - \$1,978.75]

Find us on facebook-B&D Automotive

An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Warranty on parts and labor is 12 months or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Find us on facebook-B&D Automotive

Vehicle Received: 11/22/2019

Customer Number : 756

Signature _____

Date _____

Labor:	941.60
Parts:	1,172.61
HazMat:	2.50
Discount:	-210.82
Sub:	1,905.89
Tax:	72.86
Total:	\$1,978.75
Bal Due:	\$0.00

Our Email Address: **KOESTER1717@AOL.COM**