

Utah

Buyer's Order

Dealer Seller Name and Address Forrest Motors LLC 925 S State St Orem, UT 84097 (801) 709-1520	Buyer Name, Address, Phone, Email Matthew Steven Bayer 1722 Edelweiss Dr Westcliffe, CO 81252 (719) 306-9606 031630479	Buyer Name, Address, Phone, Email Kalea Marie Bayer 1722 Edelweiss Dr Westcliffe, CO 81252 (719) 663-1078 170562924	Buyer Name, Address, Phone, Email
Date 7/13/2024	Stock No. 853213	Salesperson Forrest Hale	
App. No.		Contract No. 2078	

Definitions. Contract refers to this Buyer's Order. Buyer, you and your refer to each Buyer signing this Contract. Seller, we, us and our refer to the Dealer/Seller. Vehicle means the motor vehicle described in the Vehicle Information section. Trade in Vehicle(s) refers to each vehicle described in the Trade-in Information section that is being traded to the Dealer/Seller as part of this transaction. Manufacturer refers to the entity that is the maker of the Vehicle.

Agreement to Purchase. You agree to buy the Vehicle from us for the amount stated in this Contract. You agree to sign any documents necessary to complete this transaction. You may only cancel this contract according to the conditions described in the Manufacturer or Trade-In sections. If you refuse to take delivery of the Vehicle, we may keep any deposits you have made to us. In addition, refusal to take delivery will make you responsible for our damages, expenses, and attorney's fees in connection to this Contract unless prohibited by the law of Utah. If you do not breach this Contract, any deposits will be used toward the purchase of the Vehicle.

Vehicle Information			
☐ New ☒ Used ☐ Demo ☐ Other			
Year 2017	Make Nissan	Model NV3500 HD Passenger	Style Passenger
VIN 5BZAF0AA5HN853213		Odometer Reading 77106	
Lic. No.		Color Silver	
Other			

FINANCING ARRANGEMENT DISCLOSURES

☒ Purchaser (Buyer) is solely responsible for financing arrangements. THE PURCHASER OF THE MOTOR VEHICLE DESCRIBED IN THIS CONTRACT ACKNOWLEDGES THAT THE SELLER OF THE MOTOR VEHICLE HAS MADE NO PROMISES, WARRANTIES, OR REPRESENTATIONS REGARDING SELLER'S ABILITY TO OBTAIN FINANCING FOR THE PURCHASE OF THE MOTOR VEHICLE. FURTHERMORE, PURCHASER UNDERSTANDS THAT IF FINANCING IS NECESSARY IN ORDER FOR THE PURCHASER TO COMPLETE THE PAYMENT TERMS OF THIS CONTRACT ALL THE FINANCING ARRANGEMENTS ARE THE SOLE RESPONSIBILITY OF THE PURCHASER.

Signature of the Purchaser: Matthew Steven Bayer
Signature of the Purchaser: Kalea Marie Bayer
Signature of the Purchaser:

- Seller agrees to seek financing arrangements for Purchaser (Buyer)
- (1) THE PURCHASER OF THE MOTOR VEHICLE DESCRIBED IN THIS CONTRACT HAS EXECUTED THE CONTRACT IN RELIANCE UPON THE SELLER'S REPRESENTATION THAT THE SELLER CAN PROVIDE FINANCING ARRANGEMENTS FOR THE PURCHASE OF THE MOTOR VEHICLE. THE PRIMARY TERMS OF THE FINANCING ARE AS FOLLOWS:
- INTEREST RATE BETWEEN N/A % AND 0.00 % PER ANNUM, TERM BETWEEN MONTHS AND MONTHS. MONTHLY PAYMENTS BETWEEN \$ 0.00 PER MONTH AND \$ N/A PER MONTH BASED ON A DOWN PAYMENT OF \$ 1920.00
- (2) (a) IF SELLER IS NOT ABLE TO ARRANGE FINANCING WITHIN THE TERMS DISCLOSED, THEN SELLER MUST WITHIN SEVEN CALENDAR DAYS OF THE DATE OF SALE MAIL NOTICE TO THE PURCHASER THAT HE /S NOT BEEN ABLE TO ARRANGE FINANCING
- (b) PURCHASER THEN HAS 14 DAYS FROM THE DATE OF SALE TO ELECT, IF PURCHASER CHOOSES, TO RESCIND THE CONTRACT OF SALE PURSUANT TO SECTION 41-3-401.
- (c) IN ORDER TO RESCIND THE CONTRACT OF SALE, THE PURCHASER SHALL:
- (i) RETURN TO SELLER THE MOTOR VEHICLE HE PURCHASED.
- (ii) PAY THE SELLER AN AMOUNT EQUAL TO THE CURRENT STANDARD MILEAGE RATE FOR THE COST OF OPERATING A MOTOR VEHICLE ESTABLISHED BY THE FEDERAL INTERNAL REVENUE SERVICE FOR EACH MILE THE MOTOR VEHICLE HAS BEEN DRIVEN, AND
- (iii) COMPENSATE SELLER FOR ANY PHYSICAL DAMAGE TO THE MOTOR VEHICLE.
- (3) IN RETURN, SELLER SHALL GIVE BACK TO THE PURCHASER ALL PAYMENTS OR OTHER CONSIDERATION PAID BY THE PURCHASER, INCLUDING ANY DOWN PAYMENT AND ANY MOTOR VEHICLE TRADED IN.
- (4) IF THE TRADE-IN HAS BEEN SOLD OR OTHERWISE DISPOSED OF BEFORE THE PURCHASER RESCINDS THE TRANSACTION, THEN THE SELLER SHALL RETURN TO THE PURCHASER A SUM EQUIVALENT TO THE ALLOWANCE TOWARD THE PURCHASE PRICE GIVEN BY THE SELLER FOR THE TRADE-IN, AS NOTED IN THE DOCUMENT OF SALE.
- (5) IF PURCHASER DOES NOT ELECT TO RESCIND THE CONTRACT OF SALE AS PROVIDED IN SUBSECTION (2)(b) OF THIS FORM:
- (a) THE PURCHASER IS RESPONSIBLE FOR ADHERENCE TO THE TERMS AND CONDITIONS OF THE CONTRACT OF SALE BEING FOUND IN DEFAULT OF THE TERMS AND CONDITIONS;
- (b) THE TERMS AND CONDITIONS OF THE DISCLOSURES SET FORTH IN SECTION (1) OF THIS FORM ARE NOT BINDING ON THE SELLER; AND
- (c) IF FINANCING IS NECESSARY FOR THE PURCHASER TO COMPLETE THE PAYMENT TERMS OF THE CONTRACT OF SALE, THE PURCHASER IS SOLELY RESPONSIBLE FOR MAKING ALL THE FINANCING ARRANGEMENTS.
- (6) SIGNING THIS DISCLOSURE DOES NOT PROHIBIT THE PURCHASER FROM SEEKING HIS OWN FINANCING.

Signature of the Purchaser: _____
Signature of the Seller: Forrest Motors LLC

Insurance Information

Buyer has arranged the following insurance on the motor vehicle:

Insurance Company _____

Policy No. _____

Phone _____

Trade-In Information**Trade-in 1**

Year	Make
Model	Style
Lic. No.	Color
VIN	Odometer

Lienholder Name _____

Address _____

Phone _____

Trade-In Allowance
\$ 0.00Payoff
\$ N/A

Payoff good through

Trade-in 2

Year	Make
Model	Style
Lic. No.	Color
VIN	Odometer

Lienholder Name _____

Address _____

Phone _____

Trade-In Allowance
\$ 0.00Payoff
\$ N/A

Payoff good through

Trade-in Terms

Trade-in Vehicle. You will transfer title to the Trade-in Vehicle to us free of all liens except those noted on this Contract. You give permission to us to contact the lienholder(s) for payoff information. If the payoff information that we obtain from the lienholder(s) differs from the amount disclosed in this Contract, you agree to pay the difference to us if the actual amount of the balance owed is greater than the amount listed in this Contract. If the actual amount of the balance owed is less than the amount listed in this Contract, we will pay you the difference.

If you do not deliver the Trade-in Vehicle to us at the time of the initial appraisal, we may reappraise the Trade-in Vehicle when it is delivered to us. If the reappraised value is lower than the original appraisal, you will cancel this transaction as long as you have not taken delivery of the vehicle.

You represent that (a) you are the sole true and lawful owner of the Trade-in Vehicle, (b) the Trade-in Vehicle has never been titled under any state or federal brand such as "defective," "rebuilt," "salvage," "junk," and (c) you have disclosed otherwise in an odometer statement, the mileage of the Trade-in Vehicle shown in this Contract is the actual mileage of the Trade-in Vehicle, (d) all emission control equipment is on the Trade-in Vehicle and is in satisfactory working order, and (e) the frame on the Trade-in Vehicle has not been damaged by collision or other event and repaired. If any of these representations are not true, we may elect to cancel the transaction. We may also choose to reappraise the Trade-in Vehicle and adjust the Total Balance Due instead of canceling the transaction. You agree to immediately pay us the difference.

Itemization of Sale

1. Vehicle Sales Price	\$ 46500.00
Taxes	
2. Sales Tax	\$ N/A
3. Other Tax	\$ N/A
4. Subtotal (Add lines 1 through 3)	\$ 46500.00
Title, License & Other Fees	
5. Certificate of Title Fee	\$ N/A
6. License and/or Registration Fee	\$ N/A
7. Documentary Service Fee*	\$ N/A
8. Age Property Tax	\$ N/A
9. Filing	\$ N/A
10. Emission	\$ N/A
11. Temp Permit	\$ N/A
12.	\$ N/A
13.	\$ N/A
14.	\$ N/A
15.	\$ N/A
16. Total Other Fees (Add lines 5 through 15)	\$ N/A
Additional Items	
17.	\$ N/A
18.	\$ N/A
19.	\$ N/A
20.	\$ N/A
21.	\$ N/A
22.	\$ N/A
23.	\$ N/A
24.	\$ N/A
25.	\$ N/A
26.	\$ N/A
27. Total Additional Items (Add lines 17 through 26)	\$ N/A
28. Cash Sale Price (Add lines 4+16+27)	\$ 46500.00
29. Trade-in Allowance	\$ N/A
30. Trade-in Payoff Balance	\$ N/A
31. Net Trade Allowance (Line 29-30, if negative, enter \$0 here and enter amount on line 38.)	\$ N/A
32. Deposit	\$ N/A
33. Cash Down Payment	\$ 1920.00
34. Manufacturer's Rebate	\$ N/A
35. Deferred Down Payment	\$ N/A
36. Other Down Payment	\$ N/A
37. Total Credits (Add lines 31 through 36)	\$ 1920.00
38. Trade-in Balance Owning (see line 31)	\$
39. Lease Balance Owning	\$ N/A
40. Total Balance Due (Line 28-37-38-39)	\$ 44580.00

We may retain or receive a portion of any amounts paid to others.

*A Documentary Service Fee represents costs to the dealer for preparing and processing documents and other services related to the sale or lease of your vehicle. These fees are not set or state-mandated by state statute or rule.

USAA

PO Box 25145

Lenexa Valley, PA 18002



Additional Terms

Governing Law and Interpretation. This Contract is governed by the law of Utah and applicable federal law and regulations.

If any section or provision of this Contract is not enforceable, the other terms will remain part of this contract. You authorize us to correct any clerical error or omissions in this Contract or in any related document.

Manufacturer. We are not an agent of the Manufacturer. The Manufacturer can change the price, design or standard features of the Vehicle at any time without notice. If we cannot obtain the Vehicle from the Manufacturer at the price in effect as of the date of this Contract, or if we cannot obtain the agreed upon product from the Manufacturer, you or we can cancel this Contract.

If you cancel this Contract under the terms of this section, we will refund to you any amounts you have paid to us. If you have delivered a Trade-in Vehicle to us, we will return it to you. If we have already sold the Trade-in Vehicle, we will pay you the amount we received for the sale after adjusting for any payoff we made to a lienholder and costs for repair and reconditioning, if any.

Name and Location. Your name and address indicated on page 1 are your exact legal name and your principal residence.

Insurance. You represent that the insurance information you have given us is accurate.

Retail Installment Sales Contract. In the event that you and we enter into a retail installment sales contract for the financing of the purchase of the Vehicle, the terms of the retail installment sales contract will control any inconsistencies between this Contract and the retail installment sales contract.

Returned Payment Charge. If you make any payment by check required by this Contract that is dishonored (and not honored if we represent it) then you agree to pay us a service charge of \$20.00; additional fees may be imposed as provided by law.

If you have scheduled any other form of payment (electronic transfer, for example) and that payment is dishonored, you agree to pay us a service charge of \$20.00.

Seeking Financing Arrangements for Buyer. If the "Seller agrees to seek financing arrangements for Purchaser (Buyer)" disclosure is checked on page 1, we agree to assist you in securing financing to purchase the Vehicle. You agree to timely provide us with information we request in order to help arrange financing. We do not promise or guarantee that we will be successful in securing financing for your Vehicle purchase.

You understand and agree that we are not obligated to deliver the Vehicle to you before financing is completed. If we deliver the vehicle to you before financing is completed, we may require additional promises in an amendment to this Contract or a separate conditional delivery agreement signed by you and us.

The terms of this section are not intended to limit or change any applicable remedies described in the "Seller agrees to seek financing arrangements for Purchaser (Buyer)" disclosure or required by law.

Telephone Monitoring and Calling. You agree that we may from time to time monitor and record telephone calls made or received by us or our agents regarding your account to assure the quality of our service. In order for us to service the account or to collect any amounts you may owe, and subject to applicable law, you agree that we may from time to time make calls and send text messages to you using prerecorded/artificial voice messages or through the use of an automatic dialing device at any telephone number you provide to us in connection with your account, including a mobile telephone number that could result in charges to you.

Vehicle Condition. You understand the Vehicle may have undergone prior mechanical or body repair. The damage, necessitating repair may have occurred during manufacture, transit or while in the possession of prior owner or operators.

Vehicle Inspection

By initialing below, you represent that you have thoroughly inspected the Vehicle and approve and accept it. You had an opportunity to have the Vehicle inspected by a third party of your choice and at your expense. You are purchasing the Vehicle based on your inspection. You are not relying on any opinion, statement, or promise of the Seller or its employees that is not contained in the written agreements you are signing today.

WJB

AMB

Warranty Information

☐ **Vehicle Manufacturer Warranty.** The Vehicle is subject to an express warranty made by the Manufacturer. It is a standard written manufacturer's warranty and made by the Manufacturer and not by the Seller. By signing this Contract, each Buyer acknowledges receiving a copy of it.

☐ **Dealer Warranty.** The Vehicle is subject to an express written warranty made by the Seller. By signing this Contract, each Buyer acknowledges receiving a copy of it.

The Seller is responsible to fulfill any separate written warranty made by Seller on its own behalf. If the Manufacturer or another supplier provides a warranty, they are responsible for satisfying its terms, NOT the Seller.

If neither box above is checked under Warranty Information the Used Vehicle is sold AS-IS and the following paragraph applies:

THIS VEHICLE IS SOLD "AS-IS" WITH ALL FAULTS, WITHOUT ANY WARRANTY, EITHER EXPRESS OR IMPLIED AND BUYER IS SOLELY RESPONSIBLE FOR COST OF ANY REPAIRS TO THE VEHICLE. THE SELLER EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY. THERE IS NO WARRANTY THAT THE GOODS WILL BE FIT FOR A PARTICULAR PURPOSE. BUYER ASSUMES ALL RISKS AND RESPONSIBILITIES.

Used Car Buyer Notice

If you are buying a used vehicle, The information you see on the window form for this vehicle is part of this contract. Information on the window form overrides any contrary provisions in the contract of sale.

(Spanish Translation) Si compra un vehiculo usado: La información que ve adherida en la ventanilla forma parte de este contrato. La información contenida en el formulario de la ventanilla prevalece por sobre toda otra disposición en contrario incluida en el contrato de compraventa.

Notices

☐ **Trade-in Balance Due.** You understand that the balance owed on the Trade-in exceeds the Trade-in Allowance and that as a result the Total Balance Due has been increased by \$ N/A of negative equity.

☐ **Lease Balance Due.** You understand the Total Balance Due includes the amount of \$ _____ for a lease balance due from a prior transaction.

Signatures

This agreement is not binding upon the Dealer/Seller until it is signed by an authorized representative of the Dealer/Seller.


You represent that you are of legal age and have legal capacity to enter into this Contract.

☐ **A separate Arbitration Agreement between you and us is part of this Contract.**

You received a copy of this Contract and by signing below, you agree to the terms on all pages of this Contract and acknowledge you had a chance to read and review it before you signed it.

Entire Agreement. Your and our entire agreement is contained in this Contract. There are no unwritten agreements regarding this Contract.


Buyer Matthew Stoven Bayer 7/13/2024
Date


Buyer Kales Marie Bayer 7/13/2024
Date

Buyer _____ Date _____

Dealer/Seller Forrest Motors LLC 7/13/2024
Date

State Of Colorado
Joint Tenancy with Rights of Survivorship
Acknowledgement of Intent
C.R.S. 38-11-101

Any Alteration or Erasure may Void this Document

To create joint tenancy with rights of survivorship, there must be specific language declaring such intent, signed under penalty of perjury in the second degree by all owners. This form is only applicable to multiple owners.

Joint Tenancy with rights of Survivorship is defined as: A form of legal co-ownership of property (also known as survivorship). At the death of one co-owner, the surviving co-owner becomes sole owner of the property. Transfer of ownership requires copy of death certificate and signature of survivor.

Tenancy in Common is defined as: The equal or unequal holding of property by two or more persons. At the death of one co-owner, the deceased share of the property goes to his/her estate and is to be divided according to his/her will or the law in the absence of a will. Transfer of ownership requires documents appointing a personal representative for the decedent.

Vehicle Identification Number <u>5B2AFOAASHN853213</u>	Year <u>2017</u>	Make <u>Niss</u>	Model <u>NY</u>
---	---------------------	---------------------	--------------------

If any owner chooses Tenancy in Common or if neither box is checked; the Colorado Certificate of Title will be issued as Tenancy in Common.

Owner One	I <u>Matthew Steven Bayer</u> (print name) request the Colorado Certificate of Title for the Vehicle described above be issued in: ☒ Joint Tenancy With Rights of Survivorship ☐ Tenancy in Common Per C.R.S. 42-6-116; I certify under penalty of perjury in the second degree that the above information is true and correct to the best of my knowledge. <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 80%;">Owners Signature <u>Matthew Bayer</u></td><td style="width: 20%;">Date <u>9/11/2024</u></td></tr></table>	Owners Signature <u>Matthew Bayer</u>	Date <u>9/11/2024</u>
Owners Signature <u>Matthew Bayer</u>	Date <u>9/11/2024</u>		
Owner Two	I <u>Kalea Marie Bayer</u> (print name) request the Colorado Certificate of Title for the Vehicle described above be issued in: ☒ Joint Tenancy With Rights of Survivorship ☐ Tenancy in Common Per C.R.S. 42-6-116; I certify under penalty of perjury in the second degree that the above information is true and correct to the best of my knowledge. <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 80%;">Owners Signature <u>Kalea M Bayer</u></td><td style="width: 20%;">Date <u>9/4/2024</u></td></tr></table>	Owners Signature <u>Kalea M Bayer</u>	Date <u>9/4/2024</u>
Owners Signature <u>Kalea M Bayer</u>	Date <u>9/4/2024</u>		
Owner Three	I _____ (print name) request the Colorado Certificate of Title for the Vehicle described above be issued in: ☐ Joint Tenancy With Rights of Survivorship ☐ Tenancy in Common Per C.R.S. 42-6-116; I certify under penalty of perjury in the second degree that the above information is true and correct to the best of my knowledge. <table border="1" style="width: 100%; border-collapse: collapse;"><tr><td style="width: 80%;">Owners Signature</td><td style="width: 20%;">Date</td></tr></table>	Owners Signature	Date
Owners Signature	Date		

Keep Colorado Wild

Do you want to stay opted in to the Keep Colorado Wild Pass?

- ☐ Yes (Selecting YES supports Colorado's parks and wildlife and adds the pass to this vehicle's annual registration. This adds \$29 to your registration.)
- ☐ No (Selecting NO removes the pass from this vehicle unless I opt in to the pass at the next renewal period.)

The \$29 Keep Colorado Wild Pass is a 50% or greater savings on a regular annual state parks pass, it is non-refundable and non-transferable, and is calculated as part of this vehicle's registration unless you decline.

- Provides entry to all Colorado state parks
- Protects wildlife, lands, and water
- Supports search and rescue programs
- Funds trails and local community projects
- Helps make the outdoors safe and available to all

Verification of Vehicle Identification Number

C.R.S. 24-32-3323, 38-29-122, 42-3-105(l)(c), 42-6-107(l)(b)

Any Alteration or Erasure MAY Void This Document

Type of Vehicle ➡ ☒ Passenger ☐ Tractor ☐ Motor Home ☐ Motorcycle
☐ SUV ☐ Bus ☐ Special Mobile Machinery ☐ Off-Highway Vehicle
☐ Truck ☐ Trailer ☐ Manufactured Home

Vehicle Information

Vehicle Identification Number (VIN)

5 B Z A F O A A 5 H N S S 3 2 1 3

Year: 2017 Make: NISS Body: Van Model: NV Width: Length:

Color: Silver CWT: 1664 GVWR: Print Fuel Type: Gas

License Plate Number: State: Expiration Date:

Temporary Tag Number: State: Expiration Date:

Additional Vehicle Identification Number (VIN)

Motor Number

Coach Number

Reason for Inspection:

☒ Out of State ☐ Title Correction ☐ Other (Explain)

Verified by:

☐ Manufactured Home Dealer

☐ Licensed Colorado Dealer

Dealer Number

☒ County Clerk (at their discretion)

☐ Licensed Colorado Emission

Station Number

☐ County Assessor (at their discretion)

☐ Colorado Law Enforcement

☐ Other*

(Explain)

FEDERAL AND STATE LAW REQUIRE THAT THE OWNER(S) TRANSFER AND ODOMETER DISCLOSURE
FALSE STATEMENT MAY RESULT IN FINES AND/OR IMPRISONMENT

REASSIGNMENT OF TITLE - OWNER(S) TRANSFER AND ODOMETER DISCLOSURE
I (we) the undersigned owner(s) hereby transfer, convey and assign all rights, title and interest in the vehicle described herein to the new owner named in the last reassignment block completed below and warrant the title to be free and clear of all encumbrances, except a lien in favor of the person identified below within that block as new lienholder. If any this odometer reading (check one of the following):
() reflects the actual mileage for this vehicle;
() reflects the amount of mileage in excess of the odometer mechanical limits.
() is not the actual mileage for this vehicle. WARNING ODOMETER DISCREPANCY.

Model: 1990 Ford F1 VIN: 1F350300000000000
Year: 1990
Make: Ford
First REASSIGNMENT OF TITLE - OWNER(S) TRANSFER AND ODOMETER DISCLOSURE
Forrest Motors LLC
Print Name of Owner(s)/Transferor or Company
Address: 925 S State St
City: Green State UT Zip: 84097
Signature of Transferor(s) in ink (must be notarized)
Date: July 13, 2024
Subscribed and Sworn to this day of 20

Notary Seal
Notary Public or M.V. Examining Officer
NEW OWNER (name must be printed)
NAME: Matthew Steven Bayer Or Kalea Marie Bayer
ADDRESS: 1722 Edelweiss Dr
CITY: Westcliffe, CO 81252
Signature of Purchaser (New Owner)
NEW LIEN-HOLDER (Name must be printed)
NAME: USA
ADDRESS: 20 Box 25145
CITY: Lehigh Valley STPA ZIP: 18002
Signature of Owner/Authorized Agent
LIEN RELEASE
Signature of Lienholder Releasing Interest
Date Title

SECOND REASSIGNMENT OF TITLE - OWNER(S) TRANSFER AND ODOMETER DISCLOSURE
I (we) certify that on the date of this statement the odometer on the above described vehicle reads the mileage here recorded, and that to the best of my/our knowledge and belief this odometer reading (check one of the following):
() reflects the actual mileage for this vehicle;
() reflects the amount of mileage in excess of the odometer mechanical limits.
() is not the actual mileage for this vehicle. WARNING ODOMETER DISCREPANCY.

Print Name of Owner(s)/Transferor or Company
Print Name of Authorized Agent
Address
City State Zip
Signature of Transferor(s) in ink (must be notarized)
Date 20
Subscribed and Sworn to this day of 20
Notary Seal
Notary Public or M.V. Examining Officer
NEW OWNER (name must be printed)
NAME
ADDRESS
CITY
Signature of Purchaser (New Owner)
NEW LIEN-HOLDER (Name must be printed)
NAME
ADDRESS
CITY ST ZIP
Signature of Owner/Authorized Agent
LIEN RELEASE
Signature of Lienholder Releasing Interest
Date Title

THIRD REASSIGNMENT OF TITLE - OWNER(S) TRANSFER AND ODOMETER DISCLOSURE
I (we) certify that on the date of this statement the odometer on the above described vehicle reads the mileage here recorded, and that to the best of my/our knowledge and belief this odometer reading (check one of the following):
() reflects the actual mileage for this vehicle;
() reflects the amount of mileage in excess of the odometer mechanical limits.
() is not the actual mileage for this vehicle. WARNING ODOMETER DISCREPANCY.

Print Name of Owner(s)/Transferor or Company
Print Name of Authorized Agent
Address
City State Zip
Signature of Transferor(s) in ink (must be notarized)
Date 20
Subscribed and Sworn to this day of 20
Notary Seal
Notary Public or M.V. Examining Officer
NEW OWNER (name must be printed)
NAME
ADDRESS
CITY
Signature of Purchaser (New Owner)
NEW LIEN-HOLDER (Name must be printed)
NAME
ADDRESS
CITY ST ZIP
Signature of Owner/Authorized Agent
LIEN RELEASE
Signature of Lienholder Releasing Interest
Date Title

UTAH CERTIFICATE OF TITLE

New Title



Title Number: UT010828131

Vehicle Type: Truck

Year: 2017 Make: NISS

Model: NV

Body Style: Van

VIN/HIN: 5BZAF0AA5HN853213

Cylinders: 8

Fuel: Gasoline

Odometer: 77100

Date Issued: 08/27/2024



FORREST MOTORS LLC
925 S STATE ST
OREM UT 84097-7027

Owner Information:

FORREST MOTORS LLC
925 S STATE ST
OREM UT 84097-7027

Lienholder Information:

Vehicle History: This Utah title is not a vehicle history report. If you are buying or selling this vehicle, please visit the National Motor Title Information System (NMVTIS) website to obtain the most current history of the vehicle at https://vehiclehistory.bja.ojp.gov/nmvtis_vehiclehistory.

ODOMETER READING REFLECTS THE ACTUAL MILEAGE

Request For Lien Change

Complete this section. Send the title and required fee to the Division of Motor Vehicles. Please check one box.

☐ Issue a title free of liens

☐ Issue a title showing the following as the NEW LIEN HOLDER

LIEN RELEASE - Signature of lien holder (releasing interest)

Vehicle owner's signature requesting lien change

X

Title of signer

New lien holder's name

Date

Address

City

State

ZIP Code

Division of Motor Vehicles
UTAH STATE TAX COMMISSION
210 North 1950 West
Salt Lake City, Utah 84134



TC-127 Rev. 03/19 CDR



C8093010



Physical Address:
Custer County - Westcliffe
205 S 6th Street
Westcliffe CO 81252



Mailing Address:
PO BOX 150
WESTCLIFFE CO 81252-0150



COLORADO
Department of Revenue
Division of Motor Vehicles

September 17, 2024
Letter: L0128557341

APPLICATION FOR COLORADO CERTIFICATE OF TITLE FOR A MOTOR VEHICLE

VEHICLE ID	YEAR	MAKE	MODEL	BODY	FUEL TYPE
5BZAF0AA5HN853213	2017	NISS	NV	PV	Gasoline
EMPTY	CAPACITY	DIMENSIONS	ODOMETER	CODE	
6864	0		77106	Actual Mileage	
COUNTY	MSRP	PURCHASE PRICE	PURCHASE DATE	TITLE	SALES/USE
Custer County - Westcliffe	35,400.00	46,500.00	13-Jul-2024	47.20	2,278.50
PREVIOUS TITLE	PREVIOUS STATE	TITLE NUMBER	DATE ACCEPTED	TITLE TYPE	TOTAL FEES
UT010828131	UT	012154644	17-Sep-2024	Regular	2,616.57

LEGAL ADDRESS: 1722 EDELWEISS DR WESTCLIFFE CO 81252-9174

TITLE ADDRESS: USAA PO BOX 25145 LEHIGH VALLEY PA 18002-5145

OWNER(S)
OWNER TYPE JTWROS
 NAME

Standard MATTHEW STEVEN BAYER
Standard KALEA MARIE BAYER

LIENHOLDER(S)

LIENHOLDER	RECEIVED	MATURITY	EXTENSION	AMOUNT
USAA	17-Sep-2024	17-Sep-2034		44,580.00

I affirm under penalty of perjury in the second degree that the facts on the face of this document are true and correct to the best of my knowledge; and that the motor vehicle described is subject only to the lien(s) shown.

x
Owner or Agent Signature

9/17/2024
Date

ATTESTATION OF SECURE AND VERIFIABLE IDENTIFICATION

[X] Secure and verifiable identification on enclosed forms.
[] I, the undersigned witness, affirms that the named owner of the vehicle identified on this document presented to me the secure and verifiable identification as described below



CERTIFICATE OF TITLE



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

08/01/2024 2:59:09 PM

Repair Order #
40370

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR
WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

2017 Nissan NV3500 HD

Odometer In: 78400

Odometer Out: 78402

License: TEMP CO

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Repair Order

Vehicle Time In: 7/19/2024 11:51:47AM

Vehicle Time Out: 8/1/2024 2:57:27PM

CONCERN AND CAUSE

CUSTOMER STATES :
COMPLETE VEHICLE INSPECTION,
REAR BRAKES SQUEAL,
CHECK ENGINE LIGHT, EVAP SYSTEM LEAK,
HESITATES TAKING OFF FROM A STOP,
DRIVERS SIDE DOOR DOES NOT LOCK,
SERVICE A/C, WORKS GOOD, JUST WANTS SERVICED

INSPECTION RESULTS: SCANNED CODES P0420 | Three Way Catalyst System Bank 1, P0443 | Purge Volume Control / Valve, P00FE | Refer to OEM repair information for code description, P0174 | Fuel Injector Lean System B2. FREEZE FRAME DATA DID NOT SHOW LEAN CONDITION. FUEL TRIMS ARE NORMAL AT THIS TIME. INSPECTED EVAP SYSTEM. VENT SYSTEM APPEARS TO BE WORKING FINE WITH NO RESTRICTION. PURGE SOLENOID IS WORKING. ACTIVATED PURGE FOR 20 MINUTES AND RETESTED. PURGE IS FLOWING EVEN WHEN COMMANDED OFF. CHECKED THE ELECTRICAL CONTROL AND FOUND THE CONTROL IS TURNING OFF AS COMMANDED, PURGE SOLENOID IS STICKING OPEN AT TIMES, THIS WILL CAUSE LEAN CODE AND VENT CODE. NEEDS PURGE SOLENOID. INSPECTED CATALYTIC CONVERTERS AND O2 SENSORS. LOTS OF RUST, BANK 2 CATALYTIC CONVERTER PIPE HAS BEEN WELDED BACK TOGETHER BUT HAS HOLES. DOWNSTREAM O2 SENSOR IS BEHIND THIS REPAIR AND IS LIKELY PICKING UP FALSE AIR FROM THE LEAK. EXHAUST IS TOO RUSTY TO WELD EASILY, WILL LIKELY LEAK. BANK 1 CATALYTIC CONVERTER RATTLES INTERNALLY. NEEDS BOTH CATALYTIC CONVERTER - MANIFOLD ASSEMBLIES, DOWNSTREAM CATALYTIC CONVERTER PIPE ASSEMBLIES, WILL MORE THEN LIKELY NEED ALL O2 SENSORS BECAUSE OF RUST. HESITATION WILL NEED TO BE RECHECKED AFTER PURGE REPLACEMENT. INSPECTED DRIVERS DOOR LOCK, POWER AND GROUND IS PRESENT. NEEDS LOCK ACTUATOR/LATCH ASSEMBLY. A/C SYSTEM WAS 1lbs LOW CHARGE. ADDED DYE FOR FUTURE LEAKS. REAR BRAKES ARE GLAZED AND PADS AND ROTORS WILL NEED REPLACED TO STOP SQUEALING. AWD/4WD - Current Codes, P180D | Rotary Position Sensor, P1817 | Shift Actuator, P1819 | Shift Actuator Circuit, P180F | Motor System, P1867 | Incomplete Shift, P1816 | PNP Switch / Circuit. DID NOT DIAGNOSIS OR GET INTO 4WD SYSTEM.

Labor: \$154.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$154.00

USED VEHICLE INSPECTION

INSPECT TIRES, BRAKES, STEERING AND SUSPENSION COMPONENTS. EXAMINE BELTS AND HOSES FOR WEAR. TEST LIGHTS, WINDSHIELD WIPERS AND WASHER SYSTEM. TOP OFF ALL FLUIDS, CHECK FOR LEAKS, AND ADJUST TIRE PRESSURE.

LUBE, OIL, AND FILTER CHANGE

DRAIN AND REFILL CRANKCASE WITH PREMIUM MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER, TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$25.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

0W/20 Full Synthetic Oil
Nissan Oil Filter
Air Filter
Interstate Battery

Quantity

6.90
1.00
1.00
1.00

Sale

\$5.99
\$8.55
\$42.54
\$179.99

Extended

\$41.33
\$8.55
\$42.54
\$179.99

Labor: \$0.00

Parts: \$272.41

Sublet: \$0.00

Job Total: \$272.41





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

08/01/2024 2:59:09 PM

Repair Order #

40370

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

Repair Order

2017 Nissan NV3500 HD

Odometer In: 78400

Odometer Out: 78402

License: TEMP CO

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Continued From Previous Page

AIR CONDITIONING SYSTEM CHARGE

Includes Evacuating, Vacuum, And Recharge System With Freon And Add Leak Detector Oil/Dye. Inspect All Connections And Seals, Check For Leaks With Ultraviolet Light And Freon Detector. Does Not Include System Repairs.

Description

BG Air Conditioning Oil With Dye
R134A Refrigerant

Quantity

Sale

Extended

1.00

\$6.95

\$6.95

1.00

\$28.99

\$28.99

Job Total: \$120.93

Labor: \$84.99

Parts: \$35.94

Sublet: \$0.00

PURGE CONTROL SOLENOID Remove & Replace

Description

Vapor Canister Purge Solenoid

Quantity

Sale

Extended

1.00

\$181.70

\$181.70

Job Total: \$258.70

Labor: \$77.00

Parts: \$181.70

Sublet: \$0.00

DOOR LATCH Remove & Replace

Description

Door Lock Actuator - Front Left

Quantity

Sale

Extended

1.00

\$174.75

\$174.75

Job Total: \$359.55

Labor: \$184.80

Parts: \$174.75

Sublet: \$0.00

DISC ROTOR Remove & Replace

Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary).
DOES NOT include refinishing.

Description

Brake Pads - Rear - Fleet

Brake Rotor (Rotor Only) - Rear - Premium

Quantity

Sale

Extended

1.00

\$131.39

\$131.39

2.00

\$177.79

\$355.58

Job Total: \$671.77

Labor: \$184.80

Parts: \$486.97

Sublet: \$0.00





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

08/01/2024 2:59:09 PM

Repair Order #
40370

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

Repair Order

2017 Nissan NV3500 HD

Odometer In: 78400

License: TEMP CO

Odometer Out: 78402

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Continued From Previous Page



Service Advisor: Kevin Owens

Technician(s): Patrick D #39, ; Pete S #53,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$710.59
Parts Total: \$1,151.77

Shop Supplies: \$25.00
HazMat: \$2.95

Sub Total: \$1,890.31
Tax Total: \$98.85
Grand Total: \$1,989.16
Balance Due: \$1,989.16



SIGNATURE..... DATE.....





Car Pros Muffler Masters

3015 North Stone Avenue
Colorado Springs, CO 80907
(719) 636-1087
mufflermasterscs@gmail.com
http://mufflermasterscs.com

Invoice for RO #29334

Service Advisor: Sean Heuertz
Date Created: 12/02/24 at 08:00 AM MST
Client: MATTHEW BAYER
Vehicle: 2017 Nissan NV3500 SL

MATTHEW BAYER
1722 Edelweiss Drive
Westcliffe, CO 81252
Phone: (719) 306-9606
Email: MATTHEW.BAYER@OUTLOOK.COM

2017 Nissan NV3500 SL 5.6L 8Cyl GAS
VK56DE Naturally Aspirated
VIN: 5BZAF0AA5HN853213
License: DHUK28
Color: N/A
Odometer In: 80397 / Out: 80430

RO # 29334
Time-In: 12/02/24 at 08:00 AM MST

Client concerns:

- CUSTOMER REQUESTS QUOTE FOR EXHAUST REPAIR, CHECK HISTORY FOR PREVIOUS RECOMMENDATIONS
- CUSTOMER REQUESTS QUOTE FOR WIPERS
- CUSTOMER REQUESTS QUOTE FOR NEW TIRES
- CUSTOMER STATES THAT THE VEHICLE WILL RUMBLE AT 55MPH AND OVER, NOTICED SKID PLATE IS RATTLING, CHECK AND ADVISE

1 - CUSTOMER REQUESTS QUOTE FOR EXHAUST REPAIR, CHECK HISTORY FOR PREVIOUS RECOMMENDATIONS

Note: There is a heat shield on the exhaust pipe that is rattling. Could put hose clamps or remove it

✓ Approved on 12/02/24 at 08:00 AM MST

0

0

2 - CUSTOMER REQUESTS QUOTE FOR NEW TIRES, KEEP BEST OF THE TIRES COMING OFF FOR THE SPARE

Tech: JG

Note: wash the mud off from the rear wheels mount tires and torque wheels too 131lbs

Labor:	DISMOUNT AND REMOUNT 4 NEW TIRES AND COMPUTER SPIN BALANCE, ADJUST AIR PRESSURE		\$114.00
Parts:	1/4 WHEEL WEIGHT	6	\$23.94
	DISCOVERER STRONGHOLD AT RWL - LT265/70/17 - E - Tire #1 - 1UTAHF91V3224, Tire #2 - 1UTAHF91V3224, Tire #3 - 1UTAHF91V3224, Tire #4 - 1UTAHF91V3224	4	\$943.44
Fees:	WASTE TIRE REMOVAL FEE		\$4.50
	WASTE TIRE REMOVAL FEE		\$4.50
	WASTE TIRE REMOVAL FEE		\$4.50
	WASTE TIRE REMOVAL FEE		\$4.50
	NEW TIRE STATE WASTE TIRE FEE		\$0.55
	NEW TIRE STATE WASTE TIRE FEE		\$0.55
	NEW TIRE STATE WASTE TIRE FEE		\$0.55
	NEW TIRE STATE WASTE TIRE FEE		\$0.55

✓ Approved on 12/02/24 at 03:13 PM MST

Subtotal \$1,101.58 + est. Tax \$84.33

\$1,185.91

3 - CUSTOMER STATES THAT THE VEHICLE WILL RUMBLE AT 55MPH AND OVER, NOTICED SKID PLATE IS RATTLING, CHECK AND ADVISE

Tech: JG

Note: There is no skid plate but the front bumper is missing 2 bolts and could cause a rattle in the front. Also the hood looks loose driving down the highway. Recommend installing new bolts and adjusting the hood latch and bumpers. install bolts and a hose clamp and weld 2 small leaks in the exhaust

Labor:		\$84.50
✓ Approved on 12/02/24 at 08:00 AM MST		\$84.50

4 - Multipoint Vehicle Inspection

Tech: JG

Labor:	Complimentary Multi-point Vehicle Inspection	\$0.00
--------	--	--------

✓ Approved on 12/02/24 at 08:00 AM MST

0

0

WHEEL ALIGNMENT, LIFTED, LOWERED OR MODIFIED VEHICLES

Adjust to manufactures specifications, where applicable, set tire air pressure, check for steering angle reset procedure, road test vehicle

✓ Approved on 12/02/24 at 03:13 PM MST

\$135.00

\$135.00

6 - RECOMMEND REPLACING THE REAR WHEEL LUG THAT IS STRIPPED

Tech: JG

Note: when removing the right rear wheel one lug nut seized on the wheel stud. Cut off lug nut and install a new wheel stud and lug nut

Labor:	Remove & Replace Rear Wheel Lug Stud (One)		\$101.39
Parts:	Wheel Lug Stud	1	\$20.42
	Wheel Lug Nut	1	\$16.99

✓ Approved on 12/02/24 at 03:13 PM MST

Subtotal \$138.80 + est. Tax \$3.07

\$141.87

7 - REPLACE WIPER BLADE(S)

Tech: JG

Note: adjusted both wiper arms and tighten the nuts

Labor:	REPLACE WIPER BLADE(S)		\$0.00
Part:	WIPER BLADE	2	\$37.98

✓ Approved on 12/02/24 at 03:13 PM MST

Subtotal \$37.98 + est. Tax \$3.11

\$41.09

8 - RECOMMEND REPLACING THE OUTER TIE ROD ENDS AND PITMAN ARM

Tech: JG

Note: When installing the pitman arm it was seized to the gear box and had to cut it off. Install both outer tie rod ends the left side adjustment was also seized. Test drove and everything feels good

Labor:	Remove & Replace Outer Tie Rod (Both Sides)		\$152.09
	Remove & Replace Steering Pitman Arm		\$386.82
	Additional Labor for Pitman Arm Removal		\$150.00
Parts:	Steering Tie Rod End	2	\$215.92
	Steering Pitman Arm	1	\$214.94

✓ Approved on 12/02/24 at 03:13 PM MST

Subtotal \$1,119.77 + est. Tax \$35.33

\$1,155.10

9 - RECOMMEND REMOVING THE DRIVESHAFT AND SENDING OUT FOR REPAIR

Tech: JG

Note: Felt a vibration at 55. Put the vehicle on the rack drove it to 55 and you could see the drive shaft was bent. Took the shaft and had it straighten and balanced and there is a considerable difference when driving

Labor:	Remove & Replace Driveshaft		\$185.89
--------	-----------------------------	--	----------

✓ Approved on 12/04/24 at 12:30 PM MST

\$185.89

10 - Custom Sublet

Sublet:	REPAIR DRIVESHAFT DUE TO MIS-MOUNTING/DAMAGE DURING CARRIER BEARING REPLACEMENT		\$275.00
---------	---	--	----------

✓ Authorized on 12/05/24 at 12:30 PM MST

Subtotal \$275.00 + est. Tax \$22.55

\$297.55

RO Fees

Fees:	SHOP SUPPLIES		\$39.86
	HAZMAT FEE		\$3.95
	SERVICE		\$99.40

Subtotal

\$143.21

work to be done along with the necessary materials and labor and hereby grant Car Pros Muffler Masters and its employees permission to be described above for testing and/or inspection. I understand and acknowledge the existence of an express mechanic's lien on the vehicle to be associated with the repairs. Any warranty on parts and labor is good for one year or 12,000 miles, whichever comes first unless otherwise stated. I hereby indemnify and hold Car Pros Muffler Masters, its owners and employees harmless for any claim, damage, injury, or loss of life that may occur as a result of any market part installed on the vehicle and agree that the above have no liability for any defects or malfunctioning thereof. CAR PROS MUFFLER MASTERS EMPLOYEES ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO ANY VEHICLES OR PROPERTY LEFT THEREWITH DUE TO WEATHER, ACTS OF GOD, FIRE, THEFT, VANDALISM, OR ANY OTHER CAUSE. I UNDERSTAND THAT MY VEHICLE WILL BE PARKED IN AN OUTDOOR PARKING LOT FOLLOWING THE COMPLETION OF SERVICE AND AGREE TO ASSUME ALL LIABILITY AND RISKS ASSOCIATED THEREWITH. () Customers Initials

Total Repair Order & Signature:

X

Total Jobs:	\$3,058.32
Total Fees:	\$163.41
Subtotal:	\$3,221.73
Taxes:	\$151.66
Grand Total:	\$3,373.39
BALANCE DUE:	\$3,373.39





5BZAF0AA5HN853213

Odometer:80417

Thank You for Choosing Car Pros Muffler
Masters !!!!

Nissan : NV3500 : 2017 : Passenger ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

04/02/2025 2:55:56 PM

Repair Order #

43199

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

Repair Order

Vehicle Time In: 3/14/2025 2:58:57PM

2017 Nissan NV3500 HD

Odometer In: 83897

Odometer Out: 83897

License: DHU-K28 CO

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Vehicle Time Out: 4/2/2025 9:08:17AM

CONCERN AND CAUSE

CUSTOMER STATES :LOF

CK, AND ADJUST REAR BRAKES HAS SQUEAK WITH LOW PEDAL

CK. REAR H VAC BLOWER TICKING

P0175 CODE HAS BAD IDLE

VENT CONTROL VALVE CODE STUCK OPEN

INSPECTION RESULTS:

HVAC noise is rear blower motor - need to remove blower motor and inspect

sounds out of balance -upon inspection technician found the blower motor fan cage was cracked causing it to waiver back and forth making the bearing go bad.

Front brake pads look to have been replaced without the rotors being changed.

The rotors are very covered with rust

The rear pads and rotors are warped and making noise - replaced these under warranty

The P0447 vent control valve had a broken wire - This was repaired -

Technician found the connector to the MAF sensor was loose and dirty - Re-tensioned the connector pins and cleaned the connector. This was setting both codes P0172 and P0175. - cleared the codes and test drove - both codes are off at this point in time.

Has two of the coolant tees on the heater hoses are broken, this is serviced as a unit with both hose from Nissan.

Labor: \$154.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$154.00

LUBE, OIL, AND FILTER CHANGE SYNTHETIC

DRAIN AND REFILL CRANKCASE WITH PREMIUM SYNTHETIC MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE.

INSPECT AIR AND CABIN FILTER , TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$25.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

0W/20 Full Synthetic Oil

Nissan Oil Filter

Quantity

6.90

Sale

\$5.99

Extended

\$41.33

1.00

\$8.55

\$8.55

Labor: \$0.00

Parts: \$49.88

Sublet: \$0.00

Job Total: \$49.88

BLOWER MOTOR ASSEMBLY Remove & Replace

Description

Blower Motor Assembly - Rear

Quantity

1.00

Sale

\$315.57

Extended

\$315.57

Labor: \$539.00

Parts: \$315.57

Sublet: \$0.00

Job Total: \$854.57

AIR CONDITIONING SYSTEM CHARGE

Includes Evacuating, Vacuum, And Recharge System With Freon And Add Leak Detector Oil/Dye. Inspect All Connections And Seals, Check For Leaks With Ultraviolet Light And Freon Detector. Does Not Include System Repairs.

Description

BG Air Conditioning Oil With Dye

Quantity

1.00

Sale

\$6.95

Extended

\$6.95





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

04/02/2025 2:55:56 PM

Repair Order #

43199

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

2017 Nissan NV3500 HD

Odometer In: 83897

Odometer Out: 83897

License: DHU-K28 CO

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Repair Order

Continued From Previous Page

R134A Refrigerant

Labor: \$84.99

Parts: \$74.79

Sublet: \$0.00

2.34

\$28.99

\$67.84

Job Total: \$159.78

HEATER HOSES Remove & Replace

NOTE: Deduct 0.2 when used in conjunction with Radiator Hose(s) - R&R.

Description

Heater hose tee assembly

Nissan Coolant (Blue)

Quantity

1.00

Sale

\$131.08

Extended

\$131.08

2.00

\$23.49

\$46.98

Labor: \$308.00

Parts: \$178.06

Sublet: \$0.00

Job Total: \$486.06

FRONT DISC ROTOR Remove & Replace

Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary).
DOES NOT include refinishing.

Description

Brake Pads - Front - Fleet

Brake Rotor (Rotor Only) - Front - Premium

Quantity

1.00

Sale

\$168.47

Extended

\$168.47

2.00

\$198.87

\$397.74

Labor: \$154.00

Parts: \$566.21

Sublet: \$0.00

Job Total: \$720.21

REAR DISC ROTOR Remove & Replace

Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary).
DOES NOT include refinishing.

Description

Brake Pads - Rear - Fleet

Brake Rotor (Rotor Only) - Rear - Premium

Quantity

1.00

Sale

\$131.39

Extended

\$131.39

2.00

\$177.79

\$355.58

Labor: \$0.00

Parts: \$486.97

Sublet: \$0.00

Job Total: \$486.97

DIAGNOSE AND REPAIR VENT CONTROL VALVE CODE

Labor: \$154.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$154.00

Brake Pads - Rear - Fleet, Brake Rotor (Rotor Only) - Rear - Premium

\$-486.97



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM
MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

for RO #29334

04/02/2025 2:55:56 PM

Repair Order #
43199

COUNTRY SIDE HEATING AND SOLAR

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Cell 7193069606Matt ; Cell 7193715757Jason

Repair Order

2017 Nissan NV3500 HD

Odometer In: 83897

License: DHU-K28 CO

Odometer Out: 83897

VIN: 5BZAF0AA5HN853213

Eng: 5.6 L 5552 CC V8 DOHC

Continued From Previous Page

Service Advisor: Cory B

Technician(s): Jason C #46, ; Matt W #50,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$1,418.99
Parts Total: \$1,184.51

Shop Supplies: \$25.00
HazMat: \$2.95

Sub Total: \$2,631.45
Tax Total: \$105.23
Grand Total: \$2,736.68
Balance Due: \$2,736.68



SIGNATURE.....

DATE.....





Car Pros Muffler Masters

3015 North Stone Avenue
Colorado Springs, CO 80907
(719) 636-1087
mufflermasterscs@gmail.com
http://mufflermasterscs.com

Invoice for RO #34823

Service Advisor: JONATHAN GREEN
Date Created: 05/05/26 at 11:29 AM MDT
Client: MATTHEW BAYER
Vehicle: 2017 Nissan NV3500 SL

MATTHEW BAYER
1722 Edelweiss Drive
Westcliffe, CO 81252
Phone: (719) 306-9606
Email: MATTHEW.BAYER@OUTLOOK.COM

2017 Nissan NV3500 SL 5.6L 8Cyl GAS
VK56DE Naturally Aspirated
VIN: 5BZAF0AA5HN853213
License: DHUK28
Color: N/A
Odometer In: 103773 / Out: 103777

RO # 34823
Time-In: 05/05/26 at 11:29 AM MDT

Client concerns:

- EXHAUST QUOTE - POSS. MANIFOLD GASKET LEAK
- FRONT SUSPENSION FEELS LOOSE - CHECK AND ADVISE
- OIL CHANGE / WAS 1QT LOW AFTER 8000 MILES
- MPI
- PULLS HARD TO THE RIGHT
- CHECK FLUID SERVICES

1 - OIL AND FILTER CHANGE 0W20 FULL SYNTHETIC OIL AND FILTER CHANGE

Tech Z S

Note: Performed oil and filter change. Added 6.9qts of 0w20. Reset oil light and put new sticker in the window. Topped off window wash and checked fluid levels. Replaced drain plug gasket and torqued drain plug to 25ft lbs. Set tire pressure to 55psi front and 80psi rear. Road tested and checked for leaks

Labor:	Engine oil and filter change, top off fluids as needed, adjust tire pressure correctly, road test vehicle	7	\$35.59
Parts:	0W20 FULL SYNTHETIC OIL (DEXOS APPROVED) PER QUART	1	\$4.99
	WASHER FLUID PER GALLON	1	\$13.60
	Engine Oil Filter ##		\$0.00
Fees:	LUG NUT TORQUE _____		\$0.00
	OIL CAPACITY _____		\$0.00

Subtotal \$145.11 + est. Tax \$8.98 **\$154.09**

✓ Approved on 05/05/26 at 12:00 PM MDT

2 - STEERING AND SUSPENSION DIAGNOSTIC

Tech Z S

Note: After road testing I found the vehicle has a pull to the right. I found the idler and arm have excessive play. Left front tie rod and left front lower ball joint have some play. Pitman arm is tight. Right ball joints are tight. Right tie rods are tight. Steering wheel has some play in it. Recommend replacing idler and arm, left inner tie rod, and left lower ball joint, then re test. If the steering wheel feels like it has too much play, the steering gear might need to be replaced or adjusted

Labor:	STEERING AND SUSPENSION DIAGNOSTIC		\$95.00
Fees:	LUG NUT TORQUE _____		\$0.00
	OIL CAPACITY _____		\$0.00

\$95.00

✓ Approved on 05/05/26 at 12:01 PM MDT

3 - Remove & Replace Spark Plugs

Tech Z S

Note: Removed both front tires and inner wheel liners. Replaced spark plugs and coil boots. Torqued lugnuts to 140ft lbs. Road tested

Labor:	Remove & Replace Spark Plugs NV Full Size Van		\$322.98
Parts:	Direct Ignition Coil Boot	2	\$168.26
	Spark Plug, DILZKAR7B11, Laser Iridium	8	\$485.20
Fees:	LUG NUT TORQUE _____		\$0.00
	OIL CAPACITY _____		\$0.00

Subtotal \$976.44 + est. Tax \$53.58 **\$1,030.02**

✓ Approved on 05/05/26 at 05:31 PM MDT

5 - Remove & Replace Exhaust Manifold Gasket

Note: Removed front wheels and inner tire liners. Removed the manifold heat shields. Removed manifolds from rest of exhaust. Removed manifold studs and cleaned up threads in the block. Removed manifolds and resurfaced them. Installed manifolds and studs. I had to extract 2 studs and thread chased the threads. Torqued manifold nuts to 21ft lbs. Installed heat shields and O2 sensors. Installed the manifolds/cats back onto the rest of the exhaust. Installed inner wheel liners and wheels. Torqued lugnuts to 140ft lbs. Pressure tested exhaust to check for leaks. No leaks detected.

After fixing the exhaust leaks I found a ticking noise coming from engine. I did some research and found a technical service bulletin for the ticking noise. The noise could be coming from cylinder number 7 and its from scratching or scuffing on the cylinder walls. The only way to fix that noise is to replace the engine block according to Nissan.

Labor:	Remove & Replace Left and Right Exhaust Manifold Gasket (Both Sides) Both Banks , NV Full Size Van		\$1,424.93
	RESURFACE SEALING SURFACE FOR EXHAUST MANIFOLD(EACH) TO CORRECT WARPAGE OR SURFACE DISTORTION WITHING .002		\$254.40
Parts:	REMOVE BROKEN OR STRIPPED BOLT THAT IS SEIZED OR SNAPPED		\$178.99
	Exhaust Flange Stud and Nut	1	\$9.36
Fees:	Exhaust Manifold Gasket	2	\$152.40
	LUG NUT TORQUE _____/_____		\$0.00
	OIL CAPACITY _____/_____		\$0.00

Subtotal \$2,020.08 + est. Tax \$13.26

\$2,033.34

✓ Approved on 05/05/26 at 05:31 PM MDT

5 - WHEEL ALIGNMENT 4 WHEEL PASSENGER CAR/LIGHT DUTY TRUCK

Tech: Z S

Note: Set tire pressure to 55psi front and 80psi rear. Performed alignment. Tried adjusting front camber and caster but the left front cam bolt is seized in the lower control arm and cannot be adjusted. After trying the lube it up and press it out, I determined that control arm is going to have to be replaced in order to adjust camber. Adjusted front toe. After alignment I reset steering angle sensor with scan tool. Road tested. Steering wheel is now straight.

Labor:	Perform suspension/steering alignment, adjust to manufactures specifications, set tire air pressure, check for steering angle reset procedure, road test vehicle		\$114.95
		1	\$0.00
Part:	Front Camber, Front Caster		

\$114.95

✓ Approved on 05/05/26 at 05:31 PM MDT

6 - Remove & Replace Tie Rod

Tech: Z S

Note: Removed and replaced left front tie rod and tie rod end. Installed grease zerks and greased the tie rod along with the rest of the steering and suspension components. Tightened tie rod nuts and installed new cotter pins

Labor:	Remove & Replace Outer Tie Rod (One Side) NV Full Size Van		\$95.00
		1	\$201.56
Part:	Steering Tie Rod End Assembly		\$0.00
Fees:	LUG NUT TORQUE _____/_____		\$0.00
	OIL CAPACITY _____/_____		

Subtotal \$296.56 + est. Tax \$16.53

\$313.09

✓ Approved on 05/05/26 at 05:31 PM MDT

7 - Remove & Replace Suspension Ball Joint

Tech: Z S

Note: Removed left front wheel, brake caliper and bracket. Popped tie rod end from steering knuckle. Loosened upper ball joint nut and removed axle nut to pop axle out of hub. Removed steering knuckle. Removed and replaced lower ball joint and installed grease zerk. Installed everything taken off in reverse order. Torqued axle nut to 240ft lbs. Greased lower ball joint and installed new cotter pins. Installed wheel and torqued lugnuts to 140ft lbs. Aligned and road tested

Labor:	Remove & Replace Front Upper Suspension Control Arm (Both Sides) NV Full Size Van		\$379.98
		1	\$223.23
Part:	Suspension Ball Joint		\$0.00
Fees:	LUG NUT TORQUE _____/_____		\$0.00
	OIL CAPACITY _____/_____		

Subtotal \$603.21 + est. Tax \$18.30

\$621.51

✓ Approved on 05/05/26 at 05:31 PM MDT

Remove & Replace Steering Idler Arm

Work: Removed center link from idler arm. Removed center link from pitman arm. Installed idler arm. Installed center link to idler arm and pitman arm. Installed new cotter pins. Road tested. Steering feels better now.

Labor:	Remove & Replace Steering Idler Arm NV Full Size Van, Power		\$151.99
Part:	Steering Idler Arm	1	\$648.47
Fees:	LUG NUT TORQUE _____/_____		\$0.00
	OIL CAPACITY _____/_____		\$0.00

✓ Approved on 05/05/26 at 05:31 PM MDT

Subtotal \$800.46 + est. Tax \$53.17

\$853.63

RO Fees

Fees:	SUPPLIES/ MATERIAL & CONSUMMABLES	\$59.38
	HAZMAT FEE	\$3.95
	SERVICE	\$164.18

Subtotal **\$227.51**

I authorize the above repair work to be done along with the necessary materials and labor and hereby grant Car Pros Muffler Masters and its employees permission to operate on the vehicle described above for testing and/or inspection. I understand that aftermarket replacement parts may be used unless otherwise specified by customer. I understand and acknowledge the existence of an express mechanic's lien on the vehicle to secure the amount associated with the repairs. Any warranty on parts and labor is good for one year or 12,000 miles, whichever comes first unless otherwise stated. I agree to completely indemnify and hold Car Pros Muffler Masters, its owners and employees harmless for any claim, damage, injury, or loss of life that may occur as a result of an after-market part installed on the vehicle and agree that the above have no liability for any defects or malfunctioning thereof. CAR PROS MUFFLER MASTERS AND ITS EMPLOYEES ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO ANY VEHICLES OR PROPERTY LEFT THEREWITH DUE TO WEATHER, ACTS OF GOD, FIRE, THEFT, VANDALISM, OR ANY OTHER CAUSE. I UNDERSTAND THAT MY VEHICLE WILL BE PARKED IN AN OUTDOOR PARKING LOT FOLLOWING THE COMPLETION OF SERVICE AND AGREE TO ASSUME ALL LIABILITY AND RISKS ASSOCIATED THEREWITH. (_____) Customers Initials

Work Authorization Signature:

X 

Total Jobs: \$5,051.81

Total Fees: \$227.51

Subtotal: \$5,279.32

Taxes: \$168.71

Grand Total: \$5,448.03

BALANCE DUE: \$5,448.03

Declined Jobs:**1 - WYNN'S FULL SYNTHETIC/ELECTRONIC POWER STEERING FLUSH**

Tech: Z S

Labor:	Perform power steering fluid exchange. Procedure: Verified fluid compatibility with manufacturer. Using WYNN'S Power Steering Service Center, extract off all fluid in reservoir. Added BG Quick Clean to reservoir and made sure level was correct for vehicle. Started vehicle and turned steering full lock left to right to ensure quick clean penetrated inside steering rack and all lubricated steering components. While vehicle is running, using WYNN'S SERVICE CENTER performed fluid exchange ensuring the level of fluid in reservoir was maintained. Exchanged fluid with two quarts of premium power steering fluid recommended for vehicle. Verified level was correct and test drove vehicle.	\$107.39
Part:	POWER STEERING SERVICE KIT	1 \$46.99

X Declined on 05/05/26 at 05:31 PM MDT

Subtotal \$154.38 + est. Tax \$3.85

\$158.23

2 - WYNN'S Rear Differential Service

Tech: Z S

Labor:	Remove & replace old, worn differential fluid with new BG premium full synthetic gear oil to factory spec and capacity. Inspect differential for leaks or damaged components. Test Drive vehicle.	\$89.50
Parts:	ULTRA GUARD 75W-90 GEAR LUBE ##	3 \$104.97
	LIMITED SLIP FRICTION MODIFIER	2 \$49.98

X Declined on 05/05/26 at 05:31 PM MDT

Subtotal \$244.45 + est. Tax \$12.71

\$257.16

COOLANT PRESSURE TEST

Labor

Pressurize coolant system and check for any leaks

\$89.50

X Declined on 05/05/26 at 05:31 PM MDT

\$89.50





5BZAF0AA5HN853213

Odometer:103773

THANK YOU FOR CHOOSING CAR PROS
MUFFLER MASTERS!!!!

Nissan : NV3500 : 2017 : Passenger ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.