



AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

01/27/2026 8:20:03 AM

Repair Order #
46826

2001 Chevrolet Tahoe

Odometer In: 176861

Odometer Out: 176861

License: APW-W74 CO

VIN: 1GNEK13T41R129987

Ref #:

Eng: 5.3 L 325 CID V8

Repair Order

Vehicle Time In: 1/19/2026 9:11:49AM

Vehicle Time Out: 1/27/2026 8:09:42AM

CONCERN AND CAUSE

CUSTOMER STATES :

LOF

CHECK A/C

INSPECTION RESULTS:

A/C condenser is leaking

The blower motor had debris in it - when removed it sounds as it should

The water pump is leaking - Replaced the belts under warranty

LUBE, OIL, AND FILTER CHANGE

DRAIN AND REFILL CRANKCASE WITH PREMIUM MOTOR OIL, REPLACE OIL FILTER. LUBRICATE CHASSIS WHERE APPLICABLE. INSPECT AIR AND CABIN FILTER, TOP OFF ALL FLUID LEVELS AND APPLY REMINDER STICKER

Labor: \$25.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$25.00

Multi Point LOF Inspection

PERFORM Multi Point LOF Inspection

Description

5W/30 Synthetic Blend Oil

Oil Filter

Quantity

6.00

1.00

Sale

\$3.99

\$5.27

Extended

\$23.94

\$5.27

Labor: \$0.00

Parts: \$29.21

Sublet: \$0.00

Job Total: \$29.21

BLOWER MOTOR ASSEMBLY Remove & Replace

DOES NOT include Air Conditioning System recover, evacuate and/or recharge.

Labor: \$164.00

Parts: \$0.00

Sublet: \$0.00

Job Total: \$164.00

AIR CONDITIONING SYSTEM CHARGE

Includes Evacuating, Vacuum, And Recharge System With Freon And Add Leak Detector Oil/Dye. Inspect All Connections And Seals, Check For Leaks With Ultraviolet Light And Freon Detector. Does Not Include System Repairs.

Description

BG Air Conditioning Oil With Dye

R134A Refrigerant

Quantity

1.00

1.00

Sale

\$6.95

\$28.99

Extended

\$6.95

\$28.99

Labor: \$84.99

Parts: \$35.94

Sublet: \$0.00

Job Total: \$120.93

CONDENSER Remove & Replace

DOES NOT include Air Conditioning System recover, evacuate and/or recharge.

Description

A/C Condenser

Quantity

1.00

Sale

\$338.97

Extended

\$338.97

Labor: \$328.00

Parts: \$338.97

Sublet: \$0.00

Job Total: \$666.97





AUSTIN AUTOMOTIVE

2625 EAST MAIN STREET
CANON CITY CO, 81212

Phone: 719-275-5055

VISIT US AT WWW.AUSTINAUTOMOTIVE.COM

MON - THURS 7:30AM - 5:30PM / FRI 7:30AM - 4:30PM

01/27/2026 8:20:03 AM

Repair Order #

46826

MATT/KALEA BAYER

1722 EDELWEISS DR

WESTCLIFFE CO, 81252

Matt Bayer (719) 306-9606 ; Kalea Bayer (719)
663-1078

2001 Chevrolet Tahoe

Odometer In: 176861

License: APW-W74 CO

Ref #:

Odometer Out: 176861

VIN: 1GNEK13T41R129987

Eng: 5.3 L 325 CID V8

Repair Order

Continued From Previous Page

FLUSH AC SYSTEM

Description

Air Conditioning Flush Solvent - R134a and R12 - 1 qt

Quantity

1.00

Sale

\$94.87

Extended

\$94.87

Job Total: \$176.87

Labor: \$82.00

Parts: \$94.87

Sublet:\$0.00

WATER PUMP Remove & Replace

Description

Water Pump - New

Thermostat Housing Seal

Dexcool Coolant (Orange)

Belt - Serpentine

Belt - Air Conditioning

Quantity

1.00

Sale

\$200.00

Extended

\$200.00

1.00

\$6.15

\$6.15

2.00

\$14.99

\$29.98

1.00

\$74.58

\$74.58

1.00

\$48.69

\$48.69

Job Total: \$687.40

Labor: \$328.00

Parts: \$359.40

Sublet:\$0.00

Belt - Air Conditioning, Belt - Serpentine

\$-123.27

Recommendations

- 10/09/2024 Work Order #41389, Sub Est 1 indicates a Coolant flush and heater connectors - \$378 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.
- 04/10/2025 Work Order #43463, Sub Est 1 indicates a Front Axle Seals - \$584 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.
- 01/27/2026 Work Order #46826, Sub Est 1 indicates a Driver Door Bushings - \$387 was previously needed for your vehicle. Please reply for a detailed estimate and explanation.

Customer Authorization

1/21/26 13:43

Written by: CB Initiated By: Customer Phone 719-306-9606

Authorized By

BAYER, MATT/KALEA

Previous Est.

\$ 1,401.77

Add'l Cost

\$ 1,800.00

Revised Est.

\$3,201.77

Service Advisor: Cory B

Technician(s): Kyle S #55, ; Patrick D #39, ; Pete S #53,

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

12 month, 12,000 mile warranty, whichever occurs first, is provided on all parts and labor unless otherwise specified. All warranty repairs must be performed at this facility. For warranty service outside a 25 mile radius from your original repairing location, contact the NAPA Auto Care Warranty Administrator at 800-452-NAPA (6272). For warranty service inside a 25 mile radius from your original repairing location, please contact your original location for service.

Labor Total: \$1,011.99

Parts Total: \$735.12

Shop Supplies: \$25.00

HazMat: \$2.95

Sub Total: \$1,775.06

Tax Total: \$66.14

Grand Total: \$1,841.20

Balance Due: \$1,841.20



SIGNATURE..... DATE.....

