

# S.M.A.R.T

SEATON'S MACHINES, ALLIED REPAIR AND TRADE  
SOLUTIONS LTD

25 1/2 Chisholm Avenue,  
Kingston 13, Jamaica.  
info@smartsja.com  
(876) 580-8151 / (876) 863-2341

Date: January 28, 2024

Institution: Fair Prospect High School

Address: Portland

To: Mr. Hamilton (HOD)

## Repair Estimates for Woodwork Machines

### Estimate to include:

- Travel to the machine's location.
- Identifying machines for repairs.
- Identifying parts and accessories needed to facilitate repairs.
- Prepare and submit estimates.
- Supply and install parts and accessories.
- Complete realignment and calibration of machines etc.
- Deoxidation of machines/tool services (Optional).

Please note that this project may incur additional costs, and any additional costs incurred will be added to the final invoice upon the satisfactory completion of the project. Please note that portable tools repair if applicable will be added to a separate invoice upon completion of project.

**50%** of the estimated repair cost is required at the start of each project.

The 50% deposit needed to start this project is

**\$305,175.00**

Please note cheques must be made out to company  
'Seaton's machines, allied repair & trade solutions ltd'

Estimated time of completion **15 days**



---

Gavin Seaton (Operations Manager)

TRN 002790572

# S.M.A.R.T

SEATON'S MACHINES, ALLIED REPAIR AND TRADE  
SOLUTIONS LTD

25 1/2 Chisholm Avenue,  
Kingston 13, Jamaica.  
info@smartsja.com  
(876) 580-8151 / (876) 863-2341

Below is an itemized breakdown of the operation needed to complete the repairs to the woodwork machines.

|                                           |                                                                                                                                                                                                                            |               |
|-------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| (1) One 220v 3ph 15a x 6" Jointer/Planer. |                                                                                                                                                                                                                            |               |
| Observation/Inspection                    | Actions to be taken                                                                                                                                                                                                        | Cost          |
|                                           | a) To remove repair and re install one set 3x6 blade<br>(b) To repair or replace one 220v 3ph 15a starter switch<br>(c)to service and re install defective isolator switch.<br>(d) Service motor and connecting mechanisms | \$143, 780.00 |
| (2) One 220v 1ph x 16 Thickness/Planer    |                                                                                                                                                                                                                            |               |
| Observation/Inspection                    | Actions Taken                                                                                                                                                                                                              | Cost          |
|                                           | (a) remove repair and re install one set 3x16 blade<br>(b) repair starter switch<br>(c) repair service line<br>(d) re align post assembly                                                                                  | \$172, 470.00 |
| (3)One 220v 3ph 15a Drill Press           |                                                                                                                                                                                                                            |               |
| Observation/Inspection                    | Actions Taken                                                                                                                                                                                                              | Cost          |
|                                           | (a) repair or supply new stop/start switch<br>(b)supply and install new chuck and key<br>(c)service elevating sleeve assembly                                                                                              | \$93, 470.00  |
| (4) One 230v 3ph x 36 Lathe               |                                                                                                                                                                                                                            |               |
| Observation/Inspection                    | Actions Taken                                                                                                                                                                                                              | Cost          |
|                                           | (a) to repair tail stock assembly<br>(b) to remove service and reinstall defective motor<br>(e) To de-oxidize unit                                                                                                         | \$137, 300.00 |
| (5) One (8") Pedestal Grinder             |                                                                                                                                                                                                                            |               |
| Observation/Inspection                    | Actions Taken                                                                                                                                                                                                              | Cost          |
|                                           | To supply and install one set 8" carborundum grinding stone                                                                                                                                                                | \$68 330.00   |

# S.M.A.R.T

SEATON'S MACHINES, ALLIED REPAIR AND TRADE  
**SOLUTIONS** LTD

25 1/2 Chisholm Avenue,  
Kingston 13, Jamaica.  
info@smartsja.com  
(876) 580-8151 / (876) 863-2341

Woodwork project estimate \$610,378.00

I

## BANKING INFO

Seatons Machines Allied Repair and Trade Solutions Ltd.

Bank: CIBC (First Caribbean Bank)

Branch: Portmore

Account number: 1002259000

Account type: Chequing account

Please note cheques must be made out to company  
'Seaton's machines, allied repair & trade solutions ltd'