$$(\bar{x}_1 + \bar{x}_2 + \bar{x}_3 + \bar{x}_4)$$
 Figure 2.61 POS minimization of $f(x_1, \dots, x_4) =$

 ΠM (0, 1, 4, 8, 9, 12, 15).