
## iRobot Dexter Hand Quick Start Guide


7/23/2013



Power the hand by connecting the **brown wire to +24 VDC** and the **black wire to GROUND** with a 5 A current limit.



Use a male-to-male RJ45 coupler to connect the palm to the computer for communication.



To mount the palm, use 3 M6 X 1.0 bolts at a maximum depth of 5.50 mm into the housing.

