
## 1. TOPOLOGI JARINGAN Test ETL AC to DC








No	Parameter	
1	Diameter Antena :	1.8m
2	Satelit:	N1 IBS
3	Modem:	Hughes HT2524
4	BUC:	10 Watt
5	PSU:	SP-100-27 Mean Well AC to DC
6	Combiner:	ETL System TEEL1-4007 L-band Bias TEE

Hasil Test Power PSU AC to DC 25V











# 2. Topologi Test ETL AC to DC 48V DC to DC 24V





No	Parameter	
1	Diameter Antena:	1.8m
2	Satelit:	N1 IBS
3	Modem:	Hughes HT2524
4	BUC:	10 Watt
5	PSU:	1. Converter SD-150C-24 48/24V Meanwell AC to DC
		2. Converter SD-150C-24 48/24V Meanwell DC to DC
6	Combiner:	ETL System TEEL1-4007 L-band Bias TEE

## Hasil Test Power PSU AC to DC 48V DC to DC 24V





Auto Refresh 1 🗸

### Advanced Menu

- Advanced Menu
  General
  IDU/ODU
  Firmware
  CAC
  Downlink
  Uplink
  Sysinfo
  Association
  Layer 2
  Network Layer
  Web Acceleration
  VOIP
  DNS
  Pkt Dump
  Diagnostics
  Caching
  Cfg
  Logs
  Installation
  Enterprise options

HT2524 Advanced Configuration and Statistics Subscriber\_Account\_Number:IBSTESTBUC2 ESN:12916325 SAI:25395(0x6333)

SW Version :7.4.0.38 (M) 7.1.0.34 (F)

System State Code :11.3.1


09/18/2024 08:13:30

System State Code 21.1.4


UpTime (d.h:m:s) 0.00:02:44

Available Memory 1449488 KB

Downlink		SbcStatus		
SQF		114	Installation Status	Installed
FLL Lock Status		Locked	First Registration Time	2024-07-19 08:39:35
Requested Modcod		81	Most Recent Registration Time	2024-09-17 08:17:04
Over-the-Air Freque	ncy (KHz)	4040000	Satellite Name	PSN-VI-P6C
Symbol Rate (Sps)		34000000	Config Format/Version/RevDate	6/P6C_WB_A.36/10/01/2023
Beam ID		111	Tenant Name	
Gateway ID		1	WIFI CC/Locale	US840/,
Outroute ID		7.	SBC State Code	0.0.0
Stream ID		0	-	
Downlink State Code		0.0.0	SysInfo	
			MGMT Routing Advertisement	22
	Uplink		MGMT Services	2
TDMA Mode		Active	SysInfo State Code	0.0.0
Transmit Rate		16APSK 1024K 1/2	Acce	alation
Inroute Group 5		Association		
Last EsNo		90	Association State	CREATING_IPGW_POOL
Power Attenuation		5.60 dB	IPGW ID	
Transmit Frequency		6038360000	Association Time	N/A
Allocation State		ALOHA	CMM Timeouts	0
Stream Error Rate		84.21%	Keep Alive Timeouts	0
Stream ACK / NAK		30 / 160	Association State Code	21.1.4
Aloha ACK / NAK		9 / 32	FAP State Code	24.1.2
SCMA Data ACK / NA	AK.	0 / 0	ROHC Profiles	NONE
Uplink State Code		0.0.0	PEP	
	LAN (eth0)		Backbone Status	1
Interface State		Up 1G FD	Total Backbones Up	0
IPv4 Address		192 168 0 1	Tx   Rx PBP	0   4
IPv6 Address			Tx   Rx SACKs	0   0
Tx   Rx Packets		2493   994	Tx   Rx Resets	0   0
Tx   Rx Bytes		3104712   119178	PEP State Code	23.1.1
	Satellite (sat)		IP	SEC
MGMT IPv6 Address	fd0d:edc5:ff02:1044	:0000:0000:00c5:1665	IPSec feature	Disabled
WAN IPv6 Address fd0d:edc5:ff01:1044:0000:0000:0000:6333		Web Acceleration		
Tx   Rx Packets 10   8		MBV 5	Lib	
		MOV CALA-	1312	




# 3. Topologi Test ETL DC to DC Baterai






No	Parameter	
1	Diameter Antena:	1.8m
2	Satelit:	N1 IBS
3	Modem:	Hughes HT2524
4	BUC:	10 Watt
5	PSU:	Converter SD-150C-24 48/24V Meanwell DC to DC
6	Combiner:	ETL System TEEL1-4007 L-band Bias TEE


#### Hasil Test Power PSU DC to DC 24V







## Hasil Test Power PSU DC to DC 26V





Auto Refresh 1 🗸

Auto Refresh 1

Advanced Menu
General
IDU/ODU
Firmware
CAC
Downlink
Uplink
Sysinfo
Association
Layer 2
Network Layer
Web Acceleration
VOIP
DNS
Pkt Dump
Diagnostics
Caching
Cfg
Logs
Installation
Enterprise options

HT2524 Advanced Configuration and Statistics 
Subscriber\_Account\_Number:IBSTESTBUC2 ESN:12916325 SAI:25395(0x6333)
SW Version :7.4.0.38 (M) 7.1.0.34 (F) System State Code :0.0.0 09/19/2024 09:09:46

 $\begin{array}{ccc} \text{System State Code} & & \text{UpTime (d.h:m:s)} \\ \textbf{0.0.0} & \textbf{0.02:09:09} \end{array}$ 

Available Memory 1476248 KB

Downlink			ShrStatus		
SOF	DOWIIIIK	121	Installation Status	Installed	
FILL Lock Status		Locked	First Registration Time	2024-07-19 08:39:35	
FLL Lock Status Locked Requested Modcod 83		Most Recent Registration Time	2024-07-19 08:39:35		
Over-the-Air Freque	on (VUz)	4040000	Satellite Name	2024-09-17-08:17:04 PSN-VI-P6C	
Symbol Rate (Sps)	icy (KHZ)	34000000	Config Format/Version/RevDate	6/P6C_WB_A.36/10/01/2023	
Beam ID		111	Tenant Name	6/F6C_WB_A.36/T0/01/2023	
Gateway ID		1	WIFI CC/Locale	US840/.	
Outroute ID		7	SBC State Code	0.0.0	
Stream ID		0	SBC State Code	0.0.0	
Downlink State Code		0.0.0	SysInfo		
DOWNING State Code		0.0.0	MGMT Routing Advertisement	1539	
	Uplink		MGMT Services	128	
TDMA Mode		Active	SysInfo State Code	0.0.0	
Transmit Rate		16APSK 1024K 1/2			
Inroute Group		10	Association		
Last EsNo		97	Association State	ASSOCIATED	
Power Attenuation		4.90 dB	IPGW ID	P6CIK111PSNIGWL2G1	
Transmit Frequency		5919640000	Walled Garden	No	
Allocation State		IDLE	Association Time	Thu Sep 19 07:08:11 2024	
Stream Error Rate		21.42%	CMM Timeouts	0	
Stream ACK / NAK		22412 / 6108	Keep Alive Timeouts	18	
Aloha ACK / NAK		462 / 419	Association State Code	0.0.0	
SCMA Data ACK / NA	K	0 / 0	FAP State Code	0.0.0	
Uplink State Code		0.0.0	ROHC Profiles	RTP-V2 UDP-V2	
LAN (eth0)			PEP		
Interface State		Up 1G FD	Backbone Status	Up   Up   Up   Up   Up	
IPv4 Address		192.168.0.1	Total Backbones Up	5	
IPv6 Address			Tx   Rx PBP	1380   998	
Tx   Rx Packets		9420   5525	Tx   Rx SACKs	0   1	
Tx   Rx Bytes		5194928   510245	Tx   Rx Resets	34   19	
			PEP State Code	0.0.0	
Satellite (sat)			IPSI	er.	
MGMT IPv6 Address					
WAN IPv6 Address	fd0d:edc5:ff01:1044:	0000:0000:0000:6333	IPSec feature	Disabled	
Tx   Rx Packets 2076   1657		Web Acceleration			
Tx   Rx Bytes 739793   154475		Web Acceleration Disabled :GW does not support			
			Web Acceleration	Disabled .dw does not support	

©2021 HUGHES

