DC Debug Matrices

```
=== DC Analysis Debug Info ===

Unknowns:
V1
V2
I_V_2

G_dc (Conductance Matrix) =
[[0.001 +0.j -0.001 +0.j 1. +0.j]
[-0.001 +0.j 0.0015+0.j 0. +0.j]
[1. +0.j 0. +0.j 0. +0.j]
RHS_dc = [0.+0.j 0.+0.j 10.+0.j]
```