26DOC52D

JSEA DOCUMENTATION

FOR GYRODOS ROBOTICS' ROV MILOTIC/PALKIA

La Salle College Robotics Team

Gyrodos ROBOTICS

EST. 2024 • HKG

PROGRESS	TASK	HAZARDS	RISK REDUCING MEASURE	PIC
DESIGNING AND MAKING OF ROV	MOVING COMPONENTS FOR ASSEMBLY	COMPONENTS MAY DROP AND GET DAMAGED OR BROKEN.	USE A CART TO CARRY THE COMPONENT BOX IN ORDERTO PREVENT ITEMS FROM FALLING	MECHANICAL ENGINEERING DEPARTMENT
	MODULAR DESIGN	COMPONENTS MAY BREAK WHEN APPLING TOO MUCH PRESSURE ONTO THE COMPONENTS	APRROPRIATELY TIGHTEN SCREWS, USE WASHERS TO DISSPIATE FORCE	MECHANICAL ENGINEERING DEPARTMENT
SYSTEMS AND SOFTWARE	INITIALIZING AND DEACTIVATING THE ELECTRICAL SUBSYSTEMS	NOT CLOSING ALL THE ENERGY SOURCES AFTER TESTING MAY CAUSE SHORT CIRCUIT WHEN WORKING ON CIRCUIT LATER	DIVE TEAM CALLS OUT TO EE THAT "ALL POWER IS OFF" BEFORE STARTING DISASSEMBLY	ELECTRICAL ENGINEERING DEPARMENT
OPERATING THE ROV	NAVIGATING THE ROV IN TASKS	MISCOMMUNICATIONS LEADING TO UNINTENDED ROV MOVEMENTS. THEREFORE, IT MAY LEAD TO FAILURES WHEN EXECUTING THE UNDERWATER TASKS.	THE SPOTTER SHOULD REPORT THEIR FINDINGS AND POINT ON THE SCREEN FOR THE PILOT, SO THAT THERE IS NO MISUNDERSTANDING	DIVE TEAM
	TURNING ON THE ROV'S MOTORS	FINGERS MAY BE STUCK IN THE MOTOR AND PEOPLE MAY GET HURT	INSTALL IP20 RATED THRUSTER GUARDS	MECHANICAL ENGINEERING DEPARTMENT
	SUPERVISORY CONTROL OF ROV SYSTEMS	CONTROLLER DISCONNECTING, MAY LEAD TO THE MALFUNCTION OF THE ROV	PREPARE TWO CONTROLLER BACKUPS TO CONNECT IN CASE ONE FAILS	DIVE TEAM
RETRIEVING THE ROV AFTER OPERATING	CONDUCTING SUBSEA VEHICLE RECOVERY	THE ROV MAY FALL BACK INTO WATER OR ON THE GROUND DURING RETRIEVING WHICH MAY LEAD TO DAMAGE TO THE EXTERIOR	PILOT THE ROV TO THE SURFACE AND GRAB BOTH HANDLES OF THE FRAME TIGHTLY	MECHANICAL ENGINEERING DEPARTMENT