We connected VCC to VSYS to get 5.0v that ultrasonic operates on Your Sensor might differ from the one shown here. Ask a TA if you are unsure of how to connect.

