

TWN4

HID iCLASS Elite Key Update

DocRev9, April 15, 2026



ELATEC GmbH

Contents

1	Overview	3
2	Requirements	4
3	Key Update	5
3.1	Present Preparation Card	5
3.2	Present Media Card	5
3.3	Good To Know	5
4	Disclaimer	6

1 Overview

This document describes the process of updating the default keyset of a HID SIO card to a custom authentication key using configuration cards. Once the key update is successfully completed, the SIO card will only work with iCLASS credentials with keysets that match to the respective Elite key.

2 Requirements

In order to do the update, you need:

- A TWN4 MultiTech / MultiTech 2 / Mini with firmware 3.08 or later and I-Option set
- SIO card must be present
- The tag type HID iCLASS must be active
- A Elite Key Preparation Card
- A Elite Key Media Card

3 Key Update

The key update is automatically triggered by the reader during the function call of SearchTag. This means whenever the reader searches for transponders and a HID Configuration Card is detected, the reader processes it.

A TWN4 reader in standard configuration cyclically scans for transponders, so as soon as it has detected a configuration card, the card will be processed. If the reader is running e.g. Simple Protocol, the update process is started after the function SearchTag has been called. As soon as the update is in progress, this is signalled by cyclic beeping. If there is an error during processing, the beeper sounds three short low frequency beeps. In case of success, the beeper sounds three short beeps in high-low-high frequency. Keep in mind that processing of a configuration card can take more than 15 seconds, so please be patient and pay attention to well positioning of the card on the reader during that time.

3.1 Present Preparation Card

As first step, present the Preparation Card to the reader. Processing this card takes approximately 1-2 seconds, this step has to be carried out in order to make the SIO card process the respective Media Card.

3.2 Present Media Card

As second step, present the Media Card. Compared to the Preparation Card, processing of this card should take much longer, expect a processing time of 15 to 20 seconds. This can also be observed as the beeper cyclically sounds a short beep.

Once the Media Card has been processed successfully, the SIO card is ready for use with HID iCLASS credentials that have been rolled out with the respective Elite keys.

3.3 Good To Know

If the key update is conducted e.g. using Simple Protocol, as all processing is done during the call of SearchTag which is a blocking function, this can and probably will cause a timeout condition on the host system.

4 Disclaimer

ELATEC GmbH reserves the right to change any information or data in this document without prior notice. The distribution and the update of this document is not controlled. ELATEC GmbH declines all responsibility for the use of product with any other specifications but the ones mentioned above. Any additional requirement for a specific custom application has to be validated by the customer himself at his own responsibility. Where application information is given, it is only advisory and does not form part of the specification.

All referenced brands, product names, service names and trademarks mentioned in this document are the property of their respective owners.