

How to prepare surfaces to repair cracks concrete floor.

Step 1 : Block out your injection ports.



Step 2 : Mix your Epoxy.



Step 3 : Attach your injection port.



Step 4 : Spread sealer over the cracks



Step 5: Inject Epoxy into the ports.



Step 6 : Cut off the injection ports.



Video : <https://youtu.be/y1rOtvvxRzY>

Feedback : Activity and Demonstration

Kwa Thema Skills School

Subject : Maintenance

Grade : Year 3

Date : / /

Marks : 6

Time : 30 mins

Question:1

1. Stages of how to prepare surfaces to repair cracks on wall and on concrete floor.

Stage 1 : _____



Stage 2 : _____



Stage 3 : _____



Stage 2 : _____



Stage 4 : _____



Stage 6 : _____

