

Category	Command	Shortcut(s)	Search Shortcut
File	 New..	Ctrl+N	
File	 Open..	Ctrl+O	
File	Open Recent		
File	Recent File..		
File	 Browse Recent Documents..		
File	 Browse Recent Folders..		
File	 Open Drawing..		
File	 Close..	Ctrl+W	
File	 Make Drawing from Part..		
File	 Make Assembly from Part..		
File	 Save..	Ctrl+S	
File	 Save As..		
File	 Save All..		
File	Page Setup..		
File	 Print Preview..		
File	 Print..	Ctrl+P	
File	 Print3D..		
File	 Publish to eDrawings..		
File	 Pack and Go..		
File	Send To..		
File	 Reload..		
File	Find References..		
File	 Properties..		
File	Exit..		
Edit	 Undo..	Ctrl+Z	
Edit	 Redo..	Ctrl+Y	
Edit	 Repeat Last Command..	Enter	
Edit	 Select All..	Ctrl+A	
Edit	 Cut..	Ctrl+X	
Edit	 Copy..	Ctrl+C	
Edit	 Paste..	Ctrl+V	
Edit	 Delete..	Delete	
Edit	Copy to Adobe Illustrator..		
Edit	 Rebuild..	Ctrl+B	r
Edit	 Rebuild All Configurations..	Ctrl+Shift+B	
Edit	 Rollback..		
Edit	Roll to Previous..		
Edit	Roll to End..		
Edit	Suppress		
Edit	 This Configuration..		
Edit	All Configurations..		
Edit	Specified Configurations..		
Edit	Unsuppress		
Edit	 This Configuration..		
Edit	All Configurations..		
Edit	Specified Configurations..		
Edit	Unsuppress with Dependents		
Edit	 This Configuration..		
Edit	All Configurations..		

Category	Command	Shortcut(s)	Search Shortcut
Edit	Specified Configurations..		
Edit	 Sketch..		
Edit	 Sketch Plane..		
Edit	 Exit Sketch without Saving Changes..		
Edit	Design Table		
Edit	Edit Table..		
Edit	Edit Table in New Window..		
Edit	Bend Table		
Edit	Edit Table..		
Edit	Edit Table in New Window..		
Edit	Delete..		
Edit	Object		
Edit	Display Content..		
Edit	Display as Icon..		
Edit	Reset Size..		
Edit	 Definition..		
Edit	 Flip Normal..		
Edit	Appearance		
Edit	 Appearance..		
Edit	 Material..		ma
Edit	 Copy Appearance..	Ctrl+Shift+C	
Edit	 Paste Appearance..	Ctrl+Shift+V	
Edit	 Sketch/Curve Color..		
Edit	 Properties..		
View	 Redraw..	Ctrl+R	
View	Screen Capture		
View	 Image Capture..		
View	 Record Video..		
View	 Stop Video Record..		
View	Display		
View	 Wireframe..		
View	 Hidden Lines Visible..		
View	 Hidden Lines Removed..		
View	 Shaded With Edges..		
View	 Shaded..		
View	 Draft Quality HLR/HLV..		
View	 Shadows In Shaded Mode..		
View	 Ambient Occlusion..		
View	 Perspective..		
View	 Section View..		sec
View	 Camera View..		
View	 Curvature..		
View	 Zebra Stripes..		
View	 Surface Curvature Combs..		
View	 Draft Analysis..		
View	 Undercut Analysis..		
View	 Parting Line Analysis..		
View	 RealView Graphics..		
View	 Cartoon..		

Category	Command	Shortcut(s)	Search Shortcut
View	 Simulation Display..		
View	Tangent Edges Visible..		
View	Tangent Edges as Phantom..		
View	Tangent Edges Removed..		
View	Isolate..		
View	Modify		
View	 Orientation..		
View	 Zoom to Fit..	F	zf
View	 Zoom to Area..	Z	
View	 Zoom In/Out..		
View	 Zoom to Selection..		
View	 Rotate..		
View	 Pan..		
View	 Roll..		
View	 Turn Camera..		
View	 Previous View..	Ctrl+Shift+Z	
View	Set Current View As		
View	 Front..		
View	 Back..		
View	 Top..		
View	 Bottom..		
View	 Left..		
View	 Right..		
View	Rotate About Scene Floor..		
View	Zoom About Screen Center..		
View	 Perspective..		
View	 Section View..		
View	 Zebra Stripe Properties..		
View	 Draft Analysis..		
View	 Undercut Analysis..		
View	 Parting Line Analysis..		
View	Lights and Cameras		
View	 Add Directional Light..		
View	 Add Point Light..		
View	 Add Spot Light..		
View	 Add Sunlight..		
View	 Add Camera..		
View	 Add Walk-through..		
View	Properties		
View	Light1..		
View	Delete		
View	Light1..		
View	Hide / Show		
View	 Hide All Types..		
View	 All Annotations..		
View	 Axes..		
View	 Temporary Axes..		
View	 Cameras..		
View	 Center of mass..		

Category	Command	Shortcut(s)	Search Shortcut
View	 Bounding Box..		
View	 Coordinate Systems..		
View	 Datum Reference Frame..		
View	 Curves..		
View	 Dimension Names..		
View	 Lights..		
View	 Live Section Planes..		
View	 Origins..		
View	 Parting Lines..		
View	 Planes..		
View	 Points..		
View	 Routing Points..		
View	 Sketches..		
View	 Sketch Dimensions..		
View	 Sketch Planes..		
View	 Weld Bead..		
View	Annotation Link Errors..		
View	Annotation Link Variables..		
View	 Decals..		
View	 Grid..		
View	 Simulation Symbols..		
View	 Sketch Relations..		
View	Bodies..		
View	 Primary Planes..		
View	Toolbars		
View	CommandManager..		
View	 2D to 3D..		
View	 Align..		
View	 Annotation..		
View	 Assembly..		
View	 Blocks..		
View	 Configurations..		
View	 Curves..		
View	 Dimensions/Relations..		
View	 Fastening Feature..		
View	 MBD Dimension..		
View	Display States..		
View	 Drawing..		
View	 Explode Sketch..		
View	 Features..		
View	 Formatting..		
View	Layer..		
View	 Layout Tools..		
View	 Line Format..		
View	 Macro..		
View	 Mold Tools..		
View	MotionManager..		
View	 Quick Snaps..	F3	
View	 Reference Geometry..		

Category	Command	Shortcut(s)	Search Shortcut
View	 Render Tools..		
View	 Screen Capture..		
View	 Selection Filter..		
View	 Sheet Format..		
View	 Sheet Metal..		
View	 Sketch..		
View	 Sketch Ink..		
View	MBD..		
View	 SOLIDWORKS Add-ins..		
View	 Spline Tools..		
View	 Standard..		
View	 Standard Views..		
View	 Structure System..		
View	 Surfaces..		
View	 Table..		
View	 Tools..		
View	 View..		
View	View (Heads-Up)..		
View	 Web..		
View	 Weldments..		
View	Customize..		
View	Workspace		
View	Default..		
View	Widescreen..		
View	Dual Monitor..		
View	User Interface		
View	FeatureManager Tree Area..	F9	
View	 Dynamic Reference Visualization (Parent)..		
View	 Dynamic Reference Visualization (Child)..		
View	Toolbars..	F10	
View	Task Pane..	Ctrl+F1	
View	MotionManager..		
View	Status Bar..		
View	 Touch Mode..		
View	 Full Screen..	F11	
Insert	Boss/Base		
Insert	 Extrude..	E	
Insert	 Revolve..	R	
Insert	 Sweep..		
Insert	 Loft..		lo
Insert	 Boundary..		
Insert	 Thicken..		
Insert	Cut		
Insert	 Extrude..	Alt+E	
Insert	 Revolve..	Alt+R	
Insert	 Sweep..		
Insert	 Loft..		
Insert	 Boundary..		
Insert	 Thicken..		

Category	Command	Shortcut(s)	Search Shortcut
Insert	 With Surface..		
Insert	Features		
Insert	 Fillet/Round..		f
Insert	 Chamfer..		
Insert	 Hole Wizard..		
Insert	 Advanced Hole..		
Insert	 Thread..		
Insert	 Simple Hole..		
Insert	 Draft..		
Insert	 Shell..		
Insert	 Rib..		
Insert	 Scale..		
Insert	 Dome..		
Insert	 Freeform..		
Insert	 Deform..		
Insert	 Indent..		
Insert	 Flex..		
Insert	 Wrap..		
Insert	 Cavity..		
Insert	 Join..		
Insert	 Combine..		
Insert	 Intersect..		
Insert	 Split..		
Insert	 Move/Copy..		m
Insert	 Delete/Keep Body..		
Insert	 Convert to Mesh Body..		
Insert	 Segment Imported Mesh Body..		
Insert	 3D Texture..		
Insert	 Imported..		
Insert	Save Bodies..		
Insert	Create Assembly..		
Insert	Pattern/Mirror		
Insert	 Linear Pattern..		pat
Insert	 Circular Pattern..		
Insert	 Mirror..		mi
Insert	 Table Driven Pattern..		
Insert	 Sketch Driven Pattern..		
Insert	 Curve Driven Pattern..		
Insert	 Fill Pattern ..		
Insert	 Variable Pattern ..		
Insert	Fastening Feature		
Insert	 Mounting Boss..		
Insert	 Snap Hook..		
Insert	 Snap Hook Groove..		
Insert	 Vent..		
Insert	 Lip / Groove..		
Insert	FeatureWorks		
Insert	 Recognize Features..		
Insert	 Options..		

Category	Command	Shortcut(s)	Search Shortcut
Insert	Surface		
Insert	 Extrude..		
Insert	 Revolve..		
Insert	 Sweep..		
Insert	 Loft..		
Insert	 Boundary Surface..		
Insert	 Planar..		
Insert	 Flatten..		
Insert	 Fillet/Round..		f
Insert	 Chamfer..		
Insert	 Offset..		
Insert	 Radiate..		
Insert	 Ruled Surface..		
Insert	 Fill..		
Insert	 Freeform..		
Insert	 Mid Surface..		
Insert	 Parting Surface..		
Insert	 Surface From Mesh..		
Insert	 Extend..		
Insert	 Trim..		
Insert	 Untrim..		
Insert	 Delete Hole..		
Insert	 Knit..		
Insert	 Move/Copy..		m
Insert	 Convert to Mesh Body..		
Insert	Face		
Insert	 Delete..		
Insert	 Replace..		
Insert	 Move..		
Insert	 Heal Edges..		
Insert	 Import Diagnostics..		
Insert	Curve		
Insert	 Split Line..		
Insert	 Projected..		
Insert	 Composite..		
Insert	 Curve Through XYZ Points..		
Insert	 Curve Through Reference Points..		
Insert	 Helix/Spiral..		
Insert	Reference Geometry		
Insert	 Plane..		pl
Insert	 Live Section Plane..		
Insert	 Axis..		
Insert	 Coordinate System..		cs
Insert	 Point..		
Insert	 Center of Mass..		
Insert	 Mate Reference..		
Insert	 Grid System..		
Insert	 Bounding Box..		
Insert	Sheet Metal		

Category	Command	Shortcut(s)	Search Shortcut
Insert	 Base Flange..		
Insert	 Convert To Sheet Metal..		
Insert	 Edge Flange..		
Insert	 Miter Flange..		
Insert	 Swept Flange..		
Insert	 Hem..		
Insert	 Jog..		
Insert	 Sketched Bend..		
Insert	 Cross Break..		
Insert	 Closed Corner..		
Insert	 Welded Corner..		
Insert	 Break Corner..		
Insert	 Corner Relief..		
Insert	 Corner Trim..		
Insert	 Sheet Metal Gusset..		
Insert	 Unfold..		
Insert	 Fold..		
Insert	 Lofted Bends..		
Insert	 Bends..		
Insert	 Rip..		
Insert	 Tab and Slot..		
Insert	 Normal Cut..		
Insert	Bend Table		
Insert	From File..		
Insert	New..		
Insert	 Forming Tool..		
Insert	Structure System		
Insert	 Structure System..		
Insert	 Primary Member..		
Insert	 Secondary Member..		
Insert	 Profile Properties..		
Insert	Weldments		
Insert	 Weldment..		
Insert	 Structural Member..		
Insert	 Trim/Extend..		
Insert	 Gusset..		
Insert	 End Cap..		
Insert	 Fillet Bead..		
Insert	 Weld Bead..		
Insert	Molds		
Insert	 Insert Mold Folders..		
Insert	 Parting Line..		
Insert	 Shut-Off Surfaces..		
Insert	 Parting Surface..		
Insert	 Tooling Split..		
Insert	 Core..		
Insert	 Scale..		
Insert	 Radiate Surface..		
Insert	 Ruled Surface..		

Category	Command	Shortcut(s)	Search Shortcut
Insert	 Split..		
Insert	 Cavity..		
Insert	 Exploded View..		
Insert	 Explode Line Sketch..		
Insert	 Model Break View..		
Insert	 Part..		
Insert	Mirror Part..		
Insert	 Sketch..		
Insert	 3D Sketch..		
Insert	 3D Sketch On Plane..		
Insert	Derived Sketch..		
Insert	Sketch From Drawing..		
Insert	 Slicing..		
Insert	DXF/DWG..		
Insert	Design Study		
Insert	 Add..		
Insert	Parameters..		
Insert	Tables		
Insert	 Bill of Materials..		bom
Insert	 Design Table..		
Insert	 Title Block Table..		
Insert	 General Table..		
Insert	 General Tolerance..		
Insert	 Bend Table..		
Insert	Annotations		
Insert	 Note..		
Insert	 Balloon..		
Insert	 Stacked Balloon..		
Insert	 Surface Finish Symbol..		
Insert	 Weld Symbol..		
Insert	 Geometric Tolerance..		
Insert	 Datum Feature Symbol..		
Insert	 Datum Target..		
Insert	 Cosmetic Thread..		
Insert	 Area Hatch/Fill..		
Insert	 Location Label..		
Insert	Object..		
Insert	 Hyperlink..		
Tools	SOLIDWORKS Applications		
Tools	SOLIDWORKS Explorer..		
Tools	 Sustainability..		
Tools	 Costing..		
Tools	 Part Reviewer..		
Tools	SOLIDWORKS Task Scheduler..		
Tools	Xpress Products		
Tools	 DriveWorksXpress..		
Tools	 DFMXpress..		
Tools	 SimulationXpress..		
Tools	 FloXpress..		

Category	Command	Shortcut(s)	Search Shortcut
Tools	 Asset Publisher..		
Tools	 Defeature..		
Tools	 Export To AEC..		
Tools	 Select..		
Tools	 Magnified Selection..	G	
Tools	 Box Selection..		
Tools	 Lasso Selection..		
Tools	 Select over Geometry..		
Tools	 Select All..	Ctrl+A	
Tools	 Invert Selection..		
Tools	 Power Select..		
Tools	Compare		
Tools	DrawCompare..		
Tools	 Documents..		
Tools	 Features..		
Tools	 Geometry..		
Tools	 3D PMI..		
Tools	 Report Manager..		
Tools	Find/Modify		
Tools	 Find and Replace Annotation..		
Tools	 Find/Modify Features..		
Tools	 Simplify..		
Tools	Design Checker		
Tools	 Check Active Document..		
Tools	 Check Against Existing File..		
Tools	 Build Checks..		
Tools	 Learn Checks Wizard..		
Tools	 Feature Paint..		
Tools	 Format Painter..		
Tools	Sketch Entities		
Tools	 Line..	L	I
Tools	 Corner Rectangle..		
Tools	 Center Rectangle..		
Tools	 3 Point Corner Rectangle..		
Tools	 3 Point Center Rectangle..		
Tools	 Parallelogram..		
Tools	 Straight Slot..		
Tools	 Centerpoint Straight Slot..		
Tools	 3 Point Arc Slot..		
Tools	 Centerpoint Arc Slot..		
Tools	 Polygon..		
Tools	 Circle..	C	
Tools	 Perimeter Circle..		
Tools	 Centerpoint Arc..		
Tools	 Tangent Arc..		
Tools	 3 Point Arc..		a
Tools	 Ellipse..		e
Tools	 Partial Ellipse..		
Tools	Parabola..		

Category	Command	Shortcut(s)	Search Shortcut
Tools	 Conic..		
Tools	 Spline..		
Tools	 Style Spline..		
Tools	 Spline on Surface..		
Tools	 Equation Driven Curve..		
Tools	 Point..		
Tools	 Centerline..		
Tools	 Midpoint Line..		
Tools	 Text..		
Tools	 Plane..		
Tools	 Route Line..		
Tools	 Belt/Chain..		
Tools	Sketch Tools		
Tools	 Fillet..		
Tools	 Chamfer..		
Tools	 Offset Entities..		o
Tools	 Offset On Surface..		
Tools	 Convert Entities..		
Tools	 Intersection Curve..		
Tools	 Face Curves..		
Tools	 Segment..		
Tools	 Trim..	T	tr
Tools	 Extend..	X	
Tools	 Split Entities..		
Tools	 Jog Line..		
Tools	 Construction Geometry..		
Tools	 Make Path..		
Tools	 Mirror..		
Tools	 Dissolve..		
Tools	 Dynamic Mirror..		
Tools	 Stretch Entities..		
Tools	 Move..		
Tools	 Rotate..		
Tools	 Scale..		
Tools	 Copy..		
Tools	 Replace Entity..		
Tools	 Linear Pattern..		
Tools	 Circular Pattern..		
Tools	 Edit Linear Pattern..		
Tools	 Edit Circular Pattern..		
Tools	 Edit Polygon..		
Tools	 Create Sketch from Selections..		
Tools	 Repair Sketch..		
Tools	 SketchXpert..		
Tools	Align		
Tools	 Sketch..		
Tools	 Align Grid/Origin..		
Tools	Modify..		
Tools	Close Sketch to Model..		

Category	Command	Shortcut(s)	Search Shortcut
Tools	Check Sketch for Feature..		
Tools	2D to 3D		
Tools	 Front..		
Tools	 Top..		
Tools	 Right..		
Tools	 Bottom..		
Tools	 Left..		
Tools	 Back..		
Tools	 Auxiliary..		
Tools	 Extrude..		
Tools	 Cut..		
Tools	Pen Tools		
Tools	Pen..		
Tools	 Eraser..		
Tools	 Select..		
Tools	 Ruler..		
Tools	 Protractor..		
Tools	 Convert to Shape..		
Tools	 Convert to Entities..		
Tools	 Sketch Picture..		
Tools	 Pen Sketch..		
Tools	 Area Hatch/Fill..		
Tools	Sketch Settings		
Tools	 Automatic Relations..		
Tools	Automatic Solve..		
Tools	Enable Snapping..		
Tools	 Shaded Sketch Contours..		
Tools	 No Solve Move..		
Tools	 Detach Segment on Drag..		
Tools	Override Dims on Drag/Move..		
Tools	Pen Settings		
Tools	 Pen Properties..		
Tools	 Touch..		
Tools	 Auto Convert to Shape..		
Tools	 Auto Convert to Entities..		
Tools	Blocks		
Tools	 Make..		b
Tools	 Edit ..		
Tools	 Insert....		
Tools	 Add/Remove Entities..		
Tools	 Rebuild..		
Tools	 Save..		
Tools	 Explode..		
Tools	Spline Tools		
Tools	 Add Tangency Control..		
Tools	 Add Curvature Control..		
Tools	 Insert Spline Point..		
Tools	 Insert Control Vertex..		
Tools	 Simplify Spline..		

Category	Command	Shortcut(s)	Search Shortcut
Tools	 Convert to Style Spline..		
Tools	 Convert to Generic Spline..		
Tools	 Convert to Interpolating Spline..		
Tools	 Fit Spline..		
Tools	 Show Spline Handles..		
Tools	 Show Spline Control Polygon..		
Tools	 Show Inflection Points..		
Tools	 Show Minimum Radius of Curvature..		
Tools	 Show Curvature..		
Tools	Dimensions		
Tools	 Smart..	D	
Tools	 Horizontal..		
Tools	 Vertical..		
Tools	 Ordinate..		
Tools	 Horizontal Ordinate..		
Tools	 Vertical Ordinate..		
Tools	 Angular Running Dimension..		
Tools	 Path Length..		
Tools	 Align Ordinate..		
Tools	 Fully Define Sketch..		
Tools	Relations		
Tools	 Add..		
Tools	 Display/Delete..		
Tools	Quick Snaps		
Tools	 Points..		
Tools	 Center Points..		
Tools	 Mid-points..		
Tools	 Quadrant Points..		
Tools	 Intersections..		
Tools	 Nearest..		
Tools	 Tangent..		
Tools	 Perpendicular..		
Tools	 Parallel..		
Tools	 Horizontal/Vertical..		
Tools	 H/V To Points..		
Tools	 Length..		
Tools	 Grid..		
Tools	 Angle..		
Tools	 Geometry Analysis..		
Tools	 Equations..		
Tools	 Thickness Analysis..		
Tools	 Symmetry Check..		
Tools	MBD Dimension		
Tools	 Auto Dimension Scheme..		
Tools	 Location Dimension..		
Tools	 Size Dimension..		
Tools	 Basic Location Dimension..		
Tools	 Basic Size Dimension..		
Tools	Datum..		

Category	Command	Shortcut(s)	Search Shortcut
Tools	 Geometric Tolerance..		
Tools	 Pattern Feature..		
Tools	 General Profile Tolerance..		
Tools	 Show Tolerance Status..		
Tools	 Import Scheme..		
Tools	 Copy Scheme..		
Tools	 Delete All Tolerances..		
Tools	 TolAnalyst Study..		
Tools	Macro		
Tools	 Edit..		
Tools	 New..		
Tools	 Record..		
Tools	 Run..		
Tools	 Stop..		
Tools	Evaluate		
Tools	 Measure..	Ctrl+T	
Tools	 Markup View..		
Tools	 Mass Properties..		
Tools	 Section Properties..		
Tools	 Performance Evaluation..		
Tools	 Check..		
Tools	 Interference Detection..		
Tools	 Import Diagnostics..		
Tools	 Deviation Analysis..		
Tools	Add-Ins..		
Tools	Save/Restore Settings..		
Tools	Customize..		
Tools	 Options..		
Window	 Span Displays..		
Window	Viewport		
Window	 Single View..		
Window	 Two View - Horizontal..		
Window	 Two View - Vertical..		
Window	 Four View..		
Window	 Link Views..		
Window	 New Window..		
Window	Cascade..		
Window	 Tile Horizontally..		
Window	 Tile Vertically..		
Window	Arrange Icons..		
Window	Close All..		
Window	 Browse Open Documents..		
Help	 Welcome to SOLIDWORKS..	Ctrl+F2	
Help	 SOLIDWORKS Help..		
Help	SOLIDWORKS Tutorials..		
Help	API Help..		
Help	Search		
Help	 SOLIDWORKS Help..	H	
Help	 Commands..	W	

Category	Command	Shortcut(s)	Search Shortcut
Help	 Files and Models..	I	
Help	 MySolidWorks..		
Help	 Knowledge Base..	K	
Help	 Community Forum..	O	
Help	 Blogs..		
Help	 CAD Models..		
Help	 Training..		
Help	 Twitter..		
Help	 Youtube..		
Help	Release Notes..		
Help	What's New		
Help	HTML..		
Help	PDF..		
Help	 Interactive..		
Help	 Introducing SOLIDWORKS (pdf)..		
Help	Moving from 2D to 3D..		
Help	Use SOLIDWORKS Web Help..		
Help	Check for Updates..		
Help	SolidNetWork License Manager..		
Help	My Products..		
Help	About SOLIDWORKS..		
Others	 Front	Ctrl+1	
Others	 Back	Ctrl+2	
Others	 Left	Ctrl+3	
Others	 Right	Ctrl+4	
Others	 Top	Ctrl+5	
Others	 Bottom	Ctrl+6	
Others	 Isometric	Ctrl+7	
Others	 Normal To	Ctrl+8,SpaceBar	
Others	Command option toggle	A	
Others	 Expand/Collapse Tree		
Others	 Collapse all Items.	Shift+C	
Others	 Filter Edges		
Others	Find/Replace	Ctrl+F	
Others	Next Edge	N	
Others	 Force Rebuild	Ctrl+Q	
Others	 Force Rebuild All Configurations	Ctrl+Shift+Q	
Others	 Shortcut Bar	S	
Others	Show Flat Tree View		
Others	 Filter Vertices	V	
Others	Scroll to FeatureManager tree bottom	End	
Others	 Escape		
Others	Toggle Notes Upper Case.	Shift+F3	
Others	 Toggle Selection Filter Toolbar	F5	
Others	 Toggle Selection Filters	F6	
Others	 Spell Checker	F7	
Others	Hide/Show Display Pane.	F8	
Others	Scroll to FeatureManager tree top	Home	
Others	Next Command Manager Tab	Ctrl+Next	

Category	Command	Shortcut(s)	Search Shortcut
Others	Select Annotation View	SingleQuote	
Others	Previous Command Manager Tab	Ctrl+Prior	
Others	 View Selector	Ctrl+SpaceBar	
Others	 Filter Faces		
Others	Accept Edge	Y	
Others	Zoom Out		
Others	Zoom In	Shift+Z	
Others	Move Selection Breadcrumbs, Confirmation		
Others	 Cancel		
Others	 Make Horizontal		
Others	 Make Vertical		
Others	 Make Collinear		
Others	 Make Coradial		
Others	 Make Perpendicular		
Others	 Make Parallel		
Others	 Make Tangent		
Others	 Make Concentric		
Others	 Make Midpoint		
Others	 Make Intersection		
Others	 Make Coincident		
Others	 Make Curves Equal Length		
Others	 Make Equal		
Others	 Make Symmetric		
Others	 Make Fixed		
Others	 Make Pierce		
Others	Make Tangent Face		
Others	 Merge Points		
Others	 Make Normal		
Others	 Make Parallel to YZ plane		
Others	 Make Parallel to ZX plane		
Others	 Adds equal curvature to the common end of		
Others	 Adds equal tangent to the common end of t		
Others	 Make AlongZ		
Others	 Show Triad Manipulator		
Others	 Instant3D		
Others	 Instant2D		
Others	Parent/Child...		
Others	 Trimetric		
Others	 Dimetric		
Others	Exit Isolate		
Others	 Select Other		
Others	 Hide/Show Components		
Others	 Change Layer		
Others	 Layer Properties		
Others	 Flexible or Rigid		
Others	 SmartMates		
Others	 Hide the Hovered-over Component/Bodies	TAB	
Others	 Show the Hovered-over Component/Bodies	Shift+TAB	
Others	 Show all the hidden Components/Bodies	Ctrl+Shift+TAB	

Category	Command	Shortcut(s)	Search Shortcut
Others	 Small (default)		
Others	 Medium		
Others	 Large		
Others	 Shaded Sketch Contours		
Others	 Select over Geometry		
Search	 Search SOLIDWORKS Help	H	
Search	 Search Commands	W	
Search	 Search Files and Models	I	
Search	 Search MySolidWorks		
Search	 Search Knowledge Base	K	
Search	 Search Community Forum	O	
Search	 Search Blogs		
Search	 Search CAD Models		
Search	 Search Training		
Search	 Search Twitter		
Search	 Search Youtube		
Macros	 New Macro Button 		